



नेपाल सरकार

राष्ट्रिय मामिला तथा स्थानीय विकास मन्त्रालय

केन्द्रीय आयोजना कार्यान्वयन इकाई

भूकम्पीय आवास पुर्ननिर्माण आयोजना

जगन्नाथ, सप्तरी

सिन्धुपाल्चोक

पुनःप्रमाणीकरण गर्नुपर्ने लाभग्राही विवरण ।

Table with 23 columns: S.N, G ID, RV/RS, Grievant Name, House Owner Name, District, VDC/MUN (P), Ward (P), EA, Tole, GP/NP, WARD, HH SN, Slip No, Related P.A, HIOP_ADD, HIOP_COND, SC, SDG, STS, MDG, PDG, RDG, RTS, Clarification, Mobile, Longiturd, Latitude, Altitude. Rows 1-38 contain detailed data for various households in Sindhu Palchok.

39	253704	RV	Hari Nath Neupane	Hari Nath Neupane	Sindhupalchowk	Badegaun	3	0		Indrawati	6	160	398927			2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade-1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place		85.604736, 85.604836	27.772604, 27.772648	1115.2466, 1117.2858
40	253707	RV	Surya Bikram Thapa	Surya Bikram Thapa, Uttam Bikram Thapa	Sindhupalchowk	Badegaun	3	0		Indrawati	6	161	398929	Sindhupalchowk,8 himtar-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.605118	27.772753	1116.3979
41	253807	RV	Surya Bikram Thapa	Surya Bikram Thapa, Uttam Bikram Thapa	Sindhupalchowk	Badegaun	3	0		Indrawati	6	161	398929	Sindhupalchowk,8 himtar-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.605118	27.772753	1116.3979
42	253815	RV	Krishna Prasad Acharya	Krishna Prasad Acharya	Sindhupalchowk	Badegaun	3	0		Indrawati	6	166	398934	Bhaktapur,Madhya pur Thimi-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.606171	27.772821	1127.7858
43	253705	RV	Ram Prasad Neupane	Ram Prasad Neupane	Sindhupalchowk	Badegaun	3	0		Indrawati	6	167	398935	Bhaktapur,Balkot-5	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.606659	27.772772	1126.6703
44	253823	RV	Devendra Raj Neupane	Debendra Raj Neupane	Sindhupalchowk	Badegaun	3	0		Indrawati	6	169	398937	Bhaktapur,Madhya pur Thimi-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.606773	27.772825	1120.9802
45	253650	RV	Ram Lal Rasali	Ram Lal Rasali, Tilak Bahadur Kami	Sindhupalchowk	Badegaun	4	0		Indrawati	5	24	557474	Kathmandu,Danch hi-8	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.60144	27.783844	1243.1804
46	253651	RV	Tilak Bahadur Kami	Ram Lal Rasali, Tilak Bahadur Kami	Sindhupalchowk	Badegaun	4	0		Indrawati	5	24	557475	Kathmandu,Danch hi-8	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.60144	27.783844	1243.1804
47	253747	RV	Ganesh Acharya	Ganesh Acharya	Sindhupalchowk	Badegaun	4	0		Indrawati	5	40	557491	Kathmandu,Mulpa ni-5	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place		85.603645	27.781904	1176.2922
48	253658	RV	Kedar Nath Acharya	Kedar Nath Acharya	Sindhupalchowk	Badegaun	4	0		Indrawati	5	41	557492	Kathmandu,Kages wori-Manahara-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.603607	27.781902	1154.5122
49	253654	RV	Khadananda Timalisina	Khadananda Timalisina	Sindhupalchowk	Badegaun	4	0		Indrawati	5	43	557494	Kathmandu,Gokar neswor-1	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place		85.603386	27.781765	1147.1443
50	253653	RV	Krishna Prasad Timalisina	Krishna Prasad Timalisina	Sindhupalchowk	Badegaun	4	0		Indrawati	5	44	557495	Kathmandu,Mulpa ni-9	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place		85.603432	27.781895	1177.6162
51	253657	RV	Tek Nath Acharya	Tek Nath Acharya	Sindhupalchowk	Badegaun	4	0		Indrawati	5	45	557496	Kathmandu,Shank arapura-5	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.603249	27.781927	1172.0349
52	253745	RV	Sabitri Timalisina	Sabitri Timalisina	Sindhupalchowk	Badegaun	4	0		Indrawati	5	51	557502	Kathmandu,Gokar neswor-8	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.603699	27.783354	1248.1145
53	251373	RV	Dinesh Acharya	Dinesh Acharya	Sindhupalchowk	Badegaun	4	0		Indrawati	5	72	557523	Kathmandu,Kapan- 1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.597542	27.780825	1150.7952
54	253655	RV	Lal Chandra Acharya	Lal Chandra Acharya	Sindhupalchowk	Badegaun	4	0		Indrawati	5	84	557535	Kathmandu,Kathm andu-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.598373	27.780901	1134.3439
55	253744	RV	Ramkumari Acharya	Ram Kumari Acharya	Sindhupalchowk	Badegaun	4	0		Indrawati	5	86	557536	Kathmandu,Kapan- 1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.598381	27.780844	1133.6694
56	253656	RV	Ramhari Acharya	Ramhari Acharya	Sindhupalchowk	Badegaun	4	0		Indrawati	5	92	557543	Kathmandu,Danch hi-7	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.597397	27.780939	1129.8328
57	253746	RV	Rajan Prasad Acharya	Rajan Prasad Acharya	Sindhupalchowk	Badegaun	4	0		Indrawati	5	137	556216	Kathmandu,Gokar neswor-15	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.594116	27.778202	1069.1531
58	253751	RV	Arjun Bikram Thapa	Arjun Bikram Thapa, Dev Bikram Thapa	Sindhupalchowk	Badegaun	5	0		Indrawati	6	34	557262	Kathmandu,Kathm andu-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	14820914	85.624832	27.782631	1454.3469
59	253756	RV	Gyan Bikram Thapa	Gyan Bikram Thapa chhetri	Sindhupalchowk	Badegaun	5	0		Indrawati	6	55	556235	Kavrepalanchowk, Ugratara Jangal-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808932611	85.621674	27.787119	1473.3345
60	253750	RV	Baburam Khadka	Baburam Khadka	Sindhupalchowk	Badegaun	5	0		Indrawati	6	59	556240	Kathmandu,Kathm andu-7	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851067001	85.623169	27.786541	1448.9886
61	253754	RV	Hari Bahadur Khadka	Hari Bahadur Khadka	Sindhupalchowk	Badegaun	5	0		Indrawati	6	60	556241	Kathmandu,Kathm andu-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849731981	85.623154	27.786552	1466.2462
62	253753	RV	Jiban Khadka	Jiban Khadka	Sindhupalchowk	Badegaun	5	0		Indrawati	6	62	556243	Kathmandu,Kathm andu-14	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841949887	85.62619	27.788433	1335.9689
63	253752	RV	Chok Prasad Bhattarai	Chok Prasad Bhattarai	Sindhupalchowk	Badegaun	5	0		Indrawati	6	77	556183	Kathmandu,Danch hi-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813679597	85.626915	27.797075	1200.3048
64	253725	RV	Suntali Tamang	Suntali Tamang	Sindhupalchowk	Badegaun	6	0		Indrawati	5	141	1190669			1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9813216889	85.594177	27.785923	1149.6057
65	253732	RV	Bishnu Rashaili	Bishnu Rashaili	Sindhupalchowk	Badegaun	6	0		Indrawati	5	177	1190708			1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849375382	85.590584	27.781948	1100.355
66	253738	RV	Gangaram Tamang	Gangaram Tamang	Sindhupalchowk	Badegaun	7	0		Indrawati	5	34	551534	Kathmandu,Kapan- 99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803850557	85.608177	27.787329	1426.7482
67	253740	RV	Jute Lama	Jute Lama	Sindhupalchowk	Badegaun	7	0		Indrawati	5	45	551546			1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9823124223	85.606804	27.787325	1402.1421
68	253742	RV	Guman Tamang	Guman Tamang	Sindhupalchowk	Badegaun	7	0		Indrawati	5	52	1190503			2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9803422851	85.602951, 85.603142	27.78743, 27.787779	1272.4968, 1273.962
69	253708	RV	Birendra Himalaya	Birendra Himalaya	Sindhupalchowk	Badegaun	9	0		Indrawati	5	68	367041	Sindhupalchowk,C hautara-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741088892	85.614182	27.791208	1556.8823
70	253709	RV	Shyam Buddha Nakarmi	Shyam Budhha Nakarmi	Sindhupalchowk	Badegaun	9	0		Indrawati	5	72	367046	Kathmandu,Kathm andu-9	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841442385	85.61364	27.791224	1542.2512
71	253714	RV	Dinesh Chandra Himalaya	Dinesh Chandra Himalaya	Sindhupalchowk	Badegaun	9	0		Indrawati	5	89	1175968	Kavrepalanchowk, Banaga-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808055200	85.613617	27.791328	1547.4276
72	250598	RV	Surendra Himalaya	Surendra Himalaya	Sindhupalchowk	Badegaun	9	0		Indrawati	5	92	1175971	Kathmandu,Kathm andu-16	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9849188291	85.614143	27.791418	1542.5944
73	253643	RV	Amir Prasad Kayastha	Amir Prasad Kayast	Sindhupalchowk	Badegaun	9	0		Indrawati	5	95	1175974	Bhaktapur,Bhaktap ur-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841257520	85.615471	27.793804	1526.934
74	253713	RV	Bishnu Bhakta Bidhyadhar	Bishnu Bhakta Bidhyadhar	Sindhupalchowk	Badegaun	9	0		Indrawati	5	102	1175980	Kathmandu,Kathm andu-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841820066	85.614517	27.790575	1561.9928
75	249297	RV	Rammaya Paudel	Namraj Poudel	Sindhupalchowk	Bansbari	1	0	Bansbari	Melamchi Municipality	12	9	338709	Kathmandu,Kages wori-Manahara-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860234272	85.572113	27.799671	762.96997
76	249459	RV	Rammani Nepal	Rammani Nepal	Sindhupalchowk	Bansbari	2	0	Bansbari	Melamchi Municipality	12	7	11900008	Kathmandu,Gokar neswor-99	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741114398	85.566002	27.794447	929.71063
77	249456	RV	Debendra Prasad Nepal	Debendra Prasad Nepal	Sindhupalchowk	Bansbari	2	0	Bansbari	Melamchi Municipality	12	8	1190009			2	Grade 4, Grade 2	Reconstruct, Minor Repair	Grade 4, Grade 3	Grade 4, Unrecognized	Grade 4, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9843611950	85.565971, 85.572574	27.791134, 27.794477	738.45129, 925.87671
78	249474	RV	Manju Kumari Chalise	Bachuram Nepal	Sindhupalchowk	Bansbari	2	0	Bansbari	Melamchi Municipality	12	10	11990011	Sindhupalchowk,8 ansbari-7	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741188165	85.566116	27.794752	937.28314
79	249460	RV	Ishwori Prasad Nepal	Ishwori Prasad Nepal	Sindhupalchowk	Bansbari	2	0	Bansbari	Melamchi Municipality	12	12	1190013			2	Grade 4, Grade 2	Reconstruct, Minor Repair	Grade 4, Grade 2	Grade 4, Grade 2	Grade 4, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9849147942	85.566208, 85.572151	27.790308, 27.794704	725.34937, 936.13819
80	249464	RV	Shiva Prasad Nepal	Siba Prasad Nepal	Sindhupalchowk	Bansbari	2	0	Bansbari	Melamchi Municipality	12	13	1190014	Kathmandu,Shank arapura-99	Partial Damage	3	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 5, Grade 1	Grade 5, Grade 5, Grade 1	Grade 5, Grade 5, Grade 1	Reconstruct, Minor Repair	Habitable House in Other Place	16223195	85.570641, 85.57235	27.790621, 27.79492	726.71838, 939.45441
81	249367	RV	Rohani Prasad Nepal	Rohini Prasad Nepal	Sindhupalchowk	Bansbari	2	0	Bansbari	Melamchi Municipality	12	24	1190023			2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9813936333	85.565628, 85.572845	27.791113, 27.794279	734.0047, 943.67548
82	249729	RV	Bandha Tharuni	Sita Majhi	Sindhupalchowk	Bansbari	2	0	Bansbari	Melamchi Municipality	12	28	1190029			1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849503371	85.570221	27.787954	713.77179
83	249626	RV	Sita Majhi	Sita Majhi	Sindhupalchowk	Bansbari	2	0	Bansbari	Melamchi Municipality	12	28	1190028			1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849503371	85.570221	27.787954	713.77179
84	249709	RV	Chitra Kumari Nepal	Chitra Kumari Nepal	Sindhupalchowk	Bansbari	2	0	Bansbari	Melamchi Municipality	12	35	1190037	Kathmandu,Gokar neswor-99	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9843456262	85.571159	27.790092	734.33649
85	249385	RV	Prakash Nepal	Prakash Nepal	Sindhupalchowk	Bansbari	2	0	Bansbari	Melamchi Municipality	12	36	1190098			2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Unrecognized	Grade 5, Un						

135	249324	RV	Shuku Tamangni	Suku Tamangni	Sindhupalchowk	Bansari	249324	7	0	Bansbari	Melamchi Municipality	12	38	551338				1	Grade 2	Minor Repair	Grade 4	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	85.574036	27.791971	745.1283	
136	249349	RV	Prem Lal Shrestha	Suntali Shrestha	Sindhupalchowk	Bansbari		7	0	Bansbari	Melamchi Municipality	12	40	551340				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	85.574226	27.792171	722.29279	
137	249370	RV	Madhusudan Luitel	Madhusudan Luitel	Sindhupalchowk	Bansbari		8	0	Bansbari	Melamchi Municipality	12	109	338489	Kathmandu,Chapali Bhradakali-8	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741110253	85.534439	27.807968	1253.6465	
138	249372	RV	Shiva Prasad Luitel	Shiv Prasad Luitel	Sindhupalchowk	Bansbari		8	0	Bansbari	Melamchi Municipality	12	110	338490	Kathmandu,Chapali Bhradakali-8	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841390954	85.534515	27.80788	1248.7837	
139	249400	RV	Yung Bahadur Tamang	Young Bahadur Tamang	Sindhupalchowk	Bansbari		9	0	Bansbari	Melamchi Municipality	12	44	338467				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9843549451	85.544655	27.807871	1362.3835
140	249717	RV	Sun Bahadur Tamang	Sun Bahadur Tamang	Sindhupalchowk	Bansbari		9	0	Bansbari	Melamchi Municipality	12	47	338470				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9851066094	85.545578	27.806797	1365.8767
141	249613	RV	Netra Bahadur Tamang	Netra Bahadur Tamang	Sindhupalchowk	Bansbari		9	0	Bansbari	Melamchi Municipality	12	59	338683				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9860256127	85.545471	27.805779	1353.5789
142	253907	RV	Bhim Lal Shrestha	Tanka Bahadur Shrestha	Sindhupalchowk	Baramchi		2	0		Jugal	5	116	329394				2	Grade 2, Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	85.774109	27.837111	1126.1758	
143	250593	RV	Dan Bahadur Shrestha	Tanka Bahadur Shrestha	Sindhupalchowk	Baramchi		2	0		Jugal	5	116	329393				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	85.774109	27.837111	1126.1758	
144	253901	RV	Nir Bahadur Shrestha	Tanka Bahadur Shrestha	Sindhupalchowk	Baramchi		2	0		Jugal	5	116	329395				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	85.774109	27.837111	1126.1758	
145	253900	RV	Tanka Bahadur Shrestha	Tanka Bahadur Shrestha	Sindhupalchowk	Baramchi		2	0		Jugal	5	116	329276				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	85.774109	27.837111	1126.1758	
146	253898	RV	Bishnu Prasad Ghimire	Bishnu Parsad Ghimire	Sindhupalchowk	Baramchi		2	0		Jugal	5	154	329333	Kathmandu,Kathmandu-35	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9851010495	85.780518	27.841755	1175.4806
147	254462	RV	Shibahari Ghimire	Shivahari Ghimire	Sindhupalchowk	Baramchi		2	0		Jugal	5	220	329317	Kathmandu,Kathmandu-35	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.768204	27.849457	850.77063	
148	253896	RV	Yagya Prasad Paudel	Yagya Parsad Paudel	Sindhupalchowk	Baramchi		3	0		Jugal	5	1	329189	Bhaktapur,Mathyapur Thimi-3	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Usual Place		85.767204	27.85162	920.3905	
149	254458	RV	Aasalal Tamang	Asha Lal Tamang	Sindhupalchowk	Baramchi		3	0		Jugal	5	13	329199				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9741420185	85.762871	27.860889	1109.7433
150	253773	RV	Min Bahadur Magar	Min Bahadur Magar	Sindhupalchowk	Baramchi		3	0		Jugal	5	23	1177409				1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741314903	85.762672	27.860136	1097.8737
151	253769	RV	Man Bahadur Lamichhane	Man Bahadur Lamichhane	Sindhupalchowk	Baramchi		9	0		Jugal	5	1	513363	Kathmandu,Kathmandu-9	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	14462707	85.761848	27.869442	1232.1393
152	254460	RV	Puspa Raj Timalasina	Pushpa Raj Timalasina	Sindhupalchowk	Baramchi		9	0		Jugal	5	32	513398	Kathmandu,Kathmandu-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741183888	85.75985	27.870907	1137.7791
153	251365	RV	Shibahari Upadhyaya	Shivahari Upadhyaya	Sindhupalchowk	Baramchi		9	0		Jugal	5	34	513401	Kathmandu,Kathmandu-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741215074	85.759872	27.870539	1140.0266
154	253774	RV	Krishna Prasad Paudel	Krishna Prasad Paudel	Sindhupalchowk	Baramchi		9	0		Jugal	5	37	513404	Kathmandu,Kathmandu-14	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803578455	85.75943	27.871786	1129.1587
155	253903	RV	Krishna Hari Paudel	Krishna Hari Paudel	Sindhupalchowk	Baramchi		9	0		Jugal	5	45	513412	Bhaktapur,Mathyapur Thimi-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741258141	85.759407	27.87048	1119.3752
156	253904	RV	Chet Narayan Paudel	Bedh Maya Upadhyaya	Sindhupalchowk	Baramchi		9	0		Jugal	5	46	513413	Bhaktapur,Mathyapur Thimi-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741180249	85.759438	27.8706	1116.4722
157	253902	RV	Tika Datta Paudel	Tika Datta Paudel	Sindhupalchowk	Baramchi		9	0		Jugal	5	47	513414	Bhaktapur,Mathyapur Thimi-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860927775	85.759422	27.870762	1119.1644
158	254459	RV	Rishiram Paudel	Rishi Ram Paudel	Sindhupalchowk	Baramchi		9	0		Jugal	5	57	513426	Bhaktapur,Mathyapur Thimi-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741079020	85.758278	27.870115	1048.3678
159	254024	RV	Kesari Tamang	Bisman Tamang	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	2	399076	23-6-1-0-2			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9616425688	85.905128	27.804436	1164.6517
160	254034	RV	Buddha Bdr Lama	Buddha Bahadur Lama	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	19	399095				1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9616650199	85.904152	27.804157	1140.6609
161	253952	RV	Rama Karki Basnet	Ruma Karki Basnet	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	72	399049				1	Grade 2	Minor Repair	Grade 2	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9818126828	85.900681	27.802513	1114.3883
162	253836	RV	Ram Sharan Karki	Ram Sharan Karki	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	76	399703				1	Grade 2	Minor Repair	Grade 2	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9851011800	85.900719	27.801476	1099.3936
163	253943	RV	Sabitri Basnet	Sabitri Basnet	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	100	399677				1	Grade 2	Minor Repair	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9818017157	85.90033	27.802704	1101.6942
164	251357	RV	Purna Bdr Basnet	Purna Bahadur Basnet	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	134	399612	Lalitpur,Lalitpur-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741037229	85.900002	27.792821	1016.1838
165	254211	RV	Kamala Basnet	Kamala Basnet	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	139	399617				2	Grade 4, Grade 1	Reconstruct, Minor Repair	Grade 3, Grade 2	Grade 4, Grade 2	Grade 4, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9817025125	85.900421	27.800535	1043.4268
166	254021	RV	Kala Bhandari	Kala Bhandar Basnet, Sharmila Basnet	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	144	399623				1	Grade 2	Minor Repair	Grade 4	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9619416484	85.900154	27.800005	1044.6005
167	252287	RV	Sharmila Basnet	Kala Bhandar Basnet, Sharmila Basnet	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	144	399622				1	Grade 2	Minor Repair	Grade 4	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9619416484	85.900154	27.800005	1044.6005
168	254026	RV	Ambar Bdr Karki	Raj Kumar Karki	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	199	399557				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849262354	85.898659	27.802299	1036.4197
169	253830	RV	Gopi Lal Biswokarma	Gopial Bishwakarma	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	217	1174452				1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9841101336	85.898087	27.803267	1009.3846
170	254031	RV	Tek Bdr Bk	Tek Bahadur Bishwakarma	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	225	1174460				2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	85.897652	27.803724	1022.789	
171	254197	RV	Rabin Rokka	Rabin Rokka	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	238	1174473				1	Grade 2	Minor Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9851044555	85.892929	27.801764	875.35028
172	254023	RV	Ningi Sherpini	Ninji Sherpini	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	243	1176180	23-6-1-0-230			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9860636780	85.896004	27.797899	818.43439
173	254202	RV	Bishnu Kaji Bhujel	Bishnu Kaji Bhujel	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	246	1176182				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841901808	85.896141	27.796959	855.47729
174	254146	RV	Umesh Shrestha	Umesh Shrestha	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	247	1176183				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841101607	85.896065	27.796991	819.93317
175	254029	RV	Dipendra Shrestha	Dipendra Shrestha, Rajendra Shrestha	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	263	1176026	23-6-1-0-248			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9843091028	85.896233	27.795576	828.6369
176	254025	RV	Tilak Bdr Shrestha	Tilak Bahadur Shrestha	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	264	1176027	23-6-1-0-249			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9841563890	85.895996	27.797812	830.21466
177	253949	RV	Tasi Angmu Sherpa	Tashi Aangmu Sherpa	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	265	1176028				1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9611105489	85.896507	27.795696	832.82904
178	253946	RV	Khel Bdr Shrestha	Khel Bahadur Shrestha	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	282	1176045				1	Grade 2	Minor Repair	Grade 3	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9851065240	85.896416	27.794973	838.9422
179	253837	RV	Puspa Shrestha	Kismet Shrestha	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	296	1176163				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841956746	85.896423	27.794806	828.86237
180	250587	RV	Dil Bdr Shrestha	Dil Bahadur Shrestha	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	306	1176127				1	Grade 2	Minor Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9851038942	85.896965	27.794968	827.05835
181	253955	RV	Sangel Sherpa	Dolma Sherpa	Sindhupalchowk	Barhabise		1	0		Barhabise Municipality	3	307	1176128				1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable				

184	254144	RV	Nima Dorje Sherpa	Nima Dorje Sherpa	Sindhupalchowk	Barhabise	1	0		Barhabise Municipality	3	311	1176133		Kathmandu,Kathmandu-6	No Damage	1	Grade 3	Major Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	9801264231	85.896996	27.794437	821.86859
185	254027	RV	Furlamu Sherpa	Fur Lamu Sherpa	Sindhupalchowk	Barhabise	1	0		Barhabise Municipality	3	317	1176139				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818314264	85.8974	27.793379	852.27332
186	253953	RV	Niraj Timsina	Niraj Timsina	Sindhupalchowk	Barhabise	1	0		Barhabise Municipality	3	318	1176140	23-6-1-0-290			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9843039102	85.897148	27.793758	821.08929
187	254204	RV	Tulsi Maya Shrestha	Tulashi Maya Shresrha	Sindhupalchowk	Barhabise	1	0		Barhabise Municipality	3	320	1176142				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841844863	85.897362	27.793423	844.29535
188	254145	RV	Ek Bdr Basnet	Ek Bahadur Basnet	Sindhupalchowk	Barhabise	1	0		Barhabise Municipality	3	321	1176143				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849104702	85.89817	27.793873	856.11353
189	254148	RV	Sharmila Shakya	Sharmila Shakya	Sindhupalchowk	Barhabise	1	0		Barhabise Municipality	3	324	1176146				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841910199	85.897438	27.793427	847.66089
190	254121	RV	Janak Lal Shrestha	Janak Lal Shrestha	Sindhupalchowk	Barhabise	1	0		Barhabise Municipality	4	333	1176105				1	Grade 2	Minor Repair	Grade 4	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841901686	85.897652	27.792952	828.25507
191	254030	RV	Sharmila Shrestha	Sharmila Shrestha	Sindhupalchowk	Barhabise	1	0		Barhabise Municipality	3	334	1176106				2	Grade 3, Grade 2	Major Repair , Minor Repair	Grade 3, Grade 3	Grade 3, Unrecognized	Grade 3, Unrecognized	Major Repair , Unrecognized	Matrix & Photo not cleared or mismatch	9843019823	85.897461, 85.897591	27.793045, 27.79319	823.4176, 830.57788
192	254080	RV	Shyam Thapa	Shyam Thapa	Sindhupalchowk	Barhabise	2	0		Barhabise Municipality	3	62	401065		Kathmandu,Kathmandu-10	Partial Damage	1	Grade 4	Reconstruct	Grade 3	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9851010717	85.908455	27.797495	1238.437
193	254079	RV	Purna Bdr Thapa	Purna Bahadur Thapa	Sindhupalchowk	Barhabise	2	0		Barhabise Municipality	3	64	401067		Kathmandu,Kathmandu-15	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841533915	85.908485	27.797884	1248.4252
194	254076	RV	Dan Bdr Karki	Laati Karki, Yanta Bahadur Karki	Sindhupalchowk	Barhabise	2	0		Barhabise Municipality	3	89	401019	23-6-2-0-87			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9741015783	85.907196	27.798662	1244.0565
195	253959	RV	Bhupendra Thapa	Bhupendra Thapa	Sindhupalchowk	Barhabise	2	0		Barhabise Municipality	3	104	401111				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803191494	85.906204	27.80168	1244.3469
196	253958	RV	Sarita Khadka	Sarita Khadka	Sindhupalchowk	Barhabise	2	0		Barhabise Municipality	3	116	401123				1	Grade 2	Minor Repair	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9849015472	85.907158	27.797869	1215.9773
197	253957	RV	Bhagwati Giri	Bhagwati Giri	Sindhupalchowk	Barhabise	2	0		Barhabise Municipality	3	120	401127				1	Grade 1	Not Required	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9808487159	85.90728	27.798326	1228.9672
198	254082	RV	Gopini Bhandari Basnet	Gopini Bhandari	Sindhupalchowk	Barhabise	2	0		Barhabise Municipality	3	142	401150				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9621175956	85.905205, 85.905212	27.800919, 27.801018	1189.1072, 1204.575
199	254084	RV	Nirmala Thapa	Nirmala Thapa	Sindhupalchowk	Barhabise	2	0		Barhabise Municipality	3	159	400017				3	Grade 2, Grade 5, Grade 5	Minor Repair, Reconstruct, Reconstruct	Grade 1, Grade 5, Grade 5	Grade 1, Grade 5, Grade 5	Grade 1, Grade 5, Grade 5	Minor Repair, Reconstruct, Reconstruct	Habitable House in Usual Place	9843575405	85.902229, 85.902672, 85.902794	27.801895, 27.802128, 27.802156	1178.0559, 1184.1056, 1188.7686
200	253984	RV	Yasoda Bhandari	Pradip Bhandari	Sindhupalchowk	Barhabise	3	0		Barhabise Municipality	3	21	844139				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9611105423	85.915298	27.809111	1354.6685
201	253982	RV	Tilak Bdr Bhandari	Tilak Bahadur Bhandari	Sindhupalchowk	Barhabise	3	0		Barhabise Municipality	3	27	844146				1	Grade 2	Minor Repair	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9741261391	85.913368	27.805302	1360.1519
202	253965	RV	Nawaraj Bhandari	Nawaraj Bhandari	Sindhupalchowk	Barhabise	3	0		Barhabise Municipality	3	41	844065		Kathmandu,Kathmandu-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851030222	85.912086	27.802534	1413.3054
203	253970	RV	Radha Bohara	Dil Bahadur Bhandari, Ganesh Bahadur Bhandari	Sindhupalchowk	Barhabise	3	0		Barhabise Municipality	3	54	844080	23-6-3-0-50			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9614461302	85.913963	27.80258	1465.9735
204	253983	RV	Dayaram Bhandari	Daya Ram Bhandari, Purna Bahadur Bhandari	Sindhupalchowk	Barhabise	3	0		Barhabise Municipality	3	78	1176010	23-6-3-0-74			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9843014182	85.910706	27.802301	1373.3073
205	253985	RV	Hira Kumari Bhandari	Daya Ram Bhandari, Purna Bahadur Bhandari	Sindhupalchowk	Barhabise	3	0		Barhabise Municipality	3	78	1176011	23-6-3-0-74			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9843014182	85.910706	27.802301	1373.3073
206	254002	RV	Durga Bdr Thapa	Durga Bahadur Thapa	Sindhupalchowk	Barhabise	3	0		Barhabise Municipality	3	105	843365		Sindhupalchowk,Gat-9	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741043073	85.909035	27.801468	1323.4315
207	253973	RV	Sita Ram Thapa	Sita Ram Thapa	Sindhupalchowk	Barhabise	3	0		Barhabise Municipality	3	117	1174403				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741088762	85.90834	27.800863	1320.8956
208	254003	RV	Kunti Maya Magar	Hira Bahadur Magar	Sindhupalchowk	Barhabise	3	0		Barhabise Municipality	3	149	843495				1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9841391496	85.911438	27.795561	1329.9156
209	253890	RV	Sukulal Pain	Naru Pain, Suku Lal Pain	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	4	541080	23-6-4-0-4			2	Grade 3, Grade 5	Major Repair , Reconstruct	Grade 3, Grade 5	Grade 4, Unrecognized	Grade 4, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9621161681	85.918655	27.801119	1649.8784
210	253863	RV	Man Bdr Tamang	Man Bahadur Tamang	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	50	541054				1	Grade 1	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9741312340	85.942947	27.816092	2065.8848
211	253878	RV	Lato Rumba	Lata Rumba	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	57	541062				1	Grade 1	Not Required	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9621191915	85.938759	27.815039	1893.1172
212	253853	RV	Damodar Tamang	Damodar Tamang	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	66	541072				1	Grade 1	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849321631	85.934975	27.82056	1766.3347
213	253840	RV	Ramesh Thapa Magar	Ramesh Thapamagar	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	76	541135				1	Grade 1	Not Required	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9860040815	85.939423	27.822548	2053.2031
214	254368	RV	Dal Bdr Magar	Bhakta Magar, Dala Bahadur Magar	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	84	541149	23-6-4-0-79			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9621162900	85.938652	27.820826	1990.9479
215	253766	RV	Shyam Kumari Tamang	Kharka Bahadur Lama	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	90	541156				1	Grade 1	Not Required	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9621153856	85.938286	27.825918	1998.5127
216	253927	RV	Ful Bdr Thing	Ful Bahadur Thing	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	103	541179				1	Grade 1	Not Required	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9741312024	85.925209	27.824125	2156.5208
217	254385	RV	Kailash Magar	Kailash Magar, Padam Bahadur Magar	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	106	541184	23-6-4-0-99			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9843771395	85.926407	27.824108	2129.1245
218	253884	RV	Uttam Dhoj Shrestha	Uttar Dhoj Shrestha	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	124	541122		Kathmandu,Kathmandu-5	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841101960	85.924202	27.822741	2069.3828
219	252289	RV	Bil Bdr Tamang	Bel Bahadur Tamang, Dala Bahadur Tamang	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	143	541300	23-6-4-0-135			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9843689358	85.930473	27.822264	1900.4441
220	253920	RV	Ambar Bdr Pain	Ambar Bahadur Pain	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	193	541390				1	Grade 1	Not Required	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9813919024	85.925102	27.812777	1456.0248
221	253869	RV	Kumari Rumbasya	Kumari Rumbasya, Som Bahadur Pain	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	210	541360				1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9818918713	85.920242	27.798605	1729.3719
222	253867	RV	Som Bdr Pain	Kumari Rumbasya, Som Bahadur Pain	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	210	541359				1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9818918713	85.920242	27.798605	1729.3719
223	253912	RV	Chandra Bdr Tamang	Chandra Bahadur Tamang	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	222	541375				1	Grade 1	Not Required	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9614730746	85.920013	27.797966	1703.7021
224	254365	RV	Adhik Bdr Dumjan	Adhik Bahadur Dumjan, Ganga Bahadur Dumjan	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	228	541229	23-6-4-0-216			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9861071857	85.919838	27.798864	1702.0608
225	253852	RV	Sabita Tamang	Nabin Tamang	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	236	541221				1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9803186684	85.919556	27.798672	1694.9899
226	254007	RV	Kamala Tamang	Damar Bahadur Dumjan, Nabin Dumjan, Nirajan Dumjan	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	239	541226	23-6-4-0-226			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9803421163	85.919655	27.799028	1717.6127

227	254397	RV	Nabin Dumjan	Damar Bahadur Dumjan, Nabin Dumjan, Nirajan Dumjan	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	239	541225	23-6-4-0-226			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9803421163	85.919655	27.799028	1717.6127	
228	253881	RV	Chakra Bdr Tamang	Chakra Bahadur Tamang, Kami Tamang	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	256	541250	23-6-4-0-243			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9621178745	85.9207	27.799864	1711.4427	
229	254363	RV	Rabindra Shrestha	Rabindra Shrestha	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	270	541043				1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9860219884	85.918442	27.800152	1639.4117	
230	253930	RV	Lal Bdr Shrestha	Harka Bahadur Shrestha	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	276	541406	23-6-4-0-262			1	Grade 4	Reconstruct	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9614897141	85.917877	27.800041	1614.9067	
231	254372	RV	Kumari Shrestha	Tika Bahadur Shrestha	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	294	541427				1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9803676147	85.914742	27.798754	1542.991	
232	253937	RV	Basu Shrestha	Basu Shrestha, Chandra Bahadur Shrestha	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	296	541431				1	Grade 1	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9804137766	85.914497	27.798845	1550.631	
233	253858	RV	Chandra Bdr Shrestha	Basu Shrestha, Chandra Bahadur Shrestha	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	296	541430				1	Grade 1	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9804137766	85.914497	27.798845	1550.631	
234	254290	RV	Bal Bdr Pain	Krishna Bahadur Lama	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	303	541446		Kathmandu,Kathm andu-3	No Damage	1	Grade 4	Reconstruct	Grade 3	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841019229	85.917755	27.801884	1614.6639	
235	254305	RV	Krishna Bdr Lama	Krishna Bahadur Lama	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	303	541445		Kathmandu,Kathm andu-3	No Damage	1	Grade 4	Reconstruct	Grade 3	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841019229	85.917755	27.801884	1614.6639	
236	253866	RV	Krishna Kumari Tamang	Krishna Kumari Tamang	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	332	541349				1	Grade 1	Not Required	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9611096951	85.914413	27.800842	1543.329	
237	253864	RV	Som Lama	Ram Bahadur Lama, Som Lama	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	336	399584	23-6-4-0-318			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9614461521	85.915497	27.80055	1562.9108	
238	253924	RV	Resham Kumari Tamang	Resham Kumari Tamang	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	337	399585				1	Grade 1	Not Required	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849798447	85.916145	27.801308	1561.877	
239	253914	RV	Mohan Bdr Tamang	Krishna Kumari Yonjan, Mekh Bahadur Tamang, Mohan Bahadur Tamang, Rudra Bahadur Tamang	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	338	399589	23-6-4-0-319			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9616425320	85.916	27.801136	1567.8901	
240	254369	RV	Padam Kumari Pakhrintamang	Krishna Kumari Yonjan, Mekh Bahadur Tamang, Mohan Bahadur Tamang, Rudra Bahadur Tamang	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	338	399587	23-6-4-0-319			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9616425320	85.916	27.801136	1567.8901	
241	254370	RV	Sima Tamang	Krishna Kumari Yonjan, Mekh Bahadur Tamang, Mohan Bahadur Tamang, Rudra Bahadur Tamang	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	338	399588	23-6-4-0-319			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9616425320	85.916	27.801136	1567.8901	
242	250577	RV	Dev Raj Tamang	Devraj Tamang	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	343	399597				1	Grade 1	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9614461346	85.915634	27.800394	1568.2925	
243	254278	RV	Diby Kumari Tamang	Druba Tamang	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	362	844024	23-6-4-0-342			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9808837013	85.912262	27.800793	1465.5359	
244	253768	RV	Raju Tamang	Raju Tamang, Tek Bahadur Tamang	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	385	643402		Sindhupalchowk,Barhabise-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9621178376	85.917702	27.805901	1513.6729
245	253883	RV	Tek Bdr Tamang	Raju Tamang, Tek Bahadur Tamang	Sindhupalchowk	Barhabise	4	0		Barhabise Municipality	3	385	843401		Sindhupalchowk,Barhabise-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9621178376	85.917702	27.805901	1513.6729
246	254254	RV	Sekhar Kumar Khadka	Santosh Khadka	Sindhupalchowk	Barhabise	5	0		Barhabise Municipality	4	23	552498				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741181959	85.91703	27.797077	1545.5813	
247	254248	RV	Rama Sunar	Rama Sunar	Sindhupalchowk	Barhabise	5	0		Barhabise Municipality	4	91	552416				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741412106	85.913597	27.796457	1405.0736	
248	254311	RV	Dil Bdr Thapa	Dil Bahadur Thapa	Sindhupalchowk	Barhabise	5	0		Barhabise Municipality	4	141	552471				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741123107	85.917816	27.79294	1517.1162
249	247972	RV	Purna Bdr Sunar	Purna Bahadur Sunar	Sindhupalchowk	Barhabise	5	0		Barhabise Municipality	4	155	550086				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 4, Grade 2	Grade 4, Grade 2	Grade 4, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9808194494	85.915878, 85.916428	27.794222, 27.794888	1479.7737, 1507.806
250	254320	RV	Ganesh Shrestha	Ambar Bahadur Shrestha	Sindhupalchowk	Barhabise	6	0		Barhabise Municipality	4	10	552535	23-6-6-0-10			1	Grade 4	Reconstruct	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9851073515	85.913338	27.791492	1374.6888	
251	254322	RV	Indra Laxmi Bhandari	Indra Laxmi Bhandari	Sindhupalchowk	Barhabise	6	0		Barhabise Municipality	4	53	553818				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.912071	27.792081	1321.5734	
252	254182	RV	Pratap Lama	Juju Man Tamang	Sindhupalchowk	Barhabise	6	0		Barhabise Municipality	4	64		23-6-6-0-63			1	Grade 5	Reconstruct	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.911888	27.794231	1332.0736	
253	254269	RV	Nabaraj Raut	Shamser Bahadur Raut	Sindhupalchowk	Barhabise	6	0		Barhabise Municipality	4	110	553879	23-6-6-0-109			1	Grade 3	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9818311790	85.911697	27.792379	1326.8644	
254	254185	RV	Baburam Tamang	Uma Tamang	Sindhupalchowk	Barhabise	6	0		Barhabise Municipality	4	152	553933				1	Grade 2	Minor Repair	Grade 4	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843091175	85.910301	27.789957	1230.739	
255	254333	RV	Uma Tamang	Uma Tamang	Sindhupalchowk	Barhabise	6	0		Barhabise Municipality	4	152	553932				1	Grade 2	Minor Repair	Grade 4	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843091175	85.910301	27.789957	1230.739	
256	254330	RV	Boj Bdr Muktan(Tamang)	Boj Bahadur moktan Tamang	Sindhupalchowk	Barhabise	6	0		Barhabise Municipality	4	153	553934				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843091317	85.910065	27.78953	1276.9648	
257	254319	RV	Naina Bdr Paudyal	Naina Bahadur Paudyal	Sindhupalchowk	Barhabise	6	0		Barhabise Municipality	4	185	551971				3	Grade 2, Grade 5, Grade 5	Minor Repair, Reconstruct, Reconstruct	Grade 3, Grade 5, Grade 5	Grade 2, Unrecognized, Unrecognized	Grade 2, Unrecognized, Unrecognized	Minor Repair, Unrecognized, Unrecognized	Habitable House in Usual Place	11489328	85.907669, 85.907722	27.789492, 27.789656	1181.7803, 1183.094	
258	254164	RV	Goma Neupane	Goma Neupana	Sindhupalchowk	Barhabise	7	0		Barhabise Municipality	4	16	551990				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841069820	85.906303	27.787415	1142.9086	
259	254221	RV	Tenzen Sherpa	Tenzen Sherpa	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	2	552577				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841915916	85.897911	27.791655	834.58065
260	254230	RV	Mohan Laxmi Basnet	Mohan Lachhmi Basnet	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	3	552578				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818580835	85.89801	27.791645	828.00452
261	254114	RV	Pasang Lamu Tamang	Pashang Lamu Tamang	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	12	552587				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741162085	85.898163	27.79137	822.03949	
262	254129	RV	Hari Lal Dhamala	Hari Lal Dhamala	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	13	552588		Kathmandu,Kathm andu-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849012775	85.898155	27.791105	813.1062
263	253987	RV	Subesh Sunar	Subesh Sunar	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	3	14	552589		Sindhupalchowk,C hautara-8	Partial Damage	1	Grade 4	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9841919687	85.8983	27.791061	835.07727	
264	254198	RV	Rudra Bdr Basnet	Rudra Bahadur Basnet	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	3	15	552590		Sindhupalchowk,Barhabise-1	Complete Damage	1	Grade 2	Minor Repair	Grade 2	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9851000791	85.898163	27.790915	831.3891
265	254225	RV	Jib Maya Shrestha	Jib Maya Shrestha	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	16	552591				2	Grade 2, Grade 2	Minor Repair, Minor Repair	Grade 3, Grade 3	Grade 2, Grade 2	Grade 2, Grade 2	Minor Repair, Minor Repair	Habitable House in Usual Place	9808858307	85.898254, 85.898376	27.790981, 27.791035	806.87732, 830.54529	
266	254229	RV	Tara Devi Basnet	Tara Devi Basnet	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	20	552600				1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9860040368	85.898338	27.791029	826.88812
267	250586	RV	Upesh Basnet	Chhebi Basnet	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	21	552601				1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9841308537	85.898224	27.79073	833.03308
268	254117	RV	Tej Bdr Basnet	Tej Bahadur Basnet	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	25	552604				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Us				

271	254232	RV	Janardhan Basnet	Janardan Basnet	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	32	552612			1	Grade 3	Not Required	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9851078779	85.89875	27.790583	821.91309	
272	254119	RV	Thakur Dhoj Khadka	Thakur Dhwaj Khadka	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	33	552613	Sindhupalchowk, P edku-5	Complete Damage	1	Grade 3	Not Required	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841898202	85.898804	27.790693	839.1095	
273	254124	RV	Bibi Rani Tamangthapa	Bibirani Tamang	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	35	552616			1	Grade 3	Not Required	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849921295	85.898849	27.790997	861.38477	
274	254222	RV	Babita Shrestha	Babita Shrestha	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	36	552617			1	Grade 3	Not Required	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9842185716	85.898811	27.791033	839.75507	
275	254113	RV	Sanu Maya Tamang	Sanumaya Tamang	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	37	552618			1	Grade 3	Not Required	Grade 4	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841890962	85.899223	27.790621	835.39551	
276	254139	RV	Thakyo Sherpa	Thakchyo Sherpa	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	38	552619			1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843532371	85.899231	27.790529	851.62665	
277	247973	RV	Padam Tamang	Helamo Lama, Padam Tamang	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	39	552620			1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9614461314	85.899414	27.79038	844.03638	
278	254219	RV	Rita Basnet Budhathoki	Rita Basnet	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	43	552623			1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849469224	85.900108	27.790445	872.64539	
279	254171	RV	Krishna Lal Shrestha	Amrit Lal Shrestha	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	53		23-6-8-0-26		1	Grade 4	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849570417	85.898232	27.790258	818.01636	
280	254220	RV	Khadga Bdr Basnet	Khadag Bahadur Basnet	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	54	552631			4	Grade 5, Grade 5, Grade 2, Grade 2	Reconstruct, Minor Repair, Minor Repair	Grade 5, Grade 5, Grade 3	Grade 5, Grade 5, Unrecognized	Grade 5, Grade 5, Unrecognized	Reconstruct, Unrecognized, Unrecognized	Matrix & Photo not cleared or mismatch	9741098995	85.90448, 85.904671, 85.904724, 85.9046	27.793232, 27.793386, 27.793438, 27.793617	1060.4247, 1072.9594, 1075.6396, 1081.9325	
281	254136	RV	Bhakta Lal Shrestha	Krishna Lal Shrestha	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	58	552636	Sindhupalchowk, Barhabise-9	Complete Damage, Partial Damage	1	Grade 3	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9849261028	85.900055	27.78965	825.77869	
282	254130	RV	Jhaktal Shrestha	Krishna Lal Shrestha	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	58	552637	Sindhupalchowk, Barhabise-9	Complete Damage, Partial Damage	1	Grade 3	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9849261028	85.900055	27.78965	825.77869	
283	254123	RV	Krishna Lal Shrestha	Krishna Lal Shrestha	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	58	552635	Sindhupalchowk, Barhabise-9	Complete Damage, Partial Damage	1	Grade 3	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9849261028	85.900055	27.78965	825.77869	
284	254214	RV	Bir Bdr Pradhan	Bir Bahadur Pradhan	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	60	552639			1	Grade 2	Minor Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849012570	85.900124	27.789589	838.6748	
285	254132	RV	Hari Krishna Shrestha	Laxami Bahadur Shrestha	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	78	551657	23-6-8-0-48		1	Grade 4	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9818278814	85.897995	27.788929	820.89679	
286	254226	RV	Sobit Man Shrestha	Sobit Man Shrestha	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	95	552652	Sindhupalchowk, Barhabise-1	Partial Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9851032083	85.898148, 85.898175	27.788498, 27.790772	840.3772, 827.13324	
287	254125	RV	Bharat Shrestha	Punya Maya Shrestha	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	103	552661	23-6-8-0-72		3	Grade 5, Grade 5, Grade 3	Reconstruct, Reconstruct, Major Repair	Grade 5, Grade 5, Grade 3	Grade 5, Grade 5, Unrecognized	Grade 5, Grade 5, Unrecognized	Reconstruct, Reconstruct, Reconstruct	Matrix & Photo not cleared or mismatch	9862827880	85.898628, 85.898697	27.788963, 27.790194	823.64172, 827.36578	
288	254172	RV	Laxman Shrestha	Punya Maya Shrestha	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	103	552670	23-6-8-0-72		3	Grade 5, Grade 5, Grade 3	Reconstruct, Reconstruct, Major Repair	Grade 5, Grade 5, Grade 3	Grade 5, Grade 5, Unrecognized	Grade 5, Grade 5, Unrecognized	Reconstruct, Reconstruct, Reconstruct	Matrix & Photo not cleared or mismatch	9862827880	85.89843, 85.898628, 85.898697	27.788927, 27.788963, 27.790194	802.02014, 823.64172, 827.36578	
289	254126	RV	Ram Shrestha	Punya Maya Shrestha	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	103	552669	23-6-8-0-72		3	Grade 5, Grade 5, Grade 3	Reconstruct, Reconstruct, Major Repair	Grade 5, Grade 5, Grade 3	Grade 5, Grade 5, Unrecognized	Grade 5, Grade 5, Unrecognized	Reconstruct, Reconstruct, Reconstruct	Matrix & Photo not cleared or mismatch	9862827880	85.89843, 85.898628, 85.898697	27.788927, 27.788963, 27.790194	802.02014, 823.64172, 827.36578	
290	254224	RV	Renu Shrestha	Punya Maya Shrestha	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	103	552660	23-6-8-0-72		3	Grade 5, Grade 5, Grade 3	Reconstruct, Reconstruct, Major Repair	Grade 5, Grade 5, Grade 3	Grade 5, Grade 5, Unrecognized	Grade 5, Grade 5, Unrecognized	Reconstruct, Reconstruct, Reconstruct	Matrix & Photo not cleared or mismatch	9862827880	85.89843, 85.898628, 85.898697	27.788927, 27.788963, 27.790194	802.02014, 823.64172, 827.36578	
291	254140	RV	Binod Shrestha	Vinod Shrestha	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	147	551711			3	Grade 2, Grade 5, Grade 5	Minor Repair, Reconstruct, Reconstruct	Grade 3, Grade 5, Grade 5	Grade 2, Grade 5, Grade 5	Grade 2, Grade 5, Grade 5	Minor Repair, Reconstruct, Reconstruct	Habitable House in Usual Place		85.899101, 85.899139, 85.899232	27.788651, 27.78867, 27.788673	821.91498, 828.68048, 852.97699	
292	254231	RV	Laxmi Raj Shrestha	Laxami Raj Shrestha	Sindhupalchowk	Barhabise	8	0		Barhabise Municipality	4	159	551721	Kathmandu, Kathmandu-17/Kathmandu, Kathmandu-17	Partial Damage, Partial Damage	1	Grade 4	Major Repair	Grade 3	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9843729888	85.899193	27.788557	744.95319	
293	254156	RV	Sanu Maya Shrestha	Kabit Man Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	6	551727	23-6-9-0-5	Sindhupalchowk, Barhabise-1	Complete Damage	1	Grade 4	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9801098354	85.899414	27.788441	764.8045
294	254110	RV	Gobardhan Shrestha	Gita Shrestha, Gobardhan Shrestha, Netra Bahadur Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	8	551730	Sindhupalchowk, Ramche-7	Partial Damage, Partial Damage	6	Grade 4, Grade 4, Grade 5, Grade 2, Grade 2, Grade 3	Major Repair, Major Repair, Major Repair, Minor Repair, Minor Repair, Minor Repair	Grade 3, Grade 3, Grade 5, Grade 2, Grade 3, Grade 2	Unrecognized, Unrecognized, Grade 5, Grade 2, Grade 2, Grade 2	Unrecognized, Unrecognized, Grade 5, Grade 2, Grade 2, Grade 2	Unrecognized, Unrecognized, Minor Repair, Major Repair	Habitable House in Other Place	9841268839	85.898781, 85.899223, 85.899719, 85.899948, 85.90004	27.787106, 27.787159, 27.78723, 27.788103, 27.788343	792.02283, 804.20953, 810.96942, 819.14856, 829.84253, 832.92102	
295	254235	RV	Netra Bdr Shrestha	Gita Shrestha, Gobardhan Shrestha, Netra Bahadur Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	8	551731	Sindhupalchowk, Ramche-7	Partial Damage, Partial Damage	6	Grade 4, Grade 4, Grade 5, Grade 2, Grade 2, Grade 3	Major Repair, Major Repair, Major Repair, Minor Repair, Minor Repair, Minor Repair	Grade 3, Grade 3, Grade 5, Grade 2, Grade 3, Grade 2	Unrecognized, Unrecognized, Grade 5, Grade 2, Grade 2, Grade 2	Unrecognized, Unrecognized, Grade 5, Grade 2, Grade 2, Grade 2	Unrecognized, Unrecognized, Minor Repair, Major Repair	Habitable House in Other Place	9841268839	85.898781, 85.899223, 85.899719, 85.899948, 85.90004	27.787106, 27.787159, 27.78723, 27.788103, 27.788343	792.02283, 804.20953, 810.96942, 819.14856, 829.84253, 832.92102	
296	250581	RV	Nischal Shrestha	Gita Shrestha, Gobardhan Shrestha, Netra Bahadur Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	8	551732	Sindhupalchowk, Ramche-7	Partial Damage, Partial Damage	6	Grade 4, Grade 4, Grade 5, Grade 2, Grade 2, Grade 3	Major Repair, Major Repair, Major Repair, Minor Repair, Minor Repair, Minor Repair	Grade 3, Grade 3, Grade 5, Grade 2, Grade 3, Grade 2	Unrecognized, Unrecognized, Grade 5, Grade 2, Grade 2, Grade 2	Unrecognized, Unrecognized, Grade 5, Grade 2, Grade 2, Grade 2	Unrecognized, Unrecognized, Minor Repair, Major Repair	Habitable House in Other Place	9841268839	85.898781, 85.899223, 85.899719, 85.899948, 85.90004	27.787159, 27.78723, 27.788103, 27.788322, 27.788343	792.02283, 804.20953, 810.96942, 819.14856, 829.84253, 832.92102	
297	253690	RV	Rabindra Shrestha	Rabindra Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	37	551760	Kathmandu, Kathmandu-35	Partial Damage	1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	9841901619	85.899803	27.787046	828.92975	
298	253699	RV	Raju Shrestha	Laxami Devi Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	41	551764	23-6-9-0-32		1	Grade 4	Reconstruct	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9860109230	85.899834	27.787302	849.96173	
299	254094	RV	Ishwor Lal Shakha	Ishwari Lal Shakh	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	42	551766	Kathmandu, Kathmandu-28/Sindhupalchowk, Ramche-7	Complete Damage, Partial Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	11489275	85.900101	27.787338	835.90448	
300	254105	RV	Aman Lal Shrestha	Kamal Lal Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	43	551768	23-6-9-0-33		1	Grade 4	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9851052908	85.899727	27.78734	837.24036	
301	254102	RV	Gauri Maya Shresthashakya	Gauri Maya Shakya	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	44	551769	Kathmandu, Kathmandu-28	Partial Damage	1	Grade 3	Major Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9841901650	85.900024	27.787571	831.21893	
302	254109	RV	Bayan Bdr Shrestha	Bayan Bahadur Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	55	552680			3	Grade 4, Grade 4, Grade 2	Major Repair, Major Repair, Minor Repair	Grade 3, Grade 3, Grade 3	Grade 3, Grade 4, Grade 2	Grade 3, Grade 4, Grade 2	Major Repair, Reconstruct, Minor Repair	Habitable House in Usual Place	9851004711	85.898888, 85.898987, 85.899605	27.783575, 27.783804, 27.788078	795.5722, 820.56354, 825.24286	

303	254107	RV	Amrit Shrestha	Tek Bahadur Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	56	552681		Sindhupalchowk,R amche-7/Sindhupalchowk, Ramche-7	Partial Damage, Partial Damage	2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Unrecognized, Grade 2	Unrecognized, Grade 2	Unrecognized, Minor Repair	Habitable House in Other Place	9851000006	85.899556	27.780762	837.354	
304	254244	RV	Nahendra Bdr Shrestha	Nahendra Bahadur Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	65	552689				4	Grade 4, Grade 2, Grade 5	Major Repair, Minor Repair, Reconstruct, Reconstruct	Grade 3, Grade 2, Grade 5	Grade 3, Grade 5	Grade 3, Grade 2, Grade 5	Major Repair, Minor Repair, Reconstruct, Reconstruct	Habitable House in Usual Place	9841769165	85.899185, 85.899673, 85.899606, 85.89978	27.788374, 27.788429, 27.788605, 27.788607	793.13159, 813.13641, 836.56055, 842.22375	
305	253694	RV	Krishna Gopal Shrestha	Krishna Gopal Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	67	552691				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 3, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9803112883	85.89949, 85.900093	27.786724, 27.78739	797.33472, 842.10565	
306	253691	RV	Ram Bdr Khadka	Shyam Man Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	77	552703	23-6-9-0-56			1	Grade 4	Major Repair	Grade 2		Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9861187487	85.898911	27.78846	822.61938	
307	254090	RV	Bipin Shrestha	Bipin Shrestha, Nabin Shrestha, Padam Lal Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	85	552711	23-6-9-0-64			1	Grade 3	Major Repair	Grade 3		Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849012610	85.899063	27.788286	822.21979	
308	254099	RV	Dal Bdr Shrestha	Dal Bahadur Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	89	552715		Sindhupalchowk,R amche-7	Partial Damage	1	Grade 4	Major Repair	Grade 3	Grade 3	Grade 3	Grade 3	Major Repair	Habitable House in Other Place	9860856196	85.898972	27.788277	847.03796
309	254095	RV	Rajan Shrestha	Tilak Bahadur Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	94	552723	23-6-9-0-72			1	Grade 4	Major Repair	Unrecognized	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.89917	27.787815	798.21899	
310	253700	RV	Rajesh Shrestha	Tilak Bahadur Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	94	552722	23-6-9-0-72			1	Grade 4	Major Repair	Unrecognized	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.89917	27.787815	798.21899	
311	254104	RV	Ram Krishna Shrestha	Ram Krishna Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	95	552724		Kathmandu,Kathm andu-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841101777	85.899132	27.787766	808.05823
312	251362	RV	Diwakar Shrestha	Diwakar Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	100	552727		Lalitpur ,Lalitpur-9	Partial Damage	2	Grade 4, Grade 5	Major Repair, Reconstruct, Reconstruct	Grade 3, Grade 5	Unrecognized, Grade 5	Unrecognized, Grade 5	Unrecognized, Grade 5	Habitable House in Other Place	9841282205	85.899353, 85.899429	27.787666, 27.787674	808.02863, 810.09204	
313	247974	RV	Jwari Lal Shrestha	Jwari Lal Shrestha	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	138	552770		Sindhupalchowk,K adambas-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741273014	85.894234	27.779638	821.55945
314	254247	RV	Shree Prasad Salhaita	Bikram Bahadur Kutlu	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	145	552801		Kathmandu,Kathm andu-20	Partial Damage	3	Grade 5, Grade 5, Grade 5	Reconstruct, Reconstruct, Reconstruct	Grade 5, Grade 5, Grade 5	Grade 5, Grade 5, Grade 5	Grade 5, Grade 5, Grade 5	Reconstruct, Reconstruct, Reconstruct	Habitable House in Other Place	9841678432	85.894226, 85.894272, 85.894386	27.779177, 27.779202, 27.779234	801.57111, 821.65729, 826.88037	
315	254246	RV	Kanchhi Tamang	Kanchhi Tamang	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	150	552782				1	Grade 5	Minor Repair	Grade 3	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9860336706	85.894585	27.778933	814.41406
316	248155	RV	Gopal Bk	Gopal Bishwakarma	Sindhupalchowk	Barhabise	9	0		Barhabise Municipality	4	159	552793				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843373273	85.894882	27.778692	811.86621
317	253606	RV	Pemba Sherpa	Pemba Sherpa	Sindhupalchowk	Baruwa	1	0		Pachpokhari Thangpal	2	49	404256		Sindhupalchowk,M elamchi-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9810882813	85.62851	27.999893	2097.8726
318	250010	RV	Pem Dorje Sherpa	Pema Dorje Sherpa	Sindhupalchowk	Baruwa	1	0		Pachpokhari Thangpal	2	56	404263		Dhading,Baireni-8	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741035343	85.624001	28.002523	1946.7448
319	253603	RV	Suresha Waiba	Suresh Waiba	Sindhupalchowk	Baruwa	1	0		Pachpokhari Thangpal	2	71	404310		Kathmandu,Kathm andu-9	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9801153455	85.621964	27.946606	1505.8578
320	253602	RV	Ashok Sangbo Tamang	Ashok Syangbo Tamang, Gopal Syangbo Tamang	Sindhupalchowk	Baruwa	1	0		Pachpokhari Thangpal	2	126	334107		Kathmandu,Danch hi-9	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803452660	85.634224	27.973688	1389.2583
321	253611	RV	Mingmar Tamang	Mingmar Tamang, Pote Tamang	Sindhupalchowk	Baruwa	2	0		Pachpokhari Thangpal	2	14	391239		Kathmandu,Shank arapura-7	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808835394	85.623421	27.98477	1725.9574
322	253612	RV	Pode Tamang	Mingmar Tamang, Pote Tamang	Sindhupalchowk	Baruwa	2	0		Pachpokhari Thangpal	2	14	391238		Kathmandu,Shank arapura-7	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808835394	85.623421	27.98477	1725.9574
323	253553	RV	Pode Tamang	Mingmar Tamang, Pote Tamang	Sindhupalchowk	Baruwa	2	0		Pachpokhari Thangpal	2	14	391238		Kathmandu,Shank arapura-7	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808835394	85.623421	27.98477	1725.9574
324	253615	RV	Lawang Tamang	Lawang Tamang, Sete Tamang	Sindhupalchowk	Baruwa	2	0		Pachpokhari Thangpal	2	21	391248		Kathmandu,Shank arapura-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803996516	85.61879	27.981188	1945.2678
325	253614	RV	Sene Tamang	Lawang Tamang, Sete Tamang	Sindhupalchowk	Baruwa	2	0		Pachpokhari Thangpal	2	21	391249		Kathmandu,Shank arapura-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803996516	85.61879	27.981188	1945.2678
326	253550	RV	Dawa Sherpa	Dawa Sherpa	Sindhupalchowk	Baruwa	2	0		Pachpokhari Thangpal	2	88	404370		Kathmandu,Kathm andu-7	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741137741	85.600632	28.000736	2207.0193
327	253419	RV	Dolma Sangbo Lama	Dolma Syangbo Lama, Ngawang Phinju Syambo tamang	Sindhupalchowk	Baruwa	6	0		Pachpokhari Thangpal	2	17	336011		Kathmandu,Mulpa ni-8	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808454999	85.619217	27.919994	1537.6439
328	253421	RV	Dolma Syangbo Lama	Dolma Syangbo Lama, Ngawang Phinju Syambo tamang	Sindhupalchowk	Baruwa	6	0		Pachpokhari Thangpal	2	17	336011		Kathmandu,Mulpa ni-8	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808454999	85.619217	27.919994	1537.6439
329	253502	RV	Ngawang Vinju Sangbo	Dolma Syangbo Lama, Ngawang Phinju Syambo tamang	Sindhupalchowk	Baruwa	6	0		Pachpokhari Thangpal	2	17	336010		Kathmandu,Mulpa ni-8	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808454999	85.619217	27.919994	1537.6439
330	253500	RV	Ngemha Gyalbo Tamangni	Nema Gyamo Tamani	Sindhupalchowk	Baruwa	6	0		Pachpokhari Thangpal	2	26	336021		Kathmandu,Shank arapura-99	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9818651017	85.61998	27.920601	1585.8945
331	253417	RV	Ngemha Gyalbo Tamangni	Nema Gyamo Tamani	Sindhupalchowk	Baruwa	6	0		Pachpokhari Thangpal	2	26	336021		Kathmandu,Shank arapura-99	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9818651017	85.61998	27.920601	1585.8945
332	253418	RV	Karpo Lama	Karpo Lama	Sindhupalchowk	Baruwa	6	0		Pachpokhari Thangpal	2	33	336428				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 3	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9808029213	85.619598, 85.619987	27.920744, 27.920864	1579.0853, 1584.7915	
333	253505	RV	Bhim Bdr Sangbo	Bhim Bahadur Syangbo	Sindhupalchowk	Baruwa	6	0		Pachpokhari Thangpal	2	34	336429		Kathmandu,Shank arapura-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9751047028	85.61937	27.920746	1571.1667
334	253506	RV	Ngemha Lama	Nehema Lama	Sindhupalchowk	Baruwa	6	0		Pachpokhari Thangpal	2	35	336430		Kathmandu,Shank arapura-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841249413	85.619881	27.9207	1583.924
335	253508	RV	Chewang Nurpu Lama	Chewang Norbu Lama	Sindhupalchowk	Baruwa	6	0		Pachpokhari Thangpal	2	36	336431		Kathmandu,Shank arapura-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841213483	85.620049	27.920681	1592.4105
336	253507	RV	Damersi Tamang	Damai Sing Tamang	Sindhupalchowk	Baruwa	6	0		Pachpokhari Thangpal	2	37	336432		Kathmandu,Gokar neswor-15	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841446603	85.619881	27.92008	1584.7405
337	253428	RV	Pema Sangbo Tamang	Pema Syangbo Tamang, Prakash Syangbo	Sindhupalchowk	Baruwa	7	0		Pachpokhari Thangpal	2	2	336126	23-7-7-0-2			1	Grade 3	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9808913852	85.623917	27.927921	1534.799	
338	253425	RV	Dandul Lama	Dandul Lama	Sindhupalchowk	Baruwa	7	0		Pachpokhari Thangpal	2	74	336256		Kathmandu,Shank arapura-2	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813786308	85.613007	27.938313	2129.4683
339	253422	RV	Nhondo Lama	Nhondo Lama	Sindhupalchowk	Baruwa	7	0		Pachpokhari Thangpal	2	75	336257		Kathmandu,Shank arapura-2	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841192130	85.612907	27.938128	2136.1599
340	253423	RV	Dolma Lamani	Dolma Lamani	Sindhupalchowk	Baruwa	7	0		Pachpokhari Thangpal	2	81	336263		Kathmandu,Budha nilkantha-7	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808390631	85.610947	27.94017	2263.1577
341	253439	RV	Lahkpa Lama	Lhaka Lama, Pemba Gylen Lama	Sindhupalchowk	Baruwa	8	0		Pachpokhari Thangpal	2	62	336079		Kathmandu,Shank arapura-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803207401	85.615654	27.927164	1970.2701
342	253433	RV	Pemba Gyaljen Lama	Lhaka Lama, Pemba Gylen Lama	Sindhupalchowk	Baruwa	8	0		Pachpokhari Thangpal	2	62	336078		Kathmandu,Shank arapura-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade								

348	255384	RV	Sun Bahadur Tamang	Sun Ba Tamang	Sindhupalchowk	Basata	1	0			Chautara Sagachowkgadhi Municipality	2	102	396460		Sindhupalchowk, Jalabire-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813004109	85.750038	27.807116	1517.6401
349	255385	RV	Dil Bahadur Tamang	Dil Bahadur Tamang	Sindhupalchowk	Basata	1	0			Chautara Sagachowkgadhi Municipality	2	104	396463		Sindhupalchowk, Jalabire-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.750259	27.807076	1509.9445
350	255340	RV	Man Bahadur Tamang	Man Bahadur Tamang	Sindhupalchowk	Basata	1	0			Chautara Sagachowkgadhi Municipality	2	126	395411		Bhaktapur, Sipadol-9	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849492701	85.749397	27.807146	1514.3719
351	255424	RV	Ram Prasad Kafle	Ram Prasad Kafle	Sindhupalchowk	Basata	2	0			Chautara Sagachowkgadhi Municipality	2	4	395429		Sindhupalchowk, Jalabire-4	Partial Damage	2	Grade 3, Grade 5	Major Repair, Reconstruct	Grade 3, Grade 5	Grade 3, Grade 5	Grade 3, Grade 5	Minor Repair, Reconstruct	Habitable House in Other Place	9741023789	85.765289, 85.766151	27.811525, 27.811722	783.29871, 797.05835
352	255476	RV	Kamal Bahadur Thapa	Kamal Bahadur Thapa	Sindhupalchowk	Basata	2	0			Chautara Sagachowkgadhi Municipality	2	22	396476				1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9843248629	85.766884	27.813486	793.5415
353	255427	RV	Ambar Bahadur Shrestha	Ambar Bahadur Shrestha	Sindhupalchowk	Basata	2	0			Chautara Sagachowkgadhi Municipality	2	38	396493				1	Grade 1	Minor Repair	Grade 2	Grade 3	Grade 3	Minor Repair	Habitable House in Usual Place		85.764977	27.815029	801.14886
354	250717	RV	Dharma Bahadur Thapa	Dharma Bahadur Thapa	Sindhupalchowk	Basata	2	0			Chautara Sagachowkgadhi Municipality	2	45	397951		Kathmandu, Kageswori-Manahara-99	Partial Damage	1	Grade 4	Major Repair	Grade 3	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9843053595	85.764366	27.814697	822.11346
355	255219	RV	Geeta Shrestha	Gita Shrestha	Sindhupalchowk	Basata	2	0			Chautara Sagachowkgadhi Municipality	2	56	397963				1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843248952			
356	255286	RV	Udhav Thapa	Udhava Thapa	Sindhupalchowk	Basata	2	0			Chautara Sagachowkgadhi Municipality	2	89	394023		Bhaktapur, Bhaktapur-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841848430	85.761757	27.812471	999.83643
357	255301	RV	Som Nath Sapkota	Som Nath Sapkota	Sindhupalchowk	Basata	3	0			Chautara Sagachowkgadhi Municipality	2	91	395319		Bhaktapur, Changu narayan-12	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849795454	85.751579	27.791552	1048.5468
358	255480	RV	Prem Pd.Parajuli	Prem Prasad Parajuli, Umakanta Parajuli	Sindhupalchowk	Basata	3	0			Chautara Sagachowkgadhi Municipality	2	103	395335		Kathmandu, Kageswori-Manahara-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.761322	27.791582	799.41956
359	255464	RV	Esta Prasad Parajuli	Issta Prasad Parajuli	Sindhupalchowk	Basata	3	0			Chautara Sagachowkgadhi Municipality	2	107	395339		Bhaktapur, Balkot-99/Bhaktapur, Balkot-99	Partial Damage, Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843232284	85.760056	27.792816	828.60406
360	255411	RV	Dhanmaya Nepal	Dhanmaya Nepal	Sindhupalchowk	Basata	3	0			Chautara Sagachowkgadhi Municipality	2	109	395341		Bhaktapur, Balkot-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860420692	85.759735	27.79315	813.42493
361	255383	RV	Bishnu Prasad Nepal	Bisnu Prasad Nepal	Sindhupalchowk	Basata	3	0			Chautara Sagachowkgadhi Municipality	2	112	395344		Bhaktapur, Balkot-9	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741036035	85.760078	27.793575	812.12195
362	255305	RV	Megh Natha Sapkota	Meghnath Sapkota	Sindhupalchowk	Basata	3	0			Chautara Sagachowkgadhi Municipality	2	118	395376		Bhaktapur, Duvakot-1	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841288498	85.751884	27.792967	1068.6873
363	255304	RV	Bhim Prasad Sapkota	Bhim Bahadur Sapkota	Sindhupalchowk	Basata	3	0			Chautara Sagachowkgadhi Municipality	2	124	395384		Bhaktapur, Duvakot-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841877848	85.751846	27.792757	1069.4897
364	255470	RV	Ramchandra Parajuli	Ram Chandra Upathaya	Sindhupalchowk	Basata	3	0			Chautara Sagachowkgadhi Municipality	2	153	395362		Kathmandu, Mulpani-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843387500	85.761284	27.791838	786.34619
365	255341	RV	Indra Lal Shrestha	Indra Lal Shrestha, Majarman Shrestha	Sindhupalchowk	Basata	4	0			Chautara Sagachowkgadhi Municipality	2	2	556927		Kathmandu, Baluwara-99/Sindhupalchowk, Jalabire-99	Complete Damage, No Damage	1	Grade 4	Reconstruct	Grade 3	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	14442607	85.766312	27.805101	745.73706
366	255482	RV	Dinesh Kumar Shrestha	Dinesh Kumar Shrestha, Kajjal Shrestha	Sindhupalchowk	Basata	4	0			Chautara Sagachowkgadhi Municipality	2	4	556930				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 2	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9841036152	85.766022, 85.766335	27.805138, 27.805239	756.15234, 757.90912
367	255350	RV	Puknath Dakal	Pukhanath Dhakal	Sindhupalchowk	Basata	4	0			Chautara Sagachowkgadhi Municipality	2	39	555169		Kathmandu, Kathmandu-99/Kathmandu, Kathmandu-99/Kathmandu, Kathmandu-99/Kathmandu, Kathmandu-99	Partial Damage, Partial Damage, Partial Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9843094875	85.762398, 85.762428	27.804382, 27.804474	805.48206, 810.13934
368	255221	RV	Ishwori Prasad Kafle	Ishowari Prasad Kafle	Sindhupalchowk	Basata	4	0			Chautara Sagachowkgadhi Municipality	2	74	555657		Bhaktapur, Bhaktapur-99	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9841664438	85.763901, 85.763977	27.799644, 27.799664	753.06952, 753.63501
369	255484	RV	Krishna Prasad Kafle	Krishna Prasad Kafle, Narayan Prasad Kafle, Ramsaran Kafle	Sindhupalchowk	Basata	4	0			Chautara Sagachowkgadhi Municipality	2	177	556413		Kathmandu, Kathmandu-99/Sindhupalchowk, Chautara-5/Sindhupalchowk, Chautara-5	Partial Damage, Partial Damage, Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741017670	85.753357	27.794525	1107.4391
370	255379	RV	Narayan Prasad Kafle	Krishna Prasad Kafle, Narayan Prasad Kafle, Ramsaran Kafle	Sindhupalchowk	Basata	4	0			Chautara Sagachowkgadhi Municipality	2	177	556494		Kathmandu, Kathmandu-99/Sindhupalchowk, Chautara-5/Sindhupalchowk, Chautara-5	Partial Damage, Partial Damage, Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741017670	85.753357	27.794525	1107.4391
371	255372	RV	Ram Sharan Kafle	Krishna Prasad Kafle, Narayan Prasad Kafle, Ramsaran Kafle	Sindhupalchowk	Basata	4	0			Chautara Sagachowkgadhi Municipality	2	177	556412		Kathmandu, Kathmandu-99/Sindhupalchowk, Chautara-5/Sindhupalchowk, Chautara-5	Partial Damage, Partial Damage, Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741017670	85.753357	27.794525	1107.4391
372	255207	RV	Yam Kumari Katuwal	Yamkumari Katuwal	Sindhupalchowk	Basata	8	0			Chautara Sagachowkgadhi Municipality	3	28	553676		Sindhupalchowk, Chautara-8	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9849924714	85.725342	27.802652	1037.7971
373	255238	RV	Sangita Katuwal	Om Bahadur Katuwal	Sindhupalchowk	Basata	8	0			Chautara Sagachowkgadhi Municipality	3	36	553684		Sindhupalchowk, Chautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 4	Grade 3	Grade 4	Reconstruct	Habitable House in Other Place	9843001610	85.723999	27.80257	1031.1329
374	255280	RV	Ram Bahadur Katuwal	Ram Bahadur Katuwal	Sindhupalchowk	Basata	8	0			Chautara Sagachowkgadhi Municipality	3	37	553685		Sindhupalchowk, Chautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860038364	85.725075	27.802845	1025.6853
375	255483	RV	Parbati Katuwal	Chandra Bahadur Katuwal	Sindhupalchowk	Basata	8	0			Chautara Sagachowkgadhi Municipality	3	42	553689		Sindhupalchowk, Chautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849056699	85.726051	27.802061	1093.8896
376	255240	RV	Chitra Kumari Katuwal	Chitrakumari Katuwal	Sindhupalchowk	Basata	8	0			Chautara Sagachowkgadhi Municipality	3	45	553692		Sindhupalchowk, Chautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841002606	85.727325	27.801668	1087.0641
377	255239	RV	Dalle Katuwal	Dalle Katuwal	Sindhupalchowk	Basata	8	0			Chautara Sagachowkgadhi Municipality	3	50	553697		Sindhupalchowk, Chautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9810247022	85.727943	27.802242	1071.5646

378	255271	RV	Chandra Bahadur Katuwal	Chandra Bahadur Katuwal	Sindhupalchowk	Batase	8	0				Chautara Sagachowkgadhi Municipality	3	63	553710		Sindhupalchowk,C hautara-3	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9808080421	85.727196	27.801752	1071.8695		
379	255270	RV	Tika Bahadur Katuwal	Tika Bahadur Katuwal	Sindhupalchowk	Batase	8	0				Chautara Sagachowkgadhi Municipality	3	66	553713		Sindhupalchowk,C hautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849703054	85.727051	27.801802	1081.4696		
380	255220	RV	Prem Bahadur Katuwal	Prem Bahadur Katuwal	Sindhupalchowk	Batase	8	0				Chautara Sagachowkgadhi Municipality	3	78	553725				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9841989493	85.725822,	27.800711,	1057.0306,	1133.8873	
381	255361	RV	Sunawarta Lama	Sunawati Lama	Sindhupalchowk	Batase	8	0				Chautara Sagachowkgadhi Municipality	3	101	553748				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9803491926	85.726784,	27.793634,	1153.7261,	1171.9447	
382	255419	RV	Birkaji Tamang	Birkaji Tamang	Sindhupalchowk	Batase	9	1				Chautara Sagachowkgadhi Municipality	3	29	553439		Sindhupalchowk,B atase-7	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808917315	85.72525	27.817852	1406.8311		
383	255391	RV	Harka Bahadur Lopchan	Harka Bahadur Lopchan	Sindhupalchowk	Batase	9	1				Chautara Sagachowkgadhi Municipality	3	114	553535		Sindhupalchowk,C hautara-3	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Major Repair	Habitable House in Other Place	9808253128	85.732033	27.818041	1571.1887		
384	255491	RV	Sanch Bahadur Tamang	Sancha Bahadur Tamang	Sindhupalchowk	Batase	9	1				Chautara Sagachowkgadhi Municipality	3	119	553541		Sindhupalchowk,C hautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803177018	85.73188	27.818394	1565.8704		
385	253366	RV	Lila Kumari Majhi	Lila Kumari Majhi	Sindhupalchowk	Bhimtar	1	0				Indrawati	11	155	392052				1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9843604211	85.637199	27.725397	687.35541		
386	253269	RV	Krishna Prasad Bhattarai	Krishna Prasad Bhattarai	Sindhupalchowk	Bhimtar	1	0				Indrawati	11	157	392054		Kathmandu,Mulpa ni-9	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741163738	85.634201	27.727259	688.74261		
387	253374	RV	Uddhap Prasad Bhattarai	Udhap Prasad Bhattarai	Sindhupalchowk	Bhimtar	1	0				Indrawati	11	158	392055		Kathmandu,Mulpa ni-9	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741048356	85.634117	27.727121	692.34442		
388	253375	RV	Rajendra Parajuli	Rajendra Parajuli	Sindhupalchowk	Bhimtar	1	0				Indrawati	11	184	393046		Kathmandu,Kages wori-Manahara-8	No Damage	2	Grade 2, Grade 5	Reconstruct, Reconstruct	Grade 4, Grade 5	Grade 4, Grade 5	Grade 4, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9803506198	85.632408,	27.729568,	711.34906,	713.66284	
389	251389	RV	Sujan Dangal	Sujan Dangal	Sindhupalchowk	Bhimtar	1	0				Indrawati	11	196	393009		Kathmandu,Kapan-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9818016938	85.632828	27.731171	745.1485		
390	253380	RV	Krishna Prasad Sapkota	Krishna Prasad Sapkota	Sindhupalchowk	Bhimtar	1	0				Indrawati	11	203	393016		Bhaktapur,Madhya pur Thimi-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841099086	85.632446	27.730799	759.74933		
391	253270	RV	Krishna Prasad Sapkota	Krishna Prasad Sapkota	Sindhupalchowk	Bhimtar	1	0				Indrawati	11	203	393016		Bhaktapur,Madhya pur Thimi-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841099086	85.632446	27.730799	759.74933		
392	253365	RV	Indira Adhikari	Indira Adhikari	Sindhupalchowk	Bhimtar	1	0				Indrawati	11	245	392185				1	Grade 2	Reconstruct	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9843423208	85.633057	27.73241	770.20728		
393	253281	RV	Mahila Danuwar	Malio Danuwar	Sindhupalchowk	Bhimtar	2	0				Indrawati	12	54	392112		Kavrepalanchowk, Gauribisauna Deupur-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813581426	85.618988	27.745834	806.07446		
394	253282	RV	Sitaram Danuwar	Sitaram Danuwar	Sindhupalchowk	Bhimtar	2	0				Indrawati	12	55	392113		Kavrepalanchowk, Gauribisauna Deupur-3	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9851182062	85.619438	27.746	791.29779		
395	253280	RV	Krishna Bahadur Raidanuwar	Krishna Bahadur Rai Danuwar	Sindhupalchowk	Bhimtar	2	0				Indrawati	12	61	392119				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9841587547	85.620865,	27.744467,	792.8172,	805.2312	
396	253273	RV	Nisha Danuwar	Nisha Danuwar	Sindhupalchowk	Bhimtar	2	0				Indrawati	12	110	403594				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 3	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9808990860	85.620705,	27.744091,	796.58057,	824.59375	
397	253271	RV	Kheel Bahadur Danuwar	Khil Bahadur Danuwar	Sindhupalchowk	Bhimtar	2	0				Indrawati	12	131	403442				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9813833752	85.61998,	27.741846,	758.69287,	779.94976	
398	253292	RV	Shree Dhar Neupane	Sri Dhar Nupana	Sindhupalchowk	Bhimtar	3	0				Indrawati	12	13	397388		Kathmandu,Kages wori-Manahara-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849364410	85.6008	27.756691	737.35297		
399	250012	RV	Suman Shrestha	Suman Shrestha	Sindhupalchowk	Bhimtar	3	0				Indrawati	12	111	396048				1	Grade 2	Minor Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9851119864	85.604843	27.752609	731.60443		
400	253302	RV	Krishna Danuwar	Krishna Bhadur Danuwar	Sindhupalchowk	Bhimtar	4	0				Indrawati	12	60	397403				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9841129906	85.607445,	27.747423,	671.79968,	788.17413	
401	253303	RV	Prem Bahadur Danuwar	Prem Bhadur Danuwar	Sindhupalchowk	Bhimtar	4	0				Indrawati	12	74	397421				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9860792063	85.611717,	27.749207,	770.69565,	783.76117	
402	253191	RV	Ram Bhakta Raidanuwar	Ram Bhakta Rai Danuwar	Sindhupalchowk	Bhimtar	5	0				Indrawati	12	3	396243		Sindhupalchowk,B himtar-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813704680	85.619942	27.741724	774.88715		
403	253194	RV	Hari B Danuwar	Hari Bjadur Danuwar	Sindhupalchowk	Bhimtar	5	0				Indrawati	12	96	404963		Kathmandu,Kathm andu-35	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851008617	85.619247	27.741213	757.64044		
404	253189	RV	Surendra B Danuwar	Surendra Bhadur Danuwar	Sindhupalchowk	Bhimtar	5	0				Indrawati	12	105	404973		Sindhupalchowk,B himtar-2	Partial Damage	2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9851173102	85.614388,	27.735634,	646.98279,	755.89941	
405	253196	RV	Balaram Danuwar	Bala Ram Danuwar	Sindhupalchowk	Bhimtar	6	0				Indrawati	12	3	403488				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 3	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9849317885	85.620071,	27.741459,	765.6955,	786.64484	
406	253195	RV	Buddhi B Danuwar	Buddhi Bhadur Danuwar	Sindhupalchowk	Bhimtar	6	0				Indrawati	12	26	403511				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9818338408	85.621117,	27.741007,	783.3551,	790.61737	
407	253213	RV	Kanchaman Danuwar	Kancha Man Danuwar, Makuri Danuwar	Sindhupalchowk	Bhimtar	8	0				Indrawati	12	4	396405				3	Grade 5, Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 5, Grade 4	Grade 5, Grade 5, Grade 2	Grade 5, Grade 5, Grade 2	Reconstruct, Reconstruct, Minor Repair	Habitable House in Usual Place	9741018008	85.623634,	27.740599,	776.40192,	776.68243,	779.09937
408	253211	RV	Makuri Danuwar	Kancha Man Danuwar, Makuri Danuwar	Sindhupalchowk	Bhimtar	8	0				Indrawati	12	4	396406				3	Grade 5, Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 5, Grade 4	Grade 5, Grade 5, Grade 2	Grade 5, Grade 5, Grade 2	Reconstruct, Reconstruct, Minor Repair	Habitable House in Usual Place	9741018008	85.62368,	27.740686,	776.68243,	779.09937	
409	255393	RV	Bhim Bdr Shrestha	Bhim Bahadur Shrestha	Sindhupalchowk	Chautara	1	0				Chautara Sagachowkgadhi Municipality	6	21	369738		Sindhupalchowk,C hautara-8	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849012293	85.725571	27.762106	1502.094		
410	255183	RV	Ek Lal Shrestha	Ek Lal Shrestha	Sindhupalchowk	Chautara	1	0				Chautara Sagachowkgadhi Municipality	6	41	406685				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	85.722466,	27.760469,	1432.4906,	1433.6123		
411	255256	RV	Dil Maya Shrestha	Dil Maya Shrestha	Sindhupalchowk	Chautara	1	0				Chautara Sagachowkgadhi Municipality	6	42	406686				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9841894581	85.722473,	27.760544,	1437.255,	1440.0314	
412	255185	RV	Kamal Bdr Shrestha	Kamal Bahadur Shrestha	Sindhupalchowk	Chautara	1	0				Chautara Sagachowkgadhi Municipality	6	53	406699				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	9803317985	85.722816,	27.759674,	1444.5176,	1461.4321	
413	255242	RV	Sanu Maya Shrestha	Rashmi Shrestha, Sanu Maya Shrestha	Sindhupalchowk	Chautara	1	0				Chautara Sagachowkgadhi Municipality	6	55	402677	23-14-1-0-49			1	Grade 4	Reconstruct	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.722824	27.759514	1444.0266		
414	255445	RV	Indra Lal Shrestha	Indra Lal Shrestha	Sindhupalchowk	Chautara	1	0				Chautara Sagachowkgadhi Municipality	6	57	402679				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9803318170	85.720398,	27.758375,	1450.4556,	1451.2979	
415	255264	RV	Ram Das Shrestha	Ram Das Shrestha	Sindhupalchowk	Chautara	1	0				Chautara Sagachowkgadhi Municipality	6	59	402681				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9843248794	85.722427,	27.759922,	1434.0907,	1446.2814	
416	255182	RV	Ashmita Parajuli	Ashmita Parajuli	Sindhupalchowk	Chautara	1	0				Chautara Sagachowkgadhi Municipality	6	63	402688				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9841989942	85.720558	27.758488	1429.7423		
417	255186	RV	Anka Bdr Shrestha	Ank Bahadur Shrestha	Sindhupalchowk	Chautara	1	0				Chautara Sagachowkgadhi Municipality	6	64	402689				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9843020113	85.721962	27.759602	1441.7928		

418	255245	RV	Sher Bdr Shrestha	Sher Bahadur Shrestha	Sindhupalchowk	Chautara	1	0		Chautara Sagachowkgadhi Municipality	6	82	402983							2	Grade 1, Grade 4	Not Required, Reconstruct	Grade 2, Grade 2	Grade 2, Grade 4	Grade 2, Grade 4	Minor Repair, Major Repair	Habitable House in Usual Place	9741407060	85.722046, 85.72216	27.759634, 27.759665	1430.5844, 1443.7078
419	255181	RV	Chnadra Prd Shrestha	Chandra Prasad Shrestha	Sindhupalchowk	Chautara	1	0		Chautara Sagachowkgadhi Municipality	6	83	402984							2	Grade 2, Grade 4	Minor Repair, Reconstruct	Grade 2, Grade 3	Grade 1, Grade 4	Grade 1, Grade 4	Not Required, Reconstruct	Habitable House in Usual Place	9803416147	85.722015, 85.722168	27.759705, 27.759733	1429.336, 1447.6422
420	255409	RV	Raju Lama	Raju Lama	Sindhupalchowk	Chautara	1	0		Chautara Sagachowkgadhi Municipality	6	111	402671							2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9841989877	85.720978, 85.721024	27.759867, 27.759893	1422.8859, 1428.9924
421	255189	RV	Ramesh Shrestha	Ramesh Shrestha	Sindhupalchowk	Chautara	1	0		Chautara Sagachowkgadhi Municipality	6	132	402617							2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9741134171	85.720581, 85.721504	27.759094, 27.759235	1422.0433, 1445.9058
422	255407	RV	Lok Bdr Shrestha	Lok Bahadur Shrestha	Sindhupalchowk	Chautara	2	0		Chautara Sagachowkgadhi Municipality	6	2	369079							3	Grade 5, Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 5, Grade 1	Grade 5, Grade 5, Grade 1	Grade 5, Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9808177075	85.716995, 85.717026, 85.717484	27.762123, 27.762836, 27.762932	1257.5923, 1266.4468, 1294.9706
423	251398	RV	Jhuma Shrestha	Jhuma Shrestha	Sindhupalchowk	Chautara	2	0		Chautara Sagachowkgadhi Municipality	6	9	369086							1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9843248581	85.717636	27.762165	1291.6404
424	255329	RV	Rajani Shrestha(Kakshapati)	Rajni Shrestha	Sindhupalchowk	Chautara	2	0		Chautara Sagachowkgadhi Municipality	6	10	369087		Kathmandu,Kathmandu-17	No Damage				1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849243564	85.722366	27.768951	1399.3363
425	255398	RV	Rajendra Shrestha	Rajendra Shrestha	Sindhupalchowk	Chautara	2	0		Chautara Sagachowkgadhi Municipality	6	12	369089							2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 3, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9818276505	85.717232, 85.717995	27.762444, 27.763124	1273.0557, 1307.4216
426	255440	RV	Dhan Bdr Shrestha	Dhan Bahadur Shrestha	Sindhupalchowk	Chautara	2	0		Chautara Sagachowkgadhi Municipality	6	32	369485							1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9803188149	85.720055	27.762959	1299.5415
427	255441	RV	Hari Bdr Shrestha	Hari Bahadur Shrestha	Sindhupalchowk	Chautara	2	0		Chautara Sagachowkgadhi Municipality	6	33	369486							1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place		85.720009	27.762873	1298.4988
428	255455	RV	Ratna Bdr Shrestha	Ratna Bahadur Shrestha	Sindhupalchowk	Chautara	2	0		Chautara Sagachowkgadhi Municipality	6	39	369493							1	Grade 1	Not Required	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841989438	85.720505	27.765375	1315.297
429	255454	RV	Surya Bdr Shrestha	Surya Bahadur Shrestha	Sindhupalchowk	Chautara	2	0		Chautara Sagachowkgadhi Municipality	6	47	369506							2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9841651779	85.721695, 85.724625	27.766901, 27.769775	1405.9421, 1472.7799
430	255327	RV	Ramkrishna Shrestha	Ram Krishna Shrestha	Sindhupalchowk	Chautara	2	0		Chautara Sagachowkgadhi Municipality	6	48	369507							2	Grade 1, Grade 5	Not Required, Reconstruct	Grade 1, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	9851021504	85.721458, 85.724503	27.767212, 27.769691	1405.6956, 1460.7755
431	255252	RV	Jashanti Shrestha	Jasanti Shrestha	Sindhupalchowk	Chautara	2	0		Chautara Sagachowkgadhi Municipality	6	64	369525							2	Grade 1, Grade 5	Not Required, Reconstruct	Grade 1, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place		85.722038, 85.722237	27.769119, 27.769194	1422.8311, 1436.6988
432	255260	RV	Dil Kumari Shrestha	Dil Kumari Shrestha	Sindhupalchowk	Chautara	2	0		Chautara Sagachowkgadhi Municipality	6	65	369527							3	Grade 5, Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 5, Grade 1	Grade 5, Grade 5, Grade 1	Grade 5, Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9841479375	85.721817, 85.721954, 85.723167	27.769201, 27.769415, 27.769594	1387.9063, 1417.0298, 1439.4115
433	255176	RV	Diwakar Maskey	Dibakar Maske	Sindhupalchowk	Chautara	2	0		Chautara Sagachowkgadhi Municipality	6	66	369530		Bhaktapur,Mathyapur Thimi-17	No Damage				1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841415891	85.72155	27.769897	1393.4489
434	255178	RV	Nar Bdr Maskey	Nar Bahadur Maske	Sindhupalchowk	Chautara	2	0		Chautara Sagachowkgadhi Municipality	6	69	369533							2	Grade 1, Grade 5	Not Required, Reconstruct	Grade 1, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	9849458791	85.723976, 85.724025	27.769201, 27.769331	1456.353, 1461.2913
435	253532	RV	Keshab Lal Shrestha	Keshav Laal Shrestha	Sindhupalchowk	Chautara	2	0		Chautara Sagachowkgadhi Municipality	6	87	369752							2	Grade 1, Grade 4	Not Required, Reconstruct	Grade 1, Grade 3	Grade 1, Grade 4	Grade 1, Grade 4	Not Required, Reconstruct	Habitable House in Usual Place	9843251315	85.723625, 85.724075	27.763136, 27.763327	1424.4932, 1429.3271
436	255438	RV	Bashu Dev Shrestha	Basu Dev Shrestha	Sindhupalchowk	Chautara	2	0		Chautara Sagachowkgadhi Municipality	6	88	369753		Kathmandu,Kathmandu-8	No Damage				1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841688999	85.723969	27.763235	1416.0574
437	255539	RV	Huma Devi Rana	Huma Devi Rana, Rashni Ghimire lama	Sindhupalchowk	Chautara	2	0		Chautara Sagachowkgadhi Municipality	6	102	402619		Sindhupalchowk,Thulosirubari-4	Complete Damage				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	11620409	85.723335	27.769272	1434.9139
438	255299	RV	Sujani Shrestha	Suman Shrestha	Sindhupalchowk	Chautara	3	0		Chautara Sagachowkgadhi Municipality	5	19	369563							1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	11260366	85.721519	27.770454	1402.6897
439	255298	RV	Suman Shrestha	Suman Shrestha	Sindhupalchowk	Chautara	3	0		Chautara Sagachowkgadhi Municipality	5	19	369562							1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	11260366	85.721519	27.770454	1402.6897
440	255395	RV	Bir Bdr Shrestha	Bir Bahadur Shrestha	Sindhupalchowk	Chautara	3	0		Chautara Sagachowkgadhi Municipality	5	21	369565		Sindhupalchowk,Chautara-2	Partial Damage				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Other Place	9841944633	85.721214	27.77039	1396.5372
441	255258	RV	Lok Bdr Shrestha	Jhamka Laal Shrestha, Lok Bahadur Shrestha	Sindhupalchowk	Chautara	4	0		Chautara Sagachowkgadhi Municipality	5	21	368826							1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9841944654	85.722511	27.77153	1390.7196
442	255451	RV	Suha Lal Shrestha	Sudha Laal Shrestha	Sindhupalchowk	Chautara	4	0		Chautara Sagachowkgadhi Municipality	5	22	368828							1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9741134394	85.722961	27.771053	1388.2345
443	255431	RV	Tilak Bdr Thapamagar	Tilak Bahadur Thapamagar	Sindhupalchowk	Chautara	4	0		Chautara Sagachowkgadhi Municipality	5	90	368912							1	Grade 2	Minor Repair	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.724319	27.770836	1429.218
444	255442	RV	Dhame Raj Shrestha	Dharna Raj Shrestha	Sindhupalchowk	Chautara	4	0		Chautara Sagachowkgadhi Municipality	5	91	368913							1	Grade 1	Not Required	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9813360843	85.724236	27.770889	1415.4612
445	255318	RV	Khadga Bdr Shrestha	Khadga Bahadur Shrestha	Sindhupalchowk	Chautara	4	0		Chautara Sagachowkgadhi Municipality	5	92	368914							1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9860606873	85.724312	27.770931	1429.6047
446	251514	RV	Keshab Thapa	Keshav Thapa	Sindhupalchowk	Chautara	4	0		Chautara Sagachowkgadhi Municipality	5	96	368919							1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9813701107	85.724213	27.770973	1419.4821
447	255433	RV	Surya Bdr Ghale	Surj Bahadur Ghale	Sindhupalchowk	Chautara	4	0		Chautara Sagachowkgadhi Municipality	5	100	368923							1	Grade 1	Not Required	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9813004632	85.723717	27.770948	1414.0524
448	255404	RV	Ram Lal Shrestha	Ram Laal Shrestha	Sindhupalchowk	Chautara	4	0		Chautara Sagachowkgadhi Municipality	5	104	368927							1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9849166370	85.722977	27.770435	1432.8246
449	255312	RV	Dev Kumari Shrestha	Dev Kumari Shrestha, Krishna Gopal Shrestha	Sindhupalchowk	Chautara	4	0		Chautara Sagachowkgadhi Municipality	5	105	368929							1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9741033634	85.723129	27.770187	1429.3071
450	255535	RV	Gyanu Maya Shrestha	Gyan Maya Shrestha	Sindhupalchowk	Chautara	5	0		Chautara Sagachowkgadhi Municipality	4	10	513460							2	Grade 1, Grade 5	Not Required, Reconstruct	Grade 2, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	9841944520	85.716583, 85.717819	27.772554, 27.773102	1350.4033, 1352.9923
451	255746	RV	Nokh Bdr Shrestha	Nokh Bahadur Shrestha	Sindhupalchowk	Chautara	5	0		Chautara Sagachowkgadhi Municipality	4	11	513461		Sindhupalchowk,Chautara-9	Complete Damage				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9818832322	85.717743	27.773092	1368.826
452	255177	RV	Laxmi Shrestha	Laxmi Shrestha	Sindhupalchowk	Chautara	5	0		Chautara Sagachowkgadhi Municipality	4	26	512553							1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849186713	85.717789	27.772791	1384.998

453	255326	RV	Santa Maya Shrestha	Santa Maya Shrestha	Sindhupalchowk	Chautara	5	0		Chautara Sagachowgadhi Municipality	4	28	512556				3	Grade 2, Grade 5, Grade 3	Minor Repair, Reconstruct, Minor Repair	Grade 2, Grade 5, Grade 2	Grade 2, Grade 5, Grade 2	Grade 2, Grade 5, Grade 2	Minor Repair, Reconstruct, Minor Repair	Habitable House in Usual Place	9808380665	85.717606, 85.717628, 85.717836	27.772865, 27.772915, 27.772943	1382.0466, 1383.7439, 1387.4934
454	255321	RV	Padam Maya Shrestha	Padma Maya Shrestha	Sindhupalchowk	Chautara	5	0		Chautara Sagachowgadhi Municipality	4	37	512565				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9810230370	85.717438	27.772923	1384.3156
455	255324	RV	Rajendra Shrestha	Rajendra Shrestha	Sindhupalchowk	Chautara	5	0		Chautara Sagachowgadhi Municipality	4	42	512569				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849345360	85.717606	27.772501	1385.9967
456	255266	RV	Ujeli Maya Shrestha	Ujeli Maya Shrestha	Sindhupalchowk	Chautara	5	0		Chautara Sagachowgadhi Municipality	4	56	512658				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	1120212	85.718765, 85.718849	27.772457, 27.772463	1396.755, 1408.5181
457	255661	RV	Krishna Bdr Shrestha	Krishna Bahadur Shrestha	Sindhupalchowk	Chautara	5	0		Chautara Sagachowgadhi Municipality	4	61	512662				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 2	Grade 4, Grade 1	Grade 5, Grade 1	Reconstruct, Minor Repair	Habitable House in Usual Place	9841088845	85.718773, 85.719154	27.772127, 27.772255	1380.3262, 1385.6594
458	255247	RV	Indra Mani Shrestha	Rahar Maya Shrestha	Sindhupalchowk	Chautara	5	0		Chautara Sagachowgadhi Municipality	4	65	512666				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 3, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9741027233	85.719177, 85.719345	27.77232, 27.772369	1379.4249, 1385.868
459	255403	RV	Krishna Maya Shrestha	Krishna Maya Shrestha	Sindhupalchowk	Chautara	5	0		Chautara Sagachowgadhi Municipality	4	78	512630				1	Grade 2	Minor Repair	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	11620288	85.719849	27.771772	1389.6973
460	255334	RV	Bhes Raj Shrestha	Ganesh Bahadur Shrestha	Sindhupalchowk	Chautara	5	0		Chautara Sagachowgadhi Municipality	4	80	512633				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	11620321	85.719765	27.77174	1399.1906
461	255446	RV	Hira Bdr Shrestha	Hira Bahadur Shrestha, Ram Chandra Shrestha	Sindhupalchowk	Chautara	5	0		Chautara Sagachowgadhi Municipality	4	81	512634				1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9841808802	85.719795	27.771563	1397.5927
462	255338	RV	Ram Chandra Shrestha	Hira Bahadur Shrestha, Ram Chandra Shrestha	Sindhupalchowk	Chautara	5	0		Chautara Sagachowgadhi Municipality	4	81	512635				1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9841808802	85.719795	27.771563	1397.5927
463	255534	RV	Shom Bdr Shrestha	Som Bahadur Shrestha	Sindhupalchowk	Chautara	5	0		Chautara Sagachowgadhi Municipality	4	105	511086				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9813851343	85.720085	27.771542	1399.5211
464	255187	RV	Rabindra Pra Shrestha	Rabindra Prasad Shrestha	Sindhupalchowk	Chautara	5	0		Chautara Sagachowgadhi Municipality	4	106	511087				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 2	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9841989041	85.720009, 85.720108	27.77137, 27.771507	1397.6903, 1401.3854
465	253529	RV	Harka Bdr Shrestha	Harka Bahadur Shrestha	Sindhupalchowk	Chautara	5	0		Chautara Sagachowgadhi Municipality	4	113	512535				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843907245	85.718933	27.772469	1389.3402
466	250706	RV	Sano Kanchha B.K	Sano Kancha Bishwakarma	Sindhupalchowk	Chautara	5	0		Chautara Sagachowgadhi Municipality	4	118	512470		Sindhupalchowk,C hautara-9	Complete Damage	1	Grade 1	Minor Repair	Grade 4	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9803873039	85.717468	27.772804	1362.9298
467	257406	RV	Jagat Bdr Shrestha	Jagat Bahadur Shrestha	Sindhupalchowk	Chautara	6	0		Chautara Sagachowgadhi Municipality	4	2	368702		Sindhupalchowk,C hautara-8	Partial Damage	1	Grade 5	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841924297	85.727348	27.788881	1050.1251
468	257404	RV	Chakra Bdr Shrestha	Chakra Bahadur Shrestha	Sindhupalchowk	Chautara	6	0		Chautara Sagachowgadhi Municipality	4	24	368726		Sindhupalchowk,C hautara-8	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9849474129	85.722466	27.78759	1151.1981
469	255702	RV	Kripa Shrestha	Kripa Shrestha, Shanti Man Shrestha, Shiva Man Shrestha	Sindhupalchowk	Chautara	7	0		Chautara Sagachowgadhi Municipality	5	8	512506		Sindhupalchowk,C hautara-5	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841560809	85.728722	27.784781	1085.7902
470	255704	RV	Shanti Man Shrestha	Kripa Shrestha, Shanti Man Shrestha, Shiva Man Shrestha	Sindhupalchowk	Chautara	7	0		Chautara Sagachowgadhi Municipality	5	8	512505		Sindhupalchowk,C hautara-5	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841560809	85.728722	27.784781	1085.7902
471	255728	RV	Karna Bdr Bhujel	Karna Bahadur Bhujel, Krishna Bahadur Bhujel, Ram Bahadur Bhujel	Sindhupalchowk	Chautara	7	0		Chautara Sagachowgadhi Municipality	5	33	512687				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9741134120	85.727142, 85.728119	27.776379, 27.780033	1189.3424, 1291.7917
472	255656	RV	Krishna Bdr Bhujel	Karna Bahadur Bhujel, Krishna Bahadur Bhujel, Ram Bahadur Bhujel	Sindhupalchowk	Chautara	7	0		Chautara Sagachowgadhi Municipality	5	33	512689				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9741134120	85.727142, 85.728119	27.776379, 27.780033	1189.3424, 1291.7917
473	255729	RV	Ram Bdr Bhujel	Karna Bahadur Bhujel, Krishna Bahadur Bhujel, Ram Bahadur Bhujel	Sindhupalchowk	Chautara	7	0		Chautara Sagachowgadhi Municipality	5	33	512688				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9741134120	85.727142, 85.728119	27.776379, 27.780033	1189.3424, 1291.7917
474	251506	RV	Hira Bhujel	Majhi Bujhel	Sindhupalchowk	Chautara	7	0		Chautara Sagachowgadhi Municipality	5	44	512727		Kathmandu,Kavres thali-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860609827	85.726662	27.779169	1185.9175
475	255399	RV	Hira Bhujel	Majhi Bujhel	Sindhupalchowk	Chautara	7	0		Chautara Sagachowgadhi Municipality	5	44	512727		Kathmandu,Kavres thali-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860609827	85.726662	27.779169	1185.9175
476	255748	RV	Majhi Bhujel	Majhi Bujhel	Sindhupalchowk	Chautara	7	0		Chautara Sagachowgadhi Municipality	5	44	512726		Kathmandu,Kavres thali-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860609827	85.726662	27.779169	1185.9175
477	255739	RV	Jhamka Bdr Ghale	Jhanka Bahadur Ghale	Sindhupalchowk	Chautara	7	0		Chautara Sagachowgadhi Municipality	5	47	512730				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9851144603	85.726074	27.775398	1315.1919
478	250709	RV	Shiva Lal Shrestha	Shiva Lal Shrestha	Sindhupalchowk	Chautara	7	0		Chautara Sagachowgadhi Municipality	5	49	512733		Kathmandu,Kathm andu-32/Kathmandu,Tok ha Sarsawati-14	Complete Damage, Partial Damage	1	Grade 4	Reconstruct	Grade 4	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9813771334	85.728897	27.779545	1216.1549
479	255744	RV	Suku Maya Tamang	Brihasspati Khatri, Sukumaya Tamang	Sindhupalchowk	Chautara	7	0		Chautara Sagachowgadhi Municipality	5	75	512714		23-14-7-0-70		1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9841822647	85.726784	27.776533	1289.7161
480	255747	RV	Man Bajra Shakya	Man Bajra Shakya	Sindhupalchowk	Chautara	7	0		Chautara Sagachowgadhi Municipality	5	99	512768				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9849269333	85.727081, 85.727127	27.776131, 27.776434	1285.7452, 1286.7632
481	255332	RV	Pushpa Kumar Nepali	Pushpa Kumar Nepali	Sindhupalchowk	Chautara	7	0		Chautara Sagachowgadhi Municipality	5	100	512769		Sindhupalchowk,K uvende-1	Complete Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841423420	85.726524	27.775707	1298.2073
482	255692	RV	Chandra Maya Kashaju	Chandra Maya Kosaju	Sindhupalchowk	Chautara	7	0		Chautara Sagachowgadhi Municipality	5	104	512773				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9741088588	85.725754, 85.725807	27.774378, 27.774429	1310.0142, 1318.1635
483	255528	RV	Surya Bdr Shrestha	Ramesh Shrestha, Surja Bahadur Shrestha	Sindhupalchowk	Chautara	8	1		Chautara Sagachowgadhi Municipality	7	5	550130				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9841271292	85.716377	27.773615	1407.4679
484	255660	RV	Bhupendra Thapa	Bhupendra Thapa	Sindhupalchowk	Chautara	8	1		Chautara Sagachowgadhi Municipality	7	19	550147				1	Grade 1	Minor Repair	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9843094787	85.715462	27.773855	1384.9839
485	255531	RV	Lok Bdr Shrestha	Bed Bahadur Shrestha	Sindhupalchowk	Chautara	8	1		Chautara Sagachowgadhi Municipality	7	22	550303		23-14-8-1-13		1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849767594	85.715157	27.774073	1399.9098
486	255530	RV	Ratna Bdr Shrestha	Ratna Bahadur Shrestha, Tula Bahadur Shrestha	Sindhupalchowk	Chautara	8	1		Chautara Sagachowgadhi Municipality	7	52	843993		23-14-8-1-32		1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9841251347	85.713593	27.775717	1409.8844
487	255599	RV	Tambi Tamang	Iman Singh Tamang	Sindhupalchowk	Chautara	8	1		Chautara Sagachowgadhi Municipality	7	91	843780				1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9863603545	85.713264	27.778099	1407.2029

488	255614	RV	Som Bdr Karki	Som Bahadur Karki	Sindhupalchowk	Chautara	8	1		Chautara Sagachowkgadhi Municipality	7	100	843785		Sindhupalchowk, Syaula-9	Complete Damage	2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 1	Unrecognized, Grade 1	Unrecognized, Grade 1	Unrecognized, Not Required	Habitable House in Usual Place	9841924860	85.713211, 85.713242	27.778505, 27.778559	1417.0082, 1419.0842	
489	255679	RV	Kanchhi Tamang	Kanchhi Tamang	Sindhupalchowk	Chautara	8	1		Chautara Sagachowkgadhi Municipality	7	120	843794				1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9810355342	85.712845	27.781359	1382.6337	
490	255662	RV	Prem Bdr Khatri	Prem Bahadur Karki	Sindhupalchowk	Chautara	8	1		Chautara Sagachowkgadhi Municipality	7	160	841003				1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9864015190	85.713707	27.775051	1421.4602	
491	255682	RV	Padam Maya Shrestha	Padam Maya Shrestha	Sindhupalchowk	Chautara	8	1		Chautara Sagachowkgadhi Municipality	7	163	841006				1	Grade 2	Minor Repair	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.713448	27.775093	1403.5802	
492	255613	RV	Hem Kumari Damini	Hem Kumari Damini	Sindhupalchowk	Chautara	8	1		Chautara Sagachowkgadhi Municipality	7	220	550172				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9843972815	85.710411	27.776001	1360.3751	
493	255592	RV	Padam Bdr B.K.	Padam Bahadur Bishwakarma	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	1	842351				3	Grade 5, Grade 4, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 3, Grade 2	Grade 5, Grade 4, Grade 2	Grade 5, Grade 4, Grade 2	Reconstruct, Major Repair, Minor Repair	Habitable House in Usual Place	9741165275	85.714638, 85.714706, 85.716896	27.773397, 27.776279, 27.776342	1351.446, 1375.8632, 1377.9445	
494	255532	RV	Narayanakaji Shrestha	Narayan Kaji Shrestha, Umesh Kumar Shrestha	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	8	842358				2	Grade 1, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Unrecognized	Grade 1, Unrecognized	Grade 1, Unrecognized	Habitable House in Usual Place	9843185253	85.715691, 85.715881	27.773731, 27.773741	1398.5469, 1399.2205	
495	255674	RV	Chandra Kaji Lama	Chandra Kaji Lama	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	10	842360				2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 1	Unrecognized, Grade 1	Unrecognized, Grade 1	Not Required	Habitable House in Usual Place	9741212341	85.716947, 85.7164	27.773638, 27.773714	1387.1426, 1390.7709	
496	255602	RV	Binod Shrestha	Hirakaji Shrestha	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	31	842010				2	Grade 1, Grade 5	Not Required, Reconstruct	Grade 1, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	9800648101	85.714127, 85.714996	27.775089, 27.775097	1382.8038, 1412.3936	
497	253526	RV	Nanda Kumari Ghale	Nand Kumari Ghale	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	32	842013				2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9810099870	85.715118, 85.715195	27.774899, 27.774927	1384.6541, 1396.5193	
498	255522	RV	Rama Giri	Rama Giri	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	44	841088				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9849165234	85.715935	27.774663	1384.7252	
499	255596	RV	Rama Giri	Rama Giri	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	44	841088				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9849165234	85.715935	27.774663	1384.7252	
500	251508	RV	Bimala Ghale	Sankhmaya Ghale	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	45	841090				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9843184121	85.715881	27.77446	1404.9695	
501	255608	RV	Putali Gurung	Ganesh Bahadur Gurung, Putali Gurung	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	52	841098				3	Grade 1, Grade 5, Grade 5	Minor Repair, Reconstruct	Grade 1, Grade 5, Grade 5	Grade 1, Grade 5, Grade 5	Grade 1, Grade 5, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	9841924053	85.715431, 85.715454, 85.715515	27.774773, 27.77483, 27.774845	1386.0479, 1388.8428, 1392.7014	
502	255667	RV	Kulman Ghale	Kul maya Ghale	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	55	842227				2	Grade 4, Grade 1	Major Repair, Minor Repair	Grade 3, Grade 1	Grade 2, Grade 1	Grade 2, Grade 1	Minor Repair, Not Required	Habitable House in Usual Place		85.715569, 85.715919	27.774864, 27.774879	1386.0291, 1414.7612	
503	251510	RV	Sabita Thapa	Sabita Ghale	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	56	842229				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9813561774	85.716103	27.774523	1372.7909	
504	255603	RV	Manoj Kumar Shrestha	Sushila Devi Ghale	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	68	842244				3	Grade 5, Grade 1, Grade 5	Reconstruct, Minor Repair, Reconstruct	Grade 5, Grade 2, Grade 5	Grade 5, Grade 2, Grade 5	Grade 5, Grade 2, Grade 5	Reconstruct, Minor Repair, Reconstruct	Habitable House in Usual Place	9848036448	85.715721, 85.715759, 85.71582	27.775528, 27.775623, 27.775663	1373.217, 1374.4987, 1390.6111	
505	255605	RV	Puja Shrestha(Ghale)	Sushila Devi Ghale	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	68	842245				3	Grade 5, Grade 1, Grade 5	Reconstruct, Minor Repair, Reconstruct	Grade 5, Grade 2, Grade 5	Grade 5, Grade 2, Grade 5	Grade 5, Grade 2, Grade 5	Reconstruct, Minor Repair, Reconstruct	Habitable House in Usual Place	9848036448	85.715721, 85.715759, 85.71582	27.775528, 27.775623, 27.775663	1373.217, 1374.4987, 1390.6111	
506	255611	RV	Niru Aale Magar(Ghale)	Ek Bahadur Ghale	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	70	842248		Chitwan, Meghauli-2	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9813847014	85.715355	27.775526	1372.4655
507	255525	RV	Ram Bdr Gurung	Ram Bahadur Gurung	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	81	842310				2	Grade 4, Grade 1	Reconstruct, Minor Repair	Grade 4, Grade 1	Grade 4, Grade 1	Grade 4, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9813447274	85.715324, 85.715355	27.775993, 27.776003	1367.7894, 1382.4307	
508	255671	RV	Kale Bdr B.K.	Kale Bahadur Bushwakarma	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	82	842313				2	Grade 4, Grade 1	Reconstruct, Minor Repair	Grade 4, Grade 1	Grade 4, Grade 1	Grade 4, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9841929225	85.714714, 85.715683	27.775959, 27.776127	1357.9982, 1368.4753	
509	255606	RV	Bushab B.K.	Ila Bishwakarma	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	86	842318				2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 4, Grade 1	Grade 4, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9818676898	85.714859, 85.714912	27.77636, 27.776449	1363.7729, 1373.9327	
510	255518	RV	Ramsharan B.K.	Thuli Kanchhi Bishwakarma	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	110	842189				1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818765479	85.714561	27.776014	1370.5122	
511	255526	RV	Thulikanchhi B.K.	Thuli Kanchhi Bishwakarma	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	110	842188				1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818765479	85.714561	27.776014	1370.5122	
512	255597	RV	Bhupal B.K.	Bhupal Bishwakarma	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	114	842195				2	Grade 1, Grade 4	Minor Repair, Reconstruct	Grade 1, Grade 4	Grade 1, Grade 4	Grade 1, Grade 4	Not Required, Reconstruct	Habitable House in Usual Place	9841924735	85.714684, 85.714699	27.776159, 27.776199	1369.7933, 1375.1989	
513	255521	RV	Nirmala Neupane(Katuwal)	Gel Bahadur Katuwal	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	116	842196				2	Grade 1, Grade 4	Minor Repair, Reconstruct	Grade 1, Grade 4	Grade 1, Grade 4	Grade 1, Grade 4	Not Required, Reconstruct	Habitable House in Usual Place	9843742225	85.714439, 85.714493	27.77574, 27.775818	1376.911, 1387.3093	
514	255672	RV	Dil Kumari Ghale	Dil Kumari Ghale	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	117	842197				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9741017810	85.714699	27.775436	1421.9961	
515	255683	RV	Som Chhiring Tamang	Kenam Tamang	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	126	842330				2	Grade 4, Grade 1	Major Repair, Not Required	Grade 4, Grade 1	Grade 4, Grade 1	Grade 4, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9806564844	85.71347, 85.713509	27.776285, 27.776363	1393.3071, 1407.3019	
516	253528	RV	Kalika Devi Katuwal	Kalika Devi Katuwal	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	149	842348				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9843071990	85.713875	27.777275	1373.79	
517	255666	RV	Chhote Tamang	Chhote Tamang	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	174	842264		Sindhupalchowk, B atase-9	Complete Damage	1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9808327997	85.71315	27.777098	1413.2216	
518	250711	RV	Tara Devi Khatri	Ganesh Bahadur Khatri	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	187	842269				1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9841368091	85.712517	27.775179	1421.9103	
519	255179	RV	Dhan Kumari Puri	Dhan Kumari Puri	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	193	842275				1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9841925121	85.711502	27.775513	1417.8434	
520	255659	RV	Padam Tamang	Chandra Kumar Basnet, Sukumaya Tamang	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	194	842277				1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741097572	85.712769	27.774876	1407.9419	
521	255595	RV	Hom Bdr Karki	Hom Bahadur Karki	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	220	842298				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841924115	85.710159	27.779663	1390.7913	
522	255668	RV	Kumari Budhathoki	Tha Kumari Budhathoki	Sindhupalchowk	Chautara	8	2		Chautara Sagachowkgadhi Municipality	7	226	550354				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818234733	85.710472	27.779034	1365.4503	

569	254912	RV	Tika Bdr. Shrestha	Tika Bahadur Shrestha	Sindhupalchowk	Fulpingdanda	4	0			Bhalephi	4	78	547297		Kathmandu,Kathmandu-2	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	974111176	85.779549	27.763733	1019.0172
570	254795	RV	Sukumaya Tamang	Sukuman Tamang	Sindhupalchowk	Fulpingdanda	5	0			Bhalephi	5	6	558091		Kathmandu,Budhanilkantha-5	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813482059	85.785233	27.756861	1217.7299
571	254844	RV	Shiva Prd Nepal	Shiva Prasad Nepal	Sindhupalchowk	Fulpingdanda	5	0			Bhalephi	5	244	333932		Bhaktapur,Madhyapur Thimi-3	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741034363	85.796822	27.760557	1138.9725
572	254839	RV	Parbati Shrestha	Parbati Shrestha	Sindhupalchowk	Fulpingdanda	7	0			Bhalephi	5	111	550000		Kathmandu,Kathmandu-34	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851145239	85.803108	27.744122	700.75098
573	254836	RV	Suntali Sharma Nepal	Suntali Sharma Nepal	Sindhupalchowk	Fulpingdanda	8	0			Bhalephi	4	137	367542				2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Minor Repair	Habitable House in Usual Place	986007868	85.797234, 85.809464	27.747711, 27.761007	1119.4524, 693.86304
574	254835	RV	Narayan Kumari Nepal	Narayan Kumari Nepal	Sindhupalchowk	Fulpingdanda	8	0			Bhalephi	4	165	367548		Kathmandu,Gaolfedi-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741424983	85.805573	27.749523	702.61011
575	254726	RV	Ajaya Karki	Ajay Karki	Sindhupalchowk	Fulpingdanda	9	0			Bhalephi	5	16	365298				1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9849747103	85.782356	27.73844	808.20288
576	254847	RV	Sanjip Shrestha	Sanjiv Shrestha	Sindhupalchowk	Fulpingdanda	9	0			Bhalephi	5	33	365015				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9849663222	85.783447	27.737684	818.59369
577	254829	RV	Purna Kumari Shrestha	Purna Kumar Shrestha	Sindhupalchowk	Fulpingdanda	9	0			Bhalephi	5	116	844400		Kavrepalanchowk,Banepa-10	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9611197045	85.780029	27.732502	645.97968
578	254837	RV	Ganesh Shrestha	Gadnesh Shrestha	Sindhupalchowk	Fulpingdanda	9	0			Bhalephi	5	128	558059				1	Grade 2	Minor Repair	Grade 2	Grade 3	Grade 3	Minor Repair	Habitable House in Usual Place	9849470638	85.780014	27.733978	651.74097
579	254834	RV	Masali Shrestha	Masali Shrestha	Sindhupalchowk	Fulpingdanda	9	0			Bhalephi	5	130	558061				1	Grade 2	Minor Repair	Grade 3	Grade 3	Grade 3	Minor Repair	Habitable House in Usual Place	11682126	85.779991	27.733232	646.92358
580	254838	RV	Rudra Bdr Shrestha	Rudra Bahadur Shrestha	Sindhupalchowk	Fulpingdanda	9	0			Bhalephi	5	131	558062		Bhaktapur,Balkot-1/Sindhupalchowk,Fulpingdanda-6	Complete Damage, Partial Damage	3	Grade 5, Grade 1, Grade 1	Reconstruct, Not Required, Minor Repair	Grade 5, Grade 1, Grade 1	Grade 5, Grade 1, Grade 1	Grade 5, Grade 1, Grade 1	Reconstruct, Minor Repair	Habitable House in Other Place	11400501	85.779922, 85.779984, 85.784668	27.732862, 27.733358, 27.7348	650.09369, 652.27533, 655.34991
581	254845	RV	Kesari Shrestha	Kesari Shrestha	Sindhupalchowk	Fulpingdanda	9	0			Bhalephi	5	136	558066				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Other Place	9849758275	85.779999	27.733425	643.32416
582	249503	RV	Norpu Sherpa	Nurpu Sherpa	Sindhupalchowk	Fulpingkatti	1	0			Bhotekoshi	4	17	510706				1	Grade 1	Minor Repair	Grade 4	Grade 1	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.930519	27.919928	1300.4241
583	249698	RV	Dorje Sherpa	Dorje Sherpa	Sindhupalchowk	Fulpingkatti	1	0			Bhotekoshi	4	20	510709				1	Grade 1	Minor Repair	Grade 4	Grade 1	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9621175218	85.929337	27.919884	1381.6935
584	249655	RV	Danorbu Sherpa	Chhiring Dorje Sherpa, Chhiring Dorje Sherpa	Sindhupalchowk	Fulpingkatti	2	0		23-19-2-0-23	Bhotekoshi	4	23	510798				1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9616357452	85.947227	27.915129	2300.748
585	249544	RV	Ang Dorje Sherpa	Ang Dorje Sherpa	Sindhupalchowk	Fulpingkatti	3	0			Bhotekoshi	4	17	333574		Kathmandu,Gokarneswor-15	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	982374664	85.94059	27.90995	1803.8241
586	249547	RV	Sushmita Tamang	Bishal Tamang	Sindhupalchowk	Fulpingkatti	4	0			Bhotekoshi	4	162	326703				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843186280	85.919983	27.905178	1343.7059
587	249559	RV	Sanjok Bhandari	Sanjog Bhandari	Sindhupalchowk	Fulpingkatti	4	0			Bhotekoshi	4	163	326704				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9621195711	85.92012	27.904701	1284.5056
588	249569	RV	Samar Bahadur Ghale	Sangita Ghale	Sindhupalchowk	Fulpingkatti	4	0			Bhotekoshi	4	168	326709				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.92086	27.905779	1268.6819
589	249576	RV	Raju Thami	Raju Thami	Sindhupalchowk	Fulpingkatti	5	0			Bhotekoshi	4	9	510860				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	961648743	85.934669	27.902899	2020.3113
590	249575	RV	Pasang Lamu Sherpa	Dorje Sherpa	Sindhupalchowk	Fulpingkatti	5	0			Bhotekoshi	4	11	510861		Sindhupalchowk,Fulpingkatti-1	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9614937800	85.934944	27.902441	2037.066
591	249574	RV	Phuchhiring Sherpa	Phuchhiring Sherpa	Sindhupalchowk	Fulpingkatti	5	0			Bhotekoshi	4	38	510841				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9616648724	85.934723, 85.935112	27.900352, 27.900515	2080.678, 2081.1938
592	249589	RV	Min Bahadur Khadka	Min Bahadur Khadka chhetri	Sindhupalchowk	Fulpingkatti	6	0			Bhotekoshi	4	94	532518		Kathmandu,Kapan-6	No Damage	1	Grade 3	Major Repair	Grade 3	Grade 3	Grade 3	Major Repair	Habitable House in Other Place	9843746377	85.931129	27.885679	1997.0802
593	249535	RV	Yog Bahadur Silwal	Yog Bahadur Silwal	Sindhupalchowk	Fulpingkatti	6	0			Bhotekoshi	4	139	532614		Lalitpur,Imadol-8	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849245821	85.932892	27.884485	2059.7107
594	249488	RV	Mithu Khatri	Tula Bahadur Khatri	Sindhupalchowk	Fulpingkatti	7	0			Bhotekoshi	4	12	532152				1	Grade 2	Minor Repair	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.927505	27.887512	1860.8676
595	249499	RV	Sang Dorje Sherpa	Sangdorje Sherpa	Sindhupalchowk	Fulpingkatti	7	0			Bhotekoshi	4	17	532157				2	Grade 2, Grade 4	Minor Repair, Reconstruct	Grade 2, Grade 4	Grade 2, Grade 4	Grade 2, Grade 4	Minor Repair, Reconstruct	Habitable House in Usual Place	16924976	85.931206, 85.931229	27.889072, 27.889416	1952.9103, 1956.5503
596	249498	RV	Soman Sherpa	Sonam Sherpa	Sindhupalchowk	Fulpingkatti	7	0			Bhotekoshi	4	30	532170				3	Grade 5, Grade 1, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2, Grade 1	Grade 5, Unrecognized, Unrecognized	Grade 5, Unrecognized, Unrecognized	Reconstruct, Unrecognized, Unrecognized	Matrix & Photo not cleared or mismatch		85.929123, 85.929298, 85.929352	27.889994, 27.890062, 27.890091	1919.7965, 1926.5437, 1926.8999
597	249519	RV	Nima Dul Sherpa	Furpa Sherpa	Sindhupalchowk	Fulpingkatti	7	0			Bhotekoshi	4	32	Null				2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place		85.929153, 85.929275	27.890343, 27.890373	1911.0313, 1924.5647
598	249495	RV	Phurpa Sherpa	Furpa Sherpa	Sindhupalchowk	Fulpingkatti	7	0			Bhotekoshi	4	32	532172				2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place		85.929153, 85.929275	27.890343, 27.890373	1911.0313, 1924.5647
599	249487	RV	Chhiring Norpu Sherpa	Chhiring Norpu Sherpa	Sindhupalchowk	Fulpingkatti	7	0			Bhotekoshi	4	37	532202				2	Grade 1, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place		85.929657, 85.929695	27.890902, 27.890934	1912.0309, 1916.5145
600	249515	RV	Som Buti Sherpa	Sombutti Sherpa, Sona Sherpa	Sindhupalchowk	Fulpingkatti	7	0			Bhotekoshi	4	42	532209				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9616424292	85.929245	27.891191	1910.6565
601	249516	RV	Sona Sherpa	Sombutti Sherpa, Sona Sherpa	Sindhupalchowk	Fulpingkatti	7	0			Bhotekoshi	4	42	532208				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9616424292	85.929245	27.891191	1910.6565
602	249491	RV	Sange Sherpa	Mingmar Sherpini	Sindhupalchowk	Fulpingkatti	7	0			Bhotekoshi	4	46	532214				2	Grade 1, Grade 5	Not Required, Reconstruct	Grade 1, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	9616650589	85.929024, 85.929123	27.888737, 27.888985	1910.057, 1917.0665
603	249506	RV	Tasi Sherpa	Tasi Sherpa	Sindhupalchowk	Fulpingkatti	7	0			Bhotekoshi	4	49	532217		Kathmandu,Gokarneswor-15	No Damage	2	Grade 4, Grade 4	Reconstruct, Reconstruct	Grade 3, Grade 2	Grade 3, Grade 3	Grade 3, Grade 3	Major Repair, Major Repair	Habitable House in Other Place	9741116286	85.928101, 85.928108	27.890244, 27.890331	1912.5056, 1917.6467
604	249528	RV	Chhyoki Sherpini	Chayoki Sherpini	Sindhupalchowk	Fulpingkatti	8	0			Bhotekoshi	4	6	532357		Bara,Nijagadh-9	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9614485136	85.910912	27.883202	1146.6636
605	249530	RV	Dal Bahadur Shrestha	Dal Bahadur Shrestha, Rana Bahdur Karki	Sindhupalchowk	Fulpingkatti	8	0			Bhotekoshi	4	18	532371		Sindhupalchowk,Fulpingkatti-9	Complete Damage	1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9611104027	85.911819	27.883226	1176.6609
606	249424	RV	Sarkini Tamang	Sarkini Tamang	Sindhupalchowk	Fulpingkatti	8	0			Bhotekoshi	4	28	532331				1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818300341	85.911819	27.883495	1167.6437
607	249420	RV	Sangmu Tamang	Sangmu Tamang	Sindhupalchowk	Fulpingkatti	8	0			Bhotekoshi	4	29	532332				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9621159933	85.912987	27.883541	1160.4495
608	249426	RV	Gyalmi Tamang	Gyalgi Tamang	Sindhupalchowk	Fulpingkatti	8	0			Bhotekoshi	4	32	532334				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9611105407	85.911835	27.88348	1171.6528
609	249425	RV	Wangmu Sherpa	Bhaktuk Tamang	Sindhupalchowk	Fulpingkatti	8	0			Bhotekoshi	4	34	532336				1	Grade 1	Major Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9611105406	85.911804	27.883505	1167.2813
610	249423	RV	Chhoten Tamang	Chhoten Tamang	Sindhupalchowk	Fulpingkatti	8	0			Bhotekoshi	4	35	532337				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9808486682	85.912003	27.883478	1159.8645
611	249435	RV	Pasang Lamu Tamang	Pasang Lamu Sherpa	Sindhupalchowk	Fulpingkatti	8	0			Bhotekoshi	4	37	532339		23-19-8-0-29		1	Grade 4	Reconstruct	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9810149735	85.913574	27.883694	1160.7568
612	249422	RV	Nijok Tamang	Sangwo Lama	Sindhupalchowk	Fulpingkatti	8	0			Bhotekoshi	4	38	532340				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9611103326	85.911797	27.883562	1175.7324
613	249421	RV	Muna Raut	Muna Raut	Sindhupalchowk	Fulpingkatti	8	0			Bhotekoshi	4	49	532102				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9621178164	85.913094	27.883751	1161.1206
614	249537	RV	Chhyamjon Tamang	Chhyamjot Tamang	Sindhupalchowk	Fulpingkatti	8	0																					

616	249529	RV	Narmaya Shrestha	Nar Maya Shrestha	Sindhupalchowk	Fulpingkatti	8	0		Bhotekoshi	4	70	432401		Bhaktapur,Katunge-17	No Damage	1	Grade 3	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	16614804	85.913422	27.883631	1182.0868
617	249427	RV	Kisha Tamangni	Keepa Tamangni	Sindhupalchowk	Fulpingkatti	8	0		Bhotekoshi	4	77	532408				1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9614890222	85.913277	27.88378	1166.2205
618	249536	RV	Krishna Khadka	Krishna Khadka	Sindhupalchowk	Fulpingkatti	8	0		Bhotekoshi	4	170	532134				1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9614765492	85.92704	27.886997	1853.3
619	256153	RV	Khom Bdr Thapa	Khom Bhaadur Thapa	Sindhupalchowk	Fulpingkot	1	0		Bhalephi	2	18	401319		Sindhupalchowk,Ja labire-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741087822	85.768036	27.803616	833.2735
620	256922	RV	Saktiram Thapa	Shakti Ram Thapa	Sindhupalchowk	Fulpingkot	1	0		Bhalephi	2	114	842735				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741184099	85.768456	27.808189	787.71277
621	256902	RV	Santa Bdr Shrestha	Santa Bahadur Shrestha	Sindhupalchowk	Fulpingkot	2	0		Bhalephi	2	25	842785				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9843139572	85.764572, 85.764587	27.794508, 27.79459	768.40607, 775.92969
622	256903	RV	Bishnu Maya Shrestha	Bishnu Maya Shrestha	Sindhupalchowk	Fulpingkot	2	0		Bhalephi	2	31	842791				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9741102798	85.764519, 85.764648	27.795284, 27.795359	762.5177, 768.85638
623	250740	RV	Surja Maya Shrestha	Surja Maya Shrestha	Sindhupalchowk	Fulpingkot	2	0		Bhalephi	2	35	842794				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9861155126	85.764618	27.794622	743.96381
624	256901	RV	Bishnu Prasad Koirala	Bishnu Prasad Koirala	Sindhupalchowk	Fulpingkot	2	0		Bhalephi	2	57	842765				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Major Repair	Habitable House in Usual Place	9741027564	85.765938, 85.767876	27.800783, 27.802254	761.28369, 829.50946
625	256908	RV	Muna Nepal	Muna Nepal	Sindhupalchowk	Fulpingkot	4	0		Bhalephi	2	103	1175101		Kathmandu,Kathmandu-11	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843340314	85.765312	27.77923	736.86163
626	256154	RV	Dal Bdr Thapa	Dala Bahadur Thapa	Sindhupalchowk	Fulpingkot	5	0		Bhalephi	3	16	401281		Sindhupalchowk,Ja labire-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741185831	85.784775	27.805361	1075.481
627	256155	RV	Maite Tamang	Maite Tamang	Sindhupalchowk	Fulpingkot	6	0		Bhalephi	3	154	1068261				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9808691624	85.793648, 85.793785	27.791224, 27.791351	1649.4132, 1652.0238
628	257026	RV	Sunmai Tamang	Dorje Tamang, Sun mai Tamangni	Sindhupalchowk	Fulpingkot	6	0		Bhalephi	3	166	1068274	23-20-6-0-165			2	Grade 5, Grade 5	Reconstruct, Reconstruct	Unrecognized, Unrecognized	Unrecognized, Unrecognized	Unrecognized, Unrecognized	Unrecognized, Unrecognized	Matrix & Photo not cleared or mismatch	9810234029	85.795204	27.791142	1706.2057
629	256140	RV	Sanukanchhi Tamang	Saanu kaanxi Tamang	Sindhupalchowk	Fulpingkot	7	0		Bhalephi	3	19	513789				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9860892769	85.792366	27.797253	1435.6527
630	256911	RV	Jagalal Tamang	Jag lai Tamang, Som lai Tamang	Sindhupalchowk	Fulpingkot	7	0		Bhalephi	3	26	513797		Kathmandu,Shankarapura-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841498587	85.791779	27.796612	1449.517
631	256152	RV	Somial Tamang	Jag lai Tamang, Som lai Tamang	Sindhupalchowk	Fulpingkot	7	0		Bhalephi	3	26	513798		Kathmandu,Shankarapura-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841498587	85.791779	27.796612	1449.517
632	256914	RV	Phulmai Tamang	Saang Bahadur Tamang	Sindhupalchowk	Fulpingkot	7	0		Bhalephi	3	94	513865				1	Grade 1	Not Required	Grade 2	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9808319010	85.79361	27.795883	1476.5125
633	256915	RV	Hiraman Tamang	Hira man Tamang	Sindhupalchowk	Fulpingkot	7	0		Bhalephi	3	95	513866				1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9818560189	85.793488	27.795853	1489.4827
634	250633	RV	Nara Bdr Gurung	Ambar Bahadur Gurung, Min Bahadur Gurung, Nar Bahadur Gurung	Sindhupalchowk	Fulpingkot	9	0		Bhalephi	3	52	513611		Kavrepalanchowk, Panchkhal-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849765278			
635	253546	RV	Shital Tamang	Lai Bahadur Tamang, Phul Bahadur Tamang, Sital Tamang	Sindhupalchowk	Gati	1	0		Barhabise Municipality	5	28	329569	23-21-1-0-28			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9813511837	85.901711	27.809963	1228.8202
636	254678	RV	Nakul Basnet	Chukul Bahadur Basnet, Nakul Basnet	Sindhupalchowk	Gati	1	0		Barhabise Municipality	5	49	329592	23-21-1-0-49			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9860038824	85.8974	27.807381	1126.9869
637	255075	RV	Shankar Basnet	Sankar Basnet	Sindhupalchowk	Gati	1	0		Barhabise Municipality	5	68	329612				1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803887369	85.897202	27.807131	1116.2395
638	254787	RV	Ratna Bahadur Shrestha	Ratna Bahadur Shrestha	Sindhupalchowk	Gati	1	0		Barhabise Municipality	5	110	329687				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 3, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9614894750	85.893417, 85.893532	27.802279, 27.80238	847.17944, 865.92395
639	250737	RV	Goma Guwaz	Ganga Bahadur Shrestha, Goma Guwaju	Sindhupalchowk	Gati	1	0		Barhabise Municipality	5	112	329689	23-21-1-0-110			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9818134313	85.893349	27.802397	848.4165
640	254744	RV	Lila Bahadur Thing	Lila Bahadur Thing	Sindhupalchowk	Gati	2	0		Barhabise Municipality	5	9	329723				1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9808012464	85.886635	27.811533	907.06635
641	254743	RV	Chini Maya Tamang	Chinimaya Tamang	Sindhupalchowk	Gati	2	0		Barhabise Municipality	5	20	329734				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	85.882393	27.815727	867.21008	
642	254780	RV	Tok Bahadur Tamang	Toka Bahadur Tamang	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	1	329735				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9621170825	85.882118	27.816231	886.89893
643	250735	RV	Dal Bahadur Adhikari	Dal Bahadur Adhikari	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	3	329737				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9621175695	85.882187	27.816322	900.79572
644	254993	RV	Bel Bahadur Rokka	Bel Bahadur Rokka	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	4	329738				2	Grade 1, Grade 5	Minor Repair, Reconstruct	Grade 3, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9803850971	85.882011, 85.883591	27.816299, 27.820349	1105.5302, 915.4881
645	254693	RV	Surya Bahadur Rokka	Surya Bahadur Rokka	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	5	329739				1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9616829884	85.882301	27.816261	870.42792
646	251429	RV	Gopal Basnet	Gopal Basnet	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	7	329741				1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9808154107	85.882042	27.816591	874.95972
647	255063	RV	Tilak Bahadur Gurung	Roshan Tamang, Tilak Bahadur Gurung	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	11	329746	23-21-3-0-5			1	Grade 3	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9611169801	85.88205	27.816774	884.33832
648	254716	RV	Narayan Bahadur Rokka	Narayan Bahadur Rokka	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	14	329750				2	Grade 1, Grade 4	Not Required, Major Repair	Grade 1, Grade 4	Grade 1, Grade 4	Grade 1, Grade 4	Not Required, Major Repair	Habitable House in Usual Place	9741240135	85.881897, 85.884048	27.817085, 27.820601	1122.8116, 882.42499
649	254983	RV	Kam Lama	Karma Lama	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	21	329759				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9611096696	85.88208	27.816601	878.47583
650	254685	RV	Ram Maya Rokka	Ram Maya Rokka, Ram Sharan Rokka	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	34	329772				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9611097373	85.88147	27.817389	929.02112
651	254691	RV	Ram Sahran Rokka	Ram Maya Rokka, Ram Sharan Rokka	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	34	329773				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9611097373	85.88147	27.817389	929.02112
652	255070	RV	Bhakta Bahadur Rokka	Bhakta Bahadur Rokka	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	71	1174766				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	85.883347	27.820589	1098.2346	
653	255068	RV	Bishnu Bahadur Rokka	Bishnu Bahadur Rokka	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	72	1174767				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9803850971	85.883469	27.820415	1106.4266
654	254677	RV	Anjana Magar	Anjana Magar, Padam Bahadur Tamang	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	84	1174781				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9621107439	85.881447	27.822458	1063.3778
655	254676	RV	Padam Bahadur Tamang	Anjana Magar, Padam Bahadur Tamang	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	84	1174780				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9621107439	85.881447	27.822458	1063.3778
656	255002	RV	Kul Bahadur Karki	Kul Bahadur Karki	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	88	1174785				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9621162855	85.878319	27.823153	953.75275
657	255009	RV	Buwalbahadur Karki	Bhuwal Bahadur Karki	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	89	1174786				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9818665082	85.878502	27.822643	1007.955
658	254671	RV	Bal Ram Basnet	Bal Ram Basnet	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	98	1174796				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9813233730	85.87841	27.820896	915.40112
659	254990	RV	Khadka Bahadur Pradhan	Khadka Bahadur Pradhan	Sindhupalchowk	Gati	3	0		Barhabise Municipality	5	106	1174804				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place		85.878151	27.821156	893.75891
660	254700	RV	Bahadur Ghal	Bahadur Ghale	Sindhupalchowk	Gati	5	0		Barhabise Municipality	5	8	1174634				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741113135	85.909691	27.818521	1946.1929
661	254760	RV	Sukra Bahadur Tamang	Som Maya Tamangni, Sukra Bahadur Tamang	Sindhupalchowk	Gati	5	0		Barhabise Municipality	5	21	1174648	23-21-5-0-20			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9621174568	85.908562	27.820204	2043.9016
662	254772	RV	Tika Bahadur Tamang	Tika Bahadur Tamang	Sindhupalchowk	Gati	5	0		Barhabise Municipality	5	23	1174650				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9810149703	85.908882	27.820374	2026.8895
663	255073</																											

664	255780	RV	Chandra Bahadur Tamang	Jeet Bahadur Tamang	Sindhupalchowk	Gati	6	0		Barhabise Municipality	6	4	548839	23-21-6-0-4			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.891541	27.830278	1977.2592
665	254992	RV	Lok Bahadur Tamang	Lok Bahadur Tamang, Santa Bahadur Tamang	Sindhupalchowk	Gati	6	0		Barhabise Municipality	6	12	548848	23-21-6-0-12			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9741504888	85.89164	27.830139	1979.7893
666	255091	RV	Lali Tamang	Man Bahadur Tamang	Sindhupalchowk	Gati	6	0		Barhabise Municipality	6	21	548936	23-21-6-0-21			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849164253	85.892502	27.829758	1976.7222
667	255104	RV	Ayiti Maya Tamang	Aaiti Tamang, Purna Bahadur Tamang	Sindhupalchowk	Gati	6	0		Barhabise Municipality	6	30	548947	23-21-6-0-30			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9860525208	85.89946	27.825031	1855.752
668	255076	RV	Hira Maya Tamang	Dil Bahadur Tamang	Sindhupalchowk	Gati	6	0		Barhabise Municipality	6	35	548703		Sindhupalchowk,R amche-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9841937322	85.894905	27.828083	1909.4695
669	255000	RV	Uttar Dhway Tamang	Ref Bahadur Tamang, Uttar dhway Tamang	Sindhupalchowk	Gati	6	0		Barhabise Municipality	6	37	548705	23-21-6-0-36			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9860658270	85.891617	27.829927	1977.5072
670	255005	RV	Govinda Tamang	Govinda Tamang, Jukta ram Tamang	Sindhupalchowk	Gati	6	0		Barhabise Municipality	6	40	548710	23-21-6-0-39			1	Grade 5	Reconstruct	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9843249476	85.89212	27.82976	1981.9413
671	255107	RV	Karna Bahadur Tamang	Chyanga Tamangni	Sindhupalchowk	Gati	6	0		Barhabise Municipality	6	42	548715	23-21-6-0-41			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.891441	27.830288	1975.876
672	255008	RV	Kanchi Kamini	Kanchhi Kamini, Kanchhi maya Kami	Sindhupalchowk	Gati	6	0		Barhabise Municipality	6	46	548720	23-21-6-0-45			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9614899304	85.891357	27.829454	1943.2672
673	255080	RV	Kami Tamang	Kami Tamang, Lal Bahadur Tamang, Pimba lal Tamang	Sindhupalchowk	Gati	6	0		Barhabise Municipality	6	55	548756	23-21-6-0-54			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849121856	85.891823	27.830151	1982.7616
674	255078	RV	Pimbalal Tamang	Kami Tamang, Lal Bahadur Tamang, Pimba lal Tamang	Sindhupalchowk	Gati	6	0		Barhabise Municipality	6	55	548755	23-21-6-0-54			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849121856	85.891823	27.830151	1982.7616
675	255086	RV	Makar Dhway Tamang	Buti Tamang, Makar dhwoj Tamang	Sindhupalchowk	Gati	6	0		Barhabise Municipality	6	56	548758	23-21-6-0-55			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9803699658	85.891838	27.829908	1984.5046
676	255079	RV	Subba Kami	Hake Kami, Subba Kami	Sindhupalchowk	Gati	6	0		Barhabise Municipality	6	76	548454	23-21-6-0-75			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.882217	27.830885	1654.806
677	254774	RV	Shankha Lal Tamang	Sankha lal Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	1	840989				1	Grade 1	Minor Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9621153540	85.892815	27.851349	1879.5352
678	254661	RV	Chatur Sherpa	Chatur Sherpa	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	5	840995				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9621104548	85.893143	27.850214	1901.1783
679	254663	RV	Bhim Bahadur Tamang	Bhim Bahadur Tamang, Chandraman Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	6	840996				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9808919570	85.892494	27.847698	1908.9988
680	254704	RV	Pasang Tamang	Pasang Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	25	840770		Sindhupalchowk,G ati-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9808706343	85.894531	27.847597	1996.2815
681	255092	RV	Anu Thapa Tamang]	Lachhiri Tamang, Uttam lal Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	26	840772	23-21-7-0-15			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9803310535	85.894829	27.847569	2002.8207
682	254708	RV	Lal Bahadur Tamang	Laibahadur Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	27	840773		Sindhupalchowk,R amche-7	Partial Damage	1	Grade 4	Reconstruct	Grade 3	Grade 3	Grade 3	Major Repair	Habitable House in Other Place	9841672971	85.895538	27.844746	1978.8828
683	255072	RV	Bhim Lal Tamang	Bhimlal Tamang, Ram kaji Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	29	548951	23-21-7-0-17			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849695384	85.895531	27.8449	1984.5717
684	254674	RV	Baj Bahadur Tamang	Kumari Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	32	548954	23-21-7-0-20			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.894623	27.843945	1913.274
685	254673	RV	Som Bahadur Tamang	Kumari Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	32	548955	23-21-7-0-20			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.894623	27.843945	1913.274
686	255001	RV	Priti Maya Tamang	Lakpa chhiri Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	34	548957				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9614937783	85.895218	27.844294	1942.9305
687	254765	RV	Bipilal Tamang	Bibilal Tamang, Dawa funjo Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	36	548960	23-21-7-0-23			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.893944	27.84605	2000.6863
688	254751	RV	Pema Sherpa	Pema Sherpa, Sanu gyami Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	42	548967	23-21-7-0-29			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.894478	27.848047	2002.7872
689	251404	RV	Dhan Kumar Lama	Jaya Lama	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	43	548969	23-21-7-0-30			2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Unrecognized, Grade 5	Unrecognized, Grade 5	Unrecognized, Reconstruct	Matrix & Photo not cleared or mismatch	9741172178	85.894737, 85.894745	27.847557, 27.847658	2001.6501, 2002.809
690	255085	RV	Puni Lama	Jaya Lama	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	43	548970	23-21-7-0-30			2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Unrecognized, Grade 5	Unrecognized, Grade 5	Unrecognized, Reconstruct	Matrix & Photo not cleared or mismatch	9741172178	85.894737, 85.894745	27.847557, 27.847658	2001.6501, 2002.809
691	255065	RV	Dawa Chiring Sherpa	Dawa chiring Sherpa, Kailo Sherpa	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	51	548730	23-21-7-0-36			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849474675	85.895027	27.848274	2005.4598
692	254991	RV	Singh Bahadur Sherpa	Bhimlal Tamang, Bir Bahadur Sherpa, Hongre Tamang, Singh Bahadur Sherpa	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	52	548732	23-21-7-0-37			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9814476879	85.895401	27.847115	2026.7151
693	254684	RV	Dim Doj Tamang	Buddhi Bahadur Tamang, Ngim dorje Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	61	548742		Sindhupalchowk,R amche-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860336716	85.895218	27.845591	2010.6709
694	254755	RV	Ram Bahadur Tamang	Larkel Sherpa, Ram Bahadur Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	62	548744	23-21-7-0-45			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9741230421	85.895485	27.846197	2030.4944
695	254763	RV	Kaji Sherpa	Kaji Sherpa	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	65	548747		Sindhupalchowk,Barhabise-8	Partial Damage	1	Grade 3	Major Repair	Grade 4	Grade 3	Grade 3	Major Repair	Habitable House in Other Place	9808206905	85.895172	27.846863	2022.0138
696	254770	RV	Lal Bahadur Lama	Laibahadur Lama	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	66	548748				1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9860907122	85.895912	27.847792	2034.3986
697	254750	RV	Chatur Bahadur Sherpa	Chatur Bahadur Sherpa	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	69	840777		Sindhupalchowk,R amche-7	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 3	Grade 4	Reconstruct	Habitable House in Other Place	9843001256	85.895782	27.847507	2038.8888
698	254720	RV	Ram Bahadur Tamang	Ram Bahadur Tamang, Tekashi Tamangni	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	70	840778	23-21-7-0-49			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9803112896	85.895523	27.847395	2029.4143
699	254761	RV	Chittar Lama	Chittar Lama	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	71	840780				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9611179478	85.895958	27.847477	2035.2606
700	254769	RV	Bir Bahadur Lama	Bir Bahadur Lama	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	72	840781				1	Grade 2	Reconstruct	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9621191895	85.89595	27.847351	2046.5732
701	254777	RV	Cherup Tamang	Chheyarup Tamang, Karma Tamang, Namkang Sherpa	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	76	840787		Kathmandu,Shank arapura-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9808700122	85.895683	27.847347	2042.1541

702	254767	RV	Kama Tamang	Chheyarup Tamang, Karma Tamang, Namkang Sherpa	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	76	840785		Kathmandu,Shank arapura-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9808700122	85.895683	27.847347	2042.1541
703	254784	RV	Namkang Sherpa	Chheyarup Tamang, Karma Tamang, Namkang Sherpa	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	76	840786		Kathmandu,Shank arapura-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9808700122	85.895683	27.847347	2042.1541
704	254754	RV	Bhime Sherpa	Bhime Sherpa, Kaji maan Lama	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	80	840792		Kathmandu,Kathm andu-16	No Damage	1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9812751659	85.895264	27.845613	2023.5226
705	255067	RV	Kajiman Lama	Bhime Sherpa, Kaji maan Lama	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	80	840791		Kathmandu,Kathm andu-16	No Damage	1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9812751659	85.895264	27.845613	2023.5226
706	254710	RV	Gyani Maya Tamang	Gyanimaya Tamang, Min Bahadur Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	86	840800	23-21-7-0-59			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9813663082	85.895645	27.846319	2051.4661
707	253548	RV	Harka Maya Raitamang	Ram Bahadur Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	87	548626				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9804959965	85.894989	27.85054	1997.3254
708	254699	RV	Kami Tamang	Kami Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	88	548627				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9621153540	85.895976	27.847418	2029.714
709	255778	RV	Dawa Gyalpa Sherpa	Dawa dorje Sherpa, Dawa gyalwo Sherpa	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	94	548636	23-21-7-0-65			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9614938264	85.895416	27.846359	2034.9075
710	254776	RV	Jiwan Tamang	Makare Tamang, Sommaya Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	105	548649	23-21-7-0-76			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9741188698	85.899529	27.843941	2066.0176
711	254669	RV	Bhim Lal Tamang	Bhim lal Tamang, Ngima Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	106	842951	23-21-7-0-77			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.899445	27.844328	2076.8308
712	254764	RV	Chavi Tamang Lama	Chhebi Tamang Lama, Nima dundup Lama	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	107	842953	23-21-7-0-78			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9621171254	85.899529	27.844137	2059.4163
713	253535	RV	Karsang Buddha Tamang	Karsang butti Tamang, Norsang Tamang	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	110	842959	23-21-7-0-81			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9823143282	85.895934	27.84609	2022.2631
714	254668	RV	Temba Tamang	Kanchhi Sherpa	Sindhupalchowk	Gati	7	0		Barhabise Municipality	6	148	549922	23-21-7-0-116			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.90313	27.835938	2126.2981
715	254994	RV	Kul Bahadur Tamang	Japhare Tamang, Kul Bahadur Tamang	Sindhupalchowk	Gati	8	0		Barhabise Municipality	6	11	548471	23-21-8-0-11			1	Grade 4	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9860626916	85.878342	27.832138	1436.9951
716	255094	RV	Jagat Bahadur Tamang	Jagat Bahadur Tamang, Ngim pasang Tamang	Sindhupalchowk	Gati	8	0		Barhabise Municipality	6	12	548473	23-21-8-0-12			1	Grade 4	Reconstruct	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9810104387	85.878212	27.83217	1431.3124
717	254702	RV	Dhan Maya Tamang	Dhan maya Tamangni	Sindhupalchowk	Gati	8	0		Barhabise Municipality	6	17	548803				3	Grade 5, Grade 1, Grade 5	Reconstruct, Not Required, Reconstruct	Grade 5, Grade 1, Grade 5	Unrecognized, Grade 1, Unrecognized	Unrecognized, Grade 1, Unrecognized	Unrecognized, Not Unrecognized	Habitable House in Usual Place	9818915932	85.871849, 85.878281, 85.878357	27.830315, 27.832378, 27.832462	1127.3669, 1435.4628, 1440.4714
718	254695	RV	Ram Bahadur Tamang	Ram Bahadur Tamang	Sindhupalchowk	Gati	8	0		Barhabise Municipality	6	21	548807				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9841181557	85.879791	27.834505	1363.2687
719	253547	RV	Gyan Bahadur Shrestha	Ganesh Bahadur Shrestha, Gyan Bahadur Shrestha	Sindhupalchowk	Gati	8	0		Barhabise Municipality	6	26	548813	23-21-8-0-24			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9813849057	85.879257	27.834539	1372.2112
720	255074	RV	Sita Tamang	Dipak Tamang, Sita Tamang	Sindhupalchowk	Gati	8	0		Barhabise Municipality	6	31	548819	23-21-8-0-29			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9813884723	85.879135	27.833582	1395.8246
721	254742	RV	Sabita Tamang	Yubaraj Tamang	Sindhupalchowk	Gati	8	0		Barhabise Municipality	6	33	548821				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9818919544	85.878876	27.833385	1390.9875
722	254714	RV	Bel Bahadur Tamang	Bel Kumar Tamang	Sindhupalchowk	Gati	8	0		Barhabise Municipality	6	35	548823				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9621170431	85.878677	27.833096	1405.7211
723	254740	RV	Som Bahadur Tamang	Som Bahadur Tamang	Sindhupalchowk	Gati	8	0		Barhabise Municipality	6	38	548776				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9803407715	85.87738	27.832401	1400.901
724	254748	RV	Sanu Maya Tamang	Krishna Bahadur Tamang	Sindhupalchowk	Gati	8	0		Barhabise Municipality	6	48	548787				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9803592049	85.878311	27.833044	1401.9138
725	254995	RV	Ful Bahadur Tamang	Phu Bahadur Tamang	Sindhupalchowk	Gati	8	0		Barhabise Municipality	6	52	548791				1	Grade 2	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9621174524	85.878189	27.833168	1410.0992
726	255781	RV	Suku Maya Tamang	Chaur Tamang, Sukumaya Tamang	Sindhupalchowk	Gati	8	0		Barhabise Municipality	6	57	548797	23-21-8-0-50			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9803371085	85.877899	27.832092	1431.8534
727	254697	RV	Jiwan Tamang	Jiban Tamang, Kamal Tamang	Sindhupalchowk	Gati	8	0		Barhabise Municipality	6	63	548480	23-21-8-0-56			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9818144515	85.871803	27.831232	1140.7251
728	254662	RV	Jit Bahadur Shrestha	Jit Bahadur Shrestha	Sindhupalchowk	Gati	8	0		Barhabise Municipality	6	98	325440				1	Grade 2	Minor Repair	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9611176039	85.869247	27.829929	956.0804
729	255006	RV	Sonam Sherpa	Chitra bahadur Tamang	Sindhupalchowk	Gati	8	0		Barhabise Municipality	6	106	325448		Kathmandu,Kathm andu-10	No Damage	1	Grade 2	Minor Repair	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Other Place	9803654234	85.870781	27.832945	1015.1261
730	254665	RV	Tara Shrestha	Tara Shrestha	Sindhupalchowk	Gati	8	0		Barhabise Municipality	6	107	325449				1	Grade 1	Minor Repair	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9813747573	85.86927	27.829926	956.14703
731	254981	RV	Fuwa Tamang	Furba Tamang	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	1	548901				1	Grade 2	Minor Repair	Grade 4	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818688842	85.88546	27.849339	1409.0991
732	254723	RV	Bel Bahadur Shrestha	Amar Bahadur Shrestha, Bed Bahadur Shrestha	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	24	549930	23-21-9-0-23			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9614714233	85.885941	27.853554	1414.116
733	254690	RV	Manmaji Shrestha	Bekhlal Shrestha, Maankaji Shrestha, Mohan Prasad Shrestha	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	32	549940	23-21-9-0-29			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9800818589	85.886307	27.853941	1421.4365
734	254782	RV	Mohan Pai. Shrestha	Bekhlal Shrestha, Maankaji Shrestha, Mohan Prasad Shrestha	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	32	549939	23-21-9-0-29			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9800818589	85.886307	27.853941	1421.4365
735	255099	RV	Shangwa Tamang	Lalman Tamang, Sangwo Tamang	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	48	549958	23-21-9-0-43			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9616649428	85.884979	27.854813	1404.9954
736	254686	RV	Bishnu Lal Shrestha	Bishnu lal Shrestha	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	52	549962				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9810188814	85.885223	27.853558	1404.8167
737	254783	RV	Nar Bahadur Gubhaj	Nar Bahadur Gubhaju	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	57	549968				1	Grade 1	Not Required	Unrecognized	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9614938434	85.885506	27.852629	1405.6934
738	254998	RV	Manish Shrestha	Khadga Bahadur Shrestha	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	85	548997	23-21-9-0-78			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9621192152	85.885674	27.855057	1407.2838

739	255776	RV	Suppa Shrestha	Khadga Bahadur Shrestha	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	85	548998	23-21-9-0-78			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9621192152	85.885674	27.855057	1407.2838
740	255100	RV	Kul Bahadur Shrestha	Padam Bahadur Shrestha	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	87	548651	23-21-9-0-80			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9851041523	85.87896	27.864449	1084.934
741	254771	RV	Tirtha Kumari Gubhaju	Tirtha Kumari Gubhaju	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	118	548684				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9843040330	85.878624, 85.878807	27.858753, 27.860306	1040.0939, 1046.9258
742	255101	RV	Nimba Doj Tamang	Mikmar Tamang, Nima Dorje Tamang	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	120	548687	23-21-9-0-112			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9808107296	85.878128	27.856611	1039.0488
743	254985	RV	Ram Kumari Shrestha	Lalit Bahadur Pradhan	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	124	548693				1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9861196797	85.878853	27.86339	1061.0254
744	255090	RV	Sita Maya Shrestha	Sita Maya Shrestha	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	128	548697	23-21-9-0-119			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9818759214	85.878181	27.859039	1027.0034
745	254984	RV	Purna Bahadur Shrestha	Purna Bahadur Shrestha	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	142	548861				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	85.87915	27.861433	1076.5261	
746	254987	RV	Bhakta Bahadur Newar	Bhakta Bahadur Newar	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	146	548865				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9803281646	85.87854	27.858418	1040.6907
747	255066	RV	Doj Tamang	Dorje Tamang, Rinjen Tamang	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	168	548888	23-21-9-0-153			1	Grade 5	Reconstruct	Unrecognized	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9803590706	85.885971	27.855461	1448.5961
748	254989	RV	Aakash Sherpa	Akash Sherpa, Dawa nurpu Tamang	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	183	840981	23-21-9-0-166			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9813083688	85.885658	27.85552	1439.4741
749	254759	RV	Surya Narayan Shrestha	Krishna Bahadur Shrestha, Surya Narayan Shrestha	Sindhupalchowk	Gati	9	0		Barhabise Municipality	6	186	840987	23-21-9-0-169			2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Unrecognized, Unrecognized	Unrecognized, Unrecognized	Unrecognized, Unrecognized	Matrix & Photo not cleared or mismatch	9818918259	85.885773, 85.885857	27.854935, 27.854952	1417.1766, 1427.4442
750	250948	RV	Sange Lama	Sange Lami	Sindhupalchowk	Ghorthali	1	0		Barhabise Municipality	1	12	367811		Sindhupalchowk,R amche-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9861018054	85.993553	27.814137	2540.27
751	250946	RV	Sange Sherpa	Sange Sherpa	Sindhupalchowk	Ghorthali	1	0		Barhabise Municipality	1	21	367825				1	Grade 2	Minor Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9818270713	85.99305	27.812368	2420.1504
752	250822	RV	Kolyang Sherpa	Kolchang Sherpa	Sindhupalchowk	Ghorthali	1	0		Barhabise Municipality	1	25	367554		Kathmandu,Kathm andu-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9810149095	85.994324	27.812378	2455.4175
753	250823	RV	Dawadoma Sherpa	Dawa Doma Sherpa	Sindhupalchowk	Ghorthali	1	0		Barhabise Municipality	1	38	367567		Kathmandu,Kathm andu-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	1476581	85.993568	27.810762	2354.1584
754	250821	RV	Sangtemba Sherpa	Sang Temba Sherpa	Sindhupalchowk	Ghorthali	1	0		Barhabise Municipality	1	42	367573				1	Grade 2	Minor Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9860146929	85.989708	27.817982	2595.3501
755	250843	RV	Nima Dorje Sherpa	Nima Dorje Sherpa	Sindhupalchowk	Ghorthali	3	0		Barhabise Municipality	1	12	367622				1	Grade 1	Not Required	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9843771479	85.995033	27.79822	2240.8052
756	251251	RV	Tasi Sherpa	Nima Dorje Sherpa	Sindhupalchowk	Ghorthali	3	0		Barhabise Municipality	1	12					1	Grade 1	Not Required	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9843771479	85.995033	27.79822	2240.8052
757	250845	RV	Dautemba Sherpa	Dautemba Sherpa	Sindhupalchowk	Ghorthali	3	0		Barhabise Municipality	1	38	367550				1	Grade 1	Not Required	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9741024463	85.992279	27.803282	2109.0396
758	250856	RV	Pema Sherpa	Pema Sherpa	Sindhupalchowk	Ghorthali	4	0		Barhabise Municipality	1	24	367780		Kathmandu,Shank arapura-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9861157839	85.986595	27.796024	1835.8976
759	250858	RV	Chandra Kumari Magar	Chandra Kumari Magar	Sindhupalchowk	Ghorthali	4	0		Barhabise Municipality	1	78	367159				1	Grade 1	Not Required	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	9843574891	85.98774	27.79204	1800.5277
760	250854	RV	Pasang Sherpa	Pasang Sherpa	Sindhupalchowk	Ghorthali	4	0		Barhabise Municipality	1	84	367166		Sindhupalchowk,K arthali-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843568574	85.986389	27.79183	1737.6224
761	250864	RV	Surya Bahadur Jirel	Surya Bahadur Jirel	Sindhupalchowk	Ghorthali	5	0		Tripurasundari	1	15	367884		Sindhupalchowk,R amche-7	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9849244074	85.975609, 85.976936	27.783857, 27.784325	1642.037, 1651.5284
762	250868	RV	Kul Bahadur Jirel	Kul Bahadur Jirel	Sindhupalchowk	Ghorthali	5	0		Tripurasundari	1	36	367105				1	Grade 2	Minor Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849860895	85.977516	27.784624	1665.0251
763	250873	RV	Junadevi Bhandari	Junadevi Bhandari khatri	Sindhupalchowk	Ghorthali	6	0		Tripurasundari	1	30	367066		Kathmandu,Mulpa ni-5	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	85.978073	27.774115	1635.0314	
764	250871	RV	Basanta Kumar Thami	Basanta Kumar Thami	Sindhupalchowk	Ghorthali	6	0		Tripurasundari	1	47	367134		Sindhupalchowk,K arthali-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843429761	85.979874	27.774885	1672.2111
765	250880	RV	Khadananda Timalisina	Sadananda Timalisina	Sindhupalchowk	Ghorthali	7	0		Tripurasundari	1	53	405712		Kathmandu,Mulpa ni-5	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841522031	85.984695	27.772181	1836.2134
766	250759	RV	Ngawa Sherpa	Ngawa Chhiti Sherpa	Sindhupalchowk	Ghorthali	8	0		Tripurasundari	1	42			Kathmandu,Kathm andu-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849550661	85.984581	27.782328	2038.3511
767	251318	RV	Nanda Lal Timalisina	Dharma Dhoj Khadka	Sindhupalchowk	Ghorthali	9	0		Tripurasundari	1	17	405638		Kathmandu,Kathm andu-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	14429843	85.981461	27.770384	1666.3591
768	250762	RV	Rabindra Khadka	Dharma Dhoj Khadka	Sindhupalchowk	Ghorthali	9	0		Tripurasundari	1	17	405637		Kathmandu,Kathm andu-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	14429843	85.981461	27.770384	1666.3591
769	250763	RV	Prem Bahadur Gurung	Prem Bahadur Gurung	Sindhupalchowk	Ghorthali	9	0		Tripurasundari	1	61	405681		Kathmandu,Kathm andu-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841060434	85.98243	27.768728	1689.9009
770	250761	RV	Man Bahadur Gurung	Man Bahadur Gurung	Sindhupalchowk	Ghorthali	9	0		Tripurasundari	1	73	405694		Kathmandu,Kathm andu-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843568520	85.981369	27.767807	1640.7323
771	255815	RV	Samyu Sherpa	Sangbu Sherpa	Sindhupalchowk	Golche	3	0		Jugal	2	37	328066		Kathmandu,Gokar neswor-1	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841142423	85.773849	28.040949	2179.8206
772	255836	RV	Bhayo Gole	Bhayo Gole	Sindhupalchowk	Golche	3	0		Jugal	2	84	329986		Sindhupalchowk,C haulara-4	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	85.756996	27.91757	1968.6826	
773	255773	RV	Hipsingh Lama	Hip Singh Lama	Sindhupalchowk	Golche	5	0		Jugal	2	21	547835		Sindhupalchowk,G olche-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	85.743874	27.898088	1721.6136	
774	255758	RV	Sitaram Syangwo	Sitaram Syangbo	Sindhupalchowk	Golche	6	0		Jugal	2	63	1177103				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9741412108	85.744255	27.884565	1550.5432
775	256412	RV	Malia Tamang	Malia Tamang	Sindhupalchowk	Gunsakot	2	0		Pachpokhari Thangpal	5	16	364362				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Minor Repair	Habitable House in Usual Place	85.67086, 85.671272	27.921703, 27.921883	1703.1296, 1714.2668	
776	253266	RV	Lal Bahadur Tamang	Lal Bahadur Tamang, Nakale Lama	Sindhupalchowk	Gunsakot	4	0		Pachpokhari Thangpal	5	45	364391	23-26-4-0-43			1	Grade 3	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	85.668167	27.920773	1674.3999	
777	256414	RV	Syarpeni Tamang	Syarponi Tamang	Sindhupalchowk	Gunsakot	5	0		Pachpokhari Thangpal	5	28	364477				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Minor Repair	Habitable House in Usual Place	85.669075, 85.669182	27.923841, 27.924044	1664.3624, 1673.7285	
778	251446	RV	Dipak Tamang	Deepak Tamang	Sindhupalchowk	Gunsakot	6	0		Pachpokhari Thangpal	5	17	364551				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	85.666977	27.923279	1637.5132	
779	256409	RV	Tek Lama	Tek Gole	Sindhupalchowk	Gunsakot	7	0		Pachpokhari Thangpal	5	9	364575				1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	85.666649	27.921005	1639.9623	
780	256410	RV	Sarki Tamang	Bal Bahadur Tamang, Bir Bahadur Tamang, Pasang Tamang, Rabina Tamang, Sarki Tamang	Sindhupalchowk	Gunsakot	7	0		Pachpokhari Thangpal	5	26	405839		Sindhupalchowk,G unsakot-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	85.666718	27.920675	1657.473	
781	256451	RV	Fulman Gole	Ful Man Tamang, Sun Gole Tamang, Tar Lama	Sindhupalchowk	Gunsakot	9	0		Pachpokhari Thangpal	5	2	405988		Sindhupalchowk,G unsakot-9	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	85.668228	27.92198	1663.8114	
782	256448	RV	Kale Thing	Kale Thing	Sindhupalchowk	Gunsakot	9	0		Pachpokhari Thangpal	5	9	405951				1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	85.668419	27.921236	1663.7535	
783	255997	RV	Dhurva Gurung	Dhurba Bahadur Gurung	Sindhupalchowk	Haibung	2	0		Melamchi Municipality	3	20	535254				2	Grade 2, Grade 3	Minor Repair, Major Repair	Grade 2, Grade 3	Grade 2, Grade 3	Grade 2, Grade 3	Minor Repair, Major Repair	Habitable House in Usual Place	9803267817	85.47718, 85.477295	27.80743, 27.807529	1598.5044, 1609.9546
784	255998	RV	Man Bahadur Gurung	Man Bahadur Gurung	Sindhupalchowk	Haibung	2	0		Melamchi Municipality	3	24	535259				2	Grade 4, Grade 2	Reconstruct, Minor Repair	Grade 4, Grade 2	Grade 4, Grade 2	Grade 4, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9860721420	85.477066, 85.477104	27.807308, 27.807405	1599.7, 1621.5894

785	255990	RV	Sunkoshi Gurung	Sudham Raj Gurung, Sunkestari Gurung	Sindhupalchowk	Haibung	2	0		Melamchi Municipality	3	32	535268								2	Grade 4, Grade 2	Reconstruct, Minor Repair	Grade 4, Grade 2	Grade 4, Grade 2	Grade 4, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9813505149	85.478027, 85.478172	27.807330, 27.807533	1571.7648, 1580.0526
786	255989	RV	Rabindra Gurung	Prakash Gurung, Rabindra Gurung	Sindhupalchowk	Haibung	2	0		Melamchi Municipality	3	34	533270								2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9808887827	85.477707, 85.477806	27.807413, 27.807463	1574.6226, 1594.4619
787	255995	RV	Bibi Maya Tamang	Bibimaya Tamang	Sindhupalchowk	Haibung	3	0		Melamchi Municipality	3	67	535662								1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9813550731	85.483757, 85.487464	27.813173, 27.823557	1459.3584, 1193.6116, 1207.9332
788	255994	RV	Ram Hari Gurung	Ram Hari Gurung	Sindhupalchowk	Haibung	3	0		Melamchi Municipality	3	97	535291								2	Grade 4, Grade 1	Reconstruct, Not Required	Grade 4, Grade 1	Grade 4, Grade 1	Grade 4, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9860186212	85.487549, 85.48764	27.823406, 27.823557	1193.6116, 1207.9332
789	255993	RV	Damodar Jung Bista	Damodar Bista	Sindhupalchowk	Haibung	3	0		Melamchi Municipality	3	98	535292		Sindhupalchowk, Thakani-1	No Damage					1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9843446267	85.487923, 85.487923	27.823515, 27.823515	1187.9031
790	255916	RV	Bahwani Damai	Laxman Damai, Lekh Bahadur Damai, Machindra Damai, Ram Bahadur Damai, Ramil Damai, Syam Bahadur Damai	Sindhupalchowk	Haibung	4	0		Melamchi Municipality	3	41	535589								2	Grade 2, Grade 5	Minor Repair, Reconstruct	Unrecognized, Unrecognized	Unrecognized, Unrecognized	Unrecognized, Unrecognized	Unrecognized, Unrecognized	Matrix & Photo not cleared or mismatch	9818481518	85.471741, 85.47242	27.81249, 27.812811	1610.6384, 1620.0544
791	253232	RV	Jit Bahadur Tamang	Jit Bahadur Tamang	Sindhupalchowk	Haibung	6	0		Melamchi Municipality	3	1	549259		Kathmandu, Sitapali-16	Partial Damage					1	Grade 4	Reconstruct	Grade 4	Grade 3	Grade 4	Reconstruct	Habitable House in Other Place	9818032147	85.466957, 85.466957	27.824945, 27.824945	1626.8339
792	255881	RV	Ram Bahadur Lama	Ram Bahadur Lama	Sindhupalchowk	Haibung	6	0		Melamchi Municipality	3	24	5949134		Kathmandu, Gokar network-5	Partial Damage					2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9741082030	85.475349, 85.475372	27.822926, 27.822969	1549.5897, 1552.4987
793	253231	RV	Ramji Banjara	Ramji Banjara	Sindhupalchowk	Haibung	7	0		Melamchi Municipality	3	23	549368		Kathmandu, Shank arapura-6	Partial Damage					1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841427869	85.465279, 85.465279	27.822552, 27.822552	1768.1417
794	255892	RV	Jit Bahadur Tamang	Man Bahadur Tamang	Sindhupalchowk	Haibung	7	0		Melamchi Municipality	3	33	549328								2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9813360448	85.464699, 85.464897	27.824034, 27.824196	1705.924, 1709.2206
795	255893	RV	Jayman Tamang	Jay Maan Tamang	Sindhupalchowk	Haibung	8	0		Melamchi Municipality	3	50	535175								2	Grade 4, Grade 2	Reconstruct, Minor Repair	Grade 3, Grade 2	Grade 4, Grade 2	Grade 4, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9818208097	85.456383, 85.456535	27.832582, 27.832615	1836.9592, 1841.5292
796	255895	RV	Parbati Giri	Parbati Giri	Sindhupalchowk	Haibung	9	0		Melamchi Municipality	3	1	549376								1	Grade 2	Minor Repair	Grade 3	Grade 3	Grade 3	Minor Repair	Habitable House in Usual Place	9849298492	85.456261, 85.456261	27.843204, 27.843204	1709.994
797	255905	RV	Gyan Bahadur Tamang	gyan Bahadur Tamang	Sindhupalchowk	Haibung	9	0		Melamchi Municipality	3	54	549430								2	Grade 5, Grade 2	Minor Repair	Grade 5, Grade 3	Grade 5, Grade 2	Grade 5, Grade 2	Minor Repair	Habitable House in Usual Place	85.463562, 85.464142	27.832062, 27.832186	1724.2098, 1731.1493	
798	255894	RV	Ram Kumar Tamang	Ram Kumar Lama	Sindhupalchowk	Haibung	9	0		Melamchi Municipality	3	55	549431								2	Grade 3, Grade 2	Major Repair, Minor Repair	Grade 4, Grade 2	Grade 4, Grade 1	Grade 4, Grade 2	Major Repair, Minor Repair	Habitable House in Usual Place	9841969494	85.463966, 85.464226	27.831768, 27.832384	1735.0631, 1753.2521
799	255902	RV	Kenam Tamang	Kenam Tamang	Sindhupalchowk	Haibung	9	0		Melamchi Municipality	3	59	549437								1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843823101	85.462234, 85.462234	27.830862, 27.830862	1673.1056
800	255898	RV	Shyam Bahadur Lama	Shyam Bahadur Lama	Sindhupalchowk	Haibung	9	0		Melamchi Municipality	3	63	549441								2	Grade 2, Grade 3	Minor Repair, Major Repair	Grade 3, Grade 4	Grade 2, Grade 3	Grade 2, Grade 3	Minor Repair, Major Repair	Habitable House in Usual Place	9849291273	85.464195, 85.464203	27.83045, 27.830606	1635.479, 1643.8168
801	255907	RV	Man Bahadur Magar	Man Bahadur Magar	Sindhupalchowk	Haibung	9	0		Melamchi Municipality	3	67	549446								1	Grade 2	Minor Repair	Grade 3	Grade 3	Grade 2	Minor Repair	Habitable House in Usual Place	85.464676, 85.464676	27.830099, 27.830099	1586.7605	
802	255896	RV	Bir Bahadur Lama	Bir Bahadur Lama	Sindhupalchowk	Haibung	9	0		Melamchi Municipality	3	76	549405		Kathmandu, Shank arapura-14	Partial Damage					1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841138601	85.465294, 85.465294	27.831757, 27.831757	1665.4113
803	255900	RV	Bir Bahadur Tamang	Bir Bahadur Tamang	Sindhupalchowk	Haibung	9	0		Melamchi Municipality	3	87	549417								1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803623272	85.463509, 85.463509	27.834196, 27.834196	1739.1743
804	251869	RV	Gurmi Sherpa	Gurmi Sherpa	Sindhupalchowk	Helambu	1	0		Helambu	1	12	367186		Kathmandu, Shank arapura-6	No Damage					1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9816025848	85.5271, 85.5271	27.951082, 27.951082	2257.8853
805	251859	RV	Kami Phurpa Sherpa	Putali Sherpa	Sindhupalchowk	Helambu	1	0		Helambu	1	23	367197		Kathmandu, Shank arapura-99	Partial Damage					1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808949166	85.528404, 85.528404	27.944626, 27.944626	2287.9985
806	249694	RV	Wang Chiring Sherpa	Wang Chiring Sherpa	Sindhupalchowk	Helambu	1	0		Helambu	1	24	367198		Kathmandu, Shank arapura-99	Partial Damage					1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9818203920	85.52787, 85.52787	27.945837, 27.945837	2294.3052
807	251860	RV	Mingmar Lama	Mingmar Lama	Sindhupalchowk	Helambu	1	0		Helambu	1	28	366077								1	Grade 2	Minor Repair	Unrecognized	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9808678797	85.528648, 85.528648	27.947371, 27.947371	2221.9946
808	251866	RV	Phurmenu Sherpa	Phurgeydu Sherpa	Sindhupalchowk	Helambu	1	0		Helambu	1	65	367337		Kathmandu, Shank arapura-6	Partial Damage					1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9803148966	85.529259, 85.529259	27.959364, 27.959364	1962.2167
809	251868	RV	Gyaljen Lama	Gyaljen Lama	Sindhupalchowk	Helambu	1	0		Helambu	1	117	367213		Sindhupalchowk, Jichok-3	Partial Damage					1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9861116237	85.550217, 85.550217	27.944025, 27.944025	1206.7306
810	251865	RV	Nima Chhiring Lama	Nima Chhiring	Sindhupalchowk	Helambu	1	0		Helambu	1	163	366006								2	Grade 1, Grade 5	Minor Repair, Reconstruct	Grade 1, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9843656956	85.558487, 85.558517	27.954851, 27.95503	1677.343, 1675.5659
811	251857	RV	Yogendra Lama	Yonden Lama	Sindhupalchowk	Helambu	1	0		Helambu	1	187	366023								1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9808636784	85.551071, 85.551071	27.952837, 27.952837	1467.6316
812	251862	RV	Bir Bahadur Kami	Bir Bahadur Kami	Sindhupalchowk	Helambu	1	0		Helambu	1	199	366032		Sindhupalchowk, Helambu-8	Partial Damage					1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	85.548988, 85.548988	27.95141, 27.95141	1374.4943	
813	251881	RV	Dawa Lama	Dawa Lama	Sindhupalchowk	Helambu	2	0		Helambu	1	12	366045								2	Grade 1, Grade 5	Minor Repair, Reconstruct	Grade 1, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9860086182	85.56459, 85.564606	27.971411, 27.971432	2426.583, 2435.8547
814	251880	RV	Urgaun Lama	Noorpu Sherpani	Sindhupalchowk	Helambu	2	0		Helambu	1	26	367357		Kathmandu, Shank arapura-2	No Damage					1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741043763	85.56649, 85.56649	27.970007, 27.970007	2470.1265
815	251882	RV	Kaji Lama	Kaji Lama	Sindhupalchowk	Helambu	2	0		Helambu	1	41	367366		Kathmandu, Gokar network-1	No Damage					2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9851006889	85.564728, 85.564766	27.969227, 27.969315	2436.3787, 2441.7317
816	251813	RV	Urken Lama	Urkin Lama	Sindhupalchowk	Helambu	5	0		Helambu	1	2	367387								3	Grade 5, Grade 2, Grade 5	Reconstruct, Minor Repair, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Unrecognized, Reconstruct	Matrix & Photo not cleared or mismatch	9615330423	85.553375, 85.553444, 85.554604	27.993849, 27.999279, 27.999405	2526.0625, 2533.8093, 2663.21
817	251756	RV	Prakash Sherpa	Prakash Sherpa	Sindhupalchowk	Helambu	6	0		Helambu	1	49	546624		Kathmandu, Shank arapura-6	Partial Damage					1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9621142786	85.5224, 85.5224	28.019928, 28.019928	2528.8997
818	251732	RV	Pemba Lamini	Pemba Lama	Sindhupalchowk	Helambu	6	0		Helambu	1	221	546709		Kathmandu, Shank arapura-3	No Damage					1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803484372	85.539276, 85.539276	28.001703, 28.001703	2033.5421
819	251747	RV	Tashi Lama	Tashi Lama	Sindhupalchowk	Helambu	7	0		Helambu	1	20	546561		Kathmandu, Shank arapura-6	Partial Damage					1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	85.538155, 85.538155	27.992373, 27.992373	1932.8816	
820	251751	RV	Kami Dawa Lama	Kami Dawa Lama	Sindhupalchowk	Helambu	7	0		Helambu	1	55	546897								1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	85.538681, 85.538681	27.999846, 27.999846	2026.0588	
821	251660	RV	Kami Sherpa	kami sherpa	Sindhupalchowk	Helambu	9	0		Helambu	1	1	546730		Kathmandu, Kapan-3	No Damage					1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741262562	85.551323, 85.551323	27.95978, 27.95978	1680.0315
822	256356	RV	Sun Lama Tamang	Girmi Lama	Sindhupalchowk	Ichok	2	0		Helambu	6	47	361207			23-30-2-0-47					1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	85.529907, 85.529907	27.927185, 27.927185	1684.3008	
823	256358	RV	Ram Maya Tamang	Dhanlana Tamang, Ram Maya Tamang	Sindhupalchowk	Ichok	2	0		Helambu	6	75	361235			23-30-2-0-75					1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	85.530319, 85.530319	27.929478, 27.929478	1786.0583	
824	256359	RV	Bahadur Tamang	Bahadur Tamang	Sindhupalchowk	Ichok	2	0		Helambu	6	153	361288								1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741231973	85.535439, 85.535439	27.9259, 27.9259	1690.7106
825	256361	RV	Ben Bahadur Pandit	Ben Bahadur Pandit, Dev Kumari Thapa pandit	Sindhupalchowk	Ichok	3	0		Helambu	6	18	361019			23-30-3-0-18		Sindhupalchowk, Jichok-4	Complete Damage		1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9843413810	85.547279, 85.547279	27.919064, 27.919064	

833	256366	RV	Sel Dorje Tamang	Seldorje Tamang	Sindhupalchowk	Ichok	4	0		Helambu	6	133	546460		Sindhupalchowk, Ichok-5	Partial Damage	1	Grade 4	Major Repair	Grade 3	Grade 3	Grade 3	Major Repair	Habitable House in Other Place	85.53434	27.924076	1638.1191	
834	256363	RV	Kumar Tamang	Kumar Tamang	Sindhupalchowk	Ichok	4	0		Helambu	6	151	546451				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818627838	85.539703	27.922215	0
835	256372	RV	Maya Tamang	Maya Tamang	Sindhupalchowk	Ichok	4	0		Helambu	6	163	546472				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 3	Grade 5, Grade 3	Grade 5, Grade 3	Reconstruct, Minor Repair	Habitable House in Usual Place	9813301882	85.535507	27.922716	1643.3573
836	250701	RV	Kanchhi Tamang	Kanchhi Maya	Sindhupalchowk	Ichok	4	0		Helambu	6	165	546446		Kathmandu, Gokar neswor-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803242007	85.535568	27.922615	1636.4438
837	256375	RV	Mangale Tamang	Mangale Tamang	Sindhupalchowk	Ichok	4	0		Helambu	6	167	335307				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.533325	27.919426	1415.8006
838	256309	RV	Biru Tamang	Biru Tamang	Sindhupalchowk	Ichok	5	0		Helambu	6	3	546032				2	Grade 4, Grade 2	Major Repair, Minor Repair	Grade 3, Grade 3	Unrecognized, Unrecognized	Unrecognized, Unrecognized	Unrecognized, Unrecognized	Matrix & Photo not cleared or mismatch	9806450938	85.535355, 85.537094	27.920141, 27.924826	1468.3004, 1669.1489
839	256310	RV	Dhan Bahadur Tamang	Dhan Badhur Tamang	Sindhupalchowk	Ichok	5	0		Helambu	6	11	546042				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9813848862	85.536263	27.924213	1663.8263
840	256312	RV	Shobha Pandit	Sova Pandit	Sindhupalchowk	Ichok	5	0		Helambu	6	50	546386		Kathmandu, Kathmandu-35	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741156598	85.545319	27.913689	1084.6722
841	256379	RV	Maina Pandit	Bhoj Badhur Pandit	Sindhupalchowk	Ichok	5	0		Helambu	6	70	546410				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9841323291	85.543457, 85.543495	27.913418, 27.913567	1102.9524, 1103.9863
842	256307	RV	Tika Bahadur Gajurel	Tika Bahadur Gajurel	Sindhupalchowk	Ichok	5	0		Helambu	6	72	546412				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9818259871	85.537735, 85.543571	27.914839, 27.915026	1102.8269, 1271.903
843	256378	RV	Karsing Khatri	Chola Khatri, Kar Simg Khatri	Sindhupalchowk	Ichok	5	0		Helambu	6	82	546425		Kathmandu, Kathmandu-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741150876	85.537804	27.914562	1269.6746
844	256308	RV	Netra Bahadur Khatri	Netra Bahadur Kc	Sindhupalchowk	Ichok	5	0		Helambu	6	83	546426		Bhaktapur, Bhaktapur-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860244966	85.537674	27.915102	1270.8256
845	251450	RV	Lok Bahadur Pandit	Lok Bahadur Pandit	Sindhupalchowk	Ichok	5	0		Helambu	6	90	546434		Kathmandu, Kapan-6	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9840020148	85.537331	27.915583	1291.0319
846	256311	RV	Naina Bahadur Khatri	Nain Bahadur Khatri	Sindhupalchowk	Ichok	5	0		Helambu	6	118	546427		Kathmandu, Kathmandu-35	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841910521	85.537659	27.915134	1276.2655
847	256197	RV	Batuli Shrestha	Kali Prasad Sheresht	Sindhupalchowk	Ichok	6	0		Helambu	7	1	546447				2	Grade 2, Grade 2	Minor Repair, Minor Repair	Grade 2, Grade 2	Grade 2, Grade 2	Grade 2, Grade 2	Minor Repair, Minor Repair	Habitable House in Usual Place	9813040253	85.543816, 85.543953	27.903242, 27.903246	1001.225, 1018.8123
848	256198	RV	Jhalak Bahadur Pandit	Khalak Bahadur Pandit	Sindhupalchowk	Ichok	6	0		Helambu	7	2	546448				2	Grade 2, Grade 4	Minor Repair, Major Repair	Grade 2, Grade 4	Grade 2, Grade 3	Grade 2, Grade 3	Minor Repair, Major Repair	Habitable House in Usual Place	9741004700	85.543976, 85.543976	27.902939, 27.902952	1008.0508, 1016.2332
849	256320	RV	Suresh Tamang	Suresh Tamang	Sindhupalchowk	Ichok	6	0		Helambu	7	6	546052		Sindhupalchowk, Ichok-8	Complete Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9813014970	85.544189	27.902922	991.79327
850	256319	RV	Tilak Bahadur Karki	Tilak Bahadur Karki	Sindhupalchowk	Ichok	6	0		Helambu	7	7	546053				2	Grade 1, Grade 5	Not Required, Reconstruct	Grade 1, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	9849826772	85.530931, 85.543976	27.901890, 27.903126	1008.2805, 1126.6462
851	256318	RV	Jogendra Kachhapati	Jogendar Kachhapati	Sindhupalchowk	Ichok	6	0		Helambu	7	9	546055		Kathmandu, Kavres thali-9	Partial Damage	1	Grade 4	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	16221833	85.544006	27.902788	1006.2488
852	256323	RV	Mangal Bahadur Dangal	Manga Bahadur Dangal	Sindhupalchowk	Ichok	6	0		Helambu	7	14	546060				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9861011475	85.543709	27.902637	1000.5507
853	256321	RV	Roshan Shrestha Kachhapati	Surendralal Sheresht	Sindhupalchowk	Ichok	6	0		Helambu	7	18	546065		Kathmandu, Kathmandu-35	No Damage	1	Grade 3	Major Repair	Grade 4	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9841508501	85.543701	27.90201	1003.9709
854	256322	RV	Nara Bahadur Basnet	Nar Bahadur Basnet	Sindhupalchowk	Ichok	6	0		Helambu	7	20	546067		Kathmandu, Kathmandu-4/Sindhupalchowk, Palchowk-4	Complete Damage, No Damage	1	Grade 4	Major Repair	Grade 3	Grade 3	Grade 3	Major Repair	Habitable House in Other Place	9751016778	85.543755	27.902475	1006.0636
855	256317	RV	Hasta Bahadur Pandit	Tara Bahadur Pandit	Sindhupalchowk	Ichok	6	0		Helambu	7	28	546065		Kathmandu, Kathmandu-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851150747	85.543488	27.902119	1003.1393
856	256324	RV	Devi Bahadur Pandit	Devi Bahadur Pandit	Sindhupalchowk	Ichok	6	0		Helambu	7	30	546077		Kathmandu, Kathmandu-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741232811	85.543419	27.902132	1024.3827
857	256313	RV	Tak Bahadur Damai	Tak Bahadur Damai	Sindhupalchowk	Ichok	6	0		Helambu	7	128	546151				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place		85.5308	27.90691	1223.5956
858	256204	RV	Bir Bahadur Tamang	Bir Bahadur Tamang, Mlang Gae Tamang, Taasi Dorje Tamang	Sindhupalchowk	Ichok	8	0		Helambu	7	18	519945				2	Grade 1, Grade 5	Not Required, Reconstruct	Grade 2, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	9621188203	85.502197, 85.50341	27.923983, 27.925842	1843.3755, 1928.3738
859	253268	RV	Mlangai Tamang	Bir Bahadur Tamang, Mlang Gae Tamang, Taasi Dorje Tamang	Sindhupalchowk	Ichok	8	0		Helambu	7	18	519944				2	Grade 1, Grade 5	Not Required, Reconstruct	Grade 2, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	9621188203	85.502197, 85.50341	27.923983, 27.925842	1843.3755, 1928.3738
860	256203	RV	Tasi Dorje Tamang	Bir Bahadur Tamang, Mlang Gae Tamang, Taasi Dorje Tamang	Sindhupalchowk	Ichok	8	0		Helambu	7	18	519946				2	Grade 1, Grade 5	Not Required, Reconstruct	Grade 2, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	9621188203	85.502197, 85.50341	27.923983, 27.925842	1843.3755, 1928.3738
861	256246	RV	Ajaya Tamang	Ajay Tamang, Dawa Lama	Sindhupalchowk	Ichok	8	0		Helambu	7	28	520984				1	Grade 1	Not Required	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9803136134	85.50415	27.922626	1889.3743
862	256252	RV	Dawa Lama	Ajay Tamang, Dawa Lama	Sindhupalchowk	Ichok	8	0		Helambu	7	28	520983				1	Grade 1	Not Required	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9803136134	85.50415	27.922626	1889.3743
863	256236	RV	Mingmar Dolma Lama	Surya Tamang	Sindhupalchowk	Ichok	8	0		Helambu	7	182	520890				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9803679529	85.512901	27.916245	1643.2853
864	251020	RV	Samsar Bahadur Shrestha	Bhupendra Shrestha, Purna Bahadur Shrestha, Samsar Bahadur Shrestha	Sindhupalchowk	Jethal	2	0		Lisankhu Pakhar	5	133	328821		Kathmandu, Kapan-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741278857	85.922729	27.702993	1954.0983
865	251226	RV	Santi Tamang (Shrestha)	Keshar Bahadur Shrestha	Sindhupalchowk	Jethal	2	0		Lisankhu Pakhar	5	136	328824				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849768052	85.92112	27.703604	1882.1589
866	251227	RV	Krishna Lal Shrestha	Gopal Shrestha	Sindhupalchowk	Jethal	2	0		Lisankhu Pakhar	5	137	328825				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803597620	85.921333	27.703951	1894.5967
867	251266	RV	Kedar Karki	Kedar Karki	Sindhupalchowk	Jethal	4	0		Lisankhu Pakhar	5	5	328886				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741157713	85.91571	27.696482	1860.8314
868	251155	RV	Jhamka Bahadur Shrestha	Jhamka Bahadur Shrestha	Sindhupalchowk	Jethal	5	0		Lisankhu Pakhar	5	1	328971				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818167486	85.908829	27.701141	1694.4108
869	251161	RV	Suku Bahadur Tamang	Suku Tamang	Sindhupalchowk	Jethal	5	0		Lisankhu Pakhar	5	7	328980				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9860210054	85.907547	27.700678	1713.7694
870	251166	RV	Ambar Bahadur Pandey	Amar Bahadur Pandey, Arjun Pandey	Sindhupalchowk	Jethal	5	0		Lisankhu Pakhar	5	38	1175770		Kathmandu, Kathmandu-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741353411	85.905289	27.701059	1726.5725
871	251158	RV	Phurba Tamang	Suresh Tamang	Sindhupalchowk	Jethal	5	0		Lisankhu Pakhar	5	87	1175821		Sindhupalchowk, Jethal-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9818512103	85.900658	27.696033	2005.8414
872	251022	RV	Suresh Tamang	Suresh Tamang	Sindhupalchowk	Jethal	5	0		Lisankhu Pakhar	5	87			Sindhupalchowk, Jethal-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9818512103	85.900658	27.696033	2005.8414
873	251169	RV	Ganga Bahadur Shrestha	Ganga Bahadur Shrestha	Sindhupalchowk	Jethal	5	0		Lisankhu Pakhar	5	93	1175827				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741044079	85.901001	27.695436	2007.4033
874	251185	RV	Amrita Shrestha	Amrita Shrestha	Sindhupalchowk	Jethal	6	0		Lisankhu Pakhar	5	33	520614				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.909218	27.701231	1700.0172
875	251089	RV	Roj Bahadur Bhandari	Roj Bahadur Bhandari	Sindhupalchowk	Jethal	7	0		Lisankhu Pakhar	5	13	520687				2	Grade 2, Grade 2	Minor Repair, Minor Repair	Grade 2, Grade 2	Grade 2, Grade 2	Grade 2, Grade 2	Minor Repair, Minor Repair	Habitable House in Usual Place	9843429462	85.882278, 85.882729	27.708897, 27.708921	1840.3468, 1842.2347
876	251093	RV	Lal Bahadur Bhandari	Lal Bahadur Bhandari	Sindhupalchowk	Jethal	7	0		Lisankhu Pakhar	5	14	520688				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place		85.88063, 85.882416	27.705843, 27.70886	1758.5912, 1838.9685
877	251078	RV	Prem Bahadur Bhandari	Prem Bahadur Bhandari	Sindhupalchowk	Jethal	7	0		Lisankhu Pakhar	5	17	520692		Kathmandu, Gokar neswor-13	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place		85.882339	27.70472	1788.8354
878	251197	RV	Thuli Maya Lama	Thuli Maya Lama	Sindhupalchowk	Jethal	7	0		Lisankhu Pakhar	5	27	520706		Bhaktapur, Balkot-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841406916	85.882957	27.704749	1823.3505

883	251087	RV	Phurba Lama	Phurba Lama	Sindhupalchowk	Jethal	7	0		Lisankhu Pakhar	5	54	520736			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9860448079	85.881172	27.709244	1820.8409
884	251091	RV	Navaraj Bhandari	Navraj Bhandari	Sindhupalchowk	Jethal	7	0		Lisankhu Pakhar	5	61	520742			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841516843	85.882095	27.708591	1830.6927
885	251090	RV	Kamala Bhandari	Kamala Bhandari	Sindhupalchowk	Jethal	7	0		Lisankhu Pakhar	5	62	520743			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843220541	85.882263	27.708595	1834.1262
886	251094	RV	Sobarna Bahadur Bhandari	Sobarna Bahadur Bhandari	Sindhupalchowk	Jethal	7	0		Lisankhu Pakhar	5	68	520751			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741103459	85.882339	27.709574	1859.8861
887	251092	RV	Sukumaya Tamang	Sukumaya Tamang	Sindhupalchowk	Jethal	7	0		Lisankhu Pakhar	5	72	520755			1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.882591	27.709549	1864.3368
888	251083	RV	Navaraj Bhandari	Navaraj Bhandari	Sindhupalchowk	Jethal	7	0		Lisankhu Pakhar	5	86	520770	Kathmandu,Shank arapura-1	Partial Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	9851052896	85.893593	27.699265	1986.7362
889	251084	RV	Pasang Tamang	Pasang Tamang	Sindhupalchowk	Jethal	7	0		Lisankhu Pakhar	5	94	520778			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803618142	85.900681	27.695648	2009.9617
890	251112	RV	Dhan Bahadur Tamang	Dhan Bahadur Tamang	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	12	326583			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.928024	27.684132	2490.7959
891	251117	RV	Dambar Bahadur Shrestha	Dambar Bahadur Shrestha, Ram Chandra Shrestha	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	14	326585			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9860602468	85.926445	27.684359	2488.5239
892	251118	RV	Ramesh Kumar Joshi	Ramesh Kumar Joshi	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	18	326591			2	Grade 2, Grade 2	Minor Repair, Minor Repair	Grade 2, Grade 2	Grade 2, Grade 2	Grade 2, Grade 2	Minor Repair, Minor Repair	Habitable House in Usual Place	9841373014	85.908379, 85.926529	27.684013, 27.686268	2357.481, 2483.2681
893	251099	RV	Ambar Bahadur Lama	Ambar Bahadur Lama, Nima Dorje Lama	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	19	326592	Kathmandu,Shank arapura-1	No Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	9854045746	85.926399	27.684181	2500.0884
894	251100	RV	Nima Dorje Lama	Ambar Bahadur Lama, Nima Dorje Lama	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	19	326593	Kathmandu,Shank arapura-1	No Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	9854045746	85.926399	27.684181	2500.0884
895	251200	RV	Gita Shrestha	Dil Bahadur Shrestha	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	20	326594	Kathmandu,Kathm andu-35	Partial Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	9849126853	85.926376	27.68412	2497.5518
896	251121	RV	Sarita Lama	Pema Dorje Lama	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	22	326596			2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9841101657	85.926041, 85.926216	27.684074, 27.684229	2469.449, 2500.2183
897	251123	RV	Tara Lal Shrestha	Tara Lal Shrestha	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	25	326598			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841261660	85.926056	27.683907	2499.5032
898	251136	RV	Bishnu Maya Shrestha	Bishnu Maya Shrestha	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	26	326599	Bhaktapur,Mathya pur Thimi-16	No Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	9851019261	85.926011	27.684137	2496.2241
899	251108	RV	Minga Dorje Lama	Ming Dorje Lama	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	51	326528			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841503387	85.924661	27.683729	2484.4104
900	251122	RV	Dambar Bahadur Shrestha	Dambar Bahadur Shrestha	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	72	326549			2	Grade 2, Grade 4	Minor Repair, Reconstruct	Grade 2, Grade 4	Grade 2, Grade 4	Grade 2, Grade 4	Minor Repair, Reconstruct	Habitable House in Usual Place	9841469274	85.925018, 85.925026	27.683851, 27.683899	2495.7468, 2498.9023
901	251124	RV	Khadga Bahadur Shrestha	Khadga Bahadur Shrestha	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	73				2	Grade 2, Grade 4	Minor Repair, Reconstruct	Grade 2, Grade 4	Grade 2, Grade 4	Grade 2, Grade 4	Minor Repair, Reconstruct	Habitable House in Usual Place	9745106561	85.925087, 85.925111	27.683809, 27.683933	2493.7686, 2496.7102
902	251104	RV	Laxmi Maya Shrestha	Laxmi Maya Shrestha, Mishre Shrestha	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	87	326567	Kathmandu,Kathm andu-35/Kathmandu,Kat hmandu-35	Partial Damage, Partial Damage	2	Grade 4, Grade 2	Reconstruct, Minor Repair	Grade 4, Grade 2	Grade 4, Grade 2	Grade 4, Grade 2	Reconstruct, Minor Repair	Habitable House in Other Place	9741028695	85.925636, 85.925934	27.684032, 27.684122	2498.9783, 2500.1228
903	251107	RV	Laxmi Shrestha	Laxmi Shrestha	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	93	326572			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841676561	85.926178	27.684229	2503.1055
904	251115	RV	Achchutam Shrestha	Hem Maya Shrestha	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	96	326575			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9819626051	85.926414	27.684509	2502.2246
905	251097	RV	Hem Maya Shrestha	Hem Maya Shrestha	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	96	326574			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9819626051	85.926414	27.684509	2502.2246
906	251105	RV	Prakash Shrestha	Krishna Kumari Shrestha, Prakash Shrestha	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	98	398978			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741007130	85.926254	27.684475	2503.2773
907	251098	RV	Kamala Shrestha	Kamala Shrestha	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	99	398979			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	16913830	85.92659	27.684591	2496.4749
908	251116	RV	Sanja Maya Lama	Sanja Maya Lama	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	100	398980			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741261036	85.926498	27.684338	2509.0125
909	251203	RV	Tul Bahadur Lama	Tila Bahadur Lama	Sindhupalchowk	Jethal	8	0		Lisankhu Pakhar	5	102	398982			1	Grade 2	Reconstruct	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.926292	27.683838	2485.3823
910	251035	RV	Sharmila Joshi	Sarmila Joshi	Sindhupalchowk	Jethal	9	0		Lisankhu Pakhar	5	6	520406	Sindhupalchowk,At tarpur-9	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741208066	85.933823	27.672644	2267.7813
911	251032	RV	Rana Bahadur Shrestha	Rana Bahadur Shrestha	Sindhupalchowk	Jethal	9	0		Lisankhu Pakhar	5	17	520416			1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place		85.926628	27.674778	2148.5645
912	251128	RV	Lila Kumari Joshi	Lilakumari Thapa	Sindhupalchowk	Jethal	9	0		Lisankhu Pakhar	5	26	520423			3	Grade 5, Grade 2, Grade 5	Reconstruct, Minor Repair, Reconstruct	Grade 5, Grade 3, Unrecognized, Grade 5	Grade 5, Unrecognized, Grade 5	Grade 5, Unrecognized, Grade 5	Reconstruct, Unrecognized, Reconstruct	Matrix & Photo not cleared or mismatch		85.938171, 85.938179, 85.938187	27.674667, 27.674744, 27.6751	2434.7725, 2436.1289, 2438.1833
913	251034	RV	Surya Bahadur Shrestha	Surya Bahadur Shrestha	Sindhupalchowk	Jethal	9	0		Lisankhu Pakhar	5	42	520439			1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place		85.936775	27.676123	2443.8403
914	251013	RV	Dil Kumar Joshi	Dilkumar Joshi	Sindhupalchowk	Jethal	9	0		Lisankhu Pakhar	5	61	520466			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.936707	27.67588	2438.6953
915	251131	RV	Kumar Shrestha	Kumar Shrestha, Pramila Shrestha	Sindhupalchowk	Jethal	9	0		Lisankhu Pakhar	5	89	520504			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.934555	27.67885	2484.8069
916	251134	RV	Pramila Shrestha	Kumar Shrestha, Pramila Shrestha	Sindhupalchowk	Jethal	9	0		Lisankhu Pakhar	5	89	520503			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.934555	27.67885	2484.8069
917	251046	RV	Indra Kumari Shrestha	Dhan Bahadur Shrestha, Lekh Bahadur Shrestha, Tilak Bahadur Shrestha	Sindhupalchowk	Jethal	9	0		Lisankhu Pakhar	5	95	520517			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.934792	27.678314	2464.717
918	251137	RV	Lekha Bahadur Shrestha	Dhan Bahadur Shrestha, Lekh Bahadur Shrestha, Tilak Bahadur Shrestha	Sindhupalchowk	Jethal	9	0		Lisankhu Pakhar	5	95	520516			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.934792	27.678314	2464.717
919	251067	RV	Saroj Shrestha	Saroj Shrestha	Sindhupalchowk	Jethal	9	0		Lisankhu Pakhar	5	114	520546			1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place		85.938461	27.673637	2442.4688
920	251051	RV	Khadka Bahadur Shrestha	Khadga Bahadur Shrestha, Padma Kumari Shrestha	Sindhupalchowk	Jethal	9	0		Lisankhu Pakhar	5	119	520551			1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9614960144	85.933479	27.680113	2476.9004
921	251044	RV	Padhya Kumari Shrestha	Khadga Bahadur Shrestha, Padma Kumari Shrestha	Sindhupalchowk	Jethal	9	0		Lisankhu Pakhar	5	119	520552			1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9614960144	85.933479	27.680113	2476.9004
922	251038	RV	Ratna Kumari Shrestha	Ratna Kumari Shrestha	Sindhupalchowk	Jethal	9	0		Lisankhu Pakhar	5	120	520553			1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9813487696	85.933655	27.679996	2470.2029
923	251040	RV	Sharmila Pandit (Shrestha)	Sarmila Pandit shrestha, Ser Bahadur Shrestha	Sindhupalchowk	Jethal	9	0		Lisankhu Pakhar	5	121	520556			1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9843172608	85.933205	27.680334	2476.8059
924	251039	RV	Sher Bahadur Shrestha	Sarmila Pandit shrestha, Ser Bahadur Shrestha	Sindhupalchowk	Jethal	9	0		Lisankhu Pakhar	5	121	520554			1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9843172608	85.933205	27.680334	2476.8059
925	256078	RV	Bhim Bahadur Shrestha	Bhim Bahadur Shrestha	Sindhupalchowk	Kadambas	1	0		Chautara Sagachowkgadhi Municipality	9	36	338364			1	Grade 2	Not Required	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.777252	27.735956	763.22845
926	256079	RV	Padam Bahadur Shrestha	Padam Bahadur Shrestha	Sindhupalchowk	Kadambas	1	0		Chautara Sagachowkgadhi Municipality	9	41	338369			2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 3	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9849858588	85.773758, 85.773819	27.737909, 27.737913	961.50323, 964.79272
927	256097	RV	Dhoj Bahadur Tamang	Dhoj Bahadur Tamang	Sindhupalchowk	Kadambas	3	0		Chautara Sagachowkgadhi Municipality	9	41	339443			2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9860190077	85.752197, 85.753036	27.722178, 27.723467	1215.7349, 1279.7487
928	256096	RV	Gyendra Raj Bharati	Gyendra Raj Bharati	Sindhupalchowk	Kadambas	3	0		Chautara Sagachowkgadhi Municipality	9	42	339444			2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place		85.752213, 85.752411	27.723297, 27.723471	1265.9723, 1268.4585
929	253199	RV	Krishna Raj Giri	Keishna Raj Giri	Sindhupalchowk	Kadambas	4	0		Chautara Sagachowkgadhi Municipality	9	13	338091	Kathmandu,Kathm andu-9	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	14486802	85.768921	27.729233	1084.3685

930	256119	RV	Renu Ban Giri	Om Giri	Sindhupalchowk	Kadambas	4	0		Chautara Sagachowkgadhi Municipality	9	15	338093		Kathmandu,Kathmandu-35	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841295951	85.768852	27.729593	1080.0914	
931	256117	RV	Laxmi Giri	Narayan Giri	Sindhupalchowk	Kadambas	4	0		Chautara Sagachowkgadhi Municipality	9	21	338099		Bhaktapur,Bhaktapur-17	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841263007	85.76889	27.729242	1077.4216	
932	256108	RV	Birendra Raj Giri	Birendra Raj Giri	Sindhupalchowk	Kadambas	4	0		Chautara Sagachowkgadhi Municipality	9	30	338058		Kathmandu,Gokarneswor-13	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849386690	85.769348	27.729977	1082.1917	
933	256107	RV	Sanu Maya Giri	Umesh Raj Giri	Sindhupalchowk	Kadambas	4	0		Chautara Sagachowkgadhi Municipality	9	39	338070		Kathmandu,Kathmandu-35	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849904405	85.769264	27.730017	1087.5173	
934	256105	RV	Juna Giri	Raju Giri	Sindhupalchowk	Kadambas	4	0		Chautara Sagachowkgadhi Municipality	9	42	338073		Kathmandu,Kathmandu-9	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	14499924	85.768333	27.728563	1075.7146	
935	256106	RV	Tara Giri	Tara Giri	Sindhupalchowk	Kadambas	4	0		Chautara Sagachowkgadhi Municipality	9	50	1174507		Kathmandu,Kathmandu-99	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849030309	85.770515	27.729103	1055.2687	
936	251333	RV	Lalit Bahdur Giri	Lalit Bahadur Giri	Sindhupalchowk	Kadambas	4	0		Chautara Sagachowkgadhi Municipality	9	59	1174516		Kathmandu,Kathmandu-34	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	14486102	85.770157	27.728689	1049.4921	
937	256120	RV	Bikram Giri	Bikram Giri	Sindhupalchowk	Kadambas	4	0		Chautara Sagachowkgadhi Municipality	9	67	1174526		Bhaktapur,Madhyapur Thimi-15	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	16638906	85.77063	27.72823	1021.3189	
938	256116	RV	Sanukanchha Giri	Sanu Kancha Giri	Sindhupalchowk	Kadambas	4	0		Chautara Sagachowkgadhi Municipality	9	126	1174617		Bhaktapur,Madhyapur Thimi-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849378612	85.770042	27.723629	888.84521	
939	253200	RV	Laxu Man Bharati	Laxman Bharati	Sindhupalchowk	Kadambas	5	0		Chautara Sagachowkgadhi Municipality	9	2	338414				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	11400010	85.762016	27.705292	628.81104	
940	256127	RV	Santa Lal Shrestha	Santa Lal Shrestha	Sindhupalchowk	Kadambas	5	0		Chautara Sagachowkgadhi Municipality	9	9	338420				2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9849310156	85.767029, 85.767052	27.712427, 27.712467	632.27344, 648.12659	
941	256123	RV	Tanka Bahadur Jogi	Tok Bahadur Jogi	Sindhupalchowk	Kadambas	5	0		Chautara Sagachowkgadhi Municipality	9	125	338241				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9808691649	85.761368	27.714258	875.3576	
942	256030	RV	Kanchhi Tamang	Kanchimaya Tamang	Sindhupalchowk	Kadambas	6	0		Chautara Sagachowkgadhi Municipality	9	52	554054				2	Grade 1, Grade 5	Minor Repair, Reconstruct	Grade 1, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	9741088884	85.761566, 85.762718	27.728743, 27.729069	1236.6868, 1245.5948	
943	256024	RV	Pramila Tamang	Pramela Tamang	Sindhupalchowk	Kadambas	6	0		Chautara Sagachowkgadhi Municipality	9	68	554071				2	Grade 1, Grade 5	Not Required, Reconstruct	Grade 1, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	9741260524	85.760391, 85.760849	27.727463, 27.72805	1206.8011, 1217.4723	
944	256009	RV	Dil Bahadur Tamang	Dil Bahadur Tamang	Sindhupalchowk	Kadambas	6	0		Chautara Sagachowkgadhi Municipality	9	82	554087				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9808080942	85.762329	27.729174	1240.9542	
945	256026	RV	Anjana Tamang	Rina Tamang	Sindhupalchowk	Kadambas	6	0		Chautara Sagachowkgadhi Municipality	9	94	554101		Sindhupalchowk, Sangachok-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849758183	85.764153	27.731562	1273.9575	
946	256029	RV	Rina Tamang	Rina Tamang	Sindhupalchowk	Kadambas	6	0		Chautara Sagachowkgadhi Municipality	9	94	554100		Sindhupalchowk, Sangachok-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849758183	85.764153	27.731562	1273.9575	
947	256038	RV	Santa Lal Majhi	Shanta Lal Majhi	Sindhupalchowk	Kadambas	7	0		Chautara Sagachowkgadhi Municipality	9	36	541942				3	Grade 5, Grade 5, Grade 1	Reconstruct, Reconstruct, Not Required	Grade 5, Grade 5, Grade 2	Grade 5, Grade 5, Grade 2	Grade 5, Grade 5, Grade 2	Reconstruct, Reconstruct, Minor Repair	Habitable House in Usual Place	9843047921	85.775673, 85.776657, 85.777145	27.721325, 27.723034, 27.723309	636.51117, 645.56439, 658.13843	
948	256036	RV	Puspa Bahadur Shrestha	Puspa Bahadur Shrestha	Sindhupalchowk	Kadambas	7	0		Chautara Sagachowkgadhi Municipality	9	50	541957				3	Grade 3, Grade 2, Grade 4	Major Repair, Minor Repair, Major Repair	Grade 2, Grade 2, Grade 3	Grade 2, Grade 2	Grade 2, Grade 2	Grade 2, Grade 2, Grade 2	Minor Repair, Minor Repair, Minor Repair	Habitable House in Usual Place	9843771088	85.779297, 85.779488	27.732523, 27.732641	643.6684, 654.16858
949	256059	RV	Krishna Maya Shrestha	Krishna Maya Shrestha	Sindhupalchowk	Kadambas	9	0		Chautara Sagachowkgadhi Municipality	9	170	541852				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9851117490	85.769508	27.740953	1177.3948	
950	256188	RV	Siva B. Basnet	Shiva Bahadur Basnet	Sindhupalchowk	Karthali	9	0		Barhise Municipality	2	59	402273				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 1, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9861162343				
951	251677	RV	Bhupendra Kumar Bhandari	Pitamber Bhandari	Sindhupalchowk	Kiwool	1	0		Helambu	2	1	512376		Sindhupalchowk, Kiwool-5	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741115653	85.553726	27.922138	1107.5532	
952	251617	RV	Krishna Bahadur Bishwakarma	Krishna Bahadur Biswakarma	Sindhupalchowk	Kiwool	1	0		Helambu	2	41	510492				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818542175	85.547295	27.909899	1043.3206	
953	251683	RV	Purnima Tamang	Lhakpa Singi Tamang	Sindhupalchowk	Kiwool	1	0		Helambu	2	49	510499				1	Grade 2	Not Required	Grade 2	Grade 2	Grade 1	Not Required	Habitable House in Usual Place	9803524151	85.547203	27.909544	1031.0187	
954	251686	RV	Karma Singi Tamang	Karma Singi Tamanh	Sindhupalchowk	Kiwool	1	0		Helambu	2	143	512179				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818814628	85.547928	27.896175	1149.3563	
955	251680	RV	Dhruba Bahadur Joti	Dhruba Bahadur Joti	Sindhupalchowk	Kiwool	1	0		Helambu	2	159	512298				1	Grade 2	Minor Repair	Unrecognized	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9803862126	85.553879	27.901897	1269.8607	
956	251609	RV	Pemba Renjen Lama	Pemba Renjen Lama	Sindhupalchowk	Kiwool	5	0		Helambu	2	3	521278				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 3, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9818929164	85.554092, 85.571831	27.927975, 27.930737	1147.5063, 1225.9149	
957	251606	RV	Man Bahadur Tamang	Man Bahadur Tamang	Sindhupalchowk	Kiwool	5	0		Helambu	2	26	521201		Sindhupalchowk, Kiwool-5	Complete Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9813360067	85.554138	27.928211	1129.6738	
958	251615	RV	Kamala Nepali	Kamala Nepali	Sindhupalchowk	Kiwool	5	0		Helambu	2	28	521205		Sindhupalchowk, Kiwool-4	Complete Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818647169	85.553719	27.927334	1144.3063	
959	251608	RV	Karmu Lamini	Thakpa Lama	Sindhupalchowk	Kiwool	5	0		Helambu	2	105	521255				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9803046825	85.567169, 85.567329	27.929766, 27.929777	1559.2009, 1578.6261	
960	251611	RV	Dawa Jyangu Lama	Dawa Jyangu Lama	Sindhupalchowk	Kiwool	5	0		Helambu	2	111	521261		Kathmandu, Shankarapura-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813893872	85.568024	27.929909	1590.2676	
961	251610	RV	Jhimba Lama	Jhimba Lama	Sindhupalchowk	Kiwool	5	0		Helambu	2	112	521262		Kathmandu, Shankarapura-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808060180	85.568314	27.930038	1605.6262	
962	251614	RV	Nurpu Lama	Nurpu Lama	Sindhupalchowk	Kiwool	5	0		Helambu	2	113	521263		Kathmandu, Shankarapura-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808013238	85.568344	27.929909	1603.8135	
963	251612	RV	Mingmar Lama	Mingmar Lama	Sindhupalchowk	Kiwool	5	0		Helambu	2	136	521236		Kathmandu, Gokarneswor-13	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841185627	85.571938	27.930813	1720.0477	
964	249779	RV	Dhandul Lama	Sange Lama	Sindhupalchowk	Kiwool	6	0		Helambu	2	10	519526				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9813965663	85.580894	27.928442	2022.89	
965	251651	RV	Ngadang	Nadang Lama	Sindhupalchowk	Kiwool	6	0		Helambu	2	35	519726				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9841418165	85.588638	27.924084	2242.3699	
966	251652	RV	Dame Lama	Dame Lama	Sindhupalchowk	Kiwool	6	0		Helambu	2	44	519735				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841233173	85.588379	27.923361	2243.741	
967	251525	RV	Dawa Lama	Dawa Lama	Sindhupalchowk	Kiwool	6	0		Helambu	2	62	521178				1	Grade 2	Minor Repair	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9803689018	85.591003	27.923109	2326.3442	
968	251535	RV	Lhakpa Lama	Lakpa Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	9	521197		Kathmandu, Shankarapura-7	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9803725012	85.595078	27.944029	2533.4517	
969	251541	RV	Dawa Lama	Dawa Lama hyalmo	Sindhupalchowk	Kiwool	7	0		Helambu	2	16	519604		Kathmandu, Shankarapura-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803249554	85.594261	27.942081	2522.7927	
970	249781	RV	Dhandul Lama	Dhan Dul Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	25	519613		Kathmandu, Shankarapura-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841280063	85.594429	27.941837	2524.5176	

971	251543	RV	Kanchha Lama	Kancha Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	26	519614	Kathmandu,Shank arapura-15	Partial Damage	3	Grade 5, Grade 5, Grade 5	Reconstruct, Reconstruct, Reconstruct	Grade 5, Grade 5, Grade 5	Grade 5, Grade 5, Grade 5	Grade 5, Grade 5, Grade 5	Reconstruct, Reconstruct, Reconstruct	Habitable House in Other Place	9808344087	85.595467, 85.59549, 85.59565	27.944698, 27.944841, 27.94496	2529.7009, 2544.0044, 2544.6326	
972	251527	RV	Kanchha Lama	Kancha Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	27	519615	Kathmandu,Shank arapura-13	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860292033	85.595261	27.94458	2536.4885
973	251532	RV	Kami Lama	Kami Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	28	519616	Kathmandu,Kathm andu-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841778201	85.595108	27.945175	2556.7937
974	251531	RV	Chiring Lama	Chiring Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	29	519617	Kathmandu,Shank arapura-3	Partial Damage	3	Grade 5, Grade 5, Grade 4	Reconstruct, Reconstruct, Reconstruct	Grade 5, Grade 5, Grade 4	Grade 5, Grade 5, Grade 3	Grade 5, Grade 5, Grade 3	Reconstruct, Reconstruct, Major Repair	Habitable House in Other Place	9803894620	85.595062, 85.5952, 85.595299	27.945023, 27.945086, 27.9452	2547.4426, 2549.4302, 2554.04	
975	251539	RV	Renjen Lama	Renjen Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	32	519620	Kathmandu,Shank arapura-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860392391	85.595718	27.94525	2558.7034
976	251533	RV	Dawa Lama	Dawa Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	33	519621	Kathmandu,Shank arapura-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808461543	85.594894	27.944355	2537.7646
977	251550	RV	Tasi Chiring Tamang	Tashi Chiring Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	34	519622	Kathmandu,Shank arapura-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813690065	85.596016	27.94523	2571.9226
978	251538	RV	Pemba Lama	Pema Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	35	519623	Kathmandu,Shank arapura-3	No Damage	1	Grade 3	Major Repair	Grade 3	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	9808077392	85.598442	27.944172	2501.4487
979	251536	RV	Chesang Lama	Chesang Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	47	519560	Kathmandu,Shank arapura-1	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9621136134	85.597397	27.943991	2516.5488
980	251530	RV	Dhindu Lama	Dhindu Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	51	519564	Kathmandu,Shank arapura-3	Partial Damage	1	Grade 5	Reconstruct	Grade 4	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9808580050	85.597153	27.944529	2554.8557
981	251537	RV	Jambu Lama	Jangbu Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	53	519566	Kathmandu,Shank arapura-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.596497	27.944014	2555.6504
982	251546	RV	Suman Kumar Sharmalama	Suman Kumar Sharma	Sindhupalchowk	Kiwool	7	0		Helambu	2	54	519567	Kathmandu,Shank arapura-2	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	984796539	85.59568	27.944256	2547.7571
983	251528	RV	Tasi Lama	Tashi Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	55	519568	Kathmandu,Shank arapura-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9818691172	85.595215	27.943901	2528.405
984	251853	RV	Pasang Lama	Pasang Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	56	519569	Kathmandu,Shank arapura-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803834742	85.595284	27.943842	2530.894
985	251547	RV	Maya Lama	Phurpa Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	57	519570	Kathmandu,Shank arapura-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841910780	85.594849	27.944384	2517.0178
986	251534	RV	Pasang Dhindu Lama	Pasang Dhindu Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	63	519701	Kathmandu,Shank arapura-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803500329	85.595139	27.94256	2521.0127
987	251549	RV	Chenga Lama	Chenga Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	65	519703	Kathmandu,Shank arapura-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813228512	85.59407	27.943253	2513.3362
988	251548	RV	Karpo Lama	Karpo Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	66	519704	Kathmandu,Shank arapura-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.594269	27.943321	2505.2827
989	251582	RV	Kami Dorje Lama	Kami Dhorje Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	67	519705	Kathmandu,Shank arapura-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9818191468	85.59404	27.943571	2512.0061
990	251613	RV	Jyangyang Lama	Jamyang Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	69	519707	Kathmandu,Shank arapura-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741204406	85.594177	27.943378	2516.9602
991	251529	RV	Temba Lama	Temba Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	72	519710	Kathmandu,Shank arapura-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803871123	85.59433	27.943569	2521.0762
992	251552	RV	Dawa Lama	Dawa Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	73	519711	Kathmandu,Shank arapura-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.594383	27.943684	2524.3435
993	251540	RV	Nurchung Lama	Nurchung Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	77	519715	Kathmandu,Shank arapura-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803441437	85.595131	27.942503	2541.6675
994	251792	RV	Kesang Lama	Kesang Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	78	519716	Kathmandu,Kathm andu-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841256468	85.595238	27.942371	2516.4827
995	251542	RV	Mingyur Lama	Mingyur Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	79	519717	Kathmandu,Kathm andu-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9818216369	85.595215	27.94293	2531.6055
996	251544	RV	Tasi Dolma Lama	Tashi Dolma Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	82	519720	Kathmandu,Kathm andu-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803681797	85.596169	27.944969	2560.6077
997	251545	RV	Pemba Dolma Lama	Pemba Dolma Lama	Sindhupalchowk	Kiwool	7	0		Helambu	2	84	519722	Kathmandu,Shank arapura-9	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849671354	85.595314	27.945318	2578.5579
998	251588	RV	Son Temba Lama	Son Temba Lama	Sindhupalchowk	Kiwool	8	0		Helambu	2	18	519753	Kathmandu,Shank arapura-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841790168	85.58564	27.952715	2437.8525
999	251587	RV	Gopal Lama	Gopal Lama	Sindhupalchowk	Kiwool	8	0		Helambu	2	19	519754	Kathmandu,Kathm andu-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813503163	85.586082	27.952641	2459.925
1000	251463	RV	Karma Lama	Karma Lama	Sindhupalchowk	Kiwool	8	0		Helambu	2	21	519756			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	981341414	85.586006	27.952896	2456.5879
1001	251586	RV	Babusingi Lama	Babu Singi Lama	Sindhupalchowk	Kiwool	8	0		Helambu	2	22	519757	Kathmandu,Shank arapura-2	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808608246	85.585716	27.952953	2452.0237
1002	251461	RV	Dharmi Dolma Lama	Damchi Dolma Lama	Sindhupalchowk	Kiwool	8	0		Helambu	2	24	519758	Kathmandu,Kathm andu-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813667997	85.585686	27.953033	2461.176
1003	251482	RV	Kinjo Lama	Gyaljen Lama	Sindhupalchowk	Kiwool	8	0		Helambu	2	25	519759	Kathmandu,Kathm andu-6	No Damage	1	Grade 3	Major Repair	Grade 3	Grade 3	Grade 3	Grade 3	Major Repair	Habitable House in Other Place	9813849212	85.586014	27.952921	2474.1792
1004	251584	RV	Karma Wangel Lama	Kami Lama	Sindhupalchowk	Kiwool	8	0		Helambu	2	29	519763	Kathmandu,Shank arapura-2	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803362740	85.587799	27.952692	2457.8916
1005	251585	RV	Kale Lama	Kale Lama	Sindhupalchowk	Kiwool	8	0		Helambu	2	30	519764	Kathmandu,Shank arapura-9	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808735472	85.587654	27.95257	2464.5994
1006	251462	RV	Dame Lama	Dame Lama	Sindhupalchowk	Kiwool	8	0		Helambu	2	31	519765	Kathmandu,Shank arapura-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860847368	85.587433	27.952383	2456.7087
1007	251854	RV	Nima Dorje Lama	Nima Dorje Lama	Sindhupalchowk	Kiwool	8	0		Helambu	2	34	519768	Kathmandu,Shank arapura-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803041335	85.58754	27.952305	2455.9204
1008	251583	RV	Chhoi Dolma Lama	Lakpa Lama	Sindhupalchowk	Kiwool	8	0		Helambu	2	35	519769	Kathmandu,Shank arapura-2	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841074542	85.587288	27.952126	2424.9229
1009	251464	RV	Bibek Lama	Bibek Lama	Sindhupalchowk	Kiwool	8	0		Helambu	2	43	519678	Kathmandu,Shank arapura-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860711355	85.584785	27.958534	2610.0439
1010	251469	RV	Manju Lama	Kancha Lama	Sindhupalchowk	Kiwool	9	0		Helambu	2	7	519689	Kathmandu,Shank arapura-9	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9810378680	85.577011	27.949476	2302.5942
1011	251468	RV	Tasi Lama	Kancha Lama	Sindhupalchowk	Kiwool	9	0		Helambu	2	7	519691	Kathmandu,Shank arapura-9	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9810378680	85.577011	27.949476	2302.5942
1012	251467	RV	Kami Lama	Kami Lama	Sindhupalchowk	Kiwool	9	0		Helambu	2	8	519692	Kathmandu,Shank arapura-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808022355	85.576675	27.948444	2274.1602
1013	251471	RV	Lakpa Singi	Lakpa Singe Lama	Sindhupalchowk	Kiwool	9	0		Helambu	2	10	519694	Kathmandu,Shank arapura-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841291284	85.576706	27.948666	2280.2976
1014	251470	RV	Chenga Lama	Chenga Lama	Sindhupalchowk	Kiwool	9	0		Helambu	2	12	5196996	Kathmandu,Kathm andu-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841329662	85.576355	27.948721	2283.8362
1015	249783	RV	Phurpa Lama	Phurpa Lama	Sindhupalchowk	Kiwool	9	0		Helambu	2	18	398127	Kathmandu,Shank arapura-9	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808027682	85.576263	27.949968	2266.2729
1016	251597	RV	Sang Gyalbu Lama	Sang Gyalbu Lama	Sindhupalchowk	Kiwool	9	0		Helambu	2	19	398128	Kathmandu,Shank arapura-9	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808056313	85.576218	27.949945	2288.689
1017	251483	RV	Dame Lama	Dame Lama	Sindhupalchowk	Kiwool	9	0		Helambu	2	29	398140	Kathmandu,Mulpa ni-99	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803617703	85.577339	27.949263	2311.

1023	251474	RV	Dipak Lama	Dipak Lama	Sindhupalchowk	Kiwool	9	0		Helambu	2	76	398087		Sindhupalchowk,M elanchi-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843522170	85.563843	27.944326	1829.3916	
1024	251478	RV	Kumar Sunar	Kumar Sunar	Sindhupalchowk	Kiwool	9	0		Helambu	2	84	398095		Kathmandu,Kathmandu-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841457973	85.565155	27.944735	1880.2605	
1025	251379	RV	Jumu Lama	Jangmu Lama	Sindhupalchowk	Kiwool	9	0		Helambu	2	108	398119		Kathmandu,Shankarapura-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851068048	85.558189	27.950794	1759.5837	
1026	251657	RV	Karchung Lama	Karchung Lama, Tulku Lama	Sindhupalchowk	Kunchok	1	0		Indrawati	2	118	409224			No Damage	2	Grade 4, Grade 2	Major Repair , Minor Repair	Grade 2, Grade 2	Grade 3, Grade 2	Grade 3, Grade 2	Major Repair , Minor Repair	Habitable House in Usual Place	9810252702	85.653267, 85.653351	27.797935, 27.798393	1361.9309, 1363.9835	
1027	251656	RV	Mokshe Bikram Thakuri	Mochha Bikram Thakuri	Sindhupalchowk	Kunchok	1	0		Indrawati	2	125	328632			No Damage	2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Unrecognized, Grade 1	Unrecognized, Grade 1	Unrecognized, Not Required	Habitable House in Usual Place	9803947493	85.646339, 85.646416	27.802839, 27.802885	1426.674, 1433.9191	
1028	251778	RV	Lalit Bahadur Rana	Lalit Bahadur Ranamagar	Sindhupalchowk	Kunchok	1	0		Indrawati	2	147	508946		Sindhupalchowk,C hautara-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841542571	85.660736	27.794561	1366.8751	
1029	251694	RV	Urmila Malla Thakuri	Urmila Malla	Sindhupalchowk	Kunchok	2	0		Indrawati	2	15	409228		Kathmandu,Kathmandu-17	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849729322	85.646957	27.802454	1424.1281	
1030	251779	RV	Ram Bahadur Giri	Ram Bahadur Giri	Sindhupalchowk	Kunchok	2	0		Indrawati	2	25	409252			No Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843841591	85.653297	27.798174	1361.569	
1031	251690	RV	Nani Maiya Thakuri	Nani Maya Malla	Sindhupalchowk	Kunchok	2	0		Indrawati	2	142	409381			No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9818519382	85.645103	27.788282	1083.0615	
1032	251708	RV	Subhadra Bharati	Subhadra Bharati	Sindhupalchowk	Kunchok	3	0		Indrawati	2	15			Kathmandu,Goldh ung-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9818276112	85.662224	27.804506	1116.9474	
1033	251711	RV	Arjun Bahadur Bharati	Arjun Bahadur Bharati	Sindhupalchowk	Kunchok	3	0		Indrawati	2	17			Bhaktapur,Katunge -8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9823239901	85.662178	27.804569	1122.6348	
1034	251709	RV	Sher Bahadur Bharati	Sher Bahadur Bharati	Sindhupalchowk	Kunchok	3	0		Indrawati	2	34			Kathmandu,Tokha Saraswati-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841310580	85.66552	27.800915	1113.3706	
1035	251707	RV	Dhan Raj Bharati	Dhan Raj Bharati	Sindhupalchowk	Kunchok	3	0		Indrawati	2	49			Kathmandu,Kages wori-Manahara-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9818345233	85.664444	27.800907	1152.4379	
1036	251632	RV	Chitra Bahadur Thapamagar	Chitra Bahadur Thapamagar	Sindhupalchowk	Kunchok	4	0		Indrawati	2	153			Bhaktapur,Bhaktapur-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841514232	85.664825	27.791786	1201.2948	
1037	251636	RV	Basanta Giri	Basanta Giri	Sindhupalchowk	Kunchok	4	0		Indrawati	2	183				No Damage	1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818804059	85.666069	27.789557	1239.6331	
1038	251645	RV	Prem Bahadur Thapa	Prem Bahadur Thapa	Sindhupalchowk	Kunchok	5	0		Indrawati	3	29			Sindhupalchowk,C hautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741260210	85.667656	27.778116	1128.8336	
1039	251644	RV	Udeya Bahadur Thapa	Uday Bahadur Thapa	Sindhupalchowk	Kunchok	5	0		Indrawati	3	42			Sindhupalchowk,C hautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9816686898	85.668213	27.778381	1118.2234	
1040	251958	RV	Ram Bahadur Baniya	Ram Bahadur Baniya	Sindhupalchowk	Kunchok	8	0		Indrawati	3	12				No Damage	2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9803504111	85.662079, 85.663246	27.782932, 27.785181	1335.1515, 1365.5825	
1041	251930	RV	Bagh Singh Tamang	Bagh Singh Tamang, Nema Tamang	Sindhupalchowk	Kuvende	2	0			Chautara Sagachowgadhi Municipality	4	18	1177846			No Damage	2	Grade 3, Grade 1	Major Repair , Not Required	Grade 4, Grade 1	Grade 4, Grade 1	Grade 4, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9841924613	85.732964, 85.733025	27.77894, 27.778948	1237.7341, 1254.2391
1042	251932	RV	Nema Tamang	Bagh Singh Tamang, Nema Tamang	Sindhupalchowk	Kuvende	2	0			Chautara Sagachowgadhi Municipality	4	18	1177847			No Damage	2	Grade 3, Grade 1	Major Repair , Not Required	Grade 4, Grade 1	Grade 4, Grade 1	Grade 4, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9841924613	85.732964, 85.733025	27.77894, 27.778948	1237.7341, 1254.2391
1043	251936	RV	Gobinda Shrestha	Amber Bahadur Shrestha, Gobinda Shrestha	Sindhupalchowk	Kuvende	2	0			Chautara Sagachowgadhi Municipality	4	24	1177877			No Damage	2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9808610667	85.73082, 85.731651	27.779251, 27.779524	1242.2568, 1252.3832
1044	251892	RV	Bhuvan Singh Tamang	Bhuvan Singh Tamang	Sindhupalchowk	Kuvende	3	0			Chautara Sagachowgadhi Municipality	4	98	1177902			No Damage	2	Grade 4, Grade 1	Reconstruct, Not Required	Grade 4, Grade 1	Grade 4, Grade 1	Grade 4, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9818834606	85.736336, 85.736343	27.778454, 27.77849	1248.9556, 1265.01
1045	251905	RV	Sanu Maya Tamang	Sanu Maya Tamang	Sindhupalchowk	Kuvende	4	0			Chautara Sagachowgadhi Municipality	4	12	512948			No Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9860654580	85.739677	27.778469	1255.3571
1046	251783	RV	Megh Nath Sapkota	Megh Nath Sapkota	Sindhupalchowk	Kuvende	4	0			Chautara Sagachowgadhi Municipality	4	26	513934		Sindhupalchowk,C hautara-9	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849474050	85.749222	27.788404	832.90582
1047	251904	RV	Ganga Maya Shrestha	Ganga Maya Shrestha	Sindhupalchowk	Kuvende	4	0			Chautara Sagachowgadhi Municipality	4	58	512988		Sindhupalchowk,C hautara-7	Partial Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	984900071	85.745155, 85.746078	27.779808, 27.78084	1109.673, 1134.3945
1048	251898	RV	Siddi Bdr Shrestha	Jagat Bahadur Shrestha, Siddhi Bahadur Shrestha	Sindhupalchowk	Kuvende	4	0			Chautara Sagachowgadhi Municipality	4	59	512989			No Damage	2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9843184067	85.745705, 85.74646	27.78022, 27.780506	1119.9418, 1122.9714
1049	251906	RV	Sharan Bdr Shrestha	Bishnu Kumar Shrestha, Saran Bahadur Shrestha	Sindhupalchowk	Kuvende	4	0			Chautara Sagachowgadhi Municipality	4	74			Sindhupalchowk,C hautara-4	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9813851750	85.745178, 85.745224	27.779554, 27.779596	1138.6118, 1143.3004
1050	251899	RV	Nawaraj Shrestha	Nabaraj Shrestha	Sindhupalchowk	Kuvende	4	0			Chautara Sagachowgadhi Municipality	4	76	513956		Sindhupalchowk,C hautara-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843756532	85.74559	27.779337	1148.6256
1051	251903	RV	Jasman Tamang	Jasman Tamang	Sindhupalchowk	Kuvende	4	0			Chautara Sagachowgadhi Municipality	4	123	513982			No Damage	2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9818034212	85.738976, 85.739006	27.777761, 27.778299	1238.1329, 1273.0989
1052	251787	RV	Bhola Nath Sapkota	Bhola Nath Sapkota	Sindhupalchowk	Kuvende	5	0			Chautara Sagachowgadhi Municipality	4	135	512964		Sindhupalchowk,C hautara-5	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9861197176	85.750298	27.780645	996.40442
1053	251844	RV	Devi Prasad Sapkota	Devi Prasad Sapkota	Sindhupalchowk	Kuvende	7	0			Chautara Sagachowgadhi Municipality	4	44	368317			No Damage	2	Grade 1, Grade 4	Minor Repair, Reconstruct	Grade 1, Grade 4	Grade 1, Grade 4	Grade 1, Grade 4	Minor Repair, Reconstruct	Habitable House in Usual Place	9741260480	85.758919, 85.759033	27.775877, 27.77606	863.03058, 868.83441
1054	251719	RV	Bhagirath Sapkota	Bhagirath Sapkota	Sindhupalchowk	Kuvende	7	0			Chautara Sagachowgadhi Municipality	4	49	368321			No Damage	2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9843238556	85.759636, 85.760422	27.77728, 27.77351	888.99792, 891.03125
1055	251720	RV	Chandra Maya Nepal	Chandra Maya Nepal	Sindhupalchowk	Kuvende	7	0			Chautara Sagachowgadhi Municipality	4	70	368344			No Damage	1	Grade 1	Not Required	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.761818	27.775383	776.20612
1056	251723	RV	Bednath Sapkota	Bedh Nath Sapkota	Sindhupalchowk	Kuvende	7	0			Chautara Sagachowgadhi Municipality	4	86	368361		Bhaktapur,Bhaktapur-17	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741156736	85.759415	27.773716	887.86365
1057	251313	RV	Rudra Prasad Sapkota	Rudra Prasad Sapkota	Sindhupalchowk	Kuvende	8	0			Chautara Sagachowgadhi Municipality	4	7	368214			No Damage	2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9860068362	85.760185, 85.76033	27.772909, 27.773134	894.04767, 896.4325
1058	251725	RV	Lekh Nath Sapkota	Lekh Nath Sapkota	Sindhupalchowk	Kuvende	8	0			Chautara Sagachowgadhi Municipality	4	9	368216			No Damage	2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9741018393	85.759727, 85.759941	27.772898, 27.773046	889.3432, 903.2052
1059	251763	RV	Ranga Prasad Nepal	Ranga Prasad Nepal	Sindhupalchowk	Kuvende	8	0			Chautara Sagachowgadhi Municipality	4	14	368221		Bhaktapur,Balkot-9	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841285809	85.760201	27.772282	897.11786
1060	251762	RV	Om Nath Nepal	Om Nath Nepal	Sindhupalchowk	Kuvende	8	0			Chautara Sagachowgadhi Municipality	4	39	368247			No Damage	1	Grade 2	Minor Repair	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9843064293	85.760269	27.772371	897.05908
1061	251768	RV	Hima Devi Subedi	Hema Devi Subedi	Sindhupalchowk	Kuvende	9	0			Chautara Sagachowgadhi Municipality	4	1	368076		Sindhupalchowk,C hautara-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849013039	85.759857	27.763014	1075.5101
1062	251773	RV	Krishna Sharma	Krishna Prasad Sharma	Sindhupalchowk	Kuvende	9	0			Chautara Sagachowgadhi Municipality	4	26	368099		Kathmandu,Kages wori-Manahara-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9861061370	85.759109	27.763952	1062.8772
1063	251772	RV	Madhuka Sharma	Madhukar Sharma	Sindhupalchowk	Kuvende	9	0			Chautara Sagachowgadhi Municipality	4	36	368112		Sindhupalchowk,C hautara-9	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851009902	85.758492	27.764803	1050.1613

1064	249775	RV	Umesh Sharma (Swanr)	Umesh Sharma	Sindhupalchowk	Kuvende	9	0		Chautara Sagachowkgadhi Municipality	4	77	368157		Lalitpur,Godawari-2	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841651195	85.761787	27.763517	1006.2026
1065	251777	RV	Maheshor Swanr	Maheshwor Swar	Sindhupalchowk	Kuvende	9	0		Chautara Sagachowkgadhi Municipality	4	93	368174		Lalitpur,Imadol-3	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9860343548	85.761833	27.76335	1017.587
1066	250031	RV	Dhan Dorje Tamang	Dhan Dorje Tamang	Sindhupalchowk	Lagarche	2	0		Pachpokhari Thangpal	8	121					2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Minor Repair	Habitable House in Usual Place		85.634438, 85.634659	27.871145, 27.871153	1531.5559, 1536.949
1067	250036	RV	Patani Adhikari	patani adhikari	Sindhupalchowk	Lagarche	4	0		Pachpokhari Thangpal	8	25		Kathmandu,Gokar newar-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860196719	85.62796	27.85541	1561.0809	
1068	250046	RV	Indra Bahadur Bhujel	indra bahadur bhujel	Sindhupalchowk	Lagarche	6	0		Pachpokhari Thangpal	8	21		Sindhupalchowk,G hortthali-6	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841143443	85.622711	27.879856	1229.4089	
1069	250047	RV	Indramani Satyal	indra madhi satyal	Sindhupalchowk	Lagarche	6	0		Pachpokhari Thangpal	8	54		Kathmandu,Kapan-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741255305	85.619118	27.88084	1222.3787	
1070	250045	RV	Chandra Prasad Satyal	chandra prasad satyal	Sindhupalchowk	Lagarche	6	0		Pachpokhari Thangpal	8	65		Kathmandu,Kathmandu-1	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741022260	85.614876	27.879137	1224.7595	
1071	250043	RV	Purna Bahadur Shrestha	purna Shrestha	Sindhupalchowk	Lagarche	6	0		Pachpokhari Thangpal	8	83					2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Minor Repair	Habitable House in Usual Place	9741002337	85.614929, 85.614929	27.885487, 27.885576	887.53345, 892.89624
1072	249940	RV	Resham Bahadur Damai	resham bahadur damai	Sindhupalchowk	Lagarche	7	0		Pachpokhari Thangpal	8	32		Sindhupalchowk,V otenamlang-9	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9807651293	85.620148	27.879137	1222.6042	
1073	249932	RV	Ambar Bahadur Damai	amber bahadur damai	Sindhupalchowk	Lagarche	7	0		Pachpokhari Thangpal	8	62		Kathmandu,Budha nilkantha-99	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803553421	85.614952	27.868757	1297.7454	
1074	248131	RV	Siddhi Bajra Lama	Siddhi Bajra Lama	Sindhupalchowk	Lisankhu	1	0		Lisankhu Pakhar	2	43	406002	Kathmandu,Kathmandu-6	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9808800413	85.873779	27.642887	1661.8394	
1075	248130	RV	Singha Bahadur Tamang	Singh Bahadur Lama	Sindhupalchowk	Lisankhu	1	0		Lisankhu Pakhar	2	64	406026				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803319386	85.867996	27.639297	1784.7944
1076	255155	RV	Sonam Tamang	Sonam Tamsng	Sindhupalchowk	Listikot	1	0		Bhotekoshi	1	25	393461	Sindhupalchowk,T atopani-7	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843047966	85.916519	27.906013	1276.1805	
1077	255152	RV	Pasanga Sherpa	Pasang Sherpa	Sindhupalchowk	Listikot	1	0		Bhotekoshi	1	31	393467				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9614995396	85.915688	27.906158	1305.2689
1078	255800	RV	Tashi Sherpa	Tasi Sherpa	Sindhupalchowk	Listikot	1	0		Bhotekoshi	1	90	393320				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9616425733	85.902428	27.903534	2059.2729
1079	255806	RV	Pasang Dorje Sherpa	Pasang Dorje Sherpa	Sindhupalchowk	Listikot	3	0		Bhotekoshi	1	51	393391				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9614890125	85.891075	27.885172	1884.2108
1080	255807	RV	Aitebir Kami	Aite Bir Kami	Sindhupalchowk	Listikot	3	0		Bhotekoshi	1	90	392242				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9611096953	85.88443	27.888233	1950.2101
1081	255161	RV	Mingmar Tamang	Mingmar Tamang	Sindhupalchowk	Listikot	3	0		Bhotekoshi	1	101	1175252				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9741124421	85.881386	27.884563	1895.4426
1082	255171	RV	Hari Chandra Khatri	Harichandra Khatri	Sindhupalchowk	Listikot	4	0		Bhotekoshi	1	33	393227				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9810261876	85.884506	27.904413	2286.3491
1083	255046	RV	Gyaljen Lama	Gyaljen Lama	Sindhupalchowk	Listikot	4	0		Bhotekoshi	1	34	393229	Sindhupalchowk,T atopani-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741189607	85.88443	27.904514	2284.2932	
1084	255056	RV	Pasang Nurpu Sherpa	Pasang Nurpu Sherpa	Sindhupalchowk	Listikot	4	0		Bhotekoshi	1	38	393233				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9808411309	85.883476	27.904903	2280.3506
1085	255057	RV	Bachu Adhikari	Bachchu Adhikari	Sindhupalchowk	Listikot	4	0		Bhotekoshi	1	40	393235				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818529543	85.883064	27.904837	2290.5061
1086	255812	RV	Tenjenga Lama	Tenjeng Lama	Sindhupalchowk	Listikot	4	0		Bhotekoshi	1	44	393239				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9861192587	85.88047	27.905012	2354.8555
1087	255047	RV	Rame Lama	Rame Lama	Sindhupalchowk	Listikot	4	0		Bhotekoshi	1	46	393242				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741129655	85.881027	27.904152	2318.7415
1088	255054	RV	Lakhsang Tamangani	Lakhsang Tamangani	Sindhupalchowk	Listikot	4	0		Bhotekoshi	1	49	393245				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741196577	85.880775	27.904268	2337.5391
1089	255050	RV	Dhugel Sherpa	Dukgel Sherpa	Sindhupalchowk	Listikot	4	0		Bhotekoshi	1	60	393257				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741149753	85.880417	27.904715	2385.5181
1090	255783	RV	Nima Sange Lama	Nima Sangema Lama	Sindhupalchowk	Listikot	4	0		Bhotekoshi	1	82	393404				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818582596	85.878891	27.9032	2377.7791
1091	255788	RV	Dhan Bdr Pradhan	Dhan Bahadur Pradhan	Sindhupalchowk	Listikot	5	0		Bhotekoshi	1	16	1175207				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803250979	85.880569	27.884777	1874.3347
1092	255045	RV	Amrit Bdr Pradhan	Amrit Bahadur Pradhan	Sindhupalchowk	Listikot	5	0		Bhotekoshi	1	27	1175212				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9813382059	85.880249	27.884617	1867.8339
1093	255143	RV	Sil Kumari Pradhan	Sil Kumari Pradhan	Sindhupalchowk	Listikot	5	0		Bhotekoshi	1	30	1175215				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9823043358	85.881241	27.884014	1846.9441
1094	255172	RV	Khadka Bdr Pradhan	Kharg Bahadur Pradhan	Sindhupalchowk	Listikot	5	0		Bhotekoshi	1	69	1175256				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9843091041	85.883896, 85.891823	27.876942, 27.877731	1192.7698, 1420.8724
1095	253521	RV	Sunman Pradhan	Sunman Pradhan	Sindhupalchowk	Listikot	5	0		Bhotekoshi	1	93	1175280				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9810174896	85.891922	27.876829	1202.2632
1096	255170	RV	Umesh Bdr Pradhan	Umesh Bahadur Pradhan	Sindhupalchowk	Listikot	5	0		Bhotekoshi	1	94	1175281				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818989862	85.8918	27.876968	1190.0033
1097	255790	RV	Ganesh Bdr Pradhan	Ganesh Bahadur Pradhan	Sindhupalchowk	Listikot	5	0		Bhotekoshi	1	100	1175289				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9860128805	85.891701	27.877222	1198.134
1098	255791	RV	Masali Pradhan	Masali Pradhan	Sindhupalchowk	Listikot	5	0		Bhotekoshi	1	102	1175291				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9808289605	85.891464	27.877338	1191.3429
1099	255686	RV	Namgel Sherpa	Namgel Sherpa	Sindhupalchowk	Listikot	6	0		Bhotekoshi	1	12	518262	Sindhupalchowk,T atopani-3/Sindhupalchowk,Tatopani-4	No Damage, Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843168250	85.871719	27.895214	2273.6414	
1100	255148	RV	Ngima Sherpa	Ngima Sherpa	Sindhupalchowk	Listikot	6	0		Bhotekoshi	1	13	518263	Sindhupalchowk,T atopani-4	Partial Damage	1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Other Place	9841034597	85.870865	27.895317	2277.0762	
1101	255167	RV	Thiki Sherpa	Dhiki Sherpa	Sindhupalchowk	Listikot	6	0		Bhotekoshi	1	33	518284				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9860182252	85.871468	27.895754	2278.4993
1102	256685	RV	Tek Bdr Sherpa	Sangbu Sherpa, Tek Bahadur Sherpa	Sindhupalchowk	Listikot	6	0		Bhotekoshi	1	36	518287				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9849708423	85.870934	27.896019	2285.8379
1103	255785	RV	Klae Sherpa	Kale Sherpa	Sindhupalchowk	Listikot	6	0		Bhotekoshi	1	38	518289				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place		85.870918	27.89502	2282.7715
1104	255794	RV	Rinjen Sherpa	Rinjen Sherpa	Sindhupalchowk	Listikot	6	0		Bhotekoshi	1	44	518296				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9843373702	85.870537	27.895269	2279.8337
1105	255795	RV	Dorje Tamang	Dorje Tamang	Sindhupalchowk	Listikot	6	0		Bhotekoshi	1	47	518299				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9843252004	85.871368	27.895546	2278.3105
1106	255131	RV	Bude Tamang	Budde Tamang	Sindhupalchowk	Listikot	6	0		Bhotekoshi	1	49	518826				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9860174877			
1107	255136	RV	Sambhu Sherpa	Shambhu Sherpa	Sindhupalchowk	Listikot	6	0		Bhotekoshi	1	57	518834				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9843546081	85.870415	27.895752	2297.3779
1108	255169	RV	Norke Sherpa	Norke Sherpa	Sindhupalchowk	Listikot	6	0		Bhotekoshi	1	61	518838				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9614485125	85.87162	27.895395	2273.241
1109	250705	RV	Chenga Snuu Sherpa	Chenga Sherpa	Sindhupalchowk	Listikot	6	0		Bhotekoshi	1	85	518868				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9813704233	85.870728	27.895679	2281.9915
1110	255159	RV	Padam Bdr Pradhan	Padam Bahadur Pradhan	Sindhupalchowk	Listikot	6	0		Bhotekoshi	1	92	518859				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9616650206			
1111	255787	RV	Man Bdr Pradhan	Man Bahadur Pradhan	Sindhupalchowk	Listikot	6	0		Bhotekoshi	1	96	518878				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9621171480	85.872574	27.894009	2252.4375
1112	255158	RV	Ram Bdr Shrestha	Ram Bahadur Shrestha	Sindhupalchowk	Listikot	6	0		Bhotekoshi	1	98	51880				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1						

1113	255784	RV	Nima Sherpa	Nima Sherpa	Sindhupalchowk	Listikot	6	0		Bhotekoshi	1	176	518639			1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9860608657	85.87191	27.894356	2252.9961
1114	250725	RV	Dhan Maya Pradhan	Dhan Maya Pradhan	Sindhupalchowk	Listikot	6	0		Bhotekoshi	1	183	521107			1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9818435534	85.874725	27.89465	2208.2642
1115	255144	RV	Ganga Bdr Newar	Ganga Bahadur Newar	Sindhupalchowk	Listikot	9	0		Bhotekoshi	1	9	521046			1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9860663617	85.857964	27.917915	2235.6628
1116	255797	RV	Tilak Bdr Newar	Tilak Bahadur Newar	Sindhupalchowk	Listikot	9	0		Bhotekoshi	1	77	518524			1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9860512092	85.849503	27.912579	2042.8528
1117	255799	RV	Man Bdr Pradhan	Man Bahadur Pradhan	Sindhupalchowk	Listikot	9	0		Bhotekoshi	1	78	518525			1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849921498	85.849434	27.912468	2040.9963
1118	255139	RV	Rana Bdr Pradhan	Rana Bahadur Pradhan	Sindhupalchowk	Listikot	9	0		Bhotekoshi	1	81	518979			1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9810307527	85.859406	27.916769	2271.8733
1119	253678	RV	Dan Prasad Lamsal	Dhan Prasad Lamsal	Sindhupalchowk	Mahangkal	9	0	sera	Helambu	4	71	543952			2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 5	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	16912804	85.539429, 85.539963	27.894558, 27.895279	1040.9784, 992.9599
1120	257415	RV	Bishu Bahadur Gurung	Bisnu Bahadur Gurung	Sindhupalchowk	Maneshowara	2	0	Sanbari	Barhabise Municipality	8	102	556605	Kathmandu,Budha nikantha-11	Partial Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9843282262	85.86293	27.821932	1361.0803
1121	257380	RV	Gopini Gurung	Gopine Gurung	Sindhupalchowk	Maneshowara	2	0	Sangbari	Barhabise Municipality	8	118	556622	Sindhupalchowk,R amche-7	Partial Damage	4	Grade 5, Grade 5, Grade 5	Reconstruct, Reconstruct, Reconstruct	Grade 5, Grade 5, Grade 5	Grade 5, Grade 5, Grade 5	Grade 5, Grade 5, Grade 5	Reconstruct, Reconstruct, Reconstruct	Habitable House in Other Place	9741184629	85.863777, 85.863846	27.822567, 27.822788	1338.3162, 1340.7212
1122	254456	RV	Harka Bahadur Tamang	Harka Bahadur Tamang	Sindhupalchowk	Maneshowara	3	0	Goletole	Barhabise Municipality	8	31	556314	Sindhupalchowk,M aneshowara-5	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9621175453	85.870049	27.806866	1486.1565
1123	257353	RV	Nanda Maya Bhujel	Gokul Bahadur Bhujel	Sindhupalchowk	Maneshowara	6	0	Katunje	Barhabise Municipality	8	20	556701	Sindhupalchowk,M ansha-6	Partial Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9843167477	85.875	27.800266	1640.0231
1124	250215	RV	Yamuna Dhital	Bimal Prashad Paudel	Sindhupalchowk	Maneshowara	6	0	Paudelgau	Barhabise Municipality	8	24	556705	Bhaktapur,Madhya pur Thimi-17	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841902848	85.879852	27.800287	1408.0837
1125	254598	RV	Kumar Adhikari	Kumar Adhikari	Sindhupalchowk	Maneshowara	9	0	Jambu	Barhabise Municipality	8	28	556684			2	Grade 2, Grade 2	Minor Repair, Minor Repair	Grade 3, Grade 3	Grade 2, Grade 2	Grade 2, Grade 2	Minor Repair, Minor Repair	Habitable House in Usual Place	9616363876	85.880264	27.817039	860.60022
1126	257378	RV	Ramji Adhikari	Ramji Adhikari	Sindhupalchowk	Maneshowara	9	0	Jambu	Barhabise Municipality	8	29	556685			2	Grade 2, Grade 2	Minor Repair, Minor Repair	Grade 3, Grade 3	Grade 2, Grade 2	Grade 2, Grade 2	Minor Repair, Minor Repair	Habitable House in Usual Place	9621175700	85.880318	27.816839	906.55676
1127	257414	RV	Subba Adhikari	Subba Adhikari	Sindhupalchowk	Maneshowara	9	0	Sugure	Barhabise Municipality	8	30	556686			2	Grade 2, Grade 2	Minor Repair, Minor Repair	Grade 3, Grade 3	Grade 2, Grade 2	Grade 2, Grade 2	Minor Repair, Minor Repair	Habitable House in Usual Place	9621178283	85.880119	27.817074	892.52594
1128	257387	RV	Usa Adhikari	Bel Bahadur Adhikari	Sindhupalchowk	Maneshowara	9	0	Jambu	Barhabise Municipality	8	32	556688			2	Grade 2, Grade 2	Minor Repair, Minor Repair	Grade 3, Grade 3	Grade 2, Grade 2	Grade 2, Grade 2	Minor Repair, Minor Repair	Habitable House in Usual Place	9851054480	85.880646	27.817123	886.77997
1129	257352	RV	Kaji Tamang	Mingama Lama	Sindhupalchowk	Maneshowara	9	0	Jambu	Barhabise Municipality	8	37	556693			2	Grade 2, Grade 2	Minor Repair, Minor Repair	Grade 3, Grade 3	Grade 2, Grade 2	Grade 2, Grade 2	Minor Repair, Minor Repair	Habitable House in Usual Place	9614937615	85.880562	27.816832	878.31689
1130	257384	RV	Sabitri Basset(Tiwari)	Raj Kumar Tiwari	Sindhupalchowk	Maneshowara	9	0	Eklebesi	Barhabise Municipality	8	49	540706			2	Grade 2, Grade 2	Minor Repair, Minor Repair	Grade 3, Grade 3	Grade 2, Grade 2	Grade 2, Grade 2	Minor Repair, Minor Repair	Habitable House in Usual Place	9841956399	85.888206	27.802063	1122.3518
1131	257474	RV	Ram Chandra Adhikari	Ratna Kumari Adhikari	Sindhupalchowk	Maneshowara	9	0	Jambu	Barhabise Municipality	8	97	556333	23-45-9-0-87		2	Grade 5, Grade 5	Reconstruct, Reconstruct	Unrecognized, Unrecognized	Unrecognized, Unrecognized	Unrecognized, Unrecognized	Unrecognized, Unrecognized	Matrix & Photo not cleared or mismatch	9621175680			
1132	253140	RV	Mandira Shrestha	Mandira Shrestha	Sindhupalchowk	Mankha	1	0		Bhalephi	8	493				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741010875	85.85154	27.757225	735.25806
1133	253019	RV	Hari Ram Parajuli	Hari Ram Parajuli	Sindhupalchowk	Mankha	6	0		Bhalephi	7	70		Makwanpur,Maka wanpurgadhi-2	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 4, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9841937673	85.83136, 85.831375	27.760201, 27.760218	824.99945, 833.35468
1134	252947	RV	Hareean Parajuli	Hari Ram Parajuli	Sindhupalchowk	Mankha	6	0		Bhalephi	7	78		Bhaktapur,Madhya pur Thimi-16	No Damage	1	Grade 3	Major Repair	Grade 3	Grade 3	Grade 3	Major Repair	Habitable House in Other Place	9741036049	85.831909	27.759901	839.33087
1135	252986	RV	Narayan Sharma Chaulagain	Narayan Sharma Chaulagai	Sindhupalchowk	Mankha	9	0		Bhalephi	6	100		Sindhupalchowk,M ansha-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9841094107	85.83156	27.762859	1077.4778
1136	256659	RV	Arjun Bdr. Adhikari	Arjun Adhikari	Sindhupalchowk	Nawalpur	1	0		Indrawati	4	40	360440	Sindhupalchowk,N awalpur-5	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808253034	85.635696	27.803724	1333.8319
1137	256722	RV	Maiya Adhikari	Maiya Adhikari	Sindhupalchowk	Nawalpur	1	0		Indrawati	4	42	360461	Sindhupalchowk,N awalpur-5	Partial Damage	1	Grade 5	Reconstruct	Grade 4	Grade 4	Grade 5	Reconstruct	Habitable House in Other Place	9818483292	85.635704	27.803915	1340.5721
1138	256715	RV	Subhadra Adhikari	Suvadra Adhikari	Sindhupalchowk	Nawalpur	1	0		Indrawati	4	62	360468	Sindhupalchowk,N awalpur-5	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808975571	85.636459	27.803953	1343.9843
1139	256586	RV	Chini Bdr. Shrestha	Chini Bahadur Shrestha	Sindhupalchowk	Nawalpur	3	0		Indrawati	4	1	363548	Kathmandu,Tarkes wor-1/Sindhupalchowk, Nawalpur-3/Sindhupalchowk, Nawalpur-3	Complete Damage, Complete Damage, No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9844822872	85.639114	27.801184	1374.0685
1140	256771	RV	Pravakar Shrestha	Kamala Devi Shrestha	Sindhupalchowk	Nawalpur	3	0		Indrawati	4	15	363564	Lalitpur,Jmadol-9	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851133118	85.639168	27.800827	1368.5458
1141	256875	RV	Himal Shrestha	Bikash Shrestha	Sindhupalchowk	Nawalpur	3	0		Indrawati	4	17	363566	Lalitpur,Lalitpur-9/Lalitpur,Lalitpur-9/Lalitpur,Lalitpur-9	No Damage, No Damage, No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808847378	85.639023	27.801065	1363.2911
1142	256594	RV	Surya Bdr. Shrestha	Ram Bhakta Shrestha	Sindhupalchowk	Nawalpur	3	0		Indrawati	4	21	363570	Sindhupalchowk,N awalpur-5	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9810031259	85.639	27.800529	1364.2784
1143	251441	RV	Laxmi Adhikari	Laxmi Adhikari	Sindhupalchowk	Nawalpur	3	0		Indrawati	4	30	363583	Sindhupalchowk,N awalpur-2	Complete Damage	1	Grade 1	Not Required	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9818115605	85.637939	27.801874	1339.0491
1144	256710	RV	Ram Chandra Dahal	Bishownath Dahal, Ramchandra Dahal	Sindhupalchowk	Nawalpur	4	0		Indrawati	4	10	557045	23-50-4-0-10		1	Grade 4	Reconstruct	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9810132787	85.606056	27.813654	1213.3363
1145	256733	RV	Shambhu Pd. Koirala	Shambu Prasad Koirala	Sindhupalchowk	Nawalpur	4	0		Indrawati	4	134	557165	Kathmandu,Gokar neswor-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841507060	85.602829	27.807673	1350.7285
1146	256786	RV	Puskar Pd. Khanal	Puspakar Prasad Dahal	Sindhupalchowk	Nawalpur	4	0		Indrawati	4	166	557208			2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9813960902	85.610329, 85.610466	27.807108, 27.807198	1447.1934, 1459.3298
1147	256870	RV	Krishna Prasad Bhattarai	Krishna Prasad Bhattarai	Sindhupalchowk	Nawalpur	5	0		Indrawati	4	21	554384			1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9808833691	85.621384	27.797255	1396.4033
1148	256534	RV	Gita Bhattarai	Gita Bhattarai	Sindhupalchowk	Nawalpur	5	0		Indrawati	4	69	554455	Sindhupalchowk,N awalpur-4	Complete Damage	1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9813981614	85.622833	27.81015	1566.2318
1149	256787	RV	Gyaneshwori Shrestha	Gayneswori Shrestha	Sindhupalchowk	Nawalpur	5	0		Indrawati	4	77	554463			1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9617876531	85.621681	27.809944	1555.8107
1150	256531	RV	Bishwonath Sapkota	Biswo Nath Sapkota	Sindhupalchowk	Nawalpur	6	0		Indrawati	4	2	554468	Sindhupalchowk,N awalpur-6	Partial Damage	1	Grade 4	Major Repair	Grade 4	Grade 3	Grade 4	Reconstruct	Habitable House in Other Place	9860846265	85.614952	27.824093	1525.7704
1151	256650	RV	Patali Tamang	Patali Tamang	Sindhupalchowk	Nawalpur	6	0		Indrawati	4	43	554836			1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9741005872	85.622597	27.813686	1578.9502
1152	256533	RV	Suntali Nakarmi	Suntali Nakarmi, Tika Ram Nakarmi	Sindhupalchowk	Nawalpur	6	0		Indrawati	4	66	554868	23-50-6-0-58		1	Grade 4	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9823170044	85.623848	27.812201	1588.0487
1153	256781	RV	Chandra Kumari Nakarmi	Chandra Kumari Nakarmi	Sindhupalchowk	Nawalpur	6	0		Indrawati	4	80	554883			2	Grade 2, Grade 2	Minor Repair, Minor Repair	Grade 1, Grade 1	Grade 4, Grade 1	Grade 4, Grade 1	Reconstruct, Minor Repair	Habitable House in Usual Place	9808975594	85.624527, 85.624557	27.812742, 27.812798	1603.2924, 1612.4589
1154	256599	RV	Sanukaji Lama	Sanu Kaji	Sindhupalchowk	Nawalpur	6	0		Indrawati	4	85	554888			1	Grade 2	Minor Repair	Grade 2	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9808420589	85.625015	27.812931	1606.6864
1155	256790	RV	Dipak Khadka	Deepak Khadka	Sindhupalchowk	Nawalpur	6	0		Indrawati	4	119	554927			1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9801033620	85.62159	27.811132	1561.392
1156	256709	RV	Tirthakaji Shrestha	Tirtha Kaji Shrestha	Sindhupalchowk	Nawalpur	6	0		Indrawati	4	125	554929	Kavrepalanchowk, Banepa-6	Partial Damage	3	Grade 1, Grade 3, Grade 4	Minor Repair, Minor Repair, Major Repair	Grade 1, Grade 1, Grade 2	Unrecognized, Unrecognized, Grade 4	Unrecognized, Unrecognized, Grade 4	Unrecognized, Unrecognized, Reconstruct	Habitable House in Other Place	9751010137	85.621414, 85.621536, 85.624992	27.810781, 27.810928, 27.813473	1567.833, 1572.2567, 1609.2014

1157	256725	RV	Sukumaya Lama	Urgan Lama	Sindhupalchowk	Nawalpur	8	0			Indrawati	4	13	363689					2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9803193926	85.627571, 85.627686	27.82585, 27.826206	1835.3533, 1835.8468	
1158	256699	RV	Patali Tamang	Patali Tamang	Sindhupalchowk	Nawalpur	8	0			Indrawati	4	93	1177690					2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9813943528	85.629921, 85.629929	27.817713, 27.817841	1769.5122, 1778.5784	
1159	256698	RV	Ramsani Lamini	Ramsani Lamini	Sindhupalchowk	Nawalpur	8	0			Indrawati	4	96	1177694					1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9803226939	85.628151	27.815935	1699.1917	
1160	256704	RV	Sunil Tamang	Sunil Tamang	Sindhupalchowk	Nawalpur	9	0			Indrawati	4	26	363439					1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9810394480	85.634171	27.824196	1558.1014	
1161	256780	RV	Sarki Tamang	Sarki Tamang	Sindhupalchowk	Nawalpur	9	0			Indrawati	4	95	363613					1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9812815697	85.641212	27.810139	1506.4314	
1162	256803	RV	Sanchamai Tamang	Chamara Tamang	Sindhupalchowk	Nawalpur	9	0			Indrawati	4	97	363614					1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9810372069	85.640854	27.810591	1509.8193	
1163	256593	RV	Suraj Adhikari	Sita Adhikari	Sindhupalchowk	Nawalpur	9	0			Indrawati	4	105	363622		Kathmandu,Kageswori-Manahara-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843696288	85.646133	27.805426	1418.6018	
1164	256661	RV	Madhab Adhikari	Madhab Adhikari	Sindhupalchowk	Nawalpur	9	0			Indrawati	4	107	363624		Sindhupalchowk,K unchok-1	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803520928	85.645943	27.805187	1417.4436	
1165	256791	RV	Arjun Bdr. Adhikari	Arjun Bahadur Adhikari	Sindhupalchowk	Nawalpur	9	0			Indrawati	4	108	363625		Sindhupalchowk,K unchok-1	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803887517	85.646057	27.805269	1416.8276	
1166	256785	RV	Thakur Bdr. Adhikar	Thakur Bahadur Adhikari	Sindhupalchowk	Nawalpur	9	0			Indrawati	4	128	363650					2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9808975593	85.640617, 85.644943	27.804398, 27.804626	1448.423, 1461.766	
1167	256668	RV	Raj Kumar Adhikari	Raj Kumar Adhikari	Sindhupalchowk	Nawalpur	9	0			Indrawati	4	132	363654		Sindhupalchowk,C hautara-9	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808136127	85.644745	27.804407	1451.7283	
1168	256728	RV	Min Bdr. Adhikari	Min Bahadur Adhikari	Sindhupalchowk	Nawalpur	9	0			Indrawati	4	150	363674					1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9803381866	85.640617	27.804445	1468.6997	
1169	256707	RV	Krishna Bdr. Adhikari	Krishna Bahadur Adhikari	Sindhupalchowk	Nawalpur	9	0			Indrawati	4	151	363675					1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9813826411	85.640472	27.804617	1470.4686	
1170	252609	RV	Yubraj Giri	Yubraj Giri	Sindhupalchowk	Palchowk	2	0			Helambu	3	42						1	Grade 2	Minor Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9860329844	85.543694	27.877123	955.55133	
1171	252640	RV	Purna Bahadur Giri	Purna Bahadur Giri	Sindhupalchowk	Palchowk	2	0			Helambu	3	84						1	Grade 1	Not Required	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch					
1172	252636	RV	Chyame Kami	Chyame Kami	Sindhupalchowk	Palchowk	3	0			Helambu	3	50			Kathmandu,Kathmandu-6	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place		85.562653	27.885792	1708.6866	
1173	252612	RV	Jit Bahadur Kami	Jaglal Kami, Jit Bahadur Kami	Sindhupalchowk	Palchowk	3	0			Helambu	3	54			Kathmandu,Kapan-1	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9818529683	85.561096	27.887405	1633.1869	
1174	252486	RV	Purna Tamang	Purna Tamang	Sindhupalchowk	Palchowk	5	0			Helambu	3	33						3	Grade 4, Grade 3, Grade 2	Reconstruct, Major Repair, Minor Repair	Grade 4, Grade 3, Grade 3	Grade 3, Unrecognized, Unrecognized	Grade 3, Unrecognized, Unrecognized	Major Repair, Unrecognized, Unrecognized	Matrix & Photo not cleared or mismatch	9813766991	85.561089, 85.563622, 85.563637	27.890448, 27.892418, 27.892447	1552.4429, 1558.5291, 1564.0964	
1175	252619	RV	Mangale Tamang	Mangale Tamang	Sindhupalchowk	Palchowk	7	0			Helambu	3	32						1	Grade 2	Minor Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9808763354	85.567131	27.894224	1628.4546	
1176	252605	RV	Dukpa Lama	Dukpa Lama	Sindhupalchowk	Palchowk	9	0			Helambu	3	2			Kathmandu,Kathmandu-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851006400	85.582733	27.905067	2171.2576	
1177	252607	RV	Pemba Lama	Pemba Lama	Sindhupalchowk	Palchowk	9	0			Helambu	3	20			Kathmandu,Shank arapura-7	Partial Damage	1	Grade 3	Major Repair	Grade 3	Grade 3	Grade 3	Grade 3	Major Repair	Habitable House in Other Place	9841839219	85.582275	27.904661	2152.4426	
1178	252627	RV	Phurpa Lama	Phurpa Lama	Sindhupalchowk	Palchowk	9	0			Helambu	3	26						1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849399164	85.581139	27.904648	2118.4089
1179	252642	RV	Dame Lama	Dame Lama	Sindhupalchowk	Palchowk	9	0			Helambu	3	36						1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9860275842	85.581009	27.905106	2119.0095
1180	250358	RV	Sitamai Timalisina	Sita Mai Timalisina	Sindhupalchowk	Pangretar	1	0			Sunkoshi	7	30	363790		Kathmandu,Kathmandu-35	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851008862	85.856468	27.747488	1060.4639	
1181	250351	RV	Bimal Timalisina	Bimal Timalisina	Sindhupalchowk	Pangretar	1	0			Sunkoshi	7	33	363793					2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 2	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Minor Repair	Habitable House in Usual Place	9841105382	85.849968, 85.85643	27.744745, 27.755409	1065.3276, 1715.36035	
1182	250362	RV	Ishwori Prasad Timalisina	Ishwori Prasad Timalisina	Sindhupalchowk	Pangretar	1	0			Sunkoshi	7	38	363798		Bhaktapur,Bhaktapur-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849384605	85.849312	27.749989	893.69867	
1183	250365	RV	Dhruva Prasad Timalisina	Dhruva Prasad Timalisina	Sindhupalchowk	Pangretar	1	0			Sunkoshi	7	44	397079					2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9860298547	85.846436, 85.849564	27.749374, 27.751442	794.15979, 915.12463	
1184	247811	RV	Khika Parajuli	Khika Prasad Parajuli	Sindhupalchowk	Pangretar	1	0			Sunkoshi	7	45	397080		Kathmandu,Kathmandu-35/Kathmandu,Kathmandu-35	No Damage, Partial Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9849544033	85.849968, 85.849991	27.746197, 27.746227	1028.2651, 1036.7633	
1185	250359	RV	Jhata Kumari Timalisina	Jhat Kumari Timalisina	Sindhupalchowk	Pangretar	1	0			Sunkoshi	7	50	397085		Bhaktapur,Madhyapur Thimi-7	Partial Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9849172213	85.84938, 85.84938	27.749012, 27.74905	892.62384, 898.20209	
1186	250366	RV	Bhakta Bir Bhujel	Bhakta Bir Bhujel	Sindhupalchowk	Pangretar	1	0			Sunkoshi	7	54	397090					2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 3	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place		85.846527, 85.849777	27.748114, 27.751202	793.75098, 942.63983	
1187	250367	RV	Madhav Bhujel	Bhakta Bir Bhujel	Sindhupalchowk	Pangretar	1	0			Sunkoshi	7	54	397091					2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 3	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place		85.846527, 85.849777	27.748114, 27.751202	793.75098, 942.63983	
1188	250313	RV	Chetnath Timalisina	Chet Nath Timalisina	Sindhupalchowk	Pangretar	1	0			Sunkoshi	7	63	397100					2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 3	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place		85.849625, 85.850693	27.749252, 27.755404	721.300, 906.33606	
1189	250316	RV	Rajkumar Shrestha	Rajkumar Shrestha	Sindhupalchowk	Pangretar	1	0			Sunkoshi	7	83	397444					3	Grade 5, Grade 2, Grade 5	Reconstruct, Minor Repair, Reconstruct	Grade 5, Grade 3, Grade 5	Grade 5, Grade 2, Grade 5	Grade 5, Grade 2, Grade 5	Reconstruct, Minor Repair, Reconstruct	Habitable House in Usual Place	9849012726	85.850311, 85.850349, 85.850365	27.755442, 27.755512, 27.755592	706.25684, 718.38434, 719.45538	
1190	250354	RV	Shakti Shrestha	Shakti Shrestha	Sindhupalchowk	Pangretar	1	0			Sunkoshi	7	85	397449					3	Grade 2, Grade 5, Grade 5	Minor Repair, Reconstruct, Reconstruct	Grade 1, Grade 5, Grade 5	Unrecognized, Grade 5	Unrecognized, Grade 5, Grade 5	Unrecognized, Reconstruct	Matrix & Photo not cleared or mismatch	9851061582	85.850388, 85.850418, 85.850784	27.755259, 27.755291, 27.755482	727.67719, 730.33765, 730.92841	
1191	250352	RV	Sukdev Timalisina	Sukudev Timalisina	Sindhupalchowk	Pangretar	1	0			Sunkoshi	7	86	397450		Kathmandu,Kathmandu-35	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841395288	85.850586	27.754734	742.15356	
1192	250315	RV	Kalika Karki	Kalika Karki, Narayan Karku	Sindhupalchowk	Pangretar	1	0			Sunkoshi	7	99	397486		23-51-1-0-81			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9841956440	85.848915	27.754002	730.62445	
1193	250369	RV	Pradip Kumar Karki	Pradip Kumar Karki	Sindhupalchowk	Pangretar	1	0			Sunkoshi	7	100	397488					1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849921009	85.849075	27.754084	709.79749	
1194	250368	RV	Chitra Kumar Mijar	Chitra Kumar Mijar	Sindhupalchowk	Pangretar	1	0			Sunkoshi	7	101	397489					1	Grade 2	Minor Repair	Grade 4	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849921130	85.850578	27.755487	731.73981	
1195	250350	RV	Jit Bahadur Pahari	Jit Bahadur Pahari	Sindhupalchowk	Pangretar	1	0			Sunkoshi	7	117	398455					1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9802719651	85.845261	27.751698	780.44342	
1196	250775	RV	Shree Krishna Rokka</																												

1204	250302	RV	Yam Bahadur Karki	Yam Bahadur Karki	Sindhupalchowk	Pangretar	5	0		Sunkoshi	7	61	394612			1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818830433	85.838913	27.750259	817.03784	
1205	250299	RV	Lkrishna Bahadur Karki	Krishna Bahadur Karki	Sindhupalchowk	Pangretar	5	0		Sunkoshi	7	70	394622			2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9751015829	85.83931, 85.839813	27.751417, 27.751715	745.84491, 755.30853	
1206	250303	RV	Rishiram Parajuli	Rishi Ram Parajuli	Sindhupalchowk	Pangretar	5	0		Sunkoshi	7	74	397911		Lalitpur,Lalitpur-14	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851110902	85.845177	27.748667	878.63647
1207	250683	RV	Dan Bahadur Karki	Dan Bahadur Karki	Sindhupalchowk	Pangretar	6	0		Sunkoshi	7	1	394626		Kathmandu,Kathmandu-99	No Damage	2	Grade 5, Grade 5	Reconstruct, Not Required	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Not Required	Habitable House in Other Place	9741171455	85.837585, 85.837753	27.750195, 27.750237	827.81586, 843.28052
1208	250308	RV	Mohan Bahadur Ghartichhetri	Mohan Bahadur Gharti Chhetrae	Sindhupalchowk	Pangretar	6	0		Sunkoshi	7	7	394634		Bhaktapur,Bhaktapur-12	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	11495055	85.837669	27.749838	835.27515
1209	250307	RV	Dor Bahadur Karki	Dor Bahadur Karki, Narayan Bahadur Karki	Sindhupalchowk	Pangretar	6	0		Sunkoshi	7	8	394636				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9843331038	85.835724, 85.836113	27.750532, 27.751488	760.1181, 817.78198
1210	250306	RV	Narayan Bahadur Karki	Dor Bahadur Karki, Narayan Bahadur Karki	Sindhupalchowk	Pangretar	6	0		Sunkoshi	7	8	394635				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9843331038	85.835724, 85.836113	27.750532, 27.751488	760.1181, 817.78198
1211	250677	RV	Bhakta Bahadur Nepal	Bhakta Bahadur Nepal	Sindhupalchowk	Pangretar	6	0		Sunkoshi	7	20	394648		Bhaktapur,Bhaktapur-15	Partial Damage	2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Minor Repair	Habitable House in Other Place	9851013423	85.837135, 85.837143	27.75186, 27.751921	767.57556, 769.60187
1212	250684	RV	Ananda Karki	Shankar Karki	Sindhupalchowk	Pangretar	6	0		Sunkoshi	7	21	394534		Kathmandu,Kathmandu-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841312731	85.835785	27.75119	799.26685
1213	250685	RV	Shankar Karki	Shankar Karki	Sindhupalchowk	Pangretar	6	0		Sunkoshi	7	21	394649		Kathmandu,Kathmandu-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841312731	85.835785	27.75119	799.26685
1214	250688	RV	Laxman Karki	Laxman Karki, Madhukar Karki, Ram Chantra Karki	Sindhupalchowk	Pangretar	6	0		Sunkoshi	7	24	394529		Bhaktapur,Bhaktapur-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813120372	85.836815	27.752247	767.93677
1215	250686	RV	Madhukar Karki	Laxman Karki, Madhukar Karki, Ram Chantra Karki	Sindhupalchowk	Pangretar	6	0		Sunkoshi	7	24	394528		Bhaktapur,Bhaktapur-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813120372	85.836815	27.752247	767.93677
1216	249336	RV	Ramchandra Karki	Laxman Karki, Madhukar Karki, Ram Chantra Karki	Sindhupalchowk	Pangretar	6	0		Sunkoshi	7	24	394527		Bhaktapur,Bhaktapur-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813120372	85.836815	27.752247	767.93677
1217	250679	RV	Man Kumari Karki	Man Kumari Karki	Sindhupalchowk	Pangretar	6	0		Sunkoshi	7	25	394530				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9806014391	85.836502, 85.836708	27.752075, 27.752111	765.72119, 775.04572
1218	250676	RV	Tara Bahadur Karki	Tara Bahadur Karki	Sindhupalchowk	Pangretar	6	0		Sunkoshi	7	28	394535				3	Grade 5, Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 5, Grade 1	Grade 5, Grade 5, Grade 1	Grade 5, Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9841902618	85.835793, 85.835823, 85.836052	27.752434, 27.752506, 27.752539	752.64105, 757.3692, 758.82227
1219	250678	RV	Padam Nath Nepal	Padam Nath Nepal	Sindhupalchowk	Pangretar	6	0		Sunkoshi	7	31	394538				1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803281795	85.834648	27.753033	758.69513
1220	250689	RV	Rama Devi Dhartichhetri	Rama Devi Gharti Chhetri	Sindhupalchowk	Pangretar	6	0		Sunkoshi	7	58	394992				1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9851048035	85.834778	27.752831	756.80273
1221	250691	RV	Yasoda Kami	Yasoda Kami	Sindhupalchowk	Pangretar	6	0		Sunkoshi	7	59	394993				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9741017450	85.833244, 85.833412	27.748909, 27.749023	964.9068, 965.65137
1222	250681	RV	Bikram Sunuwar	Bikram Sunuwar	Sindhupalchowk	Pangretar	6	0		Sunkoshi	7	67	397001				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9860864113	85.832428	27.748135	992.52496
1223	250567	RV	Sitaram Karki	Sita Ram Karki	Sindhupalchowk	Pangretar	7	0		Sunkoshi	7	9	397015		Sindhupalchowk,Pangretar-1	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741017561	85.830322	27.74716	1029.059
1224	250571	RV	Chitra Bahadur Karki	Chitra Bahadur Karki	Sindhupalchowk	Pangretar	7	0		Sunkoshi	7	42	397050		Kathmandu,Kathmandu-34	Partial Damage	2	Grade 5, Grade 5	Reconstruct, Not Required	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Not Required	Habitable House in Other Place	9741051206	85.832191, 85.832298	27.751179, 27.751183	858.75555, 860.88434
1225	250573	RV	Chandra Bahadur Karki	Chandra Bahadur Karki	Sindhupalchowk	Pangretar	7	0		Sunkoshi	7	47	397056		Kathmandu,Kathmandu-14	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813759577	85.831703	27.750237	892.10638
1226	250566	RV	Min Bahadur Karki	Min Bahadur Karki	Sindhupalchowk	Pangretar	7	0		Sunkoshi	7	51	397060				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9818044634	85.830338, 85.830533	27.74987, 27.749998	899.6311, 901.02545
1227	250570	RV	Ram Bahadur Karki	Ram Bahadur Karki	Sindhupalchowk	Pangretar	7	0		Sunkoshi	7	52	397061		Kathmandu,Kathmandu-33	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841312589	85.832024	27.750877	860.75305
1228	250692	RV	Ramsharan Karki	Ram Sharan Karki	Sindhupalchowk	Pangretar	7	0		Sunkoshi	7	62	397071		Kathmandu,Kathmandu-4	No Damage	2	Grade 5, Grade 5	Reconstruct, Not Required	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Not Required	Habitable House in Other Place	9841430380	85.830078, 85.830177	27.750431, 27.750656	871.38855, 878.95245
1229	250568	RV	Narhari Subedi	Nar Hari Subedi	Sindhupalchowk	Pangretar	7	0		Sunkoshi	7	66	397075		Sindhupalchowk,Mankha-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841421875	85.829109	27.750475	882.87079
1230	250520	RV	Debiraj Khadka	Dil Maya Khadka	Sindhupalchowk	Pangretar	7	0		Sunkoshi	7	69	397455		Lalitpur,Lalitpur-19	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803145123	85.832497	27.751938	819.55957
1231	250521	RV	Dilmaya Khadka	Dil Maya Khadka	Sindhupalchowk	Pangretar	7	0		Sunkoshi	7	69	397453		Lalitpur,Lalitpur-19	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803145123	85.832497	27.751938	819.55957
1232	250565	RV	Suresh Shrestha	Shuresh Shrestha	Sindhupalchowk	Pangretar	7	0		Sunkoshi	7	78	397464				1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741038962	85.833626	27.752277	780.25659
1233	250572	RV	Khil Prasad Nepal	Khil Prasad Nepal	Sindhupalchowk	Pangretar	7	0		Sunkoshi	7	79	397465				1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9851174467	85.833672	27.752819	755.90125
1234	250531	RV	Chitra Kumari Karki	Chitra Kumari Karki	Sindhupalchowk	Pangretar	8	0		Sunkoshi	7	32	397524		Kathmandu,Kathmandu-9	No Damage	3	Grade 5, Grade 5, Grade 5	Reconstruct, Reconstruct, Reconstruct	Grade 5, Grade 5, Grade 5	Grade 5, Grade 5, Grade 5	Grade 5, Grade 5, Grade 5	Reconstruct, Reconstruct, Reconstruct	Habitable House in Other Place	16910917	85.828651, 85.828712, 85.828789	27.753632, 27.753725, 27.753811	682.6535, 685.1059, 691.03113
1235	250532	RV	Thakur Dhoj Silwal	Raj Kumar Dangol, Thakur Dhoj Silwal, Khatri	Sindhupalchowk	Pangretar	8	0		Sunkoshi	7	68	397564				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9851011383	85.828354	27.753357	714.74384
1236	250451	RV	Kumar Senchuri	Kumar Senchuri	Sindhupalchowk	Pangretar	9	0		Sunkoshi	7	20	363920		Sindhupalchowk,Pangretar-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741513721	85.823875	27.749517	736.65021
1237	250538	RV	Durga Dhoj Karki	Durga Dhoj Karki	Sindhupalchowk	Pangretar	9	0		Sunkoshi	7	25	363102				2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Minor Repair	Habitable House in Usual Place	9849340843	85.805611, 85.80571	27.745932, 27.745941	671.43988, 699.38641
1238	250452	RV	Hom Bahadur Karki	Hom Bahadur Karki	Sindhupalchowk	Pangretar	9	0		Sunkoshi	7	31	363108		Kathmandu,Kathmandu-35	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741086150	85.80542	27.745525	656.74469
1239	250450	RV	Ramhari Karki	Ram hari Karki	Sindhupalchowk	Pangretar	9	0		Sunkoshi	7	32	363109		Kathmandu,Kathmandu-10	No Damage	2	Grade 5, Grade 5	Reconstruct, Not Required	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Not Required	Habitable House in Other Place	9851026472	85.805481, 85.805649	27.745743, 27.745909	677.71259, 679.54755
1240	247812	RV	Chandra Bahadur Karki	Chandra Bahadur Karki, Kiran Kumar Karki	Sindhupalchowk	Pangretar	9	0		Sunkoshi	7	45	363125		Kathmandu,Kathmandu-5	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841600288	85.805519	27.745619	634.52655
1241	250539	RV	Uttar Dhoj Karki	Uttar Dhoj Karki	Sindhupalchowk	Pangretar	9	0		Sunkoshi	7	50	363706		Kathmandu,Kathmandu-15	Partial Damage	1	Grade 3	Major Repair	Grade 3	Grade 3	Grade 3	Major Repair	Habitable House in Other Place	9741198698	85.80571	27.745876	678.4635
1242	257198	RV	Karna Bahadur Shrestha	Karna Bahadur Shrestha	Sindhupalchowk	Pangtang	2	0		Jugal	4	22	556034		Sindhupalchowk,Baramchi-2	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741260331	85.780716	27.901161	1662.0861
1243	257194	RV	Chundup Dong	Chundup Dong	Sindhupalchowk	Pangtang	8	0		Jugal	4	43	333400				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair					

1252	253621	RV	Kamal Bdr Chuwan	kamal bahadur chuwan	Sindhupalchowk	Pipaldanda	3	0			Chautara Sagachowkgadhi Municipality	6	103	406743		Bhaktapur, Madhya pur Thimi-15	Partial Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9841407631	85.683914, 85.683968	27.779013, 27.779032	1072.6411, 1075.9592
1253	253623	RV	Chandra Kumar Basnet	chandra kumar basnet	Sindhupalchowk	Pipaldanda	3	0			Chautara Sagachowkgadhi Municipality	6	144	406761		Sindhupalchowk, Chautara-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741097572	85.685631	27.777912	1110.1771
1254	253635	RV	Khil Bdr Chuhan	Khil Bahadur Chuhan	Sindhupalchowk	Pipaldanda	5	0			Chautara Sagachowkgadhi Municipality	6	3	511739		Sindhupalchowk, Chautara-8	Partial Damage	1	Grade 2	Reconstruct	Grade 2	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741526431	85.686602	27.788523	1219.8499
1255	251395	RV	Puspa Nath Upadhaya	Pushpanath Upadhaya	Sindhupalchowk	Pipaldanda	5	0			Chautara Sagachowkgadhi Municipality	6	18	511805		Sindhupalchowk, Chautara-8	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	11690618	85.686462	27.790512	1239.494
1256	250003	RV	Buddhi Nath Upadhaya	Buddhinath Upadhaya	Sindhupalchowk	Pipaldanda	5	0			Chautara Sagachowkgadhi Municipality	6	19	511806		Sindhupalchowk, Chautara-8	No Damage	1	Grade 2	Reconstruct	Grade 2	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741038187	85.68631	27.790472	1242.9027
1257	253512	RV	Padma Nath Upadhaya	Padhyanath Upadhaya	Sindhupalchowk	Pipaldanda	5	0			Chautara Sagachowkgadhi Municipality	6	20	511812		Sindhupalchowk, Chautara-8	Partial Damage	1	Grade 2	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741212711	85.686356	27.79047	1243.636
1258	253515	RV	Lila Nath Upadhaya	Lilanth Upadhaya	Sindhupalchowk	Pipaldanda	5	0			Chautara Sagachowkgadhi Municipality	6	24			Kathmandu, Tarkes wor-8	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803837502	85.685936	27.790689	1228.2211
1259	253514	RV	Tej Prashad Upadhaya	Tejprasad Upadhaya	Sindhupalchowk	Pipaldanda	5	0			Chautara Sagachowkgadhi Municipality	6	25			Bhaktapur, Madhya pur Thimi-15	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841715113	85.685555	27.790762	1224.7839
1260	253510	RV	Bimala Upadhaya	Tulshiram Upadhaya	Sindhupalchowk	Pipaldanda	5	0			Chautara Sagachowkgadhi Municipality	6	30	511813		Sindhupalchowk, Chautara-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741218156	85.686295	27.790562	1233.8734
1261	253467	RV	Purna Bdr Khatri	Purna Bahadur Khatri	Sindhupalchowk	Pipaldanda	6	0			Chautara Sagachowkgadhi Municipality	6	80	326880		Kathmandu, Kathmandu-35	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741144544	85.682533	27.796892	1170.5487
1262	253464	RV	Tanka Bdr Khatri	Tanka Bahadur Khatri	Sindhupalchowk	Pipaldanda	6	0			Chautara Sagachowkgadhi Municipality	6	111	326910		Sindhupalchowk, Chautara-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741259774	85.682343	27.796522	1179.5073
1263	253471	RV	Moti Bdr Khatri	Moti Bahadur Khatri	Sindhupalchowk	Pipaldanda	6	0			Chautara Sagachowkgadhi Municipality	6	113			Kathmandu, Kathmandu-35	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813118362	85.682404	27.796183	1186.5187
1264	253404	RV	Shyange Tamang	Syange Tamang	Sindhupalchowk	Pipaldanda	8	0			Chautara Sagachowkgadhi Municipality	6	9	511935				1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843529662	85.707664	27.786572	1557.8485
1265	253406	RV	Ramesh Lal Tamang	Ramesh Lal Tamang	Sindhupalchowk	Pipaldanda	8	0			Chautara Sagachowkgadhi Municipality	6	49	511977				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9808463849	85.708344, 85.709282	27.795946, 27.796257	1584.1024, 1624.0774
1266	253324	RV	Lalmal Tamang	Lalmal Tamang	Sindhupalchowk	Pipaldanda	8	0			Chautara Sagachowkgadhi Municipality	6	52	511980				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9803802372	85.707451	27.787369	1550.9531
1267	253395	RV	Krishna Bdr Shrestha	Krishna Bahadur Shrestha	Sindhupalchowk	Pipaldanda	8	0			Chautara Sagachowkgadhi Municipality	6	60	511988				2	Grade 1, Grade 1	Minor Repair, Minor Repair	Grade 2, Grade 2	Grade 3, Grade 1	Grade 3, Grade 1	Reconstruct, Minor Repair	Habitable House in Usual Place	9841944638	85.707581, 85.707603	27.797525, 27.79759	1617.5605, 1620.9377
1268	253410	RV	Lal Bdr Lama	Lal Bahadur Lama	Sindhupalchowk	Pipaldanda	8	0			Chautara Sagachowkgadhi Municipality	6	66	511995				1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	11690275	85.707649	27.797668	1606.0854
1269	253443	RV	Bir Bdr Tamang	Bir Bahadur Tamang	Sindhupalchowk	Pipaldanda	8	0			Chautara Sagachowkgadhi Municipality	6	113	511899				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9843248995	85.705902	27.794661	1680.5942
1270	250007	RV	Harimaya Tamang	Toke Lama	Sindhupalchowk	Pipaldanda	8	0			Chautara Sagachowkgadhi Municipality	6	116	511902		Sindhupalchowk, Chautara-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741180656	85.705605	27.794277	1689.0338
1271	253318	RV	Yagman Shrestha	Yagman Shrestha	Sindhupalchowk	Pipaldanda	8	0			Chautara Sagachowkgadhi Municipality	6	118					2	Grade 3, Grade 1	Reconstruct, Not Required	Grade 3, Grade 1	Grade 4, Grade 1	Grade 4, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9810098354	85.70546, 85.705521	27.794102, 27.794138	1681.3057, 1683.9027
1272	253338	RV	Bhupendra Bdr Raut	Bupendra Raut	Sindhupalchowk	Pipaldanda	9	0			Chautara Sagachowkgadhi Municipality	5	9	511661		Sindhupalchowk, Chautara-8	Partial Damage	1	Grade 2	Reconstruct	Grade 2	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9863632642	85.720352	27.798353	1237.6355
1273	253331	RV	Kamala Kumari Katuwal	Ramesh Raut	Sindhupalchowk	Pipaldanda	9	0			Chautara Sagachowkgadhi Municipality	5	11	511665		Sindhupalchowk, Chautara-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843095515	85.720306	27.798204	1247.1354
1274	253335	RV	Man Kumari Raut	Mankumari Raut, Shreekrishna Raut	Sindhupalchowk	Pipaldanda	9	0			Chautara Sagachowkgadhi Municipality	5	13	511666		Kathmandu, Tokha Sarsawati-4	Partial Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 3, Grade 5	Grade 4, Grade 5	Grade 4, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9843319001	85.718239, 85.720291	27.797892, 27.799318	1243.1572, 1245.6152
1275	253337	RV	Tak Bdr Raut	Tanka Bahadur Raut	Sindhupalchowk	Pipaldanda	9	0			Chautara Sagachowkgadhi Municipality	5	33	511695				1	Grade 2	Reconstruct	Grade 3	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9881536073	85.721107	27.797506	1247.0505
1276	253333	RV	Ghuru Lama	Ghuru Lama	Sindhupalchowk	Pipaldanda	9	0			Chautara Sagachowkgadhi Municipality	5	42	511709				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9808332521	85.725296	27.79847	1215.8035
1277	257323	RV	Tilak Narayan Shrestha	Tilak Narayan Shrestha	Sindhupalchowk	Piskar	1	0			Tripurasundari	4	48	408712		Bhaktapur, Sipadol-2	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841132918	85.938957	27.727774	2118.4438
1278	257332	RV	Kagilal Shrestha	Kaji Lal Shrestha	Sindhupalchowk	Piskar	1	0			Tripurasundari	4	56	408722		Lalitpur, Thecho-9	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9841220177	85.937996, 85.938095	27.728422, 27.728498	2068.2151, 2072.627
1279	257314	RV	Kamali Kumari Shrestha	Krishna Shrestha	Sindhupalchowk	Piskar	1	0			Tripurasundari	4	57	408723				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9614912046	85.937889	27.729376	2072.9504
1280	257225	RV	Birkhaman Thami	Sukuman Thami	Sindhupalchowk	Piskar	6	0			Tripurasundari	4	29	544304		Sindhupalchowk, Piskar-4/Sindhupalchowk, Piskar-4	No Damage, No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.914726	27.743715	1634.0325
1281	257231	RV	Ram Prasad Paudel	Ram Prasad Paudel	Sindhupalchowk	Piskar	7	0			Tripurasundari	4	49	544199		Kathmandu, Kages wori-Manahara-8	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9818844034	85.912613	27.742931	1541.3492
1282	257236	RV	Bhagawan Jung Pande	Bhagawan Jung Pandey	Sindhupalchowk	Piskar	8	0			Tripurasundari	4	16	544517		Kathmandu, Budha nilkantha-5	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9741130451	85.904991, 85.90506	27.746645, 27.746695	1332.6666, 1335.098
1283	257235	RV	Kesab Khadka	Keshab Khadka	Sindhupalchowk	Piskar	8	0			Tripurasundari	4	34	544458				2	Grade 4, Grade 1	Reconstruct, Not Required	Grade 4, Grade 2	Grade 4, Unrecognized	Grade 4, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9849262196	85.908134, 85.908142	27.747515, 27.747547	1443.369, 1447.6469
1284	257237	RV	Urmila Sapkota	Urmila Sapkota	Sindhupalchowk	Piskar	9	0			Tripurasundari	4	5	544471				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 2	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9818875143	85.90593, 85.905945	27.745066, 27.745102	1349.1461, 1358.0453
1285	257238	RV	Hark Bdr. Thami	Harka Bahadur Thami	Sindhupalchowk	Piskar	9	0			Tripurasundari	4	23	544488				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 2	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9808049817	85.90683, 85.906883	27.745705, 27.745783	1400.3179, 1405.7773
1286	250696	RV	Ram Bdr Tamang	Lakshaman Tamang	Sindhupalchowk	Ramche	2	0			Barhabise Municipality	9	72	326767				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9865064832	85.881813	27.78285	1368.0305
1287	256616	RV	Suku Man Tamang	Shukuman Tamang	Sindhupalchowk	Ramche	3	0			Barhabise Municipality	9	25	542931				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.878967	27.778679	1357.738
1288	256764	RV	Padam Lal Tamang	Padam Lal Tamang	Sindhupalchowk	Ramche	3	0			Barhabise Municipality	9	38	542945				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.879242	27.779253	1368.6475

1338	250635	RV	Nirmal Paudel	Gyanu Poudel, Nirmal Poudel	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	122	542041	Kathmandu,Kathmandu-35	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851191240	85.898277	27.786823	831.16901	
1339	256826	RV	Masali Shrestha	Masali Shrestha	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	129	542049			1	Grade 2	Minor Repair	Grade 4	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841901626	85.898422	27.787443	831.11163	
1340	256752	RV	Aaete Sharpa	Aaiti Sherpa	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	132	542051			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9865098711	85.898392	27.787481	807.48224	
1341	256757	RV	Bal Sundar Gurung	Gopal Gurung, Kamala Devi	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	140	542057			1	Grade 1	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9860658465	85.898392	27.787075	850.28052	
1342	256684	RV	Gopal Gurung	Gopal Gurung, Kamala Devi	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	140	542056			1	Grade 1	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9860658465	85.898392	27.787075	850.28052	
1343	250697	RV	Samir Tamang	Indra Maya Tamang	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	141	542058	Kathmandu,Kathmandu-8	Partial Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	980866590	85.898361	27.787212	828.26617	
1344	256671	RV	Kalyani Ghising	Kaji Tamang	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	142	542059	Sindhupalchowk,Maneshowara-7/Sindhupalchowk,Maneshowara-7	Complete Damage, Complete Damage	1	Grade 2	Minor Repair	Grade 4	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9861148559	85.898422	27.787407	820.86346	
1345	256601	RV	Bhakti Maya Sherpa	Chyungi Tamangni	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	144	542062			1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9860386853	85.898468	27.787178	827.38287	
1346	256550	RV	Ram Kumar Shrestha	Ram Kumari Shrestha	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	146	542065			1	Grade 2	Minor Repair	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9810327744	85.89827	27.787033	831.8385	
1347	256823	RV	Phul Maya Tamang	Phul Maya Tamang	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	165	542385			1	Grade 2	Minor Repair	Grade 4	Grade 3	Grade 3	Minor Repair	Habitable House in Usual Place	9849695384	85.898499	27.787401	824.51178	
1348	256900	RV	Dhan Bdr Tamang	Dhan Bahadur Tamang	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	166	542386			1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9860608899	85.898796	27.787476	834.53729	
1349	256606	RV	Sita Tamang	Sita Tamang	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	167	542387			1	Grade 1	Minor Repair	Grade 4	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9860336804	85.89859	27.787477	824.57825	
1350	256811	RV	Bhava Nath Sapkota	Bhawnath Sapkota	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	170	542389			1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849269470	85.898514	27.787493	826.12549	
1351	256491	RV	Raj Kumar Shrestha	Raj Kumar Shrestha	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	177	542396			1	Grade 1	Minor Repair	Grade 4	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9818918182	85.898315	27.787912	830.51257	
1352	256825	RV	Dolma Sherpa	Dolma Sherpa	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	178	542397			1	Grade 2	Minor Repair	Grade 3	Grade 3	Grade 3	Minor Repair	Habitable House in Usual Place	9861209555	85.89875	27.787907	819.1156	
1353	256554	RV	Mina Lama	Mina Lama	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	183	542403			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843039170	85.898903	27.787338	825.15094	
1354	256878	RV	Denesh Shrestha	Dinesh Shrestha	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	184	542404			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9851168940	85.898315	27.787054	776.58594	
1355	256641	RV	Rajesh Shrestha	Rajesh Shrestha	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	193	542409	Kathmandu,Kathmandu-16	Partial Damage	2	Grade 5, Grade 3	Reconstruct, Major Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Major Repair	Habitable House in Other Place	9851026941	85.898254, 85.898567	27.786135, 27.786259	813.38208, 838.57129
1356	256739	RV	Roshan Shak	Ishworlal Sakha	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	201	542416	Kathmandu,Kathmandu-28/Sindhupalchowk&Barhabise-9	Complete Damage, Partial Damage	1	Grade 4	Major Repair	Grade 4	Grade 3	Grade 3	Major Repair	Habitable House in Other Place	9849056070	85.898453	27.786499	818.5069	
1357	256691	RV	Nabin Shrestha	Nabin Shrestha	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	203	542418			2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Major Repair	Habitable House in Usual Place	9841105252	85.898193, 85.898666	27.786274, 27.786301	827.54297, 832.59119
1358	256521	RV	Sushila Shrestha	Nabin Shrestha	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	203	542419			2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Major Repair	Habitable House in Usual Place	9841105252	85.898193, 85.898666	27.786274, 27.786301	827.54297, 832.59119	
1359	256520	RV	Roshani Shrestha	Roshani Shrestha	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	204	542420			2	Grade 1, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9841901706	85.898026, 85.898369	27.786419, 27.786451	800.96967, 826.20599	
1360	256748	RV	Bharat Shrestha	Bharat Shrestha	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	215	542433			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803112665	85.898224	27.786093	868.66272	
1361	256890	RV	Bhawani Thapa	Bhawani Thapa	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	217	542432			2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9741261155	85.898499, 85.898506	27.785673, 27.785725	804.90253, 815.72876	
1362	256833	RV	Upendra Paudel	Lila Nath Poudel	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	224	542441	Kathmandu,Kathmandu-35	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841924835	85.898094	27.785492	811.76245
1363	256693	RV	Bhuwati Shrestha	Pun Maya Shrestha	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	225	542442			1	Grade 2	Minor Repair	Grade 3	Grade 3	Grade 3	Minor Repair	Habitable House in Usual Place	9841783856	85.89856	27.785646	795.09369	
1364	256604	RV	Shyam Kumar Padhanangu	Rupa Pradhan, Syam Kumar Pradhan	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	226	542443	Kathmandu,Kathmandu-35	No Damage	1	Grade 3	Major Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	9841891168	85.897858	27.785786	814.65881
1365	251439	RV	Amrit Bdrshrestha	Amrit Bahadur Shrestha, Shyam Kumar Pradhan	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	233	542448			1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741181515	85.898071	27.785526	828.41302	
1366	256567	RV	Chandan (Rajthala) Shrestha	Gyanmaya Rajthala	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	236	542451			1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841902069	85.898056	27.785425	832.43091	
1367	251432	RV	Ganesh Bdr Rayamajhi	Ganesh Bahadur Raymajhi	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	239	542454			2	Grade 2, Grade 3	Minor Repair, Major Repair	Grade 3, Grade 3	Grade 2, Grade 3	Grade 2, Grade 3	Minor Repair, Major Repair	Habitable House in Usual Place	9741082614	85.896942, 85.897072	27.783451, 27.783487	815.36023, 829.66187	
1368	256618	RV	Tutu Maya Shrestha	Tutu Maya Shrestha	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	241	542458			1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	11489232	85.897011	27.783358	833.48279	
1369	256572	RV	Rajendra Shrestha	Rajendra Shrestha, Shyam Sundar Shrestha	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	242	542459			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9841231054	85.897156	27.78363	820.76721	
1370	256896	RV	Roshan Shrestha	Rajendra Shrestha, Shyam Sundar Shrestha	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	242	542461			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9841231054	85.897156	27.78363	820.76721	
1371	256569	RV	Shyam Sundar Shrestha	Rajendra Shrestha, Shyam Sundar Shrestha	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	242	542460			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9841231054	85.897156	27.78363	820.76721	
1372	256690	RV	Bhimvan Thapa	Kanchhi Bhandari	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	243	542462			2	Grade 2, Grade 3	Minor Repair, Major Repair	Grade 3, Grade 4	Grade 2, Unrecognized	Grade 2, Unrecognized	Grade 2, Unrecognized	Habitable House in Usual Place	9841907888	85.896927, 85.897072	27.783581, 27.783619	777.75183, 831.7749	
1373	256676	RV	Jivan Shrestha	Bishnu Maya Shrestha	Sindhupalchowk	Ramche	7	0	Barhabise Municipality	9	246	542467			2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9843047857	85.896889, 85.897018	27.783182, 27.783306	814.09711, 838.63647	
1374	256891	RV	Krishna Prd Timalshina	Krishna Prasad Timalshina	Sindhupalchowk	Ramche	8	0	Barhabise Municipality	9	5	394481			1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849458127	85.894882	27.786781	1096.8259	
1375	256760	RV	Lok Badur Paudal	Lok Bahadur Paudal	Sindhupalchowk	Ramche	9	0	Barhabise Municipality	9	7		Sindhupalchowk,Mankha-1	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849898240	85.860954	27.717809	1689.2794	
1376	256893	RV	Shidi Badur Magar	Siddhi Bahadur Magar	Sindhupalchowk	Ramche	9	0	Barhabise Municipality	9	53	394155			2	Grade 1, Grade 5	Not Required, Reconstruct	Grade 1, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	9611193571	85.863602, 85.863625	27.774996, 27.775042	1697.8982, 1701.9362	
1377	252425	RV	Rajkumar Majhi	Raj Kumar Majhi	Sindhupalchowk	Sangachok	1	0	Chautara Sagachowkghadi Municipality	10	7	555182			1	Grade 5	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843692743	85.760757	27.70505	644.01465	
1378	252423	RV	Sarki Rana Magar	Sarki Rana Magar	Sindhupalchowk	Sangachok	1	0	Chautara Sagachowkghadi Municipality	10	13	555188	Sindhupalchowk,Sangachok-6	Partial Damage	1	Grade 3	Major Repair	Grade 3	Grade 3	Grade 3	Major Repair	Habitable House in Other Place	9741269762	85.760376	27.704926	599.44061	
1379	252430	RV	Mohanlal Shrestha	Mohan Lal Shrestha	Sindhupalchowk	Sangachok	1	0	Chautara Sagachowkghadi Municipality	10	15	3555190			2	Grade 4, Grade 2	Major Repair, Minor Repair	Grade 4, Grade 3	Grade 4, Grade 2	Grade 4, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9744033537	85.761292, 85.761299	27.704855, 27.704903	627.33466, 628.65784	
1380	252548	RV	Kanchi Bhujel	Kanchi Bhujel	Sindhupalchowk	Sangachok	1	0	Chautara Sagachowkghadi Municipality	10	16	555191															

1420	252824	RV	Ramchandra Bogati	Ram Chandra Bogati	Sindhupalchowk	Sangachok	2	0		Chautara Sagachowkgadhi Municipality	10	18	541502				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841101925	85.72966	27.719849	1470.9176
1421	251273	RV	Krishna Bdr Tamang	Krishna Bahadur Tamang	Sindhupalchowk	Sangachok	2	0		Chautara Sagachowkgadhi Municipality	10	49	541537				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9741388894	85.724388, 85.724548	27.714626, 27.714653	1382.8625, 1391.3861
1422	252806	RV	Bakhat Bdr Tamang	Bakhat Bahadur Tamang	Sindhupalchowk	Sangachok	2	0		Chautara Sagachowkgadhi Municipality	10	137	541635				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9818739355	85.71405, 85.714096	27.7115, 27.711674	1450.3641, 1451.1177
1423	252840	RV	Rahar Bdr Tamang	Rahar Bahadur Tamang	Sindhupalchowk	Sangachok	2	0		Chautara Sagachowkgadhi Municipality	10	177	541675				3	Grade 5, Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 5, Grade 1	Grade 5, Grade 5, Grade 1	Grade 5, Grade 5, Unrecognized	Grade 5, Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9841289490	85.718369, 85.718513, 85.718933	27.712236, 27.712279, 27.712732	1402.7994, 1404.5659, 1416.8058
1424	252841	RV	Nani Khanca Giri	Nani Kanxa Giri	Sindhupalchowk	Sangachok	2	0		Chautara Sagachowkgadhi Municipality	10	210	541712		Sindhupalchowk, Sangachok-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741122992	85.715279	27.707119	1367.0525
1425	249794	RV	Dhurva Giri	Dhurba Giri	Sindhupalchowk	Sangachok	3	0		Chautara Sagachowkgadhi Municipality	12	57	541803				1	Grade 2	Minor Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9818741993	85.722733	27.686144	969.74786
1426	252859	RV	Dhan Kumari Giri	Babu Ram Bharti	Sindhupalchowk	Sangachok	3	0		Chautara Sagachowkgadhi Municipality	12	60	541815				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 3	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9741280326	85.723068, 85.723099	27.687574, 27.687658	967.4209, 973.61383
1427	252851	RV	Kabita Giri	Raja Ram Giri	Sindhupalchowk	Sangachok	3	0		Chautara Sagachowkgadhi Municipality	12	65	541822				1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9808065319	85.722153	27.687418	990.75665
1428	252748	RV	Gangal Shrestha	Ganga Lal Shrestha	Sindhupalchowk	Sangachok	3	0		Chautara Sagachowkgadhi Municipality	12	83	541841		Sindhupalchowk, Sangachok-4	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741088838	85.718521	27.69116	1007.2867
1429	252752	RV	Til Kumari Giri	Jagad Bahadur Giri	Sindhupalchowk	Sangachok	3	0		Chautara Sagachowkgadhi Municipality	12	182	539989				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9803947321	85.710648	27.688013	1273.0768
1430	252742	RV	Aakal Bahadur Shrestha	Akkal Bahadur Shrestha	Sindhupalchowk	Sangachok	3	0		Chautara Sagachowkgadhi Municipality	12	231	402516		Bhaktapur, Katunge-9	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841225389	85.71154	27.691477	1219.6765
1431	252785	RV	Budhi Bal Tamang	Buddhibal Tamang	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	39	1192723		Chitwan, Meghauli-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849177284	85.701149	27.704714	1086.7964
1432	252766	RV	Bishnu Raj Giri	Bishnu Raj Giri, Dadhiraj Giri, Krishna Bahadur Giri	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	54	1192742				3	Grade 5, Grade 2, Grade 3	Reconstruct, Reconstruct	Grade 5, Grade 3, Grade 3	Grade 5, Grade 2, Grade 3	Grade 5, Grade 2, Grade 3	Grade 5, Grade 2, Grade 3	Reconstruct, Major Repair	Habitable House in Usual Place	9808733649	85.709335, 85.709427, 85.709511	27.711912, 27.711941, 27.711946	1356.1256, 1360.2238, 1365.9558
1433	252767	RV	Dadhiraj Giri	Bishnu Raj Giri, Dadhiraj Giri, Krishna Bahadur Giri	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	54	1192740				3	Grade 5, Grade 2, Grade 3	Reconstruct, Reconstruct	Grade 5, Grade 3, Grade 3	Grade 5, Grade 2, Grade 3	Grade 5, Grade 2, Grade 3	Grade 5, Grade 2, Grade 3	Reconstruct, Major Repair	Habitable House in Usual Place	9808733649	85.709335, 85.709427, 85.709511	27.711912, 27.711941, 27.711946	1356.1256, 1360.2238, 1365.9558
1434	252686	RV	Krishna Bahadur Giri	Bishnu Raj Giri, Dadhiraj Giri, Krishna Bahadur Giri	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	54	1192741				3	Grade 5, Grade 2, Grade 3	Reconstruct, Reconstruct	Grade 5, Grade 3, Grade 3	Grade 5, Grade 2, Grade 3	Grade 5, Grade 2, Grade 3	Grade 5, Grade 2, Grade 3	Reconstruct, Major Repair	Habitable House in Usual Place	9808733649	85.709427, 85.709511	27.711912, 27.711941, 27.711946	1356.1256, 1360.2238, 1365.9558
1435	252795	RV	Sukumel Kumari Giri	Arjun Raj Giri	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	58	1192746		Kathmandu, Kathmandu-99	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741019342	85.709885	27.711468	1361.4709
1436	252777	RV	Chabial Shrestha	Bhim Lal Shrestha, Chabial Shrestha, Tek Bahadur Shrestha	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	60	1192750				3	Grade 5, Grade 5, Grade 1	Reconstruct, Reconstruct, Not Required	Grade 5, Grade 5, Unrecognized	Grade 5, Grade 5, Unrecognized	Grade 5, Grade 5, Unrecognized	Grade 5, Grade 5, Unrecognized	Reconstruct, Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9810328028	85.712631, 85.712685, 85.712784	27.695265, 27.69537, 27.695406	1213.5826, 1217.5228, 1222.5702
1437	252765	RV	Pramila Shrestha	Bhim Lal Shrestha, Chabial Shrestha, Tek Bahadur Shrestha	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	60	1192751				3	Grade 5, Grade 5, Grade 1	Reconstruct, Reconstruct, Not Required	Grade 5, Grade 5, Unrecognized	Grade 5, Grade 5, Unrecognized	Grade 5, Grade 5, Unrecognized	Grade 5, Grade 5, Unrecognized	Reconstruct, Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9810328028	85.712631, 85.712685, 85.712784	27.695265, 27.69537, 27.695406	1213.5826, 1217.5228, 1222.5702
1438	252776	RV	Tek Bahadur Shrestha	Bhim Lal Shrestha, Chabial Shrestha, Tek Bahadur Shrestha	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	60	1192749				3	Grade 5, Grade 5, Grade 1	Reconstruct, Reconstruct, Not Required	Grade 5, Grade 5, Unrecognized	Grade 5, Grade 5, Unrecognized	Grade 5, Grade 5, Unrecognized	Grade 5, Grade 5, Unrecognized	Reconstruct, Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9810328028	85.712631, 85.712685, 85.712784	27.695265, 27.69537, 27.695406	1213.5826, 1217.5228, 1222.5702
1439	252793	RV	Dil Bahadur Darji	Dil Bahadur Darji	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	68	1192761				1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9861199157	85.712151	27.696245	1233.7375
1440	252661	RV	Dil Bdr Darji	Dil Bahadur Darji	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	68	1192761				1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9861199157	85.712151	27.696245	1233.7375
1441	252685	RV	Dilip Raj Giri	Kamala Giri, Parbati Giri	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	79	1192773		Bhaktapur, Sipadol-999	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9851064443	85.711815	27.694521	1212.9738
1442	252758	RV	Sharada Aryal	Bishnu Prasad Aryal	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	88	1192807				1	Grade 2	Minor Repair	Grade 4	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849652050	85.711861	27.693878	1211.7012
1443	252790	RV	Dhan Laxmi Tamangni	Dhanlaxmi Tamangni	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	105	1192824				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9860430615	85.708206	27.692209	1199.5126
1444	252678	RV	Padam Bdr Thakuri	Sushila Thakuri	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	108	1192827				1	Grade 1	Minor Repair	Grade 3	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9808899380	85.710289	27.692766	1201.0571
1445	252683	RV	Deependra Giri	Dipendra Giri, Sudip Giri	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	110	1192829				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9808178167	85.709412	27.692553	1195.8579
1446	252691	RV	Sharada Aran	Sharada Aaran	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	10	117	1192832				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	11610803	85.710518	27.69272	1200.166
1447	252803	RV	Bholanath Poudel	Bholanath Poudel	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	121	1192837				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741039157	85.711044	27.69294	1204.3533
1448	252681	RV	Ramesh Lal Shrestha	Ramesh Lal Shrestha	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	130	1192845				1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849948465	85.711617	27.69276	1209.9622
1449	252782	RV	Raj Kumar Shrestha	Raj Kumar Shrestha	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	132	1192847				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9860324661	85.711624	27.694143	1192.5459
1450	252759	RV	Mohan Lal Shrestha	Mohanlal Shrestha	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	134	1192849		Kavrepalanchowk, Banepa-99	Partial Damage	1	Grade 4	Reconstruct	Grade 3	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9849568256	85.71122	27.691618	1219.7435
1451	252797	RV	Dhruba Giri	Dhrubaraj Giri	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	182	1192674		Bhaktapur, Duvakot-12	Partial Damage	2	Grade 4, Grade 5	Reconstruct, Reconstruct	Grade 4, Grade 5	Grade 4, Grade 5	Grade 4, Grade 5	Grade 4, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9849894000	85.710503, 85.710548	27.690643, 27.690773	1258.3899, 1262.5292
1452	251277	RV	Jeevan Raj Giri	Jeevan Raj Giri	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	211	1192635		Sindhupalchowk, Sangachok-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803452760	85.712105	27.687698	1254.8344
1453	251278	RV	Deepak Giri	Deepak Giri	Sindhupalchowk	Sangachok	4	0		Chautara Sagachowkgadhi Municipality	12	284	1192587				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841924913	85.713013	27.694866	1209.264

1489	252667	RV	Man Bdr Shrestha	Man Bahadur Shrestha	Sindhupalchowk	Sangachok	6	0			Chautara Sagachowkgadhi Municipality	12	215	1191234				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9741025681	85.712639	27.696472	1238.4707
1490	252576	RV	Kamala Rai	Kamala Rai	Sindhupalchowk	Sangachok	7	0			Chautara Sagachowkgadhi Municipality	10	141	324128				1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9813132471	85.732086	27.720934	1460.1902
1491	252579	RV	Subhadra Thakuri	Suvadra Thakuri	Sindhupalchowk	Sangachok	7	0			Chautara Sagachowkgadhi Municipality	10	174	1174361				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818760298	85.732025	27.722937	1489.373
1492	252669	RV	Chetra Bdr Bogati	Chhetra Bahadur Bogati	Sindhupalchowk	Sangachok	7	0			Chautara Sagachowkgadhi Municipality	10	182	1174369				1	Grade 1	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9812597748	85.733437	27.722326	1455.9233
1493	252589	RV	Wangjung Lama	Wang Jung Lama	Sindhupalchowk	Sangachok	8	0			Chautara Sagachowkgadhi Municipality	11	55	1192541				1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9851067524	85.703957	27.693155	1169.1058
1494	252601	RV	Sita Tamang	Sita Tamang	Sindhupalchowk	Sangachok	8	0			Chautara Sagachowkgadhi Municipality	11	57	1192543				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9860187364	85.702583	27.692272	1156.457
1495	252505	RV	Jagat Bahadur Tamang	Jagat Bahadur Tamang	Sindhupalchowk	Sangachok	8	0			Chautara Sagachowkgadhi Municipality	11	58	1192544				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9860382206	85.702431	27.692507	1148.262
1496	252597	RV	Narayan Giri	Nayayan Giri	Sindhupalchowk	Sangachok	8	0			Chautara Sagachowkgadhi Municipality	11	85	1191023	Kathmandu,Kathmandu-35	No Damage		1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	984336152	85.704376	27.68795	1136.2329
1497	252514	RV	Bina Tamang	Bina Tamang	Sindhupalchowk	Sangachok	8	0			Chautara Sagachowkgadhi Municipality	11	102	1191291				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818201981	85.705696	27.690701	1179.8188
1498	252594	RV	Sukuman Lama	Suku Man Lama	Sindhupalchowk	Sangachok	8	0			Chautara Sagachowkgadhi Municipality	11	111	1191076				1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849259174	85.705208	27.690098	1164.9731
1499	252599	RV	Sanjay Tamang	Sanjay Tamang	Sindhupalchowk	Sangachok	8	0			Chautara Sagachowkgadhi Municipality	11	112	1191077				1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9843427007	85.704765	27.689701	1160.4995
1500	252512	RV	Sabita Tamang	Sabita Tamang	Sindhupalchowk	Sangachok	8	0			Chautara Sagachowkgadhi Municipality	11	123	1191088				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9813683614	85.7043	27.689919	1154.053
1501	252525	RV	Bikram Tamang	Bikram Tamang	Sindhupalchowk	Sangachok	8	0			Chautara Sagachowkgadhi Municipality	11	128	1191093				1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9818137376	85.705605	27.688894	1150.4199
1502	252526	RV	Lalman Tamang	Lai Man Tamang	Sindhupalchowk	Sangachok	8	0			Chautara Sagachowkgadhi Municipality	11	129	1191094				1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9841471466	85.705498	27.688931	1162.1034
1503	252590	RV	Sita Giri	Nab Raj Giri	Sindhupalchowk	Sangachok	8	0			Chautara Sagachowkgadhi Municipality	11	212	1191106	Sindhupalchowk,Sangachok-4	Partial Damage		1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9849319348	85.697227	27.688168	1014.2531
1504	252602	RV	Nakul Giri	Nakul Giri	Sindhupalchowk	Sangachok	8	0			Chautara Sagachowkgadhi Municipality	11	216	1191110	Sindhupalchowk,Sangachok-4	Partial Damage		1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	984929606	85.697838	27.688354	1010.4403
1505	252529	RV	Ramila Parajuli	Chatur Prasad Parajuli	Sindhupalchowk	Sangachok	8	0			Chautara Sagachowkgadhi Municipality	11	240	1191034				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	984926456	85.695175	27.689775	982.6972
1506	252518	RV	Thuli Maya Tamang	Thuli Maya Tamang	Sindhupalchowk	Sangachok	8	0			Chautara Sagachowkgadhi Municipality	11	303	1191277				1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849340760	85.702911	27.692114	1140.5647
1507	252456	RV	Shanta Giri	Shanta Giri	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	11	53	532928	Lalitpur,Lalitpur-5	Partial Damage		1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808077094	85.705345	27.663921	905.79065
1508	252381	RV	Jayaram Parajuli	Jayaram Parajuli	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	11	277	533999	Sindhupalchowk,Sangachok-5	Partial Damage		1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843529176	85.70034	27.680899	964.42975
1509	252531	RV	Jhamka Prasad Parajuli	Jhamka Prasad Parajuli	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	10	280	542077	Bhaktapur,Balkot-9	Partial Damage		1	Grade 5	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9860905719	85.699814	27.683061	958.84546
1510	252461	RV	Govinda Prasad Parajuli	Gobinda Prasad Parajuli	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	11	300	542098	Sindhupalchowk,Sangachok-5	Partial Damage		1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741030569	85.700562	27.679111	950.76068
1511	252376	RV	Dhrubha Raj Giri	Dhruba Raj Giri	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	11	323	542124	Kathmandu,Kathmandu-9	Partial Damage		1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841875774	85.704132	27.685526	1056.511
1512	252364	RV	Arjun Giri	Arjun Raj Giri	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	11	334	542161	Sindhupalchowk,Sangachok-5	Partial Damage		1	Grade 5	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841897701	85.703735	27.686857	1084.2416
1513	252379	RV	Kanti Maiya Giri	Rohit Raj Giri	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	11	339	542166	Kathmandu,Kathmandu-33	Partial Damage		1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841820469	85.704346	27.686152	1082.6825
1514	252446	RV	Madhab Raj Giri	Madhav Raj Giri	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	11	341	542168	Sindhupalchowk,Sangachok-5	Partial Damage		1	Grade 5	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841519014	85.704475	27.686207	1090.7299
1515	252445	RV	Narayan Giri	Narayan Giri	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	11	343	542170	Kathmandu,Kathmandu-35	Partial Damage		1	Grade 5	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741035293	85.704674	27.686621	1079.8916
1516	252370	RV	Indra Raj Giri	Indra Raj Giri	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	11	351	542178	Kathmandu,Kathmandu-9	Partial Damage		1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851045819	85.705681	27.682537	1103.0834
1517	252369	RV	Prem Raj Giri	Prem Raj Giri	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	11	352	542179	Kathmandu,Kathmandu-2	No Damage		1	Grade 5	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9849757404	85.705591	27.683104	1102.6801
1518	252367	RV	Kumar Giri	Kumar Giri	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	11	361	542189	Kavrepalanchowk,Baneps-11	Partial Damage		1	Grade 4	Reconstruct	Grade 3	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9849923213	85.705574	27.681704	1080.0947
1519	252374	RV	Basu Raj Giri	Basuraj Giri	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	11	364	542193	Kathmandu,Kathmandu-9	Partial Damage		1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851176899	85.705658	27.682722	1096.9464
1520	252448	RV	Dhal Kumari Giri	Dhal Kumari Giri	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	11	366	542195	Kathmandu,Kathmandu-35	Partial Damage		1	Grade 5	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9860038835	85.705208	27.682882	1093.799
1521	252449	RV	Renu Giri	Ramesh Giri	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	11	367	542196	Kathmandu,Kathmandu-35	Partial Damage		1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841920917	85.705391	27.682747	1103.8304
1522	252365	RV	Mitha Giri	Mittha Giri	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	10	372	542204	Lalitpur,Lalitpur-4	Partial Damage		1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843105663	85.705826	27.681196	1088.108
1523	252366	RV	Sabitri Giri	Ram Sharan Giri	Sindhupalchowk	Sangachok	9	0			Chautara Sagachowkgadhi Municipality	10	374	542206	Kathmandu,Kathmandu-4	Partial Damage		1	Grade 5	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841135366	85.705841	27.681835	1099.0692

1524	252375	RV	Jayram Giri	Jayram Giri	Sindhupalchowk	Sangachok	9	0		Chautara Sagachowkgadhi Municipality	11	394	542227		Kathmandu,Kathmandu-35	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851015560	85.706459	27.683228	1141.5258
1525	252378	RV	Kamala Puri	Buddhaba Giri	Sindhupalchowk	Sangachok	9	0		Chautara Sagachowkgadhi Municipality	11	397	542230				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843402209	85.706139	27.683777	1156.0342
1526	256986	RV	Resha Shrestha	Resha Shrestha	Sindhupalchowk	Sanuiruvari	1	0		Chautara Sagachowkgadhi Municipality	7	68	843273				1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9843104309	85.716377	27.761477	1297.9611
1527	256990	RV	Suman Ghimire	Suman Ghimire	Sindhupalchowk	Sanuiruvari	3	0		Chautara Sagachowkgadhi Municipality	7	24	368046				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9845114030	85.707932	27.759541	1242.5522
1528	257265	RV	Umakanta Lamsal	Chuda Mai Lamsal	Sindhupalchowk	Sanuiruvari	5	0		Chautara Sagachowkgadhi Municipality	7	8	369408		Sindhupalchowk,Bhotasp-1	No Damage	1	Grade 4	Major Repair	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place		85.676743	27.750059	738.06934
1529	257260	RV	Utter Bdr Tamang	Uttar Bahadur Tamang	Sindhupalchowk	Sanuiruvari	5	0		Chautara Sagachowkgadhi Municipality	7	42	369318				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9813812199	85.684204	27.752798	1061.5304
1530	256069	RV	Bhakta Bahadur Shrestha	Bhakta Bahadur Shrestha	Sindhupalchowk	Sanuiruvari	6	0		Chautara Sagachowkgadhi Municipality	7	173	334839				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	11620166	85.729469	27.75581	1488.4824
1531	257090	RV	Ghana Shyam Dungal	Ghan Shyam Dungal	Sindhupalchowk	Sanuiruvari	6	0		Chautara Sagachowkgadhi Municipality	7	184	334852				1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9741144560	85.728653	27.756721	1520.299
1532	256983	RV	Chameli Dulal	Chameli Dulal	Sindhupalchowk	Sanuiruvari	9	0		Chautara Sagachowkgadhi Municipality	7	74	511174		Sindhupalchowk,C haurata-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849012465	85.701591	27.7544	1085.5569
1533	256982	RV	Tara Pra Dulal	Tara Prasad Dulal	Sindhupalchowk	Sanuiruvari	9	0		Chautara Sagachowkgadhi Municipality	7	85	511185		Sindhupalchowk,C haurata-2	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9818088488			
1534	254597	RV	Ramkaji Tamang	Ram Kaji Tamang	Sindhupalchowk	Selang	2	0		Jugal	1	45	397670				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.736633	27.843777	1674.3931
1535	257034	RV	Netra Bdr Silwal	Netra Bahadur Silwal	Sindhupalchowk	Selang	6	0		Jugal	1	39	397816		Lalitpur,Lalitpur-14	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849398773	85.768082	27.846453	882.78528
1536	257151	RV	Krishna Bdr Silwal	Krishna Bahadur Silwal	Sindhupalchowk	Selang	6	0		Jugal	1	41	397818		Kathmandu,Kathmandu-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741245545	85.767509	27.846613	876.67712
1537	257030	RV	Posta Bdr Thapa	Posta Bahadur Thapa	Sindhupalchowk	Selang	6	0		Jugal	1	92	397832		Kathmandu,Kathmandu-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	14384090	85.766861	27.841955	1052.8815
1538	257038	RV	Dambar Bdr Bhattarai	Dambar Bahadur Bhattarai	Sindhupalchowk	Selang	7	0		Jugal	1	58	330852		Sindhupalchowk,Jalabire-1	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741018116	85.763954	27.841095	1208.5857
1539	257039	RV	Lila Bdr Shrestha	Lila Bahadur Shrestha	Sindhupalchowk	Selang	7	0		Jugal	1	76	330871		Sindhupalchowk,C haurata-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9810174182	85.757133	27.844179	1334.7819
1540	257085	RV	Moti Bdr Karki	Purna Bahadur Karki	Sindhupalchowk	Selang	9	0		Jugal	1	53	330969	23-60-9-0-53			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Mark & Photo not cleared or mismatch	9741204130	85.749962	27.860331	1012.3486
1541	249878	RV	Saraswati Nepal	Sarswati Nepal	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	9	409967		Kathmandu,Gokarnewar-1	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9843275323	85.52282	27.815357	1400.0469
1542	250765	RV	Kem Kumari Nepal	Kem Kumari Nepal	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	15	409973		Kathmandu,Kapan-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849907545	85.522453	27.815268	1402.7329
1543	249867	RV	Madhusudan Nepal	Madhu Sudan Nepal	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	26	409834		Kathmandu,Gokarnewar-8	No Damage	1	Grade 1	Minor Repair	Grade 1	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9841443160	85.522423	27.816689	1433.0122
1544	249868	RV	Min Prasad Sigdel	Min Prasad Sigdel	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	33	409841		Kathmandu,Budhanilkatha-8	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841076110	85.526718	27.815777	1457.9812
1545	249869	RV	Nani Babu Sigdel	Nani Babu Sigdel	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	34	409842		Kathmandu,Budhanilkatha-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741239708	85.52668	27.815796	1467.8329
1546	249870	RV	Lumani Prasad Nepal	Lumadi Prasad Nepal	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	40	409848		Kathmandu,Kapan-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841834156	85.522224	27.815125	1379.532
1547	249871	RV	Rajan Prasad Sigdel	Rajan Prasad	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	43	409851		Kathmandu,Gokarnewar-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841386096	85.527847	27.816792	1487.5319
1548	249872	RV	Bidhyanidhi Sigdel	Bidha Nidhi Sigdel	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	44	409852		Kathmandu,Kapan-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843313422	85.527824	27.816813	1505.4307
1549	249873	RV	Shanta Sigdel	Shanta Sigdel	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	48	409856		Kathmandu,Kapan-999	No Damage	1	Grade 5	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741223210	85.52713	27.816969	1500.2373
1550	249874	RV	Khilprasad Sigdel	Khil Prasad Sigdel	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	49	409857		Kathmandu,Gokarnewar-99	No Damage	1	Grade 5	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9849928067	85.527611	27.816765	1498.0903
1551	249876	RV	Suraj Sigdel	Suraj Sigdel	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	55	409863		Kathmandu,Danchhi-7	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851150693	85.527641	27.816624	1530.0663
1552	249877	RV	Bidhyanidhi Guragain	Bidhandhi Guragai	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	70	409729		Kathmandu,Shankarapura-99	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741177587	85.521538	27.8188	1471.8574
1553	249878	RV	Falkumari Nepal	Phal Kumari Nepal	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	71	409730		Kathmandu,Danchhi-99	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9860902044	85.522087	27.817476	1457.4319
1554	249914	RV	Badri Prasad Sigdel	Badri Prasad Sigdel	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	79	409738		Kathmandu,Kapan-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741025165	85.521599	27.819088	1469.059
1555	249861	RV	Tulkumari Sigdel	Tul Kumari Sigdel	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	83	409742		Kathmandu,Kathmandu-7	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851088194	85.522324	27.818712	1495.1215
1556	249862	RV	Dakshya Kumari Sigdel	Daksh Kumari Sigdel	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	84	409743		Kathmandu,Kathmandu-7	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860048153	85.522346	27.818707	1496.7738
1557	249863	RV	Min Prasad Sigdel	Min Prasad Sigdel	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	85	409744		Kathmandu,Gokarnewar-8	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843314362	85.521339	27.818018	1453.0092
1558	249864	RV	Chiranjibi Sigdel	Chiranjibi Sigdel	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	86	409745		Kathmandu,Kathmandu-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841520043	85.521378	27.817976	1438.2045
1559	249865	RV	Parshuram Sigdel	Parshu Ram Sigdel	Sindhupalchowk	Sindhukot	1	0		Melanchi Municipality	5	105	409764		Kathmandu,Danchhi-8	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849815353	85.518867	27.818693	1352.8319
1560	249924	RV	Rammani Lutel	Ramamani Lutel	Sindhupalchowk	Sindhukot	2	0		Melanchi Municipality	5	80	409981		Kathmandu,Kapan-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741037475	85.521751	27.814547	1348.6228
1561	250817	RV	Devkumari Sigdel	Dev Kumari Sigdel	Sindhupalchowk	Sindhukot	2	0		Melanchi Municipality	5	116	408893		Kathmandu,Kapan-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849238140	85.527626	27.811241	1258.9089
1562	249915	RV	Rambabu Lutel	Ram Babu Lutel	Sindhupalchowk	Sindhukot	2	0		Melanchi Municipality	5	127	409804		Kathmandu,Kapan-3	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9851065407	85.521484	27.814604	1339.2817
1563	249916	RV	Rampasad Lutel	Ram Prasad Lutel	Sindhupalchowk	Sindhukot	2	0		Melanchi Municipality	5	128	409805		Kathmandu,Budhanilkatha-6	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9844930041	85.521378	27.814716	1349.6724
1564	249917	RV	Ganga Lutel	Ganga Lutel	Sindhupalchowk	Sindhukot	2	0		Melanchi Municipality	5	130	409807		Kathmandu,Kathmandu-7	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860436586	85.521721	27.814737	1353.5151
1565	249918	RV	Bharatmani Lutel	Bharath Mani Lutel	Sindhupalchowk	Sindhukot	2	0		Melanchi Municipality	5	131	409808		Kathmandu,Gokarnewar-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843545000	85.521645	27.814659	1357.293
1566	249919	RV	Nandaprasad Nepal	Nand Prasad Nepal	Sindhupalchowk	Sindhukot	2	0		Melanchi Municipality	5	132	409809		Kathmandu,Kathmandu-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841615710	85.522583	27.813744	1363.7396
1567	249921	RV	Achyut Prasad Nepal, Madhu Sudhan Nepal	Achyut Prasad Nepal, Madhu Sudhan Nepal	Sindhupalchowk	Sindhukot	2	0		Melanchi Municipality	5	133	409811		Kathmandu,Kathmandu-6	No Damage	1	Grade 4	Reconstruct	Grade 3	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9851073720	85.522125	27.813789	1350.7799
1568	249920	RV	Madhusudan Nepal	Achyut Prasad Nepal, Madhu Sudhan Nepal	Sindhupalchowk	Sindhukot	2	0		Melanchi Municipality	5	133	409810		Kathmandu,Kathmandu-6	No Damage	1	Grade 4	Reconstruct	Grade 3	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9851073720	85.522125	27.813789	1350.7799
1569	249806	RV	Dipesh Bahadur Raya	Dipesh Bahadur Raya	Sindhupalchowk	Sindhukot	3	0		Melanchi Municipality	5		409669			No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841426288	85.517395	27.81212	1239.7494
1570	249819	RV	Indra Bahadur Bishwokarma	Indra Bahadur Bishwokarma	Sindhupalchowk	Sindhukot	5	0		Melanchi Municipality	5	53	531216		Kathmandu,Shankarapura-6	No Damage	1	Grade 5	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9803415749	85.527573	27.825912	1668.6592
1571</																												

1572	249851	RV	Bishwonath Khatiwoda	Bishwonath Khatiwoda	Sindhupalchowk	Sindhukot	6	0		Melamchi Municipality	5	101	531157		Kathmandu,Shank arapura-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841843962	85.509842	27.816397	1171.76	
1573	249736	RV	Rameshwor Chaulagain	Rameshwor Chaulagain	Sindhupalchowk	Sindhukot	7	0		Melamchi Municipality	5	28	531405		Kathmandu,Shank arapura-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860279714	85.505692	27.817312	1112.0408	
1574	249983	RV	Suntali Sapkota	Suntali Sapkota	Sindhupalchowk	Sipapokhari	1	0		Indrawati	7	16	361535		Kavrepalanchowk, Gauribisauna Deupur-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843078562	85.6054	27.751398	719.29218	
1575	249986	RV	Govinda P. Bhattarai	Govinda Prasad Bhattarai	Sindhupalchowk	Sipapokhari	1	0		Indrawati	7	22	361537		Kathmandu,Budha nikantha-14	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803375605	85.605629	27.757349	835.29602	
1576	249833	RV	Bal Krishna Dangal	Balkrishna Dangal	Sindhupalchowk	Sipapokhari	1	0		Indrawati	7	42	361559		Kathmandu,Kapan-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849494905	85.603027	27.76203	907.54578	
1577	249840	RV	Surya Keshar Dangal	Surya Keshar Dangal	Sindhupalchowk	Sipapokhari	1	0		Indrawati	7	44	361561		Kathmandu,Shank arapura-99	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841612171	85.603317	27.7619	915.93256	
1578	249909	RV	Krishna P. Dangal	Krishna Prasad Dangal	Sindhupalchowk	Sipapokhari	1	0		Indrawati	7	46	361563		Bhaktapur,Bhaktap ur-99	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841979185	85.6035	27.761995	915.26648	
1579	249827	RV	Bishnu P. Dangal	Bishnu Prasad Dangal	Sindhupalchowk	Sipapokhari	1	0		Indrawati	7	47	361564		Bhaktapur,Madhya pur Thimi-99	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9861111667	85.603691	27.762077	911.685	
1580	250764	RV	Nil Kumari Ghimire	Nilkumari Ghimire	Sindhupalchowk	Sipapokhari	1	0		Indrawati	7	70	540338		Kavrepalanchowk, Gauribisauna Deupur-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849825953	85.604485	27.761169	911.51868	
1581	249888	RV	Keshab P. Neupane	Keshab Prasad Neupane	Sindhupalchowk	Sipapokhari	1	0		Indrawati	7	145	403694		Kathmandu,Kathm andu-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851032572	85.612007	27.761992	1080.261	
1582	249968	RV	Ambika Sapkota	Ambika Sapkota	Sindhupalchowk	Sipapokhari	1	0		Indrawati	7	151	403700		Kavrepalanchowk, Gauribisauna Deupur-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843897280	85.61335	27.762138	1082.192	
1583	249892	RV	Raju Shrestha	Raju Shrestha	Sindhupalchowk	Sipapokhari	2	0		Indrawati	8	3	361580		Sindhupalchowk,8, hotSipa-3	Complete Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841040157	85.638863	27.762227	1311.4283	
1584	249906	RV	Bala Ram Acharya	Balaram Acharya	Sindhupalchowk	Sipapokhari	2	0		Indrawati	8	146	361849		Kathmandu,Kages wori-Manahara-9	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841388380	85.647026	27.772224	1100.2184	
1585	249971	RV	Khem B. Newar	Khem Bahadur Newar	Sindhupalchowk	Sipapokhari	3	0		Indrawati	8	19	361771		Bhaktapur,Balkot-9	Partial Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	980877532	85.631607, 85.631744	27.771612, 27.771799	1383.0391, 1399.271	
1586	249908	RV	Nabaraj Acharya	Nawaraj Acharya	Sindhupalchowk	Sipapokhari	3	0		Indrawati	8	36	361738		Kathmandu,Mulpa ni-9	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741043075	85.635902	27.770142	1334.7281	
1587	249831	RV	Narayan P. Acharya	Naran Acharya	Sindhupalchowk	Sipapokhari	3	0		Indrawati	8	64	361717		Kathmandu,Shank arapura-5	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851004983	85.642822	27.775738	1072.0754	
1588	250766	RV	Chiranjivi Acharya	Chiranjivi Acharya	Sindhupalchowk	Sipapokhari	3	0		Indrawati	8	66	361719		Bhaktapur,Duvakot -5	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841199005	85.642227	27.775423	1085.4225	
1589	249980	RV	Yadu Nath Acharya	Yadunath Acharya	Sindhupalchowk	Sipapokhari	3	0		Indrawati	8	67	361720		Kathmandu,Mulpa ni-9	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9741172613	85.641739, 85.641754	27.775051, 27.775059	1076.8214, 1084.1139	
1590	249886	RV	Kumale Sunuwar	Kumalae Sunuwar, Ramje Sunar, Sarmila Sunar	Sindhupalchowk	Sipapokhari	5	0		Indrawati	7	9	540034		Kathmandu,Shank arapura-2	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841639857	85.622581	27.756533	999.58624	
1591	249885	RV	Ramji Sunar	Kumalae Sunuwar, Ramje Sunar, Sarmila Sunar	Sindhupalchowk	Sipapokhari	5	0		Indrawati	7	9	540035		Kathmandu,Shank arapura-2	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841639857	85.622581	27.756533	999.58624	
1592	249838	RV	Ichhiha Ram Shrestha	Ichha Ram Shrestha	Sindhupalchowk	Sipapokhari	5	0		Indrawati	7	89	540121			2	Grade 1, Grade 5	Minor Repair, Reconstruct	Grade 1, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	9849310400	85.621483, 85.62162	27.757164, 27.757174	1011.0465, 1014.6027	
1593	249956	RV	Bharat Bdr Chaulagain	Bharat Bahadur Chaulagain	Sindhupalchowk	Sipapokhari	6	0		Indrawati	7	17	540276			1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	980482943	85.620193	27.763178	1112.5951	
1594	249891	RV	Nabaraj Chaulagain	Navaraj Chaulagain	Sindhupalchowk	Sipapokhari	6	0		Indrawati	7	19	540277		Sindhupalchowk,5i papokhari-2	Complete Damage	1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843189937	85.620972	27.763325	1148.3151
1595	249975	RV	Nirmala Dhungana	Netra Bahadur Dhungana	Sindhupalchowk	Sipapokhari	6	0		Indrawati	7	23	540281			2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9851152077	85.62159, 85.621635	27.7638, 27.765211	1099.0681, 1143.0031	
1596	248164	RV	Suntali Neupane	Pandav Neupane	Sindhupalchowk	Sipapokhari	7	0		Indrawati	7	4	540308			2	Grade 1, Grade 5	Not Required, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9849275658	85.621449, 85.62231	27.763588, 27.76271	1155.8341, 1160.1401	
1597	249898	RV	Chakra B. Kasha	Chakra Bahadur Kasahi	Sindhupalchowk	Sipapokhari	7	0		Indrawati	7	11	540316			2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9808253711	85.622185, 85.622688	27.763428, 27.76413	1123.1093, 1163.2808	
1598	249899	RV	Tara B. Kasha	Tara Bahadur Kasahi	Sindhupalchowk	Sipapokhari	7	0		Indrawati	7	12	540317			2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9849110870	85.622292, 85.622635	27.763667, 27.764093	1120.4858, 1150.7325	
1599	249830	RV	Deva Kumari Neupane	Rana Bahadur Neupane	Sindhupalchowk	Sipapokhari	7	0		Indrawati	7	13	540319			2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9810214518	85.622368, 85.622635	27.763987, 27.764284	1159.0541, 1168.356	
1600	249895	RV	Sudha Neupane	Rana Bahadur Neupane	Sindhupalchowk	Sipapokhari	7	0		Indrawati	7	13	540318			2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9810214518	85.622368, 85.622635	27.763987, 27.764284	1159.0541, 1168.356	
1601	249890	RV	Krishna B. Sarki	Krishna Bahadur Sarki	Sindhupalchowk	Sipapokhari	7	0		Indrawati	7	28	540359			2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9813844496	85.624313, 85.624542	27.765663, 27.765886	1142.2117, 1160.2596	
1602	249823	RV	Sohadra Sapkota	Madhu Sudhan Sapkota	Sindhupalchowk	Sipapokhari	7	0		Indrawati	7	97	540430			1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9851176932	85.62381	27.76026	994.79199	
1603	249960	RV	Sirjana Shrestha	Ser Bahadur Shrestha	Sindhupalchowk	Sipapokhari	9	0		Indrawati	8	27	540484			2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9808058220	85.632721, 85.632729	27.764715, 27.764734	1147.4323, 1153.3422	
1604	249979	RV	Ram B.Shrestha	Ram Bahadur Shrestha, Rukmadi Shrestha	Sindhupalchowk	Sipapokhari	9	0		Indrawati	8	29	540487			1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808846546	85.632736	27.764635	1163.5266	
1605	249961	RV	Tika Bdr Shrestha	Ram Bahadur Shrestha, Rukmadi Shrestha	Sindhupalchowk	Sipapokhari	9	0		Indrawati	8	29	540486			1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808846546	85.632736	27.764635	1163.5266	
1606	249962	RV	Subba Shrestha	Subbha Shrestha	Sindhupalchowk	Sipapokhari	9	0		Indrawati	8	53	398816			1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808014250	85.631546	27.765135	1112.621	
1607	249967	RV	Bhakta Bdr Shrashta	Bhakta Bahadur Shrestha	Sindhupalchowk	Sipapokhari	9	0		Indrawati	8	71	398835			2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9808845599	85.630241, 85.630539	27.761969, 27.76214	1043.8171, 1054.7491	
1608	249974	RV	Nabaraj Shrestha	Navaraj Shrestha	Sindhupalchowk	Sipapokhari	9	0		Indrawati	8	76	398840			2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Major Repair	Habitable House in Usual Place	9808415144	85.629944, 85.63015	27.761351, 27.761372	1046.463, 1046.8	
1609	249910	RV	Resham B. Shrestha	Resham Bahadur Shrestha	Sindhupalchowk	Sipapokhari	9	0		Indrawati	8	110	398877			2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9741168290	85.629501, 85.629578	27.760948, 27.761084	1028.1466, 1033.2423	
1610	255061	RV	Radhika Khatri Bhandari	Durga Bahadur Khatri	Sindhupalchowk	Sunkhani	1	0		Sunkoshi	5	11	407698		Kathmandu,Kapan-15	No Damage	1	Grade 5	Reconstruct	Grade 4	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741087013	85.819687	27.702152	1715.2946
1611	255632	RV	Netra Bahadur Budhathoki	Bhim Bahadur Budhathoki, Netra Bahadur Budhathoki	Sindhupalchowk	Sunkhani	2	0		Sunkoshi	5	86</																	

1656	252274	RV	Yam Bdr Khatri	Yam Bahadur Khatri	Sindhupalchowk	Syaule	9	0		Chautara Sagachowkgadhi Municipality	1	142	402448		Sindhupalchowk,C hautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849859006	85.716888	27.805532	1356.5988
1657	252188	RV	Goma Devi Nepal	Chetnath Nepal, Goma Devi Nepal	Sindhupalchowk	Syaule	9	0		Chautara Sagachowkgadhi Municipality	1	144	402450		Sindhupalchowk,C hautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841490443	85.7173	27.804998	1383.8662
1658	252196	RV	Govinda Pd Nepal	Gobinda Prasad Nepal, Krishna Prasad Nepal	Sindhupalchowk	Syaule	9	0		Chautara Sagachowkgadhi Municipality	1	149	402458		Sindhupalchowk,C hautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741088554	85.716904	27.805244	1368.8335
1659	252195	RV	Krishna Pd Nepal	Gobinda Prasad Nepal, Krishna Prasad Nepal	Sindhupalchowk	Syaule	9	0		Chautara Sagachowkgadhi Municipality	1	149	402457		Sindhupalchowk,C hautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741088554	85.716904	27.805244	1368.8335
1660	252270	RV	Krishna Pd Nepal	Krishna Prasad Nepal	Sindhupalchowk	Syaule	9	0		Chautara Sagachowkgadhi Municipality	1	151	402461		Sindhupalchowk,C hautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849767567	85.717499	27.805071	1374.6304
1661	252272	RV	Siva Pd Nepal	Shiva Prasad Nepal	Sindhupalchowk	Syaule	9	0		Chautara Sagachowkgadhi Municipality	1	152	402462		Sindhupalchowk,C hautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849342258	85.717194	27.805136	1375.1938
1662	252271	RV	Kedar Nath Padyanepal	Kedar Nath Padya Nepal	Sindhupalchowk	Syaule	9	0		Chautara Sagachowkgadhi Municipality	1	153	402463		Sindhupalchowk,C hautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841899906	85.717316	27.80514	1378.7843
1663	252273	RV	Gita Hari Nepal	Gita Hari Nepal	Sindhupalchowk	Syaule	9	0		Chautara Sagachowkgadhi Municipality	1	155	402465		Sindhupalchowk,C hautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841613100	85.717216	27.804895	1378.5449
1664	252268	RV	Jivan Nath Padya	Jib Nath Upadhya, Parvati Nepal	Sindhupalchowk	Syaule	9	0		Chautara Sagachowkgadhi Municipality	1	156	402466		Sindhupalchowk,C hautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741024169	85.717255	27.80485	1394.1198
1665	252183	RV	Parbati Nepal	Jib Nath Upadhya, Parvati Nepal	Sindhupalchowk	Syaule	9	0		Chautara Sagachowkgadhi Municipality	1	156	402467		Sindhupalchowk,C hautara-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Major reconstruct	Habitable House in Other Place	9741024169	85.717255	27.80485	1394.1198
1666	252175	RV	Chandra Bdr Khatri	Chandra Bahadur Khatri, Lok Bahadur Khatri, Rajendra Khatri	Sindhupalchowk	Syaule	9	0		Chautara Sagachowkgadhi Municipality	1	163	402475		Sindhupalchowk,C hautara-3/Sindhupalchowk, Chautara-3	Partial Damage, Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841424820	85.715958	27.808182	1288.2449
1667	252182	RV	Jethi Mai Tamang	Jethi Mai Tamang	Sindhupalchowk	Syaule	9	0		Chautara Sagachowkgadhi Municipality	1	185	402500				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9860215956	85.709984	27.801727	1643.2833
1668	248578	RV	Kesar Bahadur Gurung	Keshar Bahadur Gurung	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	11	510024			2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9803143838	85.949509, 85.953041	27.954182, 27.957903	1647.5795, 1940.353
1669	248463	RV	Keshar Bahadur Gurung	Keshar Bahadur Gurung	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	11	510024			2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9803143838	85.949509, 85.953041	27.954182, 27.957903	1647.5795, 1940.353
1670	248539	RV	Udeya Bahadur Gurung	Uday Bahadur Gurung	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	14	557878		Sindhupalchowk,T atopani-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808916600	85.950203	27.957682	1763.2247
1671	248542	RV	Lhundap Lama	Lhun Dup Lama	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	36	510501		Kathmandu,Chang unarayan-6	Partial Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9803738920	85.95269, 85.953552	27.960024, 27.960182	1740.3118, 1755.8584
1672	248579	RV	Bashudev Ghatani	Basudev Ghatani	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	54	510521			4	Grade 2, Grade 5, Grade 5, Grade 3	Minor Repair, Reconstruct, Reconstruct, Major Repair	Grade 2, Grade 5, Grade 5, Grade 3	Grade 2, Grade 5, Grade 5, Grade 3	Grade 2, Grade 5, Grade 5, Grade 3	Grade 2, Grade 5, Grade 5, Grade 3	Minor Repair, Reconstruct, Reconstruct, Major Repair	Habitable House in Usual Place	9803702750	85.954689, 85.955048, 85.956612, 85.956863	27.958466, 27.961823, 27.961924	1593.4578, 1599.0647, 1654.8477, 1658.0149
1673	248456	RV	Ganga Bahadur Khadka	Ganga Bahadur Khadka	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	82	510527			2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9851075657	85.954004, 85.955902	27.958448, 27.958628	1667.4279, 1668.8472
1674	248457	RV	Pandab Khadka	Pandav Khadka	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	83	510528			1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.954247	27.95859	1661.514
1675	248538	RV	Krishna Kumar Khadka	Manmaya Shrestha	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	91	510548		Sindhupalchowk,V otang-1	Complete Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818660436	85.955437	27.959608	1638.441
1676	248541	RV	Manmaya Shrestha	Manmaya Shrestha	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	91	510534		Sindhupalchowk,V otang-1	Complete Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818660436	85.955437	27.959608	1638.441
1677	248737	RV	Nimkuri Sharma	Nimphuri Sherpa	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	107	555128			1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9810228814	85.955971	27.959452	1595.3402
1678	248458	RV	Gokarna Newar	Gokarna Newar	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	113	555131			1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818522220	85.956421	27.961733	1629.8934
1679	248453	RV	Lakpa Sherpa	Lakpa Sherpa	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	125	555143			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818488542	85.955742	27.961452	1643.5193
1680	248455	RV	Santa Maya Shrestha	Santa Maya Shrestha	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	127	555145			1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	85.955666	27.961422	1647.9205	
1681	248576	RV	Tej Bahadur Shrestha	Tej Bahadur Shrestha	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	128	555146			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9813294728	85.955803	27.961849	1640.9496
1682	248461	RV	Dundup Tamang	Dundup Tamang	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	132	555147			1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	85.955894	27.962599	1665.0563	
1683	248811	RV	Saili Kamani	Saili Kamani	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	136	557901			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	85.9552	27.962355	1672.2783	
1684	248575	RV	Rathali Pradhan	Rathali Pradhan	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	137	557902		Sindhupalchowk,Li stkot-9	Complete Damage	1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	85.95565	27.961403	1634.5302
1685	248580	RV	Nima Sangmu Sherpa	Nim Sangmu Sherpa	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	140	557904			1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	85.955742	27.961704	1629.1887	
1686	248460	RV	Samsar B/K/	Samsar Bika	Sindhupalchowk	Tatopani	1	0		Bhotekoshi	2	142	557906			1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	85.955719	27.961073	1627.0773	
1687	248400	RV	Krishna Bahadur Tamang	Krishna Bahadur Tamang	Sindhupalchowk	Tatopani	2	0		Bhotekoshi	2	1	510576			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	85.947235	27.960178	2030.4244	
1688	248390	RV	Mithu Tamang	Mithu Tamang	Sindhupalchowk	Tatopani	2	0		Bhotekoshi	2	24	510599			2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Minor Repair	Habitable House in Usual Place	9813209962	85.95018, 85.951393	27.960182, 27.961418	1809.7748, 1887.9656
1689	248510	RV	Bir Bahadur Thami	Bir Bahadur Thami	Sindhupalchowk	Tatopani	2	0		Bhotekoshi	2	53	510636			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803130680	85.942734	27.957905	2141.9397
1690	248813	RV	Kumar Tamang	Kumar Tamang, Mangale Tamang	Sindhupalchowk	Tatopani	2	0	23-68-2-0-59	Bhotekoshi	2	62	510646			1	Grade 3	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.945068	27.955875	2044.0905
1691	248476	RV	Bal Bahadur Bhandari	Bal Bahadur Bhandari	Sindhupalchowk	Tatopani	2	0		Bhotekoshi	2	71	510655			2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 1, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	9818965135	85.951607, 85.952118	27.961275, 27.961292	1793.5693, 1796.0459
1692	248392	RV	Dipak Shrestha	Dipak Shrestha	Sindhupalchowk	Tatopani	2	0		Bhotekoshi	2	87	510673			2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 3	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	85.945076, 85.955772	27.956848, 27.961847	1649.0367, 2066.0566	
1693	248474	RV	Dipak Shrestha	Dipak Shrestha	Sindhupalchowk	Tatopani	2	0		Bhotekoshi	2	87	510673			2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 3	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	85.945076, 85.955772	27.956848, 27.961847	1649.0367, 2066.0566	
1694	248393	RV	Maya Tamang	Maya Tamang	Sindhupalchowk	Tatopani	2	0		Bhotekoshi	2	94	510681			1	Grade 2	Minor Repair	Grade 2	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9818626375	85.951599	27.9613	1800.4865
1695	248512	RV	Yukta Bahadur Paudel	Yutta Bahadur Poudel	Sindhupalchowk	Tatopani	2	0		Bhotekoshi	2	107	510695			2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	85.952843, 85.952911	27.962898, 27.963099	1809.4806, 1814.3301	
1696	248397	RV	Bir Bahadur Raut	Bir Bahadur Raut	Sindhupalchowk	Tatopani	2	0		Bhotekoshi	2	108	510696			1	Grade 2	Minor Repair	Grade 2	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	85.952492	27.962933	1823.7968	
1697	248394	RV	Khika Bahadur Paudel	Khika Bahadur Poudel	Sindhupalchowk	Tatopani	2	0		Bhotekoshi	2	111	510699			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9816634277	85.952011	27.962927	1829.4707
1698	248398	RV	Damai Thami	Damai Thami	Sindhupalchowk	Tatopani	2	0		Bhotekoshi	2	113	510001			1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	85.945831	27.964508	2120.1577	
1699	249119	RV	Anita Thami	Serabu Sherpa	Sindhupalchowk	Tatopani	3	0		Bhotekoshi	2	25	515205			2	Grade 2, Grade 4	Minor Repair, Reconstruct	Grade 2, Grade 3	Grade 2, Grade 3	Grade 2, Grade 3	Grade 2, Grade 3	Minor Repair, Major Repair	Habitable House in Usual Place	9808053102	85.958702, 85.961983	27.971468, 27.972414	1707.5502, 1813.3622
1700	249103	RV	Seranu Sherpa	Serabu Sherpa	Sindhupalchowk	Tatopani	3	0		Bhotekoshi	2	25	515202			2	Grade 2, Grade 4	Minor Repair, Reconstruct	Grade 2, Grade 3	Grade 2, Grade 3	Grade 2, Grade 3	Grade 2, Grade 3	Minor Repair, Major Repair	Habitable House in Usual Place	9808053102	85.958702, 85.961983	27.971468, 27.972414	1707.5502, 1813.3622

1701	249118	RV	Bhuti Tamangni	Tenzing Sherpa	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	26	515206		Kathmandu,Kathmandu-6	No Damage	2	Grade 1, Grade 3	Minor Repair, Major Repair	Grade 1, Grade 3	Grade 1, Grade 2	Grade 1, Grade 2	Minor Repair, Major Repair	Habitable House in Other Place	9841196124	85.960335, 85.962646	27.972132, 27.972424	1690.5228, 1795.094	
1702	248325	RV	Nir Bahadur Thami	Bir Bahadur Thami	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	32	515212				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9813200559	85.959824	27.971104	1782.594	
1703	249105	RV	Buddhiman Tamang	Budhiman Tamang	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	33	515213				1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9803476522	85.960777	27.973286	1829.5076	
1704	248718	RV	Yokpo Chhiri Sherpa	Yokpo Chhiri Sherpa	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	37	515217				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9808090885	85.961121	27.972822	1784.5265	
1705	249098	RV	Chhnam Sherpa	Chhanam Sherpa	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	49	515223				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841122282	85.962868	27.972887	1709.4902	
1706	248336	RV	Maresh Magar	Maresh Magar	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	61	515181				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9813221888	85.957817	27.962519	1579.5791	
1707	249113	RV	Kul Bahadur Shrestha	Kul Bahadur Sherst	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	69	515188				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803828453	85.962097	27.971754	1635.7063	
1708	248334	RV	Dhan Bahadur Magar	Dhan Bahadur Magar	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	80	515199				1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803828456	85.949081	27.944635	1451.7261	
1709	248389	RV	Fulmaya Tamang	Phulamaya Tamang	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	85	517578				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9808916675	85.960754	27.971338	1497.5621	
1710	249108	RV	Nhawong Chhoti Sherpa	Nhawa Chhuti Sherpa, Sange Sherpa	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	94	517585			Kathmandu,Kathmandu-6	Partial Damage	1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	9841710259	85.960449	27.970716	1646.5691
1711	248339	RV	Rajesh Magar	Rajesh Magar	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	103	515010			Kathmandu,Kapal-6	Partial Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	9801085365	85.958969	27.968721	1670.1959
1712	248445	RV	Swosthani Paudel	Swasthani Paudel	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	113	517601					1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	986109260	85.960976	27.970706	1665.8862
1713	249044	RV	Sachamaya Tamangni	Sachamaya Tamangni	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	115	517603					1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818092644	85.960606	27.969597	1671.6075
1714	248443	RV	Raj Kumar Tamang	Raj Kumar Tamang	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	118	517606					1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9808154181	85.959961	27.970245	1673.8784
1715	249045	RV	Indra Maya Gurung	Indra Maya Gurungni	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	126	517609					1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803194981	85.959709	27.96913	1641.7754
1716	249120	RV	Nurpu Sherpa	Dawa Yangji Sherpa	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	127	517610					1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9808209115	85.959785	27.969507	1655.2377
1717	249111	RV	Bal Bahadur Newar	Bal Bahadur Newar	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	128	517611					1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.959641	27.969086	1681.1897
1718	249112	RV	Hem Kumar Shrestha	Hem Kumari Shrestha	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	129	517612					1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9813625973	85.959702	27.969259	1633.5588
1719	249047	RV	Lok Bahadur Gurung	Lok Bahadur Gurung, Tej Bahadur Gurung	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	134	517618					1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843010564	85.959557	27.969255	1653.5037
1720	249046	RV	Tej Bahadur Gurung	Lok Bahadur Gurung, Tej Bahadur Gurung	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	134	517619					1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9843010564	85.959557	27.969255	1653.5037
1721	249041	RV	Pgurba Sherpini	Phurpa Sherpini	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	138	517623					1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9813435159	85.958443	27.968603	1719.0421
1722	249115	RV	Pema Sherpa	Pema Sherpa	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	147	517910					1	Grade 2	Minor Repair	Grade 2	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9841074893	85.958496	27.967512	1676.0415
1723	249107	RV	Chitra Bahadur Gurung	Chitra Bahadur Gurung	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	154	517917					1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.95932	27.968813	1637.8184
1724	249037	RV	Bishalamu Shrestha	Bishalamu Shrestha, Jal Bahadur Shrestha, Kamal Bahadur Shrestha, Shanta Bahadur Shrestha	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	157	517922					1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9808060398	85.958809	27.967178	1648.9199
1725	249035	RV	Jal Bahadur Shrestha	Bishalamu Shrestha, Jal Bahadur Shrestha, Kamal Bahadur Shrestha, Shanta Bahadur Shrestha	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	157	517920					1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9808060398	85.958809	27.967178	1648.9199
1726	249036	RV	Jal Bahadur Shrestha	Bishalamu Shrestha, Jal Bahadur Shrestha, Kamal Bahadur Shrestha, Shanta Bahadur Shrestha	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	157	517921					1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9808060398	85.958809	27.967178	1648.9199
1727	249033	RV	Shanta Bahadur Shrestha	Bishalamu Shrestha, Jal Bahadur Shrestha, Kamal Bahadur Shrestha, Shanta Bahadur Shrestha	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	157	517919					1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9808060398	85.958809	27.967178	1648.9199
1728	249124	RV	Gore Gurung	Gore Gurung	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	158	517923					1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9860386985	85.958282	27.963123	1613.8262
1729	248449	RV	Bharatraj Ghale	Bharat Raj Ghale	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	159	517925					1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9811882520	85.957863	27.963217	1600.412
1730	249106	RV	Lila K/ Gurung	Chin Bahadur Gurung	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	168	515011					1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place		85.959091	27.968485	1646.0551
1731	248451	RV	Dal Bahadur Gurung	Dal Bahadur Gurung	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	169	515012					1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.959061	27.968485	1636.4794
1732	249126	RV	Sanja Bahadur Thami	Sanj Bahadur Thami	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	170	515054					2	Grade 1, Grade 3	Not Required, Major Repair	Grade 1, Grade 3	Grade 1, Grade 3	Grade 1, Grade 3	Not Required, Major Repair	Habitable House in Usual Place	9808108012	85.953491, 85.958733	27.965807, 27.967567	1634.835, 1881.1511
1733	248327	RV	Pari Thami	Bidda Man Thami	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	177	515018					1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9808178435	85.949127	27.965162	1960.5358
1734	249040	RV	Sanjamam Thami	Sanjamam Thami	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	180	515021					1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place		85.949516	27.964989	1938.8773
1735	249102	RV	Sukumam Thami	Suku Man Thami	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	191	515032					1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.95134	27.965588	1908.8971
1736	248410	RV	Damai Thami	Damai Thami	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	192	515033					1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9803130745	85.9515	27.965876	1918.8568
1737	249125	RV	Aita Bahadur Thami	Aait Bahadur Thami	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	210	515051					1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.953545	27.965906	1884.5333
1738	249031	RV	Bumta Bahadur Thami	Bukta Bahadur Thami	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	212	515053					1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9803130517	85.95359	27.965899	1885.9247
1739	248444	RV	Kailash Rajalli	Kailash Rajalli	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	244	515087					1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9851121915	85.955414	27.963671	1723.0173
1740	248812	RV	Arjun Bahadur Raut	Arjun Bahadur Raut	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	245	515088			Sindhupalchowk,Tatopani-1	Partial Damage	1	Grade 2	Minor Repair	Grade 1	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	9849378753	85.954948	27.96394	1736.3517
1741	248341	RV	Sukummay Kamani	Ram Kaji Kami	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	246	515089					2	Grade 4, Grade 2	Reconstruct, Minor Repair	Grade 4, Grade 2	Unrecognized, Grade 2	Unrecognized, Grade 2	Unrecognized, Minor Repair	Habitable House in Usual Place	9808018756	85.95546, 85.955521	27.963491, 27.963537	1688.5345, 1697.8801
1742	249097	RV	Lal Bahadur Kami	Lal Bahadur Kami	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	254	515099					1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place		85.956833	27.962612	1625.5701
1743	248335	RV	Padam Bahadur Magar	Ambar Bahadur Aale, Padam Bahadur Magar	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	256	515102					1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9851053818	85.957497	27.963583	1860.7723
1744	249101	RV	Pasang Tamang	Somlamu Sherpa	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	259	515105			Kathmandu,Shankarapura-6	No Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	9841382156	85.957664	27.963312	1615.0386
1745	248329	RV	Nima Sherpa	Nima Sherpa	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	263	515110					1	Grade 1	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9810228485	85.957169	27.963871	1644.3625
1746	249034	RV	Kale Tamang	Kale Tamang	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	266	515113			Kathmandu,Shankarapura-7	No Damage	1	Grade 3	Major Repair	Grade 3	Grade 3	Grade 3	Major Repair	Habitable House in Other Place	9741006363	85.957581	27.962666	1604.5726
1747	248333	RV	Man Bahdur Tamang	Binod Tamang, Man Bahadur Tamang	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	270	515117					1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803965180	85.957527	27.962765	1587.7783
1748	248331	RV	Bhakta Bahadur Tamang	Bhakta Bahadur Tamang	Sindhupalchowk	Tatopani	3	0		BhoteKoshi	2	271	51																

1796	250673	RV	Mishree Lal Shrestha	Mishri Lal Shrestha	Sindhupalchowk	Tauthali	3	0					Tripurasundari	5	17	331769		Lalitpur,Tikathali-10	No Damage	1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Other Place	9851163361	85.907448	27.720666	1900.1071	
1797	250621	RV	Lal Bdr Shrestha	Chandra Bahadur Shrestha, Lal Bahadur Shrestha, Suntala Shrestha	Sindhupalchowk	Tauthali	3	0					Tripurasundari	5	42	331805		Kathmandu,Gokar neswor-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860224728	85.908333	27.726313	1893.2565	
1798	250669	RV	Suntala Shrestha	Chandra Bahadur Shrestha, Lal Bahadur Shrestha, Suntala Shrestha	Sindhupalchowk	Tauthali	3	0					Tripurasundari	5	42	331804		Kathmandu,Gokar neswor-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860224728	85.908333	27.726313	1893.2565	
1799	250626	RV	Bibek Dash Shrestha	Bhagat Kumar Shrestha, Bibek Dash Shrestha, Deepak Kumar Shrestha, Dhiraj Shrestha, Indash Shrestha, Mulke Dash Shrestha, Yagya Dash Shrestha	Sindhupalchowk	Tauthali	3	0					Tripurasundari	5	49	331821		Kathmandu,Kapan-3/Kathmandu,Kath mandu-34/Kathmandu,Kat hmandu-34/Kathmandu,Kat hmandu-3/Kathmandu,Kath mandu-34/Kathmandu,Shan karapura-7/Lalitpur,Tikathali-6	No Damage, No Damage, No Damage, No Damage, Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.908257	27.725965	1896.7305	
1800	250625	RV	Bhuban Dash Shrestha	Bhuwan Dash Shrestha, Govinda Raj Shrestha, Hemant Dash Shrestha, Kabi Dash Shrestha, Niraj Kumar Shrestha, Yub Dash Shrestha	Sindhupalchowk	Tauthali	3	0					Tripurasundari	5	50	331823		Kathmandu,Gokar neswor-1/Kathmandu,Gok arneswor-16/Kathmandu,Kat hmandu-3/Kathmandu,Kath mandu-34	No Damage, Partial Damage, Partial Damage, Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place		85.908401	27.725878	1890.0625	
1801	250771	RV	Hemanta Dash Shrestha	Bhuwan Dash Shrestha, Govinda Raj Shrestha, Hemant Dash Shrestha, Kabi Dash Shrestha, Niraj Kumar Shrestha, Yub Dash Shrestha	Sindhupalchowk	Tauthali	3	0					Tripurasundari	5	50	364727		Kathmandu,Gokar neswor-1/Kathmandu,Gok arneswor-16/Kathmandu,Kat hmandu-3/Kathmandu,Kath mandu-34	No Damage, Partial Damage, Partial Damage, Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place		85.908401	27.725878	1890.0625	
1802	250624	RV	Kabi Dash Shrestha	Bhuwan Dash Shrestha, Govinda Raj Shrestha, Hemant Dash Shrestha, Kabi Dash Shrestha, Niraj Kumar Shrestha, Yub Dash Shrestha	Sindhupalchowk	Tauthali	3	0					Tripurasundari	5	50	331825		Kathmandu,Gokar neswor-1/Kathmandu,Gok arneswor-16/Kathmandu,Kat hmandu-3/Kathmandu,Kath mandu-34	No Damage, Partial Damage, Partial Damage, Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place		85.908401	27.725878	1890.0625	
1803	250664	RV	Naresh Bdr Shrestha	Naresh Kumar Shrestha	Sindhupalchowk	Tauthali	3	0					Tripurasundari	5	55	364741					1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9851014137	85.909286	27.725842	1908.6315
1804	250662	RV	Tek Bdr Shrestha	Tek Bahadur Shrestha	Sindhupalchowk	Tauthali	3	0					Tripurasundari	5	69	364763		Bhaktapur,Balkot-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841310638	85.910164	27.725372	1932.2954	
1805	250504	RV	Hera Bdr Shrestha	Hira Bahadur Shrestha	Sindhupalchowk	Tauthali	3	0					Tripurasundari	5	88	364788		Kathmandu,Kapan-3	No Damage	1	Grade 4	Reconstruct	Grade 3	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place		85.910095	27.725603	1926.8989	
1806	250505	RV	Bhaerub Bdr Shrestha	Suman Shrestha, Takal Bahadur Shrestha, Vairav Bahadur Shrestha	Sindhupalchowk	Tauthali	3	0					Tripurasundari	5	111	364813		Kathmandu,Shank arapura-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place		85.908554	27.726465	1912.6232	
1807	250670	RV	Ram Shrestha	Ram Shrestha	Sindhupalchowk	Tauthali	3	0					Tripurasundari	5	123	364861					1	Grade 1	Not Required	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841706369	85.910385	27.72497	1932.8301
1808	250780	RV	Ganga Das Shrestha	Ganga Dash Shrestha	Sindhupalchowk	Tauthali	3	0					Tripurasundari	5	124	364862					1	Grade 1	Not Required	Grade 2	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9741122721	85.908699	27.723927	1889.4551
1809	250512	RV	Bhim Bdr Shrestha	Bhim Bahadur Shrestha, Padam Bahadur Shrestha, Prem Bahadur Shrestha	Sindhupalchowk	Tauthali	4	0					Tripurasundari	5	46	1174161					2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place		85.907707, 85.907753	27.726658, 27.726734	1900.7837, 1903.8702
1810	250514	RV	Padam Shrestha	Bhim Bahadur Shrestha, Padam Bahadur Shrestha, Prem Bahadur Shrestha	Sindhupalchowk	Tauthali	4	0					Tripurasundari	5	46	1174159					2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place		85.907707, 85.907753	27.726658, 27.726734	1900.7837, 1903.8702
1811	250513	RV	Prame Bdr Shrestha	Bhim Bahadur Shrestha, Padam Bahadur Shrestha, Prem Bahadur Shrestha	Sindhupalchowk	Tauthali	4	0					Tripurasundari	5	46	1174160					2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place		85.907707, 85.907753	27.726658, 27.726734	1900.7837, 1903.8702
1812	250516	RV	Makeer Dhoj Shrestha	Makar Dhoj Shrestha	Sindhupalchowk	Tauthali	4	0					Tripurasundari	5	57	1174175					2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Minor Repair	Habitable House in Usual Place	9741255262	85.906929, 85.906975	27.726568, 27.726645	1896.4688, 1897.1154
1813	250499	RV	Meshree Maya Shrestha	Man Kumar Shrestha, Misri Maya Shrestha, Ram Bdr Shrestha, Talak Bdr Shrestha	Sindhupalchowk	Tauthali	6	0					Tripurasundari	5	24	1176445					1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841505704	85.904678	27.725159	1868.3688
1814	250425	RV	Cheni Bdr Shrestha	Chini Bdr Shrestha	Sindhupalchowk	Tauthali	7	0					Tripurasundari	5	126	1176523					2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Unrecognized	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9741154100	85.902222	27.74003	1349.1455
1815	250422	RV	Suntala Thimi	Dhan Bdr Thami	Sindhupalchowk	Tauthali	7	0					Tripurasundari	5	178	401544	23-69-7-0-157				1	Grade 4	Reconstruct	Grade 3	Unrecognized	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.897133	27.740313	1561.1738
1816	250432	RV	Chini Bdr Shrestha	Chini Bdr Shrestha	Sindhupalchowk	Tauthali	8	0					Tripurasundari	5	167	401554					1	Grade 1	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9741215376	85.893204	27.729399	1486.3658
1817	250312	RV	Chitra Bdr Shrestha	Chitra Bdr Shrestha	Sindhupalchowk	Tauthali	9	0					Tripurasundari	5	118	391745					1	Grade 2	Minor Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849227293	85.889137	27.736244	1517.9807
1818	257215	RV	Ram Maya Shrestha	Rammaya Shrestha	Sindhupalchowk	Tekapur	1	0	DAMSIDE				Tripurasundari	6	14	339515					2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 3	Grade 5, Unrecognized	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9860722883	85.86702, 85.867165	27.756468, 27.756571	728.3808, 733.46271
1819	257201	RV	Sukra Maya Shrestha	Bhakta Dhoj Shrestha	Sindhupalchowk	Tekapur	1	0	GHATEDADA				Tripurasundari	6	29	339525					2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 4, Grade 2	Grade 4, Grade 2	Grade 4, Grade 2	Grade 4, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9741112318	85.861015, 85.861084	27.751278, 27.752441	776.08832, 797.82111
1820	257098	RV	Bhagwati Nepali	Bhagawati Nepal	Sindhupalchowk	Tekapur	2	0	BUKINI PIPAL DADA				Tripurasundari	6	10	339471					1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9849139484	85.868271	27.751875	1098.3644
1821	257219	RV	Chet Bahadur Budhathoki	Chet Bahadur Budhathoki	Sindhupalchowk	Tekapur	3	0	RATMATA				Tripurasundari	6	63	339218		Bhaktapur,Ananata lingswor-9	Partial Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9843660803	85.873482, 85.874199	27.751278, 27.75153	1244.2429, 1259.2181	
1822	257202	RV	Min Bahadur Khatri	Meen Bahadur Khatri	Sindhupalchowk	Tekapur	3	1	DHARAPANI				Tripurasundari	6	1	339188					2	Grade 1, Grade 4	Not Required, Reconstruct	Grade 1, Grade 4	Grade 1, Grade 4	Grade 1, Grade 4	Grade 1, Grade 4	Not Required, Reconstruct	Habitable House in Usual Place	9843148075	85.876022, 85.876358	27.756418, 27.756866	1106.9546, 1117.0483
1823	257199	RV	Tilak Bahadur Bohara	Tilak Bahadur Bohara	Sindhupalchowk	Tekapur	4	0	TEKANPUR				Tripurasundari	6	1	339081		Bhaktapur,Duvakot-99	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741170812	85.877655	27.751116	1333.6486
1824	257130	RV	Ratna Bahadur Bohara	Ratna Bahadur Bohara	Sindhupalchowk	Tekapur	4	0	PUCHARGAUN				Tripurasundari	6	27	339033					3	Grade 5, Grade 4, Grade 2	Reconstruct, Reconstruct, Minor Repair	Grade 5, Grade 4, Grade 2	Grade 5, Grade 4, Grade 2	Grade 5, Grade 4, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9861200695	85.877693, 85.877708, 85.877815	27.751097, 27.751156, 27.751251	1343.3234, 1348.0198, 1348.4447	
1825	257206	RV	Bhim Dhvaj Bohara	Bhim Dhoj Bohara	Sindhupalchowk	Tekapur	4	0	CHULIDADA				Tripurasundari	6	33	339040					2	Grade 4, Grade 2	Reconstruct, Minor Repair	Grade 4, Grade 2	Grade 4, Grade 2	Grade 4, Grade 1	Grade 4, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9841019655	85.879677, 85.879738	27.75148, 27.751585	1374.1982, 1381.5853
1826	257204	RV	Sushanta Bohara	Sushant Bohara	Sindhupalchowk	Tekapur	4	0	JOKHE BARI				Tripurasundari	6	37	339044					1	Grade 2	Minor Repair	Grade 2	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9841101343	85.879044	27.751255	1368.6873
1827	257101	RV	Nanda Kumari	Nanda Kumari Bohara	Sindhupalchowk	Tekapur	4	0	FOTI BESI				Tripurasundari	6	49	339526		Bhaktapur,Bhaktapur-99	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841533860	85.885887	27.754515	1107.8131	

1828	257094	RV	Nar Bahadur Bhusel	Nara Bahadur Bhujel	Sindhupalchowk	Tekanpur	4	0	JAISIDADA	Tripurasundari	6	53	339530		Sindhupalchowk,T ekangpur-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849445156	85.880081	27.754864	1268.0381
1829	251406	RV	Hira Bhusel	Hira Bhujel	Sindhupalchowk	Tekanpur	4	0	DABALI	Tripurasundari	6	59	339535		Kathmandu,Kapan-3	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9849265594	85.878273	27.750925	1340.4716
1830	257122	RV	Arjun Bohara Chhetri	Arjun Bohara Chhetri	Sindhupalchowk	Tekanpur	5	0	SALENI	Tripurasundari	6	38	339003				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803080011	85.879822	27.751293	1375.9954
1831	257097	RV	Ramesh Bohara	Ramesh Bohara	Sindhupalchowk	Tekanpur	5	0	TEKANPUR	Tripurasundari	6	41	339006		Sindhupalchowk,T ekanpur-4	No Damage	1	Grade 4	Reconstruct	Grade 3	Grade 2	Unrecognized	Unrecognized	Habitable House in Other Place	9860886287	85.878883	27.750328	1345.7603
1832	257208	RV	Prem Bhusel	Prem Bahadur Bhujel	Sindhupalchowk	Tekanpur	8	0	GAURA TOL	Tripurasundari	6	8	339349				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Unrecognized	Habitable House in Usual Place	9818901908	85.890633, 85.890846	27.746901, 27.747107	1342.7261, 1348.7284
1833	250195	RV	Aka Bdr Aryal	Ek bahadur Tamang	Sindhupalchowk	Thakani	2	0		Melamchi Municipality	4	8	536251		Sindhupalchowk,H aibung-3	Partial Damage	1	Grade 3	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9843878063	85.495316	27.829065	1583.4242
1834	250199	RV	Ram Bdr Aryal	Ram Bahadur Aryal, Roshan Aryal	Sindhupalchowk	Thakani	2	0		Melamchi Municipality	4	18	536270				2	Grade 3, Grade 2	Major Repair, Minor Repair	Grade 3, Grade 3	Unrecognized, Grade 2	Unrecognized, Grade 2	Unrecognized, Minor Repair	Habitable House in Usual Place	9861244605	85.493507, 85.494057	27.830339, 27.830936	1522.6692, 1530.4905
1835	250206	RV	Roshan Aryal	Ram Bahadur Aryal, Roshan Aryal	Sindhupalchowk	Thakani	2	0		Melamchi Municipality	4	18	536244				2	Grade 3, Grade 2	Major Repair, Minor Repair	Grade 3, Grade 3	Unrecognized, Grade 2	Unrecognized, Grade 2	Unrecognized, Minor Repair	Habitable House in Usual Place	9861244605	85.493507, 85.494057	27.830339, 27.830936	1522.6692, 1530.4905
1836	250257	RV	Jaya Ram Aryal	Jay Ram Aryal, Krishna Aryal	Sindhupalchowk	Thakani	2	0		Melamchi Municipality	4	20	536274	23-71-2-0-18			1	Grade 3	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9841257130	85.493668	27.828983	1503.5864
1837	250190	RV	Dala Bdr Aryal	Dal Bahadur Aryal, Netra Bahadur Aryal	Sindhupalchowk	Thakani	2	0		Melamchi Municipality	4	23	536228	23-71-2-0-21			2	Grade 3, Grade 4	Major Repair, Major Repair	Grade 3, Grade 3	Unrecognized, Grade 3	Unrecognized, Grade 3	Unrecognized, Major Repair	Matrix & Photo not cleared or mismatch	9841709243	85.49295, 85.492989	27.830433, 27.830553	1492.6714, 1500.177
1838	250327	RV	Lalit Bdr Aryal	Lalit Bahadur Aryal, Lila Bahadur Aryal	Sindhupalchowk	Thakani	2	0		Melamchi Municipality	4	27	536234		Kathmandu,Shank arapura-1	Partial Damage	1	Grade 4	Reconstruct	Grade 3	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841405000	85.493332	27.831453	1514.2572
1839	250275	RV	Gobinda Bdr Aryal	Dil Bahadur Aryal	Sindhupalchowk	Thakani	2	0		Melamchi Municipality	4	43	536206	23-71-2-0-39			1	Grade 4	Reconstruct	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849915511	85.491928	27.829182	1411.209
1840	250414	RV	Kumar Aryal	Krishna Bahadur Aryal, Kumar Aryal	Sindhupalchowk	Thakani	2	0		Melamchi Municipality	4	45	536209				2	Grade 4, Grade 1	Reconstruct, Not Required	Grade 3, Grade 3	Grade 3, Unrecognized	Grade 3, Unrecognized	Major Repair, Unrecognized	Matrix & Photo not cleared or mismatch	9860591068	85.49099, 85.491852	27.82513, 27.828972	1249.6082, 1397.7832
1841	250196	RV	Shankar Aryal	Krishna Bahadur Aryal, Shankar Aryal	Sindhupalchowk	Thakani	2	0		Melamchi Municipality	4	48	536213	23-71-2-0-43			1	Grade 3	Major Repair	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9851096830	85.492287	27.828125	1399.5687
1842	250185	RV	Shiba Prasad Khanal	Shiva Prasad Khanal	Sindhupalchowk	Thakani	2	0		Melamchi Municipality	4	89	536136				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 3	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9841288117	85.490944, 85.490974	27.824879, 27.824978	1236.0275, 1247.6497
1843	250189	RV	Sabina Thapa Aryal	Ambar Bahadur Aryal	Sindhupalchowk	Thakani	3	0		Melamchi Municipality	4	9	536011	23-71-3-0-9			2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Unrecognized, Grade 5	Unrecognized, Grade 5	Unrecognized, Reconstruct	Matrix & Photo not cleared or mismatch	9849693920	85.494255, 85.49437	27.826204, 27.826206	1415.5952, 1416.3439
1844	250324	RV	Krishna Prasad Khanal	Krishna Prasad Khanal	Sindhupalchowk	Thakani	3	0		Melamchi Municipality	4	50	536089		Kathmandu,Shank arapura-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849166888	85.496704	27.821409	1236.1332
1845	250265	RV	Chiranjivi Khanal	Chiranjibi Khanal	Sindhupalchowk	Thakani	3	0		Melamchi Municipality	4	56	536095		Kathmandu,Kathm andu-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	54016182	85.496315	27.821846	1226.1
1846	250348	RV	Bishal Tamang	Jay Bahadur Tamang	Sindhupalchowk	Thakani	4	0		Melamchi Municipality	4	41		23-71-4-0-41			2	Grade 4, Grade 3	Reconstruct, Major Repair	Grade 3, Grade 3	Grade 4, Unrecognized	Grade 4, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9813949165	85.473129, 85.473312	27.836679, 27.836786	1532.2992, 1532.3325
1847	250415	RV	Chalan Bdr Tamang	Chalan Bahadur Tamang	Sindhupalchowk	Thakani	4	0		Melamchi Municipality	4	102	509485		Kathmandu,Kathm andu-6	Partial Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9741025354	85.48262, 85.482788	27.832073, 27.832151	1529.3157, 1530.2833
1848	250394	RV	Aaiman Singh Tamang	Eiman Sing Tamang	Sindhupalchowk	Thakani	5	0		Melamchi Municipality	4	10	536335				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 2	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9841685678	85.498749, 85.498932	27.850809, 27.850975	1597.7194, 1605.705
1849	250789	RV	Jit Bdr Tamang	Jit Bahadur Tamang, Somar Singh Tamang	Sindhupalchowk	Thakani	5	0		Melamchi Municipality	4	56	534462				2	Grade 4, Grade 2	Reconstruct, Minor Repair	Grade 3, Grade 2	Grade 4, Unrecognized	Grade 4, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9842117317	85.495491, 85.495506	27.849678, 27.849728	1623.2361, 1628.7684
1850	250391	RV	Man Bdr Tamang	Man Bahadur Tamang	Sindhupalchowk	Thakani	5	0		Melamchi Municipality	4	135	536292		Kathmandu,Danch hi-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843762182	85.495323	27.844435	1778.4869
1851	250403	RV	Indra Bdr Tamang	Indra Bahadur Tamang	Sindhupalchowk	Thakani	6	0		Melamchi Municipality	4	13	515789				2	Grade 4, Grade 2	Major Repair, Minor Repair	Grade 3, Grade 3	Grade 4, Grade 2	Grade 4, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9818316363	85.457191, 85.457962	27.847986, 27.84827	1763.6133, 1784.1678
1852	250269	RV	Laxman Tamang	Laxman Tamang, Mangale Tamang, Ram Bahadur Tamang	Sindhupalchowk	Thakani	6	0		Melamchi Municipality	4	115	515892		Kathmandu,Danch hi-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841045106	85.479912	27.837532	1609.9827
1853	250410	RV	Mangale Tamang	Laxman Tamang, Mangale Tamang, Ram Bahadur Tamang	Sindhupalchowk	Thakani	6	0		Melamchi Municipality	4	115	515890		Kathmandu,Danch hi-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841045106	85.479912	27.837532	1609.9827
1854	250341	RV	Ram Bdr Tamang	Laxman Tamang, Mangale Tamang, Ram Bahadur Tamang	Sindhupalchowk	Thakani	6	0		Melamchi Municipality	4	115	515891		Kathmandu,Danch hi-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841045106	85.479912	27.837532	1609.9827
1855	250398	RV	Jir Lama Tamang	Jir Lama Tamang	Sindhupalchowk	Thakani	8	0		Melamchi Municipality	4	205	516439				3	Grade 2, Grade 5, Grade 3	Minor Repair, Reconstruct, Major Repair	Grade 2, Grade 5, Grade 3	Grade 2, Grade 5, Unrecognized	Grade 2, Grade 5, Unrecognized	Minor Repair, Reconstruct, Unrecognized	Habitable House in Usual Place	9813843760	85.459854, 85.459869, 85.459869	27.858536, 27.858561, 27.858582	1797.9421, 1811.3556, 1815.1959
1856	250405	RV	Pema Tamang	Pema Tamang	Sindhupalchowk	Thakani	9	0		Melamchi Municipality	4	4	515263		Kathmandu,Gokar neswor-16	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808636520	85.456833	27.86795	2161.3491
1857	248151	RV	Sen Dorje Tamang	Sen Dorge Tamang	Sindhupalchowk	Thakani	9	0		Melamchi Municipality	4	5	515264		Kathmandu,Gokar neswor-15	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9808523512	85.457504	27.868103	2166.9971
1858	250399	RV	Sanji Tamang	Phulmaya Tamang	Sindhupalchowk	Thakani	9	0		Melamchi Municipality	4	52	399464	23-71-9-0-48			1	Grade 4	Reconstruct	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9841880235	85.469368	27.872837	1941.2754
1859	247901	RV	Kubal Giri	Kubal Giri, Lok Bahadur Giri	Sindhupalchowk	Thangpalchhap	1	0		Pachpokhari Thangpal	6	27	395705	23-72-1-0-27			2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9611083008	85.643196, 85.643265	27.934092, 27.935398	1443.462, 1496.6683
1860	247825	RV	Lok Bahadur Giri	Kubal Giri, Lok Bahadur Giri	Sindhupalchowk	Thangpalchhap	1	0		Pachpokhari Thangpal	6	27	395706	23-72-1-0-27			2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9611083008	85.643196, 85.643265	27.934092, 27.935398	1443.462, 1496.6683
1861	247921	RV	Min Bahadur Chhetri	Man Bahadur Kshetri	Sindhupalchowk	Thangpalchhap	1	0		Pachpokhari Thangpal	6	40	395724	23-72-1-0-40			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9621162282	85.644295	27.934977	1485.8945
1862	247778	RV	Hari Prasad Chapagain	Hari Prasad Chapagain	Sindhupalchowk	Thangpalchhap	2	0		Pachpokhari Thangpal	6	25	395884		Kathmandu,Shank arapura-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741110506	85.635338	27.914034	1291.046
1863	247786	RV	Ram Prasad Adhikari	Ram Prasad Adhikari	Sindhupalchowk	Thangpalchhap	2	0		Pachpokhari Thangpal	6	29	395849		Kathmandu,Gokar neswor-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841594201	85.635811	27.914032	1277.3972
1864	247787	RV	Bidur Paudel	Ram Krishna Paudyal	Sindhupalchowk	Thangpalchhap	2	0		Pachpokhari Thangpal	6	33	395854		Kathmandu,Gokar neswor-9	No Damage	3	Grade 5, Grade 5, Grade 5	Reconstruct, Reconstruct, Reconstruct	Grade 5, Grade 5, Grade 5	Grade 5, Grade 5, Grade 5	Grade 5, Grade 5, Grade 5	Reconstruct, Reconstruct, Reconstruct	Habitable House in Other Place	9751010485	85.639038, 85.639084, 85.639084	27.918709, 27.918709, 27.918751	1330.5278, 1340.0958, 1343.1667
1865	247790	RV	Mithuram Paudel	Ram Krishna Paudyal	Sindhupalchowk	Thangpalchhap	2	0		Pachpokhari Thangpal	6	33	395856		Kathmandu,Gokar neswor-9	No Damage	3	Grade 5, Grade 5, Grade 5	Reconstruct, Reconstruct, Reconstruct	Grade 5, Grade 5, Grade 5	Grade 5, Grade 5, Grade 5	Grade 5, Grade 5, Grade 5	Reconstruct, Reconstruct, Reconstruct	Habitable House in Other Place	9751010485	85.638985, 85.639038, 85.639084	27.91869, 27.918709, 27.918751	1330.5278, 1340.0958, 1343.1667
1866	247779	RV	Rekha Koirala (Paudel)	Ram Krishna Paudyal	Sindhupalchowk	Thangpalchhap	2	0		Pachpokhari Thangpal	6	33	395855		Kathmandu,Gokar neswor-9	No Damage	3	Grade 5, Grade 5, Grade 5	Reconstruct, Reconstruct, Reconstruct	Grade 5, Grade 5, Grade 5	Grade 5, Grade 5, Grade 5	Grade 5, Grade 5, Grade 5	Reconstruct, Reconstruct, Reconstruct	Habitable House in Other Place	9751010485	85.638985, 85.639038, 85.639084	27.91869, 27.918709, 27.918751	1330.5278, 1340.0958, 1343.1667
1867	247851	RV	Kabita Dital	Sur Bahadur Dital	Sindhupalchowk	Thangpalchhap	2	0		Pachpokhari Thangpal	6	49	395884				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9803419731	85.635681	27.912636	1259.3461
1868	247789	RV	Ramhari Paudel	Dhurba Prasad Paudyal	Sindhupalchowk	Thangpalchhap	2	0		Pachpokhari Thangpal	6	60	395575				1	Grade 1	Minor Repair	Grade 3	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9860783523	85.635834	27.916195	1284.0109
1869	248381	RV	Dinesh Deuja	Mohan Dhwaj Deuja	Sindhupalchowk	Thangpalchhap	3	0		Pachpokhari Thangpal	6	7	395488		Kathmandu,Shank arapura-7	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9843523133	85.637154, 85.637215	27.913063, 27.913118	1212.2712, 1219.4125

1871	247802	RV	Subarna Kumar Dhital	Suvarna Kumar Dhital	Sindhupalchowk	Thangpaldhap	3	0		Pachpokhari Thangpal	6	28	395468		Kathmandu,Gokar newor-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851216818	85.635017	27.91095	1179.1501
1872	248378	RV	Dhak Bahadur Khadka	Leela Bahadur Khadka	Sindhupalchowk	Thangpaldhap	3	0		Pachpokhari Thangpal	6	61	395514				3	Grade 5, Grade 5, Grade 1	Reconstruct, Reconstruct, Minor Repair	Grade 5, Grade 5, Grade 1	Grade 5, Grade 5, Grade 1	Grade 5, Grade 5, Grade 1	Reconstruct, Reconstruct, Minor Repair	Habitable House in Usual Place	9741336234	85.633698, 85.633781, 85.633827	27.911116, 27.911161, 27.911287	1180.8336, 1184.8503, 1189.0549
1873	248376	RV	Lila Bahadur Khadka	Leela Bahadur Khadka	Sindhupalchowk	Thangpaldhap	3	0		Pachpokhari Thangpal	6	61	395513				3	Grade 5, Grade 5, Grade 1	Reconstruct, Reconstruct, Minor Repair	Grade 5, Grade 5, Grade 1	Grade 5, Grade 5, Grade 1	Grade 5, Grade 5, Grade 1	Reconstruct, Reconstruct, Minor Repair	Habitable House in Usual Place	9741336234	85.633698, 85.633781, 85.633827	27.911116, 27.911161, 27.911287	1180.8336, 1184.8503, 1189.0549
1874	247979	RV	Jiban Lal Shrestha	Mohan Lal Nagarkoti	Sindhupalchowk	Thangpaldhap	4	0		Pachpokhari Thangpal	6	35	395801		Sindhupalchowk,Mejanchi-2/Sindhupalchowk,Mejanchi-2	Partial Damage, Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841526949	85.63205	27.912477	1212.6877
1875	247819	RV	Krishna Lal Shrestha	Krishna Lal Shrestha	Sindhupalchowk	Thangpaldhap	5	0		Pachpokhari Thangpal	6	54	395603		Kathmandu,Gokar newor-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9818334647	85.631363	27.902819	1287.5836
1876	247858	RV	Nandalal Sarki	Nanda Lal Newar	Sindhupalchowk	Thangpaldhap	5	0		Pachpokhari Thangpal	6	74	395583				2	Grade 5, Grade 5	Reconstruct, Minor Repair	Grade 5, Grade 3	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9803381402	85.628021, 85.628235	27.898132, 27.898132	1221.1006, 1225.493
1877	247937	RV	Gajendra Bhattarai	Thir Bahadur Bhattarai	Sindhupalchowk	Thangpaldhap	5	0		Pachpokhari Thangpal	6	78	395589				2	Grade 1, Grade 3	Not Required, Major Repair	Grade 1, Grade 4	Grade 1, Grade 3	Grade 1, Grade 3	Not Required, Major Repair	Habitable House in Usual Place	9860369008	85.626877, 85.626907	27.898989, 27.898988	1177.9683, 1197.5267
1878	247876	RV	Krishna Bahadur Bhattarai	Thir Bahadur Bhattarai	Sindhupalchowk	Thangpaldhap	5	0		Pachpokhari Thangpal	6	78	395590				2	Grade 1, Grade 3	Not Required, Major Repair	Grade 1, Grade 4	Grade 1, Grade 3	Grade 1, Grade 3	Not Required, Major Repair	Habitable House in Usual Place	9860369008	85.626877, 85.626907	27.898989, 27.898988	1177.9683, 1197.5267
1879	247938	RV	Buddhi Bahadur Banjara	Buddhi Bahadur Banjara	Sindhupalchowk	Thangpaldhap	5	0		Pachpokhari Thangpal	6	81	395593				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9849492615	85.627281, 85.627335	27.901131, 27.901213	1181.22, 1189.7625
1880	247922	RV	Surya Adhikari	Surya Bahadur Adhikari	Sindhupalchowk	Thangpaldhap	5	0		Pachpokhari Thangpal	6	94	404879		Kathmandu,Shank arapura-7	Partial Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9843468612	85.625046, 85.626762	27.902748, 27.902755	1165.5685, 992.23834
1881	247817	RV	Surendra Shrestha	Surendra Shrestha	Sindhupalchowk	Thangpaldhap	5	0		Pachpokhari Thangpal	6	103	395629				2	Grade 1, Grade 5	Minor Repair, Reconstruct	Grade 1, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9818883697	85.626617, 85.627312	27.901247, 27.901609	1172.7278, 1181.4078
1882	248298	RV	Sher Bahadur Adhikari	Sher Bahadur Adhikari	Sindhupalchowk	Thangpaldhap	6	0		Pachpokhari Thangpal	6	10	515287		Kathmandu,Shank arapura-5	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9840022558	85.633598	27.89943	1320.9601
1883	250126	RV	Bharat Bahadur Malla	Bharat Bahadur Malla	Sindhupalchowk	Thokarpa	1	0		Sunkoshi	1	9	365826		Morang,Itahara-99	No Damage	3	Grade 5, Grade 5, Grade 5	Reconstruct, Reconstruct, Reconstruct	Grade 5, Grade 5, Grade 5	Grade 5, Grade 5, Grade 5	Grade 5, Grade 5, Grade 5	Reconstruct, Reconstruct, Reconstruct	Habitable House in Other Place		85.760483, 85.760605, 85.760681	27.681965, 27.682005, 27.68203	1186.463, 1188.0026, 1188.5011
1884	250128	RV	Kedar Prasad Bhandari	Kedar Prasad Bhandari	Sindhupalchowk	Thokarpa	1	0		Sunkoshi	1	35	365851		Kathmandu,Kathm andu-35	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841362046	85.764519	27.683441	1250.7968
1885	250129	RV	Dwarika Raj Bhandari	Dwarikaraj Bhandari	Sindhupalchowk	Thokarpa	1	0		Sunkoshi	1	36	365852		Kathmandu,Kages wori-Manahara-8	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841647651	85.764641	27.6833	1256.0112
1886	250132	RV	Chandra Kala Khatri	Chandrakala Khatri	Sindhupalchowk	Thokarpa	1	0		Sunkoshi	1	42	365858		Kathmandu,Kathm andu-34	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849788133	85.764587	27.682852	1247.8248
1887	250130	RV	Krishna Maya Bhandari	Pushparaj Bhandari, Shankarraj Bhandari	Sindhupalchowk	Thokarpa	1	0		Sunkoshi	1	77	365889		Kathmandu,Kathm andu-35	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841517288	85.765533	27.681953	1306.6647
1888	250138	RV	Yagya Prasad Bhandari	Yagya Prasad Bhandari	Sindhupalchowk	Thokarpa	2	0		Sunkoshi	1	9	365640		Bhaktapur,Mathya pur Thimi-17	Partial Damage	2	Grade 4, Grade 4	Reconstruct, Reconstruct	Grade 4, Grade 4	Grade 4, Grade 4	Grade 4, Grade 4	Reconstruct, Reconstruct	Habitable House in Other Place	9840058578	85.778275, 85.781288	27.685961, 27.688036	1516.2635, 1536.8202
1889	250137	RV	Govinda Prasad Bhandari	Govinda Prasad Bhandari	Sindhupalchowk	Thokarpa	2	0		Sunkoshi	1	27	365658		Lalitpur,Imadol-99	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 3	Grade 3	Major Repair	Habitable House in Other Place	9846952944	85.779381	27.688646	1529.1282
1890	250147	RV	Krishna Prasad Bhandari	Krishna Prasad Bhandari	Sindhupalchowk	Thokarpa	2	0		Sunkoshi	1	37	365669		Kathmandu,Kathm andu-35	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9851190441	85.778542	27.688931	1530.3296
1891	250143	RV	Harka Bahadur Neupane	Harka Bahadur Neupane	Sindhupalchowk	Thokarpa	2	0		Sunkoshi	1	65	365723		Lalitpur,Tikahali-99	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	85.777657	27.685026	1438.0205	
1892	250146	RV	Ram Prasad Khanal	Ram Prasad Khanal	Sindhupalchowk	Thokarpa	2	0		Sunkoshi	1	108	365770		Bhaktapur,Mathya pur Thimi-99	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741018150	85.776665	27.683811	1412.9457
1893	250811	RV	Shiva Prasad Neupane	Shiv Prashad Neopane	Sindhupalchowk	Thokarpa	3	0		Sunkoshi	1	31	1193558		Bhaktapur,Ananata lingswor-9	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9751003401	85.762848	27.675623	1011.9126
1894	250082	RV	Kabi Prasad Timsalina	Kabi Prashad Timsalina	Sindhupalchowk	Thokarpa	3	0		Sunkoshi	1	72	1193601		Bhaktapur,Mathya pur Thimi-15	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841046544	85.76857	27.677881	1143.8181
1895	250086	RV	Jyoti Maya Karki	Jyoti Maya Karki	Sindhupalchowk	Thokarpa	3	0		Sunkoshi	1	73	1193602		Bhaktapur,Ananata lingswor-7	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841446822	85.767403	27.678286	1191.9952
1896	250155	RV	Khin Maya Karki	Tej Bahadur Karki	Sindhupalchowk	Thokarpa	4	0		Sunkoshi	1	23	1193426		Kathmandu,Kathm andu-35	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9840061035	85.783485	27.687895	1636.4064
1897	250157	RV	Man Maya Karki	Raaju Karki	Sindhupalchowk	Thokarpa	4	0		Sunkoshi	1	25	1193428		Bhaktapur,Changu narayan-12	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849942045	85.783272	27.688139	1633.1543
1898	250153	RV	Rum Bahadur Karki	Rom Bahadur Karki	Sindhupalchowk	Thokarpa	4	0		Sunkoshi	1	40	1193444		Kathmandu,Kathm andu-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841389461	85.787895	27.687105	1599.7246
1899	250150	RV	Uttar Bahadur Karki	Rom Bahadur Karki	Sindhupalchowk	Thokarpa	4	0		Sunkoshi	1	40	1193445		Kathmandu,Kathm andu-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841389461	85.787895	27.687105	1599.7246
1900	250148	RV	Dhruva Pahari	Ram Chandra Pahari	Sindhupalchowk	Thokarpa	4	0		Sunkoshi	1	108	1193496				2	Grade 3, Grade 1	Reconstruct, Minor Repair	Grade 4, Grade 2	Grade 4, Unrecognized	Grade 4, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9841108053	85.784271, 85.7845	27.675947, 27.676109	1364.2152, 1368.4645
1901	250158	RV	Ram Chandra Pahari	Ram Chandra Pahari	Sindhupalchowk	Thokarpa	4	0		Sunkoshi	1	108	1193497				2	Grade 3, Grade 1	Reconstruct, Minor Repair	Grade 4, Grade 2	Grade 4, Unrecognized	Grade 4, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9841108053	85.784271, 85.7845	27.675947, 27.676109	1364.2152, 1368.4645
1902	250159	RV	Makhamali Rokka	Sher Bahadur Rokka	Sindhupalchowk	Thokarpa	5	0		Sunkoshi	2	79	1190956				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9849727159	85.793731, 85.797417	27.68265, 27.68273	1540.7332, 1552.5784
1903	250161	RV	Lila Kumari Khathi	Lila Kumari Khatri	Sindhupalchowk	Thokarpa	5	0		Sunkoshi	2	159	1191967		Bhaktapur,Ananata lingswor-9	Partial Damage	1	Grade 4	Reconstruct	Grade 3	Grade 3	Grade 3	Major Repair	Habitable House in Other Place	9817271618	85.791115	27.689615	1698.5184
1904	250073	RV	Chok Devi Neupane	Bhola Nath Neopane	Sindhupalchowk	Thokarpa	6	0		Sunkoshi	2	34	1193738		Sindhupalchowk,Thokarpa-5	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841137252	85.804276	27.682728	1738.4781
1905	250168	RV	Bharat Bahadur Koirala	Bharat Bahadur Koirala	Sindhupalchowk	Thokarpa	7	0		Sunkoshi	2	22	1190993				2	Grade 2, Grade 4	Minor Repair, Reconstruct	Grade 2, Grade 3	Grade 2, Grade 3	Grade 2, Grade 3	Major Repair, Major Repair	Habitable House in Usual Place	11681102	85.807503, 85.812286	27.681316, 27.681442	1694.0746, 1756.9166
1906	250810	RV	Tirtha Bahadur Basnet	Thirta Bahadur Basnet	Sindhupalchowk	Thokarpa	8	0		Sunkoshi	2	11	1191733		Kathmandu,Kathm andu-10	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place		85.803665	27.669106	1382.8079
1907	250173	RV	Khadka Kumari Mahat	Khadka Kumari Mahat	Sindhupalchowk	Thokarpa	8	0		Sunkoshi	2	39	1190912		Lalitpur,Tikahali-1	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9611100765	85.803299	27.669479	1403.1683
1908	250053	RV	Maha Kumari Neupane	Maha Kumari Neupane	Sindhupalchowk	Thokarpa	9	0		Sunkoshi	2	7	365507		Kathmandu,Kathm andu-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9861175567	85.795299	27.67296	1455.5638
1909	250057	RV	Ramji Prasad Neupane	Ramji Prasad Neupane	Sindhupalchowk	Thokarpa	9	0		Sunkoshi	2	10	365510		Kathmandu,Kathm andu-3	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9849384315	85.796349	27.672813	1461.6907
1910	250179	RV	Krishna Prasad Parajuli	Krishna Prasad Parajuli	Sindhupalchowk	Thokarpa	9	0		Sunkoshi	2	19	365519		Kathmandu,Kathm andu-35	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9851282907	85.795036	27.673565	1444.0105
1911	250061	RV	Sundar Bhandari	Sundar Bhandari	Sindhupalchowk	Thokarpa	9	0		Sunkoshi	2	25	365526		Kathmandu,Mulpa ni-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843146024	85.792603	27.669752	1328.1742
1912	250793	RV	Naresh Kumar Bhandari	Naresh Kumar Bhandari	Sindhupalchowk	Thokarpa	9	0		Sunkoshi	2	26	365527		Kathmandu,Kapan-3	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841316346	85.793404	27.670687	1341.7198
1913	250066	RV	Tika Bahadur Bhandari	Tika Bahadur Bhandari	Sindhupalchowk	Thokarpa	9	0		Sunkoshi	2	33	365535		Kavrepalanchowk, Panauti -4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841474224	85.793823	27.671368	1364.4705
1914	250059	RV	Mithu Devi Neupane	Mithu Devi Neupane	Sindhupalchowk	Thokarpa	9	0		Sunkoshi	2	37	365539															

1920	250054	RV	Dilip Kumar Bhandari	Dilip Kumar Bhandari	Sindhupalchowk	Thokarpa	9	0		Sunkoshi	2	91	365599		Bhaktapur,Bhaktapur-17	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851003797	85.793686	27.669767	1320.2969
1921	250064	RV	Krishna Prasad Neupane	Krishna Prasad Neupane	Sindhupalchowk	Thokarpa	9	0		Sunkoshi	2	112	365621				1	Grade 2	Minor Repair	Grade 2	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	984198955	85.798653	27.671303	1406.1284
1922	250060	RV	Bishnu Prasad Neupane	Bishnu Prasad Neupane	Sindhupalchowk	Thokarpa	9	0		Sunkoshi	2	113	365622		Bhaktapur,Mathyapur Thimi-99	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741027965	85.798531	27.67202	1426.0428
1923	254929	RV	Akale Bahadur Gahatraj	Akalay Bahadur Gahatraj	Sindhupalchowk	Thulosirubari	1	0		Chautara Sagachowkgadhi Municipality	13	53	539256				1	Grade 1	Minor Repair	Grade 3	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9841854696	85.711266	27.734032	1434.1377
1924	251410	RV	Nanu Giri	Nanu Giri	Sindhupalchowk	Thulosirubari	1	0		Chautara Sagachowkgadhi Municipality	13	112	539319		Kathmandu,Kathmandu-35	Partial Damage	1	Grade 4	Major Repair	Grade 3	Grade 4	Grade 4	Major Repair	Habitable House in Other Place	9846658456	85.70787	27.734106	1353.5676
1925	254933	RV	Pramila Puri	Parmila Puri	Sindhupalchowk	Thulosirubari	1	0		Chautara Sagachowkgadhi Municipality	13	116	539323		Kathmandu,Kathmandu-35	No Damage	1	Grade 4	Reconstruct	Grade 3	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9868331262	85.707642	27.733477	1349.3179
1926	254937	RV	Indra Bahadur Puri	Indra Bahadur Puri	Sindhupalchowk	Thulosirubari	1	0		Chautara Sagachowkgadhi Municipality	13	117	539324		Kathmandu,Kathmandu-35	No Damage	1	Grade 4	Major Repair	Grade 3	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9843074703	85.70771	27.733549	1334.1165
1927	254942	RV	Dev Bahadur Puri	Tika Devi Puri	Sindhupalchowk	Thulosirubari	1	0		Chautara Sagachowkgadhi Municipality	13	118	1192426		Kathmandu,Kathmandu-99	Partial Damage	3	Grade 4, Grade 4, Grade 5	Reconstruct, Reconstruct, Reconstruct	Grade 3, Grade 3, Grade 5	Grade 4, Grade 4, Grade 5	Grade 4, Grade 4, Grade 5	Reconstruct, Reconstruct, Reconstruct	Habitable House in Other Place	9841395993	85.707314, 85.70742, 85.707581	27.73341, 27.733664, 27.73386	1317.0718, 1334.651, 1337.5079
1928	251407	RV	Rupa Giri Puri	Tika Devi Puri	Sindhupalchowk	Thulosirubari	1	0		Chautara Sagachowkgadhi Municipality	13	118	539325		Kathmandu,Kathmandu-99	Partial Damage	3	Grade 4, Grade 4, Grade 5	Reconstruct, Reconstruct, Reconstruct	Grade 3, Grade 3, Grade 5	Grade 4, Grade 4, Grade 5	Grade 4, Grade 4, Grade 5	Reconstruct, Reconstruct, Reconstruct	Habitable House in Other Place	9841395993	85.707314, 85.70742, 85.707581	27.73341, 27.733664, 27.73386	1317.0718, 1334.651, 1337.5079
1929	251409	RV	Dhan Bahadur Nepali	Dhan Bahadur Nepali	Sindhupalchowk	Thulosirubari	1	0		Chautara Sagachowkgadhi Municipality	13	156	539364				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9841564965	85.707817, 85.708626	27.736305, 27.73666	1421.2659, 1435.5383
1930	250729	RV	Nurpu Tamang	Nurpu Tamang	Sindhupalchowk	Thulosirubari	1	0		Chautara Sagachowkgadhi Municipality	13	176	539385				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9841248328	85.710106	27.735691	1422.9353
1931	254935	RV	Putali Pandey	Putali Panday	Sindhupalchowk	Thulosirubari	1	0		Chautara Sagachowkgadhi Municipality	13	181	539394		Kathmandu,Kathmandu-35	No Damage	2	Grade 5, Grade 4	Reconstruct, Reconstruct	Grade 5, Grade 3	Grade 5, Grade 3	Grade 5, Grade 3	Reconstruct, Minor Repair	Habitable House in Other Place	9849645692	85.710541, 85.710548	27.735691, 27.735847	1417.76, 1423.577
1932	254948	RV	Norvu Tamang	Norbhu Tamang	Sindhupalchowk	Thulosirubari	2	0		Chautara Sagachowkgadhi Municipality	13	11	539013		Bhaktapur,Bhaktapur-99	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	85.705536	27.735342	1347.9784	
1933	254943	RV	Makar Bahadur Thapa	Makar Bahadur Thapa	Sindhupalchowk	Thulosirubari	2	0		Chautara Sagachowkgadhi Municipality	13	59	539062		Bhaktapur,Bhaktapur-99	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841082814	85.704987	27.736553	1349.2981
1934	254963	RV	Damber Bahadur Shrestha	Dambar Bahadur Shrestha	Sindhupalchowk	Thulosirubari	3	0		Chautara Sagachowkgadhi Municipality	13	28	539188		Kavrepalanchowk, Banepa-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	981838906	85.688087	27.73617	1201.3019
1935	254954	RV	Purna Maya Shrestha	Nil Bahadur Shrestha	Sindhupalchowk	Thulosirubari	3	0		Chautara Sagachowkgadhi Municipality	13	40	539831		Lalitpur,Tikahali-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841182131	85.687943	27.736567	1202.0781
1936	254952	RV	Mukta Bahadur Giri	Mukta Bahadur Giri	Sindhupalchowk	Thulosirubari	3	0		Chautara Sagachowkgadhi Municipality	13	104	327024		Bhaktapur,Bhaktapur-5	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860397612	85.698341	27.737349	1274.7471
1937	254957	RV	Sunil Rana	Sunil Rana	Sindhupalchowk	Thulosirubari	3	0		Chautara Sagachowkgadhi Municipality	13	108	326028				1	Grade 1	Not Required	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	85.694168	27.739584	1307.9225	
1938	254955	RV	Surja Bahadur Tamang	Surja Bahadur Tamang	Sindhupalchowk	Thulosirubari	3	0		Chautara Sagachowkgadhi Municipality	13	141	326958				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9818972233	85.694717, 85.694839	27.739323, 27.739534	1308.6307, 1310.5972
1939	254973	RV	Manmai Gautam	Bholanath Gautam, Maan Maya Gautam	Sindhupalchowk	Thulosirubari	4	0		Chautara Sagachowkgadhi Municipality	13	91	1193110		Kathmandu,Kathmandu-6	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741088819	85.701538	27.745199	1094.3716
1940	254974	RV	Yubak Nath Subedi	yubaknath Subedi	Sindhupalchowk	Thulosirubari	4	0		Chautara Sagachowkgadhi Municipality	13	132	1192172		Sindhupalchowk,Thulosirubari-3	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841924636	85.700623	27.741787	1200.4672
1941	254969	RV	Ramesh Rana	Durga Bahadur Rana maga	Sindhupalchowk	Thulosirubari	4	0		Chautara Sagachowkgadhi Municipality	13	148	1192183				2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9849121450	85.696556, 85.697952	27.742083, 27.742413	1189.6187, 1206.927
1942	254977	RV	Rabin Tamang	Man Bahadur Tamang, Rabin Tamang	Sindhupalchowk	Thulosirubari	5	0		Chautara Sagachowkgadhi Municipality	13	74	1192017				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9813631176	85.709457	27.740707	1268.5837
1943	253538	RV	Rachana Tamang	Man Bahadur Tamang, Rabin Tamang	Sindhupalchowk	Thulosirubari	5	0		Chautara Sagachowkgadhi Municipality	13	74	1192016				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9813631176	85.709457	27.740707	1268.5837
1944	254895	RV	Bimala Shrestha	Dhana Bahadur Shtestha	Sindhupalchowk	Thulosirubari	6	0		Chautara Sagachowkgadhi Municipality	13	72	1192247				2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9841181674	85.711464, 85.715973	27.736492, 27.737352	1356.5565, 1374.3031
1945	254932	RV	Krishna Prasad Dulal	Krishna Prasad Dulal	Sindhupalchowk	Thulosirubari	6	0		Chautara Sagachowkgadhi Municipality	13	84	1192360				1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9851054751	85.711372	27.735296	1431.713
1946	254861	RV	Ganga Maya Dulal	Ganga Maya Dulal	Sindhupalchowk	Thulosirubari	6	0		Chautara Sagachowkgadhi Municipality	13	94	1192370				2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9841455039	85.713203, 85.713318	27.734419, 27.734526	1444.1091, 1451.5081
1947	254855	RV	Keshab Prasad Dulal	Keshav Dulal	Sindhupalchowk	Thulosirubari	6	0		Chautara Sagachowkgadhi Municipality	13	130	1192455				2	Grade 5, Grade 1	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9803182159	85.714859, 85.715141	27.732927, 27.732994	1436.9274, 1444.4354
1948	254860	RV	Krishna Prasad Chaulagain	Krishna Prasad Chaulagain	Sindhupalchowk	Thulosirubari	6	0		Chautara Sagachowkgadhi Municipality	13	160	507255				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 3, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Reconstruct	Habitable House in Usual Place	9808506079	85.715561, 85.715675	27.732916, 27.733177	1464.2611, 1466.913
1949	254854	RV	Nil Nath Chaulagain	Nilnath Chaulagain	Sindhupalchowk	Thulosirubari	6	0		Chautara Sagachowkgadhi Municipality	13	221	507463				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803173597	85.715355	27.732304	1441.519
1950	254897	RV	Dhan Bahadur Rasali	Dhan Bahadur Rasali	Sindhupalchowk	Thulosirubari	8	0		Chautara Sagachowkgadhi Municipality	14	218	401957				2	Grade 1, Grade 5	Not Required, Reconstruct	Grade 1, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Not Required, Reconstruct	Habitable House in Usual Place	85.693001, 85.693092	27.716013, 27.716105	1237.4897, 1240.7223	
1951	254898	RV	Bal Krishna Sigdel	Prakash Sigdel	Sindhupalchowk	Thulosirubari	9	0		Chautara Sagachowkgadhi Municipality	14	5	1193010		Bhaktapur,Sipadol-2	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860361066	85.692078	27.720167	1334.5448
1952	252211	RV	Garbe Tamang	Garbhe Tamang	Sindhupalchowk	Votang	1	0		Pachpokhari Thangpal	3	94	369850				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	85.656456	27.978655	1858.9066	
1953	252224	RV	Chhekyap Tamang	Chhekyap Tamang	Sindhupalchowk	Votang	1	0		Pachpokhari Thangpal	3	101	369984				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9741505058	85.656609	27.980808	1796.4557
1954	252105	RV	Chhurki Tamang	Sailli Tamang	Sindhupalchowk	Votang	2	0		Pachpokhari Thangpal	3	83	535986				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	85.648193	27.972351	1815.8228	
1955	252121	RV	Nir Bahadur Tamang	Nir Bdr Tamang	Sindhupalchowk	Votang	3	0		Pachpokhari Thangpal	3	2	534328		Kathmandu,Mulpa ni-7	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741024979	85.652031	27.972876	1836.9578
1956	252037	RV	Sinendorje Tamang	Sinen Dorje Tamang	Sindhupalchowk	Votang	5	0		Pachpokhari Thangpal	3	14	534391				2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 2, Grade 5	Grade 2, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9611178739	85.648895, 85.649307	27.971779, 27.972458	1778.0342, 1797.4427
1957	252148	RV	Gyan Bahadur Tamang	Gyan Bdr Tamang	Sindhupalchowk	Votang	5	0		Pachpokhari Thangpal	3	30	534416		Kathmandu,Shank arapura-7	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9808044639	85.647537	27.971491	1781.8223

1958	252152	RV	Ngema Singi Tamang	Nghama Singi Tamang	Sindhupalchowk	Votang	5	0		Pachpokhari Thangpal	3	31	534417		Kathmandu,Shank arapura-2	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741024979	85.648216	27.972067	1774.3353
1959	252143	RV	Lai Bahadur Tamang	Lai Bdr Tamang	Sindhupalchowk	Votang	5	0		Pachpokhari Thangpal	3	33	534419		Sindhupalchowk,V otang-5	Complete Damage	2	Grade 5, Grade 2	Reconstruct, Minor Repair	Grade 5, Grade 2	Grade 5, Grade 2	Grade 5, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9741024979	85.648468, 85.648491	27.972038, 27.972076	1776.2988, 1778.6501
1960	252090	RV	Lakpa Dolmo Tamang	Fhul Maya Tamang	Sindhupalchowk	Votang	8	0		Pachpokhari Thangpal	3	42	369805				3	Grade 2, Grade 5, Grade 5	Minor Repair, Reconstruct, Reconstruct	Grade 2, Grade 2, Grade 5, Grade 5	Grade 2, Grade 2, Grade 5, Grade 5	Grade 2, Grade 5, Grade 5	Minor Repair, Reconstruct, Reconstruct	Habitable House in Usual Place	9814321071	85.650078, 85.650085, 85.650284	27.955362, 27.955368, 27.955513	1781.1799, 1784.7875, 1794.4982
1961	252091	RV	Mingmar Tamang	Fhul Maya Tamang	Sindhupalchowk	Votang	8	0		Pachpokhari Thangpal	3	42	369806				3	Grade 2, Grade 5, Grade 5	Minor Repair, Reconstruct, Reconstruct	Grade 2, Grade 5, Grade 5	Grade 2, Grade 5, Grade 5	Grade 2, Grade 5, Grade 5	Minor Repair, Reconstruct, Reconstruct	Habitable House in Usual Place	9814321071	85.650078, 85.650085, 85.650284	27.955362, 27.955368, 27.955513	1781.1799, 1784.7875, 1794.4982
1962	252065	RV	Palden Lama	Palden Lama	Sindhupalchowk	Votang	8	0		Pachpokhari Thangpal	3	64	369308		Sindhupalchowk,V otang-7;Sindhupalchowk, Votang-9	Complete Damage, No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9813165756	85.650238	27.954929	1793.5432
1963	252100	RV	Gopal Tamang	Gopal Tamang	Sindhupalchowk	Votang	9	0		Pachpokhari Thangpal	3	33	404239				1	Grade 1	Not Required	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803539193	85.646557	27.964533	1794.067
1964	251991	RV	Mina Tamang	Mina Tamang	Sindhupalchowk	Votang	9	0		Pachpokhari Thangpal	3	50	405311				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place		85.646866	27.964748	1809.8802
1965	254619	RV	Bachuram Chaulagain	Chiringibi Chaulagain	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	64	337876	23-12-1-0-59			1	Grade 4	Reconstruct	Unrecognized	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9741194627	85.49427	27.788273	1681.2078
1966	254496	RV	Gopi Dangal	Gopi Dangal	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	68	337883		Kathmandu, Nangle bhare-8	Partial Damage	1	Grade 4	Reconstruct	Grade 3	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741183766	85.49987	27.788357	1659.1755
1967	254612	RV	Kul Prasad Chaulagain	Kula Prashad Chaulagain	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	69	337884				2	Grade 4, Grade 1	Reconstruct, Not Required	Grade 3, Grade 2	Grade 4, Grade 2	Grade 4, Grade 2	Reconstruct, Minor Repair	Habitable House in Usual Place	9741262299	85.49926, 85.49943	27.787884, 27.788013	1662.4799, 1664.8436
1968	254629	RV	Tara Nath Chaulagain	Taranath Chaulagain	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	70	337885				2	Grade 1, Grade 2	Not Required, Minor Repair	Grade 3, Grade 3	Grade 2, Grade 3	Grade 2, Grade 3	Minor Repair, Major Repair	Habitable House in Usual Place	9849181975	85.49971, 85.499908	27.788446, 27.788462	1657.0706, 1660.2872
1969	252199	RV	Hari Prasad Dangal	Hari Prashad Dangal, Odanath Dangal	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	78	337894		Kathmandu, Gokar neswor-12	Partial Damage	1	Grade 3	Major Repair	Grade 3	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9849699422	85.499519	27.788786	1631.6409
1970	254509	RV	Odanath Dangal	Hari Prashad Dangal, Odanath Dangal	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	78	337893		Kathmandu, Gokar neswor-12	Partial Damage	1	Grade 3	Major Repair	Grade 3	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9849699422	85.499519	27.788786	1631.6409
1971	254510	RV	Narayan Prasad Dangal	Narayan Prashad Dangal	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	80	337897				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9808486742	85.499969	27.789974	1642.0812
1972	254499	RV	Tejanath Chaulagain	Tejanath Chaulagain	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	91	337908				2	Grade 2, Grade 2	Minor Repair, Minor Repair	Grade 2, Grade 2	Grade 3, Grade 1	Grade 3, Grade 2	Major Repair, Major Repair	Habitable House in Usual Place	9860455740	85.498085, 85.49826	27.788885, 27.78896	1607.3698, 1607.8354
1973	254495	RV	Matrika Prasad Chaulagain	Matrika Prashad Chaulagain	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	92	337909				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9841416082	85.498192	27.788925	1610.7635
1974	251343	RV	Nikhantha Chaulagain	Nikantha Chaulagain	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	101	337919		Kathmandu, Gokar neswor-12	No Damage	1	Grade 5	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841566553	85.497627	27.791576	1528.5533
1975	254627	RV	Nikhantha Chaulagain	Nikantha Chaulagain	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	101	337919		Kathmandu, Gokar neswor-12	No Damage	1	Grade 5	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841566553	85.497627	27.791576	1528.5533
1976	254508	RV	Kedar Prasad Chaulagain	Kedar Prashad Chaulagain	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	126	406673				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9846762059	85.493431	27.790394	1553.6494
1977	254617	RV	Nabin Chaulagain	Nabin Chaulagain, Purna Bhadra Chaulagain	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	131	369681		Kathmandu, Mulpa ni-8	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9751028938	85.492081	27.789261	1598.6465
1978	250602	RV	Purna Bhadra Chaulagain	Nabin Chaulagain, Purna Bhadra Chaulagain	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	131	369680		Kathmandu, Mulpa ni-8	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9751028938	85.492081	27.789261	1598.6465
1979	254621	RV	Hem Narayan Chaulagain	Hem Narayan Chaulagain	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	137	369689		Kathmandu, Shank arapura-2	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	4912214	85.495125	27.789301	1634.7728
1980	254623	RV	Hom Nath Chaulagain	Homnath Chaulagain	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	142	369694				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 2	Grade 5, Unrecognized	Grade 5, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9741174046	85.495049, 85.499809	27.788221, 27.789976	1592.5017, 1664.9434
1981	254611	RV	Homnath Sharma Chaulagain	Homnath Sharma chaulagain	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	168	368997		Kathmandu, Kath andu-2	Partial Damage	1	Grade 3	Major Repair	Grade 3	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841389621	85.491547	27.791685	1553.8201
1982	254609	RV	Dipal Chaulagain	Dipal Chaulagain	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	178	368952		Kathmandu, Gokar neswor-12	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9751028333	85.491447	27.791567	1553.9958
1983	254624	RV	Gayanu Chaulagain	Nirajan Chaulagain	Sindhupalchowk	Votehour	1	0		Melamchi Municipality	1	228	408463		Kathmandu, Kath andu-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841662464	85.501877	27.798643	1376.2899
1984	254641	RV	Lilanath Chaulagain	Lilanath Chaulagain	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	6	408441				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9741110667	85.499702	27.788124	1659.8744
1985	254502	RV	Yadu Nath Chaulagain	Yedunath Chaulagain	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	7	408442		Sindhupalchowk,V otehour-1	Complete Damage	1	Grade 1	Minor Repair	Grade 2	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9741280743	85.499733	27.788103	1670.9778
1986	254531	RV	Mani Ram Dangal	Maniram Dangal	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	12	408444				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9751017483	85.500107	27.788221	1663.2306
1987	254636	RV	Kalpna Rokka	Muna Rokka	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	86	408400		Kathmandu, Shank arapura-13	No Damage	1	Grade 3	Major Repair	Grade 4	Grade 4	Grade 4	Major Repair	Habitable House in Other Place	9841139931	85.504631	27.790104	1530.4602
1988	254637	RV	Rabindra Rokka	Muna Rokka	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	86	406948		Kathmandu, Shank arapura-13	No Damage	1	Grade 3	Major Repair	Grade 4	Grade 4	Grade 4	Major Repair	Habitable House in Other Place	9841139931	85.504631	27.790104	1530.4602
1989	254546	RV	Sarita Aryal Rokka	Nokh Bdr Rokka	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	104	406968		Kathmandu, Danch hi-2	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9860928541	85.504219	27.787622	1438.2855
1990	254632	RV	Gyan Bdr Rokkashatri	Gyan Bdr Rokka chhetri	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	117	406881		Kathmandu, Kapan-2	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 4	Reconstruct	Habitable House in Other Place	9851169532	85.50721	27.788813	1396.4194
1991	254544	RV	Lai Bdr Tamang	Lai Bdr Tamang	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	195	406863		Kathmandu, Shank arapura-1	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741255876	85.513802	27.793194	1394.4811
1992	254654	RV	Lai Bdr Tamang	Lai Bdr Tamang	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	195	406863		Kathmandu, Shank arapura-1	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741255876	85.513802	27.793194	1394.4811
1993	254540	RV	Dhum Bdr Thapa	Dhum Bdr Thapa	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	274	337870				1	Grade 2	Minor Repair	Grade 2	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9841687703	85.517921	27.792377	1272.0942
1994	254655	RV	Hira Bdr Rokka	Hira Bdr Rokka, Jhalak Bdr Rokka	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	283	337806		Makwanpur, Hatau da-9	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9810007901	85.518822	27.79147	1253.5277
1995	254406	RV	Rohini Prasad Dhimal	Rohini Prashad Dhimal	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	348	399133				1	Grade 2	Minor Repair	Grade 4	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	85.52166	27.794716	1178.6179	
1996	254653	RV	Toyannath Chaulagain	Ekadutta Chaulagain	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	351	399136				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9818745873	85.521774	27.794342	1189.4203
1997	254418	RV	Dhan Bdr Khadka	Ghana Bdr Khadka	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	384	399344				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	9803751054	85.517105	27.798437	1214.3251
1998	254539	RV	Dhan Bdr Khadka	Dhan Bdr Khadka	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	385	399345				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Minor Repair	Habitable House in Usual Place	984366569	85.51712	27.798368	1214.9877
1999	254642	RV	Shadanand Chaulagain	Khadananda Chaulagain	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	431	399267		Kathmandu, Shank arapura-1	Partial Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9849707002	85.512032, 85.512199	27.799622, 27.799664	1286.6698, 1291.0978
2000	254553	RV	Shiva Prasad Chaulagain	Krishna Prashad Chaulagain	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	433	399269		Kathmandu, Gokar neswor-12	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	85.512306	27.798874	1298.6372	
2001	254409	RV	Bharat Bdr Karki	Bharat Bdr Karki	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	438	399274				1	Grade 2	Minor Repair	Grade 3	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9803662410	85.512947	27.798365	1326.7229
2002	254416	RV	Nar Sing Bdrwaiba	Narsingh Bdr Waiba tamang	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	442	399303				1	Grade 2	Minor Repair	Grade 4	Grade 2	Grade 2	Major Repair	Habitable House in Usual Place	9808350547	85.512657	27.797863	1303.6437
2003	254547	RV	Narsing Bdr Waibatamang	Narsingh Bdr Waiba tamang	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	442	3993															

2007	254420	RV	Bir Bdr Damai	Bir Bdr Damai	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	515	399182			1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9808142871	85.506691	27.797005	1372.2614
2008	254538	RV	Ruku Priyar	Bir Bdr Damai	Sindhupalchowk	Votehour	2	0		Melamchi Municipality	1	515	399182			1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9808142871	85.506691	27.797005	1372.2614
2009	254425	RV	Ambika Lamichhane	Ambika Lamichhane	Sindhupalchowk	Votehour	4	0		Melamchi Municipality	1	111	400185	Kathmandu,Shank arapura-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741111062	85.540199	27.790279	1013.324
2010	254424	RV	Yam Bahadur Lamichhane	Rukudevji Lamichhane	Sindhupalchowk	Votehour	4	0		Melamchi Municipality	1	127	400276	Bhaktapur,Duvakot 7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841637867	85.542976	27.788546	983.69552
2011	254428	RV	Bedial Chaulagain	Bedial Chaulagain	Sindhupalchowk	Votehour	5	0		Melamchi Municipality	2	95	551858	Kathmandu,Shank arapura-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841655613	85.493057	27.795532	1529.5973
2012	254429	RV	Toyannath Chaulagain	Toya Nath Chaulagain	Sindhupalchowk	Votehour	5	0		Melamchi Municipality	2	96	551859	Kathmandu,Mulpa ni-4	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841396587	85.493073	27.795961	1537.3867
2013	254434	RV	Sarswati Sapkota	Saraswati Sapkota	Sindhupalchowk	Votehour	5	0		Melamchi Municipality	2	125	551857	Kathmandu,Shank arapura-2	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841876644	85.48996	27.799372	1600.7566
2014	254442	RV	Sarswati Sapkota	Saraswati Sapkota	Sindhupalchowk	Votehour	5	0		Melamchi Municipality	2	125	551857	Kathmandu,Shank arapura-2	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841876644	85.48996	27.799372	1600.7566
2015	254441	RV	Dhan Kumari Tamang	Dhanakumari Tamang	Sindhupalchowk	Votehour	5	0		Melamchi Municipality	2	178	551868	Kathmandu,Indray ani-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9751035053	85.491356	27.798897	1525.3546
2016	254452	RV	Premnarayan Khanal	Premnarayan Khanal	Sindhupalchowk	Votehour	6	0		Melamchi Municipality	2	7	558968	Sindhupalchowk,V otehour-2	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741370049	85.500145	27.808924	1208.1245
2017	252200	RV	Anita Kuikel Sapkota	Anita Kuikel, Shiba Prasad Sapkota	Sindhupalchowk	Votehour	6	0		Melamchi Municipality	2	42	551915	Sindhupalchowk,V otehour-2	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849965829	85.500015	27.808741	1198.3766
2018	251345	RV	Shiva Prasad Sapkota	Anita Kuikel, Shiba Prasad Sapkota	Sindhupalchowk	Votehour	6	0		Melamchi Municipality	2	42	551914	Sindhupalchowk,V otehour-2	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849965829	85.500015	27.808741	1198.3766
2019	254447	RV	Sankar Dulal	Shiba Prasad Dulal	Sindhupalchowk	Votehour	6	0		Melamchi Municipality	2	47	551921	23-12-6-0-45		1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch		85.496674	27.806742	1273.6509
2020	254451	RV	Surya Prasad Chaulagain	Tanka Nath Chaulagain	Sindhupalchowk	Votehour	6	0		Melamchi Municipality	2	56	550033	23-12-6-0-54		2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Unrecognized, Grade 5	Unrecognized, Grade 5	Unrecognized, Reconstruct	Matrix & Photo not cleared or mismatch	9843079869	85.495758, 85.495796	27.805637, 27.805651	1329.8756, 1330.0424
2021	254474	RV	Khilnath Khatiwada	Khila Nath Khatiwada	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	2	552068	Kathmandu,Shank arapura-1	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841361716	85.487984	27.803301	1472.7821
2022	254574	RV	Krishana Prasad Khatiwada	Krishna Prasad Khatiwada	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	5	552072	Kathmandu,Shank arapura-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841920521	85.488968	27.804974	1458.3539
2023	254470	RV	Bishnu Prasad Chaulagain	Bishnu Prasad Chaulagain	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	47	552050	Kathmandu,Kathm andu-7	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741319159	85.490524	27.8092	1350.9661
2024	254576	RV	Bishnu Prasad Chaulagain	Bishnu Prasad Chaulagain	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	47	552050	Kathmandu,Kathm andu-7	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9741319159	85.490524	27.8092	1350.9661
2025	254589	RV	Khodendra Prasad Khatiwada	Khodendra Prasad Khatiwada	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	65	552123	Kathmandu,Gokar neswor-1	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9841564717	85.490997	27.809988	1330.9312
2026	254584	RV	Bholanath Khatiwada	Bhola Nath Khatiwada	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	69	552122	Kathmandu,Mulpa ni-9	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9843048670	85.490654	27.810089	1311.2799
2027	254575	RV	Parbati Khatiwada	Parbati Khatiwada	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	77	551931	Kathmandu,Shank arapura-7	Partial Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9849285537	85.49099	27.810287	1333.6475
2028	254469	RV	Gurudatta Khatiwada	Guru Datta Khatiwada	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	87	551941	Kathmandu,Mulpa ni-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841016456	85.491615	27.810596	1319.0452
2029	254583	RV	Gurudatta Khatiwada	Guru Datta Khatiwada	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	87	551941	Kathmandu,Mulpa ni-4	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841016456	85.491615	27.810596	1319.0452
2030	248375	RV	Shanta Kumari Khatiwada	Shanta Kumari Khatiwada	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	88	551942	Kathmandu,Gokar neswor-7	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9808393478	85.49147	27.810417	1330.2833
2031	254473	RV	Shanta Kumari Khatiwada	Shanta Kumari Khatiwada	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	88	551942	Kathmandu,Gokar neswor-7	No Damage	1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9808393478	85.49147	27.810417	1330.2833
2032	254594	RV	Sudha Khatiwada Adhikari	Sudha Khatiwada adhikari	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	100	558932			1	Grade 2	Minor Repair	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849592338	85.48806	27.808237	1396.3146
2033	254585	RV	Jayanarayan Khatiwada	Jaya Ratna Khatiwada	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	103	558936	Kathmandu,Mulpa ni-8	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841863539	85.492996	27.810068	1333.7457
2034	254592	RV	Kamal Khatiwada	Kamal Khatiwada	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	113	558946			1	Grade 2	Minor Repair	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9849446552	85.492744	27.810709	1322.4045
2035	254586	RV	Krishana Prasad Khatiwada	Krishna Prasad Khatiwada	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	120	558954	Kathmandu,Mulpa ni-8	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741118971	85.492203	27.809778	1338.9531
2036	254475	RV	Chandra Prasad Khatiwada	Chandra Prasad Khatiwada	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	133	551881	Kathmandu,Shank arapura-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843036225	85.492714	27.810463	1333.8674
2037	254593	RV	Sitaram Khatiwada	Chandra Prasad Khatiwada	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	133	551882	Kathmandu,Shank arapura-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843036225	85.492714	27.810463	1333.8674
2038	254596	RV	Lalachandra Khatiwada	Lala Chandra Khatiwada	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	142	400351	Kathmandu,Shank arapura-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9741134921	85.490028	27.809132	1345.8176
2039	254573	RV	Bhim Prasad Khatiwada	Bhim Prasad Khatiwada	Sindhupalchowk	Votehour	7	0		Melamchi Municipality	2	144	400295	Kathmandu,Shank arapura-7	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9843226702	85.48983	27.809431	1348.2164
2040	252198	RV	Chandra Kumari Khatiwada	Chandra Kumari Khatiwada	Sindhupalchowk	Votehour	8	0		Melamchi Municipality	2	3	551788	Kathmandu,Shank arapura-2	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860158775	85.486809	27.805298	1522.4348
2041	254484	RV	Gayannath Khatiwada	Geyannath Khatiwada	Sindhupalchowk	Votehour	8	0		Melamchi Municipality	2	21	552081	Kathmandu,Shank arapura-1	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9843446566	85.48703, 85.487221	27.805195, 27.805338	1513.6582, 1519.3662
2042	254487	RV	Tika Debi Khatiwada	Tikadevi Khatiwada	Sindhupalchowk	Votehour	8	0		Melamchi Municipality	2	27	552088	Kathmandu,Shank arapura-1	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9841074459	85.486923, 85.486984	27.804356, 27.804373	1510.9771, 1522.3932
2043	254485	RV	Yadu Prasad Khatiwada	Yedu Prasad Khatiwada	Sindhupalchowk	Votehour	8	0		Melamchi Municipality	2	31	552096	Kathmandu,Shank arapura-1	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841586791	85.487183	27.805309	1523.3925
2044	254486	RV	Toyannath Khatiwada	Toya Nath Khatiwada	Sindhupalchowk	Votehour	8	0		Melamchi Municipality	2	32	552097	Kathmandu,Shank arapura-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9860931530	85.486855	27.805105	1516.8788
2045	254493	RV	Umanath Khatiwada	Umanath Khatiwada	Sindhupalchowk	Votehour	9	0		Melamchi Municipality	2	7	550007	Kathmandu,Kathm andu-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841842510	85.485268	27.80401	1569.0685
2046	254492	RV	Umanath Khatiwada	Umanath Khatiwada	Sindhupalchowk	Votehour	9	0		Melamchi Municipality	2	7	550007	Kathmandu,Kathm andu-99	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841842510	85.485268	27.80401	1569.0685
2047	254491	RV	Jiban Khatiwada	Jiban Khatiwada	Sindhupalchowk	Votehour	9	0		Melamchi Municipality	2	22	550023	Kathmandu,Shank arapura-3	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9849813784	85.486618	27.804462	1524.8317
2048	248898	RV	Dawa Tamang	Dawa Tamang, Voyo Tamang	Sindhupalchowk	Votenamlang	1	0		Pachpokhari Thangpal	7	13	362783	23-11-1-0-13		1	Grade 4	Reconstruct	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9818359715	85.659065	27.88493	1748.6801
2049	248860	RV	Pasang Lamo Tamang	Kancha Tamang, Pasang Lamo Tamang	Sindhupalchowk	Votenamlang	1	0		Pachpokhari Thangpal	7	19	362794	23-11-1-0-19		1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9803563097	85.658928	27.884512	1756.3381
2050	248776	RV	Dawa Lama	Dawa Lama, Karmu Lama	Sindhupalchowk	Votenamlang	1	9		Pachpokhari Thangpal	7	40	362562			1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9818916678	85.657585	27.884808	1727.5442
2051	248775	RV	Karma Lama	Dawa Lama, Karmu Lama	Sindhupalchowk	Votenamlang	1	9		Pachpokhari Thangpal	7	40	362561			1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9818916678	85.657585	27.884808	1727.5442
2052	248759	RV	Muna Tamang	Gopal Tamang	Sindhupalchowk	Votenamlang	2	0		Pachpokhari Thangpal	7	2	362968			1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9808582177	85.650154	27.88328	1647.8154
2053	248835	RV	Phulmaya Tamang	Sit Lal Tamang	Sindhupalchowk	Votenamlang	2	0		Pachpokhari Thangpal	7	43	362976			1	Grade 2	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9813718407			

2055	248746	RV	Saila Tamang	Bau Kaji Tamang, Mailla Tamang, Saila Tamang, Shuk Ram Tamang	Sindhupalchowk	Votenamlang	2	0		Pachpokhari Thangpal	7	58	362532	23-11-2-0-56			1	Grade 4	Reconstruct	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9813282053	85.652046	27.884237	1662.7345
2056	248748	RV	Sukuram Tamang	Bau Kaji Tamang, Mailla Tamang, Saila Tamang, Shuk Ram Tamang	Sindhupalchowk	Votenamlang	2	0		Pachpokhari Thangpal	7	58	362530	23-11-2-0-56			1	Grade 4	Reconstruct	Grade 3	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9813282053	85.652046	27.884237	1662.7345
2057	248753	RV	Man Bahadur Tamang	Chhebo Tamang, Man Bahadur Tamang, Pembasha Tamang, Subash Tamang	Sindhupalchowk	Votenamlang	2	0		Pachpokhari Thangpal	7	63	362541	23-11-2-0-61			1	Grade 4	Reconstruct	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9818930798	85.652412	27.883841	1675.5718
2058	248770	RV	Pemba Tamang	Chhebo Tamang, Man Bahadur Tamang, Pembasha Tamang, Subash Tamang	Sindhupalchowk	Votenamlang	2	0		Pachpokhari Thangpal	7	63	362542	23-11-2-0-61			1	Grade 4	Reconstruct	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9818930798	85.652412	27.883841	1675.5718
2059	248744	RV	Subas Tamang	Chhebo Tamang, Man Bahadur Tamang, Pembasha Tamang, Subash Tamang	Sindhupalchowk	Votenamlang	2	0		Pachpokhari Thangpal	7	63	362543	23-11-2-0-61			1	Grade 4	Reconstruct	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9818930798	85.652412	27.883841	1675.5718
2060	248823	RV	Jitman Tamang	Jeet Man Tamang, Kisan Bomjan Tamang, Sagar Tamang	Sindhupalchowk	Votenamlang	2	0		Pachpokhari Thangpal	7	73	362941				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9818191389	85.652863, 85.652954	27.88377, 27.883911	1677.9235, 1679.8489
2061	248824	RV	Kisan Bomjan Tamang	Jeet Man Tamang, Kisan Bomjan Tamang, Sagar Tamang	Sindhupalchowk	Votenamlang	2	0		Pachpokhari Thangpal	7	73	362942				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9818191389	85.652863, 85.652954	27.88377, 27.883911	1677.9235, 1679.8489
2062	248749	RV	Sagar Tamang	Jeet Man Tamang, Kisan Bomjan Tamang, Sagar Tamang	Sindhupalchowk	Votenamlang	2	0		Pachpokhari Thangpal	7	73	362943				2	Grade 5, Grade 1	Reconstruct, Not Required	Grade 5, Grade 1	Grade 5, Grade 1	Grade 5, Grade 1	Reconstruct, Not Required	Habitable House in Usual Place	9818191389	85.652863, 85.652954	27.88377, 27.883911	1677.9235, 1679.8489
2063	248831	RV	Sarki Tamang	Sarki Tamang	Sindhupalchowk	Votenamlang	2	0		Pachpokhari Thangpal	7	95	362662		Kathmandu, Kathmandu-12	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9851097233	85.652901	27.88085	1741.2609
2064	248668	RV	Phurba Tamang	Jag Bir Tamang, Phurba Tamang	Sindhupalchowk	Votenamlang	2	0		Pachpokhari Thangpal	7	98	362667	23-11-2-0-94			1	Grade 4	Reconstruct	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9808371082	85.653618	27.879873	1771.431
2065	248654	RV	Phulmaya Tamang	Tika Bahadur Tamang	Sindhupalchowk	Votenamlang	2	0		Pachpokhari Thangpal	7	99	362668	23-11-2-0-95			1	Grade 4	Reconstruct	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9813225634	85.654648	27.87941	1805.5581
2066	248764	RV	Dawa Tamang	Dawa Tamang	Sindhupalchowk	Votenamlang	2	0		Pachpokhari Thangpal	7	100	362669	23-11-2-0-96			1	Grade 4	Reconstruct	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9818693469	85.655479	27.87899	1839.4172
2067	248682	RV	Pasang Tamang	Pasang Tamang, Sunil Tamang	Sindhupalchowk	Votenamlang	3	0		Pachpokhari Thangpal	7	5	362853	23-11-3-0-5			1	Grade 4	Reconstruct	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9810283270	85.652168	27.897856	1792.9728
2068	248686	RV	Sunil Tamang	Pasang Tamang, Sunil Tamang	Sindhupalchowk	Votenamlang	3	0		Pachpokhari Thangpal	7	5	362852	23-11-3-0-5			1	Grade 4	Reconstruct	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9810283270	85.652168	27.897856	1792.9728
2069	248694	RV	Man Bahadur Yonjan	Bal Bahadur Tamang, Man Bahadur Yonjan	Sindhupalchowk	Votenamlang	3	0		Pachpokhari Thangpal	7	34	362881	23-11-3-0-34			1	Grade 4	Reconstruct	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9818488155	85.655197	27.886511	1669.7322
2070	248611	RV	Lal Bahadur Tamang	Kanchha Tamang, Lal Bahadur Tamang, Mailla Tamang, Risai Tamang	Sindhupalchowk	Votenamlang	4	0		Pachpokhari Thangpal	7	2	362840	23-11-4-0-2			1	Grade 4	Reconstruct	Grade 4	Grade 4	Grade 4	Reconstruct	Matrix & Photo not cleared or mismatch	9808871478	85.655869	27.882538	1761.7549
2071	248433	RV	Dipak Tamang	Dawa Tamang, Deepak Tamang	Sindhupalchowk	Votenamlang	4	0		Pachpokhari Thangpal	7	52	403246		Sindhupalchowk, Votenamlang-5	Complete Damage	2	Grade 2, Grade 5	Minor Repair, Reconstruct	Grade 2, Grade 5	Grade 1, Grade 5	Grade 1, Grade 5	Minor Repair, Reconstruct	Habitable House in Usual Place	9813758608	85.643616, 85.653877	27.882677, 27.889086	1444.0798, 1705.6942
2072	248492	RV	Astalal Shrestha	Asta Lal Shrestha, Rajendra Bahadur Shrestha, Ramchandra Shrestha, Saila Shrestha, Satya Lal Shrestha	Sindhupalchowk	Votenamlang	5	0		Pachpokhari Thangpal	7	1	536702		Kathmandu, Shank arapura-5	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9812302826	85.652443, 85.652489	27.885046, 27.885805	1650.0651, 1660.4585
2073	248416	RV	Dinesh Shrestha	Asta Lal Shrestha, Rajendra Bahadur Shrestha, Ramchandra Shrestha, Saila Shrestha, Satya Lal Shrestha	Sindhupalchowk	Votenamlang	5	0		Pachpokhari Thangpal	7	1	536705		Kathmandu, Shank arapura-5	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9812302826	85.652443, 85.652489	27.885046, 27.885805	1650.0651, 1660.4585
2074	248486	RV	Krishna Shrestha	Asta Lal Shrestha, Rajendra Bahadur Shrestha, Ramchandra Shrestha, Saila Shrestha, Satya Lal Shrestha	Sindhupalchowk	Votenamlang	5	0		Pachpokhari Thangpal	7	1	536704		Kathmandu, Shank arapura-5	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9812302826	85.652443, 85.652489	27.885046, 27.885805	1650.0651, 1660.4585
2075	248551	RV	Saila Shrestha	Asta Lal Shrestha, Rajendra Bahadur Shrestha, Ramchandra Shrestha, Saila Shrestha, Satya Lal Shrestha	Sindhupalchowk	Votenamlang	5	0		Pachpokhari Thangpal	7	1	536703		Kathmandu, Shank arapura-5	No Damage	2	Grade 5, Grade 5	Reconstruct, Reconstruct	Grade 5, Grade 5	Grade 5, Grade 5	Grade 5, Grade 5	Reconstruct, Reconstruct	Habitable House in Other Place	9812302826	85.652443, 85.652489	27.885046, 27.885805	1650.0651, 1660.4585
2076	248431	RV	Chandra Bahadur Shrestha	Chandra Bahadur Shrestha, Hari Ram Shrestha	Sindhupalchowk	Votenamlang	5	0		Pachpokhari Thangpal	7	25	536547				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	14913528	85.652557	27.885498	1654.9923
2077	248550	RV	Hareram Shrestha	Chandra Bahadur Shrestha, Hari Ram Shrestha	Sindhupalchowk	Votenamlang	5	0		Pachpokhari Thangpal	7	25	536548				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	14913528	85.652557	27.885498	1654.9923
2078	248490	RV	Jiban Tamang	Jiban Tamang, Kami Tamang, Mailli Tamang, Mangali Tamang, Nirmaya Tamang, Somo Tamang	Sindhupalchowk	Votenamlang	5	0		Pachpokhari Thangpal	7	69	536854		Sindhupalchowk, Votenamlang-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803554129	85.655533	27.884689	1702.2693
2079	248422	RV	Kami Tamang	Jiban Tamang, Kami Tamang, Mailli Tamang, Mangali Tamang, Nirmaya Tamang, Somo Tamang	Sindhupalchowk	Votenamlang	5	0		Pachpokhari Thangpal	7	69	536824		Sindhupalchowk, Votenamlang-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803554129	85.655533	27.884689	1702.2693
2080	248482	RV	Mangali Tamang	Jiban Tamang, Kami Tamang, Mailli Tamang, Mangali Tamang, Nirmaya Tamang, Somo Tamang	Sindhupalchowk	Votenamlang	5	0		Pachpokhari Thangpal	7	69	536825		Sindhupalchowk, Votenamlang-4	No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9803554129	85.655533	27.884689	1702.2693
2081	248565	RV	Deuja Tamang	Dewja Tamang	Sindhupalchowk	Votenamlang	5	0		Pachpokhari Thangpal	7	74	536869				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9810116610	85.655411	27.88459	1712.343
2082	248642	RV	Dawa Lama (Sherpa)	Dawa Lama Sherpa	Sindhupalchowk	Votenamlang	5	0		Pachpokhari Thangpal	7	96	536876				2	Grade 4, Grade 1	Reconstruct, Not Required	Grade 4, Grade 1	Grade 4, Unrecognized	Grade 4, Unrecognized	Reconstruct, Unrecognized	Matrix & Photo not cleared or mismatch	9611095024	85.672058, 85.672157	27.861883, 27.861979	2392.1409, 2394.4988
2083	248736	RV	Saila Dong	Saila Dong	Sindhupalchowk	Votenamlang	5	0		Pachpokhari Thangpal	7	115	536931				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9810091276			
2084	248571	RV	Jitlal Tamang	Jitlal Tamang	Sindhupalchowk	Votenamlang	5	0		Pachpokhari Thangpal	7	116	536933				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9810091276			
2085	248573	RV	Kanchha Bomjan	Kanchha Bomjan	Sindhupalchowk	Votenamlang	5	0		Pachpokhari Thangpal	7	117	536934				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9810091276			
2086	248369	RV	Rajkumar Pariyar	Rajkumar Nepali	Sindhupalchowk	Votenamlang	7	0		Pachpokhari Thangpal	7	6	536943		Sindhupalchowk, Votenamlang-6/Sindhupalchowk, Votenamlang-6	Complete Damage, Complete Damage	1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9813859267	85.636909	27.884188	1509.3989

2087	248741	RV	Krishna Bikram Silwal	Krishna Bikram Silwal	Sindhupalchowk	Votenamlang	7	0		Pachpokhari Thangpal	7	94	536626				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9813563330	85.63505	27.886051	1487.53
2088	248364	RV	Chandra Bahadur Gurung	Chandra Bahadur Gurung, Rudra Bahadur Gurung	Sindhupalchowk	Votenamlang	7	0		Pachpokhari Thangpal	7	97	404845				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9741267043	85.638626	27.886148	1504.6511
2089	249153	RV	Rudra Bahadur Gurung	Chandra Bahadur Gurung, Rudra Bahadur Gurung	Sindhupalchowk	Votenamlang	7	0		Pachpokhari Thangpal	7	97	404844				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9741267043	85.638626	27.886148	1504.6511
2090	249076	RV	Shanta Bahadur Gurung	Shanta Bahadur Gurung, Utam Bahadur Gurung	Sindhupalchowk	Votenamlang	8	0		Pachpokhari Thangpal	7	22	404651		Kathmandu,Shank arapura-99/Kathmandu,Shank arapura-99	No Damage, No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841144749	85.631134	27.885386	1383.3485
2091	249077	RV	Uttam Bahadur Gurung	Shanta Bahadur Gurung, Utam Bahadur Gurung	Sindhupalchowk	Votenamlang	8	0		Pachpokhari Thangpal	7	22	404650		Kathmandu,Shank arapura-99/Kathmandu,Shank arapura-99	No Damage, No Damage	1	Grade 5	Reconstruct	Grade 5	Grade 5	Grade 5	Reconstruct	Habitable House in Other Place	9841144749	85.631134	27.885386	1383.3485
2092	248721	RV	Shivaraj Gurung	Milan Gurung, Shiv Raj Gurung	Sindhupalchowk	Votenamlang	8	0		Pachpokhari Thangpal	7	38	404680		Kathmandu,Kapan-6	Partial Damage	1	Grade 5	Reconstruct	Grade 5	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place	9801241422	85.630775	27.886862	1363.5219
2093	249018	RV	Hari Bahadur Gurung	Cho Bahadur Gurung, Hari Bahadur Gurung, Man Kumari Gurung	Sindhupalchowk	Votenamlang	8	0		Pachpokhari Thangpal	7	64	404761				1	Grade 1	Not Required	Grade 1	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9813283406	85.632683	27.884834	1421.0063
2094	248957	RV	Bishnu Jumari Giri	Bishnu Kumari Giri, Chirangi Giri, Rajendra Giri	Sindhupalchowk	Votenamlang	9	0		Pachpokhari Thangpal	7	41	404826	23-11-9-0-40			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9851046472	85.632057	27.890369	1316.1886
2095	248949	RV	Rajendra Giri	Bishnu Kumari Giri, Chirangi Giri, Rajendra Giri	Sindhupalchowk	Votenamlang	9	0		Pachpokhari Thangpal	7	41	404827	23-11-9-0-40			1	Grade 5	Reconstruct	Grade 5	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	9851046472	85.632057	27.890369	1316.1886
2096	248808	RV	Tuk Bahadur Puri	Tuk Bahadur Puri	Sindhupalchowk	Votenamlang	9	0		Pachpokhari Thangpal	7	85	404711				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9810315488	85.630997	27.891655	1274.1908
2097	248876	RV	Bel Bahadur Shrestha	Bel Bahadur Shrestha, Ravi Shrestha	Sindhupalchowk	Votenamlang	9	0		Pachpokhari Thangpal	7	129	400727	23-11-9-0-125			1	Grade 4	Major Repair	Grade 4	Unrecognized	Unrecognized	Unrecognized	Matrix & Photo not cleared or mismatch	16212067	85.618858	27.892235	934.05408
2098	248807	RV	Prabha Nepali	Prama Nepali	Sindhupalchowk	Votenamlang	9	0		Pachpokhari Thangpal	7	144	400746		Ramechhap,Rampur-5	No Damage	1	Grade 4	Major Repair	Grade 4	Unrecognized	Unrecognized	Unrecognized	Habitable House in Other Place	9860201884	85.61895	27.892433	917.55414
2099	248885	RV	Bhakta Bahadur Bharati	Bhakta Bahadur Bharati	Sindhupalchowk	Votenamlang	9	0		Pachpokhari Thangpal	7	152	400830		Kathmandu,Kages wori-Manahara-4	Partial Damage	1	Grade 4	Major Repair	Grade 4	Grade 4	Grade 4	Reconstruct	Habitable House in Other Place		85.619209	27.892984	924.0462
2100	248875	RV	Gamala Silwal	Gamala Silwal	Sindhupalchowk	Votenamlang	9	0		Pachpokhari Thangpal	7	158	400837				1	Grade 1	Minor Repair	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9808294578	85.616348	27.887671	913.65491
2101	248874	RV	Chandashwori Shrestha	Chandeshori Shrestha	Sindhupalchowk	Votenamlang	9	0		Pachpokhari Thangpal	7	176	400757				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Not Required	Habitable House in Usual Place	9803506923	85.617409	27.888651	886.9411
2102	248803	RV	Ram B.K.	Ram Biswakarma	Sindhupalchowk	Votenamlang	9	0		Pachpokhari Thangpal	7	177	400759				1	Grade 1	Not Required	Grade 1	Grade 1	Grade 1	Minor Repair	Habitable House in Usual Place	9818142773	85.617424	27.888697	910.92206